




Fusick
Automotive Products Inc.

21 Thompson Road
East Windsor, CT 06088
FAX: 860-623-3118
Email: sales@fusick.com
Website: www.fusickautomotiveproducts.com

Phone: 1-860-623-1589
Phone: 1-860-623-1583
M-TH 8:00 AM to 5:30 PM
FRI 8:00 AM to 5:00 PM
SAT 9:00 AM to NOON



Welcome Buick Enthusiasts,

Thank you for your interest in our catalog covering 1936-76 Buick full size models. Many of you will associate our company with Oldsmobile, our primary business since the early 1970's. During that time span we manufactured over 1,200 parts through our investment in the tool and die process. Many Oldsmobile 88 and 98 models interchanged to Buick. Nearly all power option switches, rubber parts, door sill plates, etc. are products manufactured to our strict specifications. In addition, we provide "in house" rebuilding services for heater control valves, windshield wiper vacuum motors and more.

In the future we will add new items that will also meet our product standards. As a "GM Licensed and Approved" company, you can buy with confidence and be assured of high quality products. Our same day shipping policy guarantees quick delivery to complete your restoration in a timely manner. All of our catalogs are available free by visiting our website www.fusickautomotiveproducts.com. We look forward to assisting you with your Buick restoration.

Sincerely from your team at Fusick Automotive Products,

Office Personnel

Jason Jutras
Jason@fusick.com

Kevin McMahon
Kevin@fusick.com

Brandon Smith
BSmith@fusick.com

Michael Catania
MCatania@fusick.com

Warehouse Personnel

James Hemingway

Terrance Chase
Terrance@fusick.com

Scott Spremulli

Matt Spremulli

Michael Fusick

OVER
50
YEARS
OF SERVICE &
EXPERIENCE

Power Window and Power Seat Switches

1949-53 Buick Power Window Switches, Hydraulic Controls:

New Power Window Switches for All 1949-53 Buick models.

4566679A	Left Front Four Button Power Window Switch Assembly	235.00
4566679	Left Front Four Button Power Window Switch (no bezel)	189.00
4557610	Left Front Four Button Power Window Switch Chrome Bezel	65.00
4566678A	Single Button Power Window Switch Assembly	119.00
4566678	Single Button Power Window Switch (no bezel)	89.00
4557793	Single Button Power Window Switch Chrome Bezel	48.00
PWB48	Power Window/Seat Buttons	22.50 ea.
PWSC483	Retaining Clips for All 1948-53 Switches	3.50 ea.

NOTE: The Chrome Bezel 4557610 may differ on 1953 Buick Skylark.

1954 Buick Century and Skylark Convertible with Hydraulic Controls:

4641074A*	Left Front Four Button Power Window Switch Assembly	279.00
4641073A**	Single Button Power Window Switch Assembly	119.00

*4641074A is modified from 4566679A to accept the push-on style connection.

**4641073A is a modification of 4566678A switch. Complete assemblies only, no individual parts.



1954-57 Buick Power Window Switches, Electric Controls:

4686800A	Left Front Four Button Power Window Switch Assembly	235.00
4686800	Left Front Four Button Power Window Switch (no bezel)	175.00
4686801	Left Front Four Button Power Window Switch Chrome Bezel	65.00
4634118A	Single Button Power Window Switch Assembly	119.00
4634118	Single Button Power Window Switch (no bezel)	89.00
4634125	Single Button Power Window Switch Chrome Bezel	48.00
PWB54	Power Window Switch Button (single button switches)	22.50 ea.
PWB54LF	Power Window Switch Button (Left Front, Four Button switch)	22.50 ea.
PWSC547	Retaining Clips for All 1954-57 GM Window Switches	3.50 ea.

1958 Buick Single Button Rear Power Window Switch Assembly:

Complete power window switch assemblies include the chrome bezel, for rear door or quarters on 1958 Buick Special 4-Door Sedan & 4-Door Hardtop, Riviera Coupe & Conv.(all exc. 2-Door Sedan & Estate Wagon) and 1958 Buick Century & Super All models.

4728670A	Single Power Window Switch Assembly	119.00 ea.
4723818	Chrome Power Window Switch Bezel	48.00 ea.

1961-67 Power Window Switches: Double switch used on some 1961-64 Electra models and 1965-67 Riviera models with power windows. Complete switch assembly comes with chrome housing as pictured.

4434589	Two Button Power Window Switch	1961-67 models	130.00
----------------	--------------------------------	----------------	--------



1958-70 GM Various Power Switch and Parts Applications: New electrical contacts to repair broken or worn 1958-70 GM power window switches. Single button switches will either have a center notch or cut corner to align them into the chrome bezel in the correct direction. See photos below.

4723099	Four Button Power Window Switch Base, Left Front Door Fits 1958-63 Buick Full Size Models	115.00
4723098	Single Button Power Window Switch Base (center notch) Right Front Door or Rear Doors and Rear Quarters Fits 1958-60 Buick and 1961-63 Buick Full Size	45.00 ea.
4728670	Single Button Power Window Switch Base (corner cut) Fits 1958 Buick Special-Super-Century Sedans rear door only	45.00 ea.
PWB58	Power Window Switch Buttons for All models listed above	22.50 ea.
4LR583	Four Button Alignment Rod for 4723099 application	3.00 ea.
1SR583	Single Button Alignment Rod for 4723098 & 4728670 applications	2.00 ea.
PWSC583	Retaining Clips for All 1958-70 Switch Applications	3.50 ea.
PWSC605	Retaining Clips for 1960-65 Power Window Switches	5.50 ea.



Fusick

PWB58



Fusick



Switch Replacement Kits for the 1958-70 Applications Listed above: Kits include all the individual pieces listed above, the Switch Base, Button or Buttons, Alignment Rod and necessary Retaining Clips.

4723099KIT	Four Button Power Window Switch Kit	195.00
4723098KIT	Single Button Power Window Switch Kit (center notch)	59.00
4728670KIT	Single Button Power Window Switch Kit (corner cut)	59.00



1948-58 Power Window Switch Retainers and Reinforcements: Retainers are used on the Power Window Switch Assembly and the Reinforcements are installed on door or quarter trim pads. Four Button Retainer and Reinforcement fit 1948-56 Buick and single Button Retainer and Reinforcement fit 1948-58 Buick.

4PWR486	Four Button Power Window Switch Retainer	35.00 ea.
4PWSR486	Four Button Power Window Switch Reinforcement	29.00 ea.
1PWR488	One Button Power Window Switch Retainer	25.00 ea.
1PWSR488	One Button Power Window Switch Reinforcement	23.50 ea.




1949-53 2 way Power Seat Switch: Complete Switch & Chrome Bezel for 1949-50 models with two way power seats. New switch assembly for 1951-53 models will require slight modifications to fit original bezel. We will need customer's bezel for proper fit prior to ordering.

4566678S	Two Way Power Seat Switch & Bezel	1949-50 All	155.00
4566678	Two Way Power Seat Switch	1951-53 All	89.00



Six Way Power Seat Switch Bases and Rocker Button Assembly: New electrical contact assemblies to repair original 1959-75 six way power seat switches.

4303431	6 Way Power Seat Switch Base 1959 All, 1960 1st type with 3 Motor Type Adjuster	135.00
9711651*	6 Way Power Seat Switch Base 1960 2nd type, 1961-75 with switch in side seat panel	122.00
9711654*	6 Way Power Seat Switch Base 1961-75 with switch located in arm rest	122.00
9711696	6 Way Power Seat Rocker Button Assembly 1960-81 all with 6 way power seat switch on armrest or seat panel	45.00



***1976-81 Six way power seat switches** could use either a 9711651 or 9711654 base depending on pin and notch location; check photos at right for location of notches compared to your original. .



Power Seat Relay: New 6 prong Power Seat Relay for 1961-75 models equipped with a 4 or 6 way power seat.

5717528	Power Seat Relay	1961-64 LeSabre, Invicta, Wildcat & Electra 225, 1965-75 All with 4 or 6 way power seat	59.95
----------------	------------------	---	-------



1955-76 New Power Window Motors: Replacement Power Window Motors for all 1955-1976 2 and 4-Door Buick models equipped with power windows. Some early power window motors used a round body. Our motors have the square body and will replace original worn motors perfectly.

M3898	Right Power Window Motor (passenger side)	1955-76 All	149.00 ea.
M3899	Left Power Window Motor (driver side)	1955-76 All	149.00 ea.



Door Jamb Power Window Conduit Boot:

Rubber boot protects the power window wiring harness on All 1965-68 LeSabre, Wildcat, Electra 225 and 1967-70 Riviera.

EWC6670	Door Jamb Wiring Boot	1965-70	55.00 ea.
----------------	-----------------------	---------	-----------



Interior Dome Light Lenses and Bezels

Dome Light Switch and Chrome Cover: Slide switch used to control interior dome lights on 1948-53 Buick models.

DLS488	Dome Light Switch	1948-53, 1954 52R-72R	24.50
DL457	Dome Light Switch Cover	1948-53, 1954 52R-72R	12.50
DJP41	Rubber Mounting Pad for Switch Cover		4.50



1939-40 Dome Light Lens: Rectangular translucent Dome Lens has raised ridge down the middle, measures 3-3/4" x 2". Used on 1939-40 Coupes & Sedans exc. 80-90 series

DL398	Dome Light Lens	1939-40 models listed	24.50
--------------	-----------------	-----------------------	-------

DL398



1940-49 Convertible Dome Light Lens and Rim: Polished Stainless Steel rim complete with translucent lens, measures 2" x 3-3/8".

DL409	Dome Lens and Rim	1940-49 Convertible	47.50
--------------	-------------------	---------------------	-------

DL409



1941-49 Dome Light Lens: Translucent Dome Lens used on all closed models from 1941-49 in the center of roof. Measures 5-3/4" x 1-7/8" at widest point tapering down to 1-1/4". Includes 4 tabs to snap into bezel.

DL419	Dome Light Lens	1941-49 closed models	15.50
--------------	-----------------	-----------------------	-------

DL419



DL505

Convertible Dome Light Lens and Bezel: Used on all 1950-53 Buick Convertible models and 1954-56 Buick 50-70 Series Convertible. Attaches to rear top bow.

DL505	Dome Light Lens	1950-56 Convertible	12.00 ea.
--------------	-----------------	---------------------	-----------

DL505R	Chrome Metal Dome Light Bezel	1950-56 Convertible	35.00 ea.
---------------	-------------------------------	---------------------	-----------



DL505R



1950-60 Side Roof Dome Light Lenses: Rectangle lens with ribbed design used on both sides of the roof for many 1950-60 closed models.

Lens measures 5-1/4" long x 1-3/4" wide.

DL502	Side Roof Dome Lens	1950-60 closed	12.50 ea.
--------------	---------------------	----------------	-----------



DL502

Center Roof Dome Light Lens and Bezel: Mounts in center roof on 1950-56 Buick closed models. Tear drop-shaped Chrome Bezel is 7-1/2" x 2-3/4" and has the opening for dome light switch. Companion lens measures 4-1/2" x 2".

DL506	Dome Light Lens	1950-56 closed	14.50
--------------	-----------------	----------------	-------

DL506R	Chrome Metal Dome Light Bezel	1950-56 closed	35.00
---------------	-------------------------------	----------------	-------



DL506



DL506R

Center Roof Dome Light Lens and Chrome Bezel: 3-3/4" diameter replacement lens has three mounting tabs and smooth design. Large application for many 1957-68 Buick closed models and Wagons.

DL578B	Dome Light Lens	1957-68	18.50
---------------	-----------------	---------	-------

DLH578B	Dome Light Chrome Bezel	1957-68	26.50
----------------	-------------------------	---------	-------



DL578B



DLH578B

1959-61 Side Roof Dome Light Lenses: Dome lens used on side roof panels, two per car. Original lenses were plain. These replacement lenses have line detail. Lens measures 6-1/4" x 1-1/2" at widest point.

DL591 Side Roof Dome Lens 1959-61 closed models 24.50 ea.

Fusick DL591

Convertible Courtesy Light Lens and Housing:

Fits into lower rear arm rest on All 1954-70 Buick Convertible models.

CL877 Courtesy Light Lens 8.50 ea.

CLH622 Courtesy Light Chrome Housing 28.50 ea.

Convertible Quarter Armrest Courtesy Lens:

Opaque lens measures 2" x 1 1/4" for rear quarter arm rest area on 1971-75 LeSabre & Centurion Convertible models.

CL326 Courtesy Lens 1971-75 Conv. 9.50 ea.

Door Panel Courtesy Light Lenses: 1-1/8" x 3-3/4" lenses fit into the housing located on the lower door panels of 1973-75 LeSabre and Electra 225 models. One Red lens and one White lens used per door panel.

CL32W White Courtesy Light Lens 1973-75 models 9.50 ea.

CL33R Red Courtesy Light Lens 1973-75 models 9.50 ea.

Rear Sail Panel Courtesy Light Housing and Lens: Bright chrome plated Courtesy Light Housing attaches to the rear sail panels on 1962 Invicta 4-Door Hardtop, 1962 Electra 2 and 4-Door Hardtop, and 1963-65 Riviera. Three tab, smooth faced opaque lens measures 2" diameter.

CLH627 Sail Panel Courtesy Light Housing 49.50 ea.

CL600 Sail Panel Courtesy Light Lens 8.50 ea.

Sail Panel Courtesy Light Housing and Lens: Chrome plastic Courtesy Light Housing used on rear sail panels for 1969 Wildcat Custom 2 & 4-Door Hardtop and 1969 Electra models except for Convertible. 2" diameter lens has four mounting tabs and concentric circle design.

DLH692 Sail Panel Courtesy Light Housing 19.50 ea.

CL819 Sail Panel Courtesy Light Lens 9.50 ea.

Center Roof Dome Light Bezel and Lens: Chrome plastic Dome Light Bezel mounts to the interior roof panel on 1971-72 LeSabre except Convertible, 1973-75 Estate Wagon (uses two) and All 1973-75 LeSabre, Centurion, and Electra models except Convertibles. Opaque Dome Light Lens has a single ridge around perimeter.


DLH69 Center Roof Dome Light Housing 1971-75 25.00 ea.

DL77 Center Roof Dome Light Lens 1971-75 13.00 ea.

Front Seat Rear Robe Pullcord Escutcheon:

Chrome plated stamped steel cap used on 1953 Special 4-Door, 1954-56 Century Riviera Hardtop & Convertible, 1955 Special Estate Wagon, 1955-56 Series 41-43-46R-48-69 Custom Trim, 1956 Special Riviera Hardtop & Convertible. 4 used per car.

4605687 Front Seat Pullcord Escutcheon 29.50 ea.



Interior Door Handles and Window Crank Handles

Interior Door Handles: Chrome plated interior door handle for all 1939-53 models. Bright chrome finish with line detail on handle.

IDH393B Interior Door Handle 1939-53 All 21.50 ea.

Interior Window Crank Handles: Chrome plated interior Window and Vent Window Crank Handles for all 1939-53 models. Bright chrome finish with chrome knob and line detail in handle.

IWH393B Window Crank Handle 1939-53 All 24.50 ea.

IVH393B Vent Window Crank Handle 1939-53 All 24.50 ea.

Interior Handle Bezels: Chrome plated interior Door Handle and Window Crank Bezels with inner spring loaded ring. Used on all 1942-53 Buicks.

HE423S Handle Bezel 1942-53 All 18.50 ea.

Interior Door Handles: Interior door handles available for 1954-58 Buick 40-60 series and 1954 Buick Skylark. Excellent quality cast chrome plated handles are sold with retaining clip.

IDH548 Interior Door Handle 1954-58 Buick All 37.50 ea.

Inside Window Crank Handles:

New cast Chrome Handles come complete with retaining clips. Used on 1954-58 Buick except Century Convertible and Skylark.

IWH497 Window Crank Handle 1954-58 Buick 40.00 ea.

Inside Vent Window Crank Handles:

New cast Chrome plated Vent Window Crank Handles for 1954-58 Buick 40-60 series, and 1954 Buick Skylark. Handles include retaining clips.

IVH498 Vent Window Crank Handle 1954-58 Buick 40.00 ea.

1959-64 Window Crank Handle: Chrome, double arm Window Crank Handle fits All 1959-64 models. 4-1/2" long with Chrome knob.

IWH594 Window Crank Handle 1959-64 Buick 40.00 ea.

1959-64 Vent Window Crank Handle: 3-1/2" long with Chrome knob, correct ring design. Fits All 1959-64 models. Includes retaining clip.

IVH594 Vent Window Crank Handle 1959-64 Buick All 40.00 ea.

1965-66 Window Crank Handle: Chrome plated Window Crank Handles for 1965-66 Buick LeSabre, Wildcat, and Electra models. Includes retaining clip.

IWH6566 Window Crank Handle 1965-66 Buick 31.50 ea.


1965-66 Vent Window Crank Handle: Chrome plated Vent Window Crank Handles for 1965-66 Buick LeSabre, Wildcat, and Electra models. Includes retaining clip.

IVH6566 Vent Window Crank Handle 1965-66 Buick 24.50 ea.

Inside Paddle Style Chrome Door Handles: Chrome Interior Door Handles used on many Buick models from 1960-67. Match to originals. Sold in pairs.

IHD634 Paddle Style Door Handles, Chrome 59.50 pair

IHD634B Paddle Style Door Handles, brushed top 89.50 pair



Foam Handle Cushion: Foam cushion between door and door panel around window crank shaft or door handle shaft.

DWC350 Foam Handle Cushion 1937-60 All 3.00 ea.

Door Handle Tension Spring: Cone shaped spring installs in back of door panel around window cranks or door handles.

1267 Door Handle Tension Spring 1937-60 All 4.50 ea.

Door and Window Handle Backing Plates: Molded plastic backing plate between door panels and window crank or door opening handles.

HBP647 Handle Backing Plate 1954-75 All 4.00 ea.

1969-70 Buick Turn Signal Lever: Chrome plated plastic knob with metal lever used on 1969-70 Buick models except for cars equipped with factory cruise control.

TSL690 Turn Signal Lever 1969-70 exc. cruise 28.50

Interior Windlace Rubber Stop: Small rubber cap attaches to the top of quarter windlace on All 2-Door Riviera Hardtop & Convertible models.

WRS30 Windlace Rubber Stops 16.50 pr.

Interior Coat Hooks: Stamped steel, Chrome plated Coat Hooks for 1949-66 models and black plastic hooks for 1964-72 & 1973-77 models. Mid-sixties models may have had either steel or plastic design. Check your originals for proper match.

CH496 Interior Coat Hook, chrome 1949-66 models 11.00 ea.

CH647 Interior Coat Hook, black 1964-72 models 11.00 ea.

CH737 Interior Coat Hook, black 1973-77 models 11.00 ea.

Chrome Door Lock Buttons: Replacements for worn or broken door lock buttons.

DB37 Door Lock Button (Brown rubber) 1937-47 All 7.50 ea.

DB48 Door Lock Button (Chrome metal) 1948-58 All 16.50 ea.

DB660 Door Lock Button (Chrome plastic) 1965-66 All 7.50 ea.

DB670 Door Lock Button (Chrome plastic) 1967 All 7.50 ea.

DB682 Door Lock Button (Chrome plastic) 1968-70 All 7.50 ea.

DB737 Door Lock Button (Chrome plastic) 1971-75 All 7.50 ea.

Door Lock Ferrules: DLF647 is transparent plastic while DLF682 is metal with an inside felt seal. Ferrules attach to the door panels around the door lock button.

DLF647 Door Lock Button Ferrule 1961-63 LeSabre, 4.00 ea.
Invicta & Electra

DLF682 Door Lock Button Ferrule 1964 All, 1965 Riviera 6.00 ea.
1968-74 All

Parking Brake Knob: Black plastic knob with the word 'brake' in white lettering, for all 1948-55 Buick models.

PBK485B Park Brake Knob 1948-55 All 8.00



Rear Arm Rest Ash Tray and Sliding Cover: Quality Chrome plated Ash Tray Frame and Sliding Cover in rear arm rest on 1951-53 Special Convertible & Riviera Hardtop models. Ash tray inserts into sliding cover.

ATF513	Ash Tray Frame & Cover	1951-53 Special	39.50 ea.
AT513	Ash Tray Insert for Above	1951-53 Special	24.50 ea.



Rear Arm Rest Ash Trays and Bezels:

Bright Chrome finish Ash Tray and Chrome Bezel mounts into the rear arm rest on the following Buick models: 1948-50 Roadmaster Sedanet, 1949-53 Super-Roadmaster Conv. and Roadmaster Riviera Hardtop, 1954 Skylark, 1954-58 Super Conv. and All Roadmasters, 1958 Super, Roadmaster, Limited Convertible & Limited Hardtop

AT547	Rear Armrest Ash Tray	1948-58 listed models	38.50 ea.
AT548B	Rear Ash Tray Bezel	1948-58 listed models	14.50 ea.



Rear Arm Rest Ash Trays: Chrome plated Ash Tray Insert and Chrome Bezel located in the rear arm rest on 1959-67 LeSabre, Invicta, Wildcat, Electra 2-Door Hardtop and Convertible models, and 1966-67 Riviera.

AT6145	Rear Ash Tray	1959-67 listed models	26.50 ea.
---------------	---------------	-----------------------	-----------



Rear Arm Rest Ash Trays: Chrome plated Rear Ash Tray assemblies used on 1968-70 Riviera, 1968-70 LeSabre, Wildcat & Electra 4 Door, 1971-76 LeSabre 4-Door, 1972-74 Electra 4-Door and 1972-75 Centurion 4-Door Hardtop.

AT6869	Rear Ash Tray	1968-76 listed models	35.00 ea.
---------------	---------------	-----------------------	-----------



Manual Seat Adjuster Knob and Bezel: Chrome 'T' shaped knob with allen set screw used on 1950-60 models not equipped with power seats. Chrome plated bezel attaches to lower seat panel with bend over tabs for 1950-53 models.

4591925	Seat Adjuster Knob	1950-52 All, 1953-56 50-70 series, 1957-58 40-50-60 Series exc. 56C & 66C, 1959-60 except Wagon	33.50 ea.
4562513	Seat Adjuster Bezel	1950-53 All	17.50 ea.



Seat Back Rubber Bumpers: Rubber bumper with metal insert. Two per seat back used on 2 door models.

SB491	Seat Bumper	1951-52 Special 2-Door	11.00 ea.
SB530	Seat Bumper	1953-54 Special 2-Door, 1954 Century 2-Door	11.00 ea.
SB546	Seat Bumper	1954-56 Special & Century 2-Door	11.00 ea.
SB578	Seat Bumper	1953-56 Super & Roadmaster 2-Door, 1953-54 Skylark, 1957-58 All 2-Door models	11.00 ea.
SB61	Seat Bumper	1961-72 with round bumpers	6.50 ea.
SB65	Seat Bumper	1961-72 with oval bumpers	7.00 ea.



Inside Rearview Mirrors

Inside Day/Night Rearview Mirrors: Polished Stainless Steel backing with day/night button.

397IM	Inside Rearview Mirror	1939-50 2-pc window	105.00
480IM	Inside Rearview Mirror	1948-50 1-pc window	105.00
	with threaded mounting bracket		
480IMS	Inside Rearview Mirror	1950-53 All	105.00
	using loop mount bracket with set screw		
546IMS	Inside Rearview Mirror	1954-56 All	105.00
549IMS	Inside Rearview Mirror	1957-66 All	105.00
IM6713	Inside Rearview Mirror	1967-68 All	65.00
IM6981	Inside Rearview Mirror	1969-71 All	65.00
IMS522	Chrome Mirror Set Screw	1952-70 All	4.50

1959-60 Convertible Inside Rear View Mirror Bracket: Chrome plated Inside Mirror Bracket correct for all 1959-60 Convertible models. Large hooks on top of the bracket accept the inner sun visor rods.

4757750	Inside Mirror Bracket	1959-60 Convertible	109.00
----------------	-----------------------	---------------------	--------

Rearview Mirror with Map Light: Reproduction of the accessory Inside Mirror with Map Light which was available in 1969-71. Mirror is 12" wide with a Stainless Steel backing, includes pigtail wire to plug into the dash harness. Can also be used on 1972 models, original backing was black in 1972.

IM6981L	Inside Mirror with Map Light	1969-71	109.50
----------------	------------------------------	---------	--------

1956-58 Sun Visor Brackets: Chrome plated swivel brackets used on 1956-58 Special & Century closed models. Sold in a pair.

4650306	Sun Visor Brackets	1956-58 Special & Century	42.00 pr.
----------------	--------------------	---------------------------	-----------

1954-58 Convertible Sun Visor Center Support Hooks: Small Chrome hooks mount to the inside window trim near rearview mirror bracket and accepts the inner pins on sun visors.

SVH548	Sun Visor Hooks	1954-58 Convertible	72.00 pr.
---------------	-----------------	---------------------	-----------

1959-62 Sun Visor End Grommets: Silicone rubber grommet slips over the sun visor rod and keeps it secure in the mirror 'U' bracket. Used on All 1959-62 models where the inner visor rod sets into the rear view mirror bracket.

GS592	Sun Visor End Grommets	1959-62 models	9.50 pr.
--------------	------------------------	----------------	----------

1961-75 Sun Visor Grommet and Sleeve: Rubber grommet slides onto inner pin of sun visors. Plastic sleeve is used on outer bracket. Sold in a four piece set.

GS6400	Sun Visor Grommets and Plastic Sleeve	1961-75	8.50 set
---------------	---------------------------------------	---------	----------

Door Panel Reflector: Red reflective lenses with Chrome bezel, used on the door panels on many 1962-69 Buick models.

DPR702	Door Panel Reflector	40.00 ea.
---------------	----------------------	-----------

397IM



480IMS



546IMS

Fusick



IM6981



IMS522

4757750



Fusick

Accessories


Accessory Traffic Light Viewer: Accessory mounts onto dash and brings traffic lights into view on cars equipped with outside visors. A highly sought after accessory for All 1949-56 models.

TLV496	Accessory Traffic Light Viewer	1949-56 models	59.50
---------------	--------------------------------	----------------	-------



Accessory Visor Vanity Mirrors: Accessory mirror clips onto the sun visor with built in clips. 1936-53 Mirror features spots for maintenance reminders and travel information on either side of the mirror. The 1954-60 mirror has 'Buick is a Beauty Too' in script across the bottom.

VM360B	Visor Vanity Mirror	1936-53 All	42.00
VM546B	Visor Vanity Mirror	1954-60 All	45.00



Accessory Tissue Dispensers: Desirable dealership accessory for all Buicks from 1950-65. Mounts under the dash with included swivel bracket. Uses a normal 9-1/2" x 4-3/4" x 2" tall tissue box. 1950-59 Dispenser has a round recessed area on front for coat of arms emblem. Front face of the 1960-65 Dispenser has a brushed triangle pattern finish.

TD1B	Accessory Tissue Dispenser	1950-59 All	84.50
TD1EB	Buick Coat of Arms Emblem	1950-59 All	8.00
TD2B	Accessory Tissue Dispenser	1960-65 All	84.50
TD2EB	Buick Tri Shield Emblem	1960-65 All	8.00



TD1EB



TD1B



TD2EB



TD2B

GM Accessory Dash Compass: Popular GM accessory originally available at GM dealerships. Adheres to dashboard with included mounting plate and screw.

983335	Accessory Dash Compass	75.00
---------------	------------------------	-------



Accessory License Plate Frames: Fashionable accessory for All 1937-60 License Plates, California plate style has larger rounded corners.

LF370	1937-60 Accessory License Plate Frame	49.00
LF415C	1937-55 California License Plate Frame	55.00

For round corner California plates only.



70200

Accessory Curb Feelers: Popular accessory for any antique automobile. Alerts driver if too close to curb while parking. Attaches to edge of wheel well with included hardware.

Sold in a pair for front or rear applications.

70200	Curb Feeler Set, Vintage Style, single curly design	18.50 pair
70203	Curb Feeler Set, Fifties Style, double coil design	15.00 pair



70203

GM Accessory Locking Gas Cap: Sold complete with two keys, excellent chrome plated finish with embossed GM Logo on the key lid. Fits All 1934-58 models.

LGC348	Accessory Locking Gas Cap	1934-58 All	85.00
---------------	---------------------------	-------------	-------



Accelerator, Brake and Clutch Pedal Pads

Accelerator Pedals: Black rubber Accelerator Pedals with steel core for 1942-58 All Buick models.

AP424B	Accelerator Pedal	1942-54 All	26.50
AP556B	Accelerator Pedal	1955-56 All	49.50
AP578B	Accelerator Pedal	1957-58 All	36.50

Accelerator Rod Bellows: Black rubber boot covers the accelerator pedal rod where it passes through the floorboard.

AB488	Accelerator Rod Bellows	1948-58 All	8.50
--------------	-------------------------	-------------	------

1937-55 Brake/Clutch Rod Floor Seal: Rubber boots for brake and clutch rods where they pass through floorboards. Sold in pairs.

FS375B	Rubber Floor Seal	1937-55 All	18.50 pr.
---------------	-------------------	-------------	-----------

1932-40 Brake and Clutch Pedal Pads: Diamond pattern texture molded into pedal pad, 1932-35 50 Series, 1936-40 60-80-90 Series with manual transmission.

CB32BK	Black Brake/Clutch Pedal Pad	1932-40 Series listed	16.00 ea.
CB32BN	Brown Brake/Clutch Pedal Pad	1932-40 Series listed	16.00 ea.

1934-55 Brake and Clutch Pedal Pads: Black or Brown rubber slip-on pedal pad used on models with man. trans. exc. CB32 applications. 2-3/16"H x 3-3/16" W. Sold in pairs.

CB34B	Black Brake/Clutch Pedal Pads	1934-55 with man. trans.	21.50 pr.
CB34BR	Brown Brake/Clutch Pedal Pads	1934-55 with man. trans.	21.50 pr.

1948-55 Dynaflo Brake Pedal Pads: Black rubber Brake Pedal Pads for cars equipped with the Dynaflo Transmission only. BP278B measures 3" H x 3-1/2" W. BP285B measures 3" H x 4-1/2" W and fits All models except 40, 76, & 100 Series.

BP278B	Brake Pedal Pad	1948-52 with Dynaflo Trans	22.00
BP285B	Brake Pedal Pad	1953-55 with Manual Brakes	34.00

1957-58 Power Brake Pedal Pad: Black rubber pad has 'Power Brake' White raised letters, measures 2-5/8"H x 5-1/2" W and slides over existing metal brake pedal assembly. Used on 1957-58 Buicks with Dynaflo Transmission.

BP406B	Power Brake Pedal Pad	1957-58 with Dynaflo	67.00
---------------	-----------------------	----------------------	-------

1955-58 Parking Brake Pedal Pad: Raised 'Park' letters in White on a Black rubber pad for all 1955-58 Buick models. Measures 2-1/16" x 2-1/16" square.

PB405B	Park Brake Pedal Pad	1955-58 All	47.00
---------------	----------------------	-------------	-------

1965 & 1967-74 Automatic Brake Pedal Pad: Black rubber Brake Pedal Pad with two stainless trim moldings for 1965 and 1967-74 Buick models with automatic transmissions.

BP650B	Brake Pedal Pad	1965, 1967-74 with auto trans	25.50
---------------	-----------------	-------------------------------	-------



Buick Glove Box Liners: New replacement inserts are made from durable cardboard with a soft cloth lining. Installs using original mounting points.

GB49B	Glove Box Liner	1949 Super & Roadmaster	53.00
GB503B	Glove Box Liner	1950-53 Super & Roadmaster	53.00
GB513B	Glove Box Liner	1951-53 Special	53.00
GB545B	Glove Box Liner	1954-55 Special & Century, 1954 Skylark	53.00
GB56B	Glove Box Liner	1956 Special & Century	53.00
GB56SRB	Glove Box Liner	1956 Super & Roadmaster	53.00
GB64B	Glove Box Liner	1964 LeSabre, Wildcat & Electra	53.00
GB74B	Glove Box Liner	1974 LeSabre	53.00
GB756B	Glove Box Liner	1975-76 LeSabre	53.00



GB49B



GB513B



GB545B



GB56B

Glove Box Hinge Grommet: Self retaining oval rubber grommet installs into dash around glove box hinge for 1956-58 Buicks.

GB560 Glove Box Hinge Grommet 5.50 ea.



GB11

GB10


Glove Box Rubber Bumper: Small round, domed or flat head rubber bumpers for glove box door.

GB10 Glove Box Bumper 2.00 ea.

GB11 Glove Box Bumper 2.00 ea.

Front Lower Kick Panels: Front seat area Lower Kick Panels are a neutral colored hard cardboard die cut to original shape. Can be dyed or covered with upholstery to match your interior.

KP55BC	Kick Panels	1955 Hardtop & Convertible	43.50 pr.
KP56B	Kick Panels	1956 All models	43.50 pr.
KP57B	Kick Panels	1957 Century & Special	43.50 pr.
KP570SB	Kick Panels	1957 Super	43.50 pr.
KP58B	Kick Panels	1958 All models	43.50 pr.
KP59B	Kick Panels	1959 All models	43.50 pr.



KP570SB

Steering Column Floor Plates

1954-55 Buick Floor Plate: Triangle shaped Steering Column Floor Plate for 1954-55 Super and Roadmaster models. Black ribbed rubber over a metal inner core.

SCP545BL Steering Column Plate 1954-55 Buick 179.00

SCP545BL



SCP546

1954-56 Buick Floor Plate: Black ribbed rubber over a metal inner core. Steering Column Floor Plate used on 1954 Special, Century and Skylark as well as 1955-56 Special and Century models.

SCP546 Steering Column Plate 1954-56 Buick 227.00



SCP560

1956 Buick Floor Plate: Rectangle shaped Steering Column Floor Plate for 1956 Super and Roadmaster models. Black rubber ribbed cover over a metal core.

SCP560 Steering Column Plate 1956 Buick 289.00



1957-58 Buick Floor Plate: Black ribbed rubber cover over a metal inner core. Steering Column Floor Plate for all 1957-58 Buick models.

SCP578 Steering Column Plate 1957-58 All 185.00



SCP578


1953-76 Original Style Carpet Sets: All Carpet Sets include 1/2" thick jute insulation bonded to the underside, matching color heel pads (machine bonded) and dimmer switch grommet. All carpets listed will require customer approval of our color sample before ordering. Please contact us for desired color and materials. Many colors are available. The colors listed below are the more popular ones. We request that carpet orders are called in so we can be sure that all the correct information has been supplied for the correct carpet.

Daytona Loop Carpeting: Foam padded backing with tight loop nylon carpeting. These carpet sets are cut and sewn, rather than press molded. All exposed edging has sewn on matching welting and carpets include jute insulation bonded to the underside. Please call for color samples before placing an order.

#7151 Black	#7154 Dark Blue	#7160 Aqua	#7162 Blue	#7167 Frost Blue
#7150 Red	#7153 Dark Green	#7163 Light green	#7164 Beige	#7157 Bronze
#7165 Gray	#7166 Brown			

Grospoint Carpeting: Same high quality material as the Daytona Loop Carpet. Grospoint Carpet is a larger loop with foam backing. All Grospoint carpets are cut and sewn. Only available in Beige or Red.

Grospoint



Tuxedo Loop Carpeting: Excellent quality 80/20 Loop Tuxedo Carpets are the respective color with black strands interwoven into the material. Available in the following color combinations:

#A-1 Olive Green/Black	#A-2 Charcoal/Black	#D-4 Blue/Black	#C-3 Red/Black
#1076 Fawn/Black	#B-2 Turquoise/Black		


80/20 Loop Carpeting and Cut Pile Carpeting: Each carpet set has a machine bonded, color matching driver's side heel pad, jute insulation bonded to the underside and a dimmer switch grommet. Molded carpet sets are heat pressed into original floor pan dies for a factory fit and appearance.

80/20 Loop Carpet Colors

#01 Black	#11 Medium Saddle
#41 Red	#12 Dark Saddle
#05 Aqua	#13 Maroon
#45 Dark Green	#16 Dark Blue
#20 Gold	#10 Dark Brown
#19 Fawn (Tan)	#17 Bright Blue
#33 Dark Teal	

Cut Pile Carpet Colors

#801 Black	#875 Oxblood
#819 Dark Blue	#825 Maroon
#807 Dark Gray	#820 Saddle
#810 Brown	#815 Red
#809 Green	#1804 Silver
#7769 Light Saddle	



Daytona



Tuxedo Loop



80/20 Loop



Cut Pile

Carpet patterns are available for the following year and model Buicks:

Cut & Sewn Grospoint Carpet Set	1953 Super & Roadmaster Convertible & Riviera Coupe, 1953 Skylark	569.00 set
Cut & Sewn Daytona Carpet Set	1954-58 All models including 1954 Skylark	489.00 set
Cut & Sewn 80/20 Loop Carpet Set	1954-58 All models	299.00 set
Molded Tuxedo Carpet Set	1959-62 All models, 1963-64 some models	489.00 set
Molded 80/20 Loop Carpet Set	1959-75 All full size, 1963-75 Riviera	299.00 set
Molded Cut Pile Carpet Set	1959-75 All full size, 1963-75 Riviera	299.00 set



Door Sill Plates

1955-58 Buick Door Sill Plates: Anodized Aluminum Sill Plates for the following 2 and 4-Door Buick models.

SP562D	Door Sill Plates	1955-56 Buick 40-60 Series 2-Doors	175.00 pr.
SP554HS	Door Sill Plates	1955-56 Buick 40-60 Series 4-Door Hardtop	199.00 set of 4
SP5564D	Door Sill Plates	1955-56 Buick 40-60 Series 4-Door Sedan	199.00 set of 4
SP782D	Door Sill Plates	1957-58 Buick 40-60 Series 2-Doors	179.00 pr.



SP562D



SP554HS

1959-75 Buick Door Sill Plates: Anodized Aluminum Sill Plates complete with 'Body by Fisher' emblem. Screws included with all sill plates.

SP590D	Door Sill Plates	1959-60 LeSabre, Invicta & Electra 2-Doors	195.00 pr.
SP614	Door Sill Plates	1961-64 2-Door models, 1963-65 Riviera	95.00 pr.
SP6144D	Door Sill Plates	1961-64 4-Door Lesabre, Invicta & Wildcat	129.00 set of 4
SP6667	Door Sill Plates	1965-70 2-Door Lesabre, Wildcat & Electra	95.00 pr.
SP650	Door Sill Plates	1965-70 4-Door Lesabre, Invicta & Wildcat	139.00 set of 4
SP670T	Door Sill Plates	1966-70 Buick Riviera	119.00 pr.
SP7180	Door Sill Plates	1971-75 Full size 2-Door models, 1971-75 Riviera	129.00 pr.



SP670T



SP7180



Fisher Body Plates: Metal 'Fisher Body' tags typically attach to lower front seat panels with included screws.

4102041	Fisher Body Plate	1934-40 All	17.50 ea.
4116759	Fisher Body Plate	1941-58 All	17.50 ea.




4102041

4116759

1950-56 Buick Rubber Floor Mats: Rubber Floor Mats available in Black or Maroon for all 1950-56 Buick models. Features ribbed design, sold in a pair. Same mats used for front and rear of vehicle.

FM506BB	Black Rubber Floor Mats	1950-56 Buick	49.50 pr.
FM506BM	Maroon Rubber Floor Mats	1950-56 Buick	49.50 pr.



Buick Accessory Rubber Floor Mat Set: Floor Mat Set available in Black or Red with tri-shield Buick logo in White. Fits all 1961-75 Buick full size models and 1963-75 Riviera models. Sold in a set of four

FM715BB	Black Floor Mat Set	1961-75 Buick	239.00 set
FM715RB	Red Floor Mat Set	1961-75 Buick	239.00 set



Door Jamb Light Switches: Electrical button switch located in door jamb controls interior courtesy lights while door is open.

4598597	Door Jamb Light Switch	1941-56 All	27.50 ea.
DJP41	Door Jamb Switch Pad	1941-56 All	4.50 ea.
4709879	Door Jamb Light Switch	1959-60 All	27.50 ea.



Door Jamb Striker: Chrome plated striker plate with spring loaded tab.

DJS418	Door Jamb Striker	1941-48 All exc. Roadmaster	33.50 ea.
---------------	-------------------	-----------------------------	-----------

Dovetail Door Striker Wedge: Used on All 1937-48 models except for Roadmaster. Chrome plated wedge locks into door latch when door is closed.

DTW378	Dovetail Door Striker	1937-48 exc. Roadmaster	23.50 ea.
---------------	-----------------------	-------------------------	-----------



Door Jamb Strikers: New Door Jamb Striker Plates fit 1954-56 all Special, Century and Skylark Models, 1956 Super and Roadmaster 4-Door Hardtop models in front and rear and 1957-60 All models front or rear. Sold in pairs.

DJS549	Door Jamb Striker Plates	1954-60 models	55.00 pr.
---------------	--------------------------	----------------	-----------



Door Latch Repair Kit: Four piece kit includes two steel springs, clip and set screw to repair one door latch. For All 1939-48 Buick models.

DLRK398	Door Latch Repair Kit	1939-48 All	25.00 ea.
----------------	-----------------------	-------------	-----------



DSA642

Door Jamb Striker Bolts: New Door Jamb Striker Bolts for 1965-76 Buick models. 1965-70 design has a metal collar while 1971-76 has a nylon collar.

DSA642	Door Striker Bolt	1965-70 All models	14.50 ea.
DSA736	Door Striker Bolt	1971-76 LeSabre, Centurion, Electra & Riviera	19.50 ea.



Outside Door Handle Set Screws: Chrome plated, tapered screw used to attach the outside door handles to the shaft on 1933-49 Buicks.

ODHS348	Outside Door Handle Screws	6.75 pr.
----------------	----------------------------	----------



DSA736

Door Hinge to Body Pillar Bolts: Phillips countersunk flat head bolt with lock washer used on All 1946-60 models. 5/16-24 x 1". Used to attach door hinge to body pillar. Package of five services one door.

DHP420	Door Hinge to Body Bolts	1946-60 All	14.50 pkg of 5.
---------------	--------------------------	-------------	-----------------



Door Hinge to Door Bolts: Hex head bolt with washer, 5/16"-24 x 1-5/8". Attaches door hinge to the doors on All 1948-60 models. Package of six services one door.

DHD480	Door Hinge to Door Bolts	1948-60 All	18.00 pkg of 6.
---------------	--------------------------	-------------	-----------------

Door Latch to Door Mounting Screws: Chrome Phillips head countersunk screws with lock washers attach the door latch assembly into door. Package of six services two doors.

DLD490	Door Latch to Door Screws	1949-60 All	12.50 pkg.
---------------	---------------------------	-------------	------------



Door Striker to Door Jamb Screw package: Three screws used per door striker on All 1949-60 models to mount into door jamb. Phillips flat head countersunk screws with lock washers. Silver oxide finish 5/16-24 x 1-5/16" Package of six services two doors.

DSJ493	Door Striker Mounting Screws	1949-53 All	12.50 pkg.
---------------	------------------------------	-------------	------------

DSJ540	Door Striker Mounting Screws	1954-60 All	12.50 pkg.
---------------	------------------------------	-------------	------------




Spare Tire Retaining Nut: Cadmium plated finish hex nut used on most 1949-58 Buick models with vertical mounted spare tire.

STN458 Spare Tire Retaining Nut
1949-58 14.50




Tweed Trunk Material: Many 1940's models used a cut & sewn tweed material to finish off the trunk compartment. This material is very similar to original factory trunk material, and is available in two colors; Brown or Gray. Samples available upon request. Sold by the linear yard; material is 54" wide.

TM-BT Brown Tweed Trunk Material 99.00 yard
TM-GT Gray Tweed Trunk Material 99.00 yard



Brown Chain Link Pattern Trunk Material: Light Tan with Dark Brown printed pattern, material is sold by the yard and will need to be cut and sewn to fit trunk floor. Used on many 1946-52 Buick models. Most models use 3-1/2 yards; material is 55" wide.

TM300 Chainlink Trunk Material 95.00 per yard



Tail Lamp Mounting Pads: Molded rubber mounting pads for chrome tail lamp housing to body.

TLP190B Tail Lamp Mounting Pad 1954 Skylark 127.00 pr.
TLP100B Tail Lamp Mounting Pad 1955-57 All 48.00 pr.



TLP190B

Trunk Handle Mounting Pads:

THP200B Trunk Handle Mounting Pad 1942-48 Super & Roadmaster 45.00
THP558B Trunk Handle Mounting Pad 1955-57 Super & Roadmaster, 19.50 pr.
1958 Special, Super and Century exc. Wagon



THP200B

Tail Light Wiring Boot and Hose: Rubber boot and tube protects the wiring harness for the tail light assemblies. Sold in pairs or four piece sets.

TWB420B Tail Light Wiring Boot 1950 All, 1951 50-70 Series (4-pc set) 170.00 set
TWB419B Tail Light Wiring Boot 1953 All except Skylark 120.00 pr.
TWB521B Tail Light Wiring Boot 1953 Skylark (4-pc set) 335.00 set



TWB420B



TWB419B



TWB521B

Black Beaded Fender Welt: Used on 1937-48 all models and 1949-53 Roadmaster between rear fenders and body of car.

FW100 Black Fender Welt by the foot 2.50 per foot
FW100A Black Fender Welt 25 foot roll 29.50 roll
FW100B Black Fender Welt 50 foot roll 45.00 roll



Body and Floor Pan Rubber Plugs: Sold in a package of 20 plugs. Includes 10 each of two sizes 1/2" diam. and 7/8" diam. for holes in floor pans and body.

BFP490 Body and Floor Pan Plugs 1949-60 All 45.00 pkg.



Front Fender Chrome Porthole Inserts: One of Buick's most recognizable features is the Chrome Portholes or 'venti-ports' on the front fenders. These inserts have superior chrome finish and will add a nice finishing touch to any classic Buick.

1949 Buick Fender Porthole: Round Chrome plated inserts used on All 1949 models.

PH49B Porthole Insert 34.50 ea.

1951-52 Buick Fender Porthole: For use on All 1951-52 Special and Super models. Different designs are available for left or right side.

PH512BL Left Porthole Insert 39.50 ea.

PH512BR Right Porthole Insert 39.50 ea.

1951-52 Buick Roadmaster Fender Porthole:

Chrome porthole for All 1951-52 Roadmaster models. Uses same design on both sides.

PH512RB Porthole Insert 39.50 ea.

1952 Roadmaster Porthole Ribbed Insert:

Made from stainless steel, this insert attaches to the backside of the fender portholes on Roadmaster models.

PH512RI Porthole Ribbed Insert 11.00 ea.

1953 Buick Fender Porthole: Beautiful Chrome finish, for use on All 1953 Buick models.

PH53B Porthole Insert 46.50 ea.

1954 Buick Fender Porthole: Bright chrome

finish, for use on All 1954 Buick models. We have also reproduced the inner retaining plate.

PH54B Porthole Insert 39.50 ea.

PH54BR Retaining Plate 25.00 ea.

1955 Buick Fender Porthole: New high quality tooling with exceptional Chrome finish. Our 1955 portholes include the backing plate.

PH55B Porthole Insert 56.50 ea.

1956 Buick Fender Porthole: Recent new tooling for the 1956 portholes allows us to offer the finest manufactured.

PH56B Porthole Insert 49.50 ea.

1960 Buick Fender Porthole: Chrome plated porthole features Black highlights in ribbed section.

PH60BL Left Porthole 37.00 ea.

PH60BR Right Porthole 37.00 ea.

1961 Buick Fender Porthole: Chrome plated oval porthole has satin Black painted inside.

PH61BL Left Porthole 39.50 ea.

PH61BR Right Porthole 39.50 ea.



PH49B




PH512BL



PH512RB



PH512BR



PH512RI

PH53B



PH54B



PH54BR



PH55B

Fusick




PH56B

Fusick



PH60BL



PH61BR

Chrome Side View Mirrors: Chrome Mirror attaches with two screws through mirror base. Gasket and screws included.

490L	Left Side View Mirror	1939-47 Convertibles & Wagon	89.50
490R	Right Side View Mirror	1939-47 Convertibles & Wagon	89.50



490L

Chrome Side View Mirrors: Polished Stainless Steel mirror back with Chrome arm. Includes mounting gasket and screws.

483L	Left Side View Mirror	1948-53 Convertibles, Estate Wagons & Riviera Hardtop	89.50
483R	Right Side View Mirror	1948-53 Convertibles, Estate Wagons & Riviera Hardtop	89.50



483L



546BLSR



546BRSR



546BLSC



546BRSC

1954-58 Chrome Side View Mirrors: Mirrors manufactured using our upgraded tooling. Polished Stainless Steel mirror back with cast Chrome bases. Includes rubber mounting gasket and attaching screws.

546BLSR	Left Side View Mirror	1954-56 Super & Roadmaster	69.50
546BRSR	Right Side View Mirror	1954-56 Super & Roadmaster	69.50
546BLSC	Left Side View Mirror	1954-56 Special, Century & Skylark	69.50
546BRSC	Right Side View Mirror	1954-56 Special, Century & Skylark	69.50
578BL	Left Side View Mirror	1957-58 All	69.50
578BR	Right Side View Mirror	1957-58 All	69.50



578BR

Chrome Side View Mirrors: Same mirror used for both driver and passenger sides. Embossed 'Buick' script logo on front of mirror head. Includes mounting bracket and gasket.

590BCK	Side View Mirror	1959-60 All	149.00 ea.
---------------	------------------	-------------	------------



590BCK

Chrome Side View Mirrors: High quality Chrome reproduction of the standard side view mirrors used on 1961-67 Buicks. Same mirror used for both driver and passenger sides. Embossed Buick Tri-Shield logo on front of mirror head. Includes molded plastic base gasket.

617BCK1	Side View Mirror	1961-67 All	98.50 ea.
----------------	------------------	-------------	-----------



617BCK



1954-56 Buick Outside Chrome Door Handles: Beautiful reproduction of the difficult to find Outside Door Handles for 1954-55 Special & 1954-56 Century 2-Door Hardtop and Convertible and 1954 Skylark.

ODH546 Outside Door Handles 1954-56 Buick 159.00 pr.



1959-60 Buick Outside Chrome Door Handles: Chrome Outside Door Handles for 1959-60 LeSabre & Invicta 2-Door Hardtop and Convertible.

ODH59 Outside Door Handles 1959-60 Buick 159.00 pr.



1961-62, 1965-68 Outside Door Handle Packages: Chrome Outside Door Handle Packages come complete with two handles, two push buttons, mounting hardware and rubber handle gaskets.

DH612BC 1961-62 All models 79.50 pr.

DH7026/7 1965-68 All models except 1968 Riviera 59.50 pr.



Door Handle Gaskets: Most Door Handle Gaskets are sold as a pair. Two piece set per handle (one large and one small gasket).

HG493 Door Handle Gasket 1950 All exc. 59-76C, 76R, 79 7.50 ea.

1951 40-50 Series exc. 59 Series

1952-53 All exc. 59 & 79R Series

HG546 Door Handle Gasket 1954-56 Special & Century 4-Door 7.50 ea.

HG547 Door Handle Gasket 1954-56 Special, Century 7.50 ea.

& Skylark 2-Door

HG578 Door Handle Gasket 1957 All 2-Door models, 7.50 ea.

1957 Special & Century rear doors

1958 Special & Century front doors

HG590 Door Handle Gasket 1959-60 All models 7.50 ea.

DH612 Door Handle Gasket 1963-67 All exc. Riviera 6.50 set

(4 pc set for both handles) 1968-70 Electra 225

DH716 Door Handle Gasket 1971-76 LeSabre & Electra 14.00 ea.


DCG61 Door Lock Gasket 1954-75 All 3.50 ea.



1940-53 Roof Mounted Antenna Masts: Used on All 1940-53 models. Mounts to roof above center of windshield. Available in a 3 piece mast only. Chrome swivel base assembly is used for either antenna, sold separately.

A4033B Antenna Mast, 3-pc 1940-53 All except Convertible 34.50

AB413 Antenna Swivel Base 1941-53 All models 34.50



AG403B Antenna Base Rubber Grommet 1940-60 All 5.00

AN544B Chrome Antenna Nut 1954-60 w/ manual antenna 19.50

1949-52 Stainless Steel Headlight Bezels: Polished Stainless Steel Headlight Bezels for 1949 Super and Roadmaster and All 1950-52 models. Bezels are sold complete with inner rubber seal around bulb.

5940756 Stainless Headlight Bezels 1949-52 models 69.00 ea.



Headlight Retaining Ring: Chrome plated, stamped steel Headlight Bulb Retaining Rings. 924535 has 3 tabs for screws used to secure headlight bulb into the bucket. 5947771 is retained with springs into the bucket.

924535 Headlight Retaining Ring 1940-54 All 39.00 ea.

1955 first type

924535B Headlight Mounting Bucket 1940-54 All 39.00 ea.
(stamped sheetmetal) 1955 first type

5947771 Headlight Retaining Ring 1956-57 All 39.00 ea.

HHR61 Headlight Retaining Ring 1958-73 All 29.50 ea.



924535B

Headlight Rim Seals and Headlight Mounting Pads: Headlight Rim Seals attach to the inner lip of the headlight bezel and seal around the headlight bulb.

HL401 Headlight to Fender Mounting Pad 1940-53 All models 19.50 ea.

HLR407 Headlight Rim Inner Seals 1940-54 All models 19.50 ea.

HLR557 Headlight Rim Inner Seals 1956-57 All models 21.50 ea.



Headlight Bucket to Fender Mounting Screws and Clip Kit: Sold in a 32 piece set, used for mounting the headlight buckets into the front fenders on 1940-54 All models.

HAF414 Headlight Bucket to Fender Mounting Kit 1940-54 All 18.50 set

Headlight Retaining Adjuster Screws: Used for headlight adjustments and attaching headlight retaining ring to buckets on All 1940-60 models. Sold in a set of four.

HLS400 Headlight Retaining Adjuster Screws 1940-60 All 11.00 set of 4

Headlight Retaining Ring Springs: Used with the Adjuster Screws on 1958-60 All models.

HRS580 Headlight Retaining Springs 1958-60 All 4.50 ea.

Headlight Adjuster Screws: Uses eight per car, two per headlight. Allows adjustment for proper alignment of headlights. Two different types available, 67-3110 is a self retaining design that snaps into a rectangular hole and 68-3249 includes pop rivets to install.

67-3110 Headlight Adjuster Screw, self retaining 4.50 ea.

68-3249 Headlight Adjuster Screw, pop-riveted 4.50 ea.




1949-52 Hood Release Cables: Hood Release Cables are sold in pairs, cables include correct end connectors and braided sheathing.

HRC49B Hood Release Cable 1949 All 37.00 pr.

HRC502B Hood Release Cable 1950 All, 1951-52 Super & Roadmaster 39.00 pr.

HRC512B Hood Release Cable 1951-52 Special 39.00 pr.

HRS502B Hood Release Spring 1950-52 All models 7.00 ea.



Buick Tail Light Lenses

1942-48 Super and Roadmaster Tail

Light Lenses: Red Tail

Light Lenses for All

1942-48 Super and Roadmaster models. Sold in pairs.

TL428B Tail Light Lens 70.00 pr.

TLG428B Tail Lens Gaskets 14.50 pr.



1949 Super and Roadmaster

Tail Light Lens:

Curved Eed lens has

'Guide R-49'

with part number 5937195

on lens per original.

TL49B Tail Light Lens 34.50 ea.

TLG49B Tail Lens Gaskets 13.50 set of 4



1950-52 Tail Light Lens:

For All 1950 models and

1951-52 Super and Roadmaster.

Red Tail Light Lens has part

number 5939073 with

'Guide R-40' in raised letters.

TL502B Tail Light Lens 47.50 ea.

TLG502B Tail Lens Gasket 12.00 pr.



1953 Buick Tail Light Lens:

Red lens has 'Guide R4-53'

with part number 5943938

per original.

Used on All 1953 Buick models.

TL53B Tail Light Lens 18.50 ea.

TLG53B Tail Lens Gasket 12.00 set of 4



1954 Buick Tail Light Lens:

'Guide R4-54' and 5645027

part number on Red lens. Used

on All 1954 Buick models.

TL54B Tail Light Lens 24.50 ea.

TLG54BU Tail Lens Gasket 12.00 set of 4



1955 Buick Tail Light Lens:

Deep Red Tail Light Lens used

on All 1955 Buick models. Lens

has 'Guide R4-55' on front

with 5946071 part number.

TL55B Tail Light Lens 42.00 ea.

TLG55B Tail Lens Gasket 10.50 pr.



1956 Buick Tail Light Lens:

Red lens used on All 1956 Buick models has 'Guide R4-56' with part number 5947178.

TL56B Tail Light Lens 43.50 ea.

TLG56B Tail Lens Gasket 11.50 pr.



1957 Buick Tail Light Lens:

Upper Tail Light Lens for

1957 Special & Century models

has 'R4-57' on lower face of lens.

TL57B Tail Light Lens 40.00 ea.

TLG57B Tail Lens Gasket 11.50 pr.



1957 Stop Light and

Turn Signal Lens:

Red oval lower Stop Lamp

Lens with part number

5948169 for All 1957

Buick models.

SL57B Stop Lamp Lens 37.50 ea.

SLG57B Stop Lamp Gasket 9.50 pr.



1960 Buick Tail Light Lens:

Round Red lens used on All

1960 Buick models. Stainless

ring around center reflector

included.

TL60B Tail Light Lens 47.50 ea.



1964 Riviera Tail Light Lenses and Emblems:

Bright Red lens with a Chrome and Black oval 'R' emblem for 1964. Same lens used on both sides.

Emblems are also available separately.

TL64R Tail Light Lens 1964 Riviera 69.50 ea.

TLE64R Tail Lens Emblem 1964 Riviera 24.50 ea.

TBG634 Tail Bezel Gaskets 1963-64 Riviera 24.75 pr.

TLG634R Tail Lens Gaskets 1963-64 Riviera 12.75 pr.

TLG667R Tail Lens Gaskets 1966-67 Riviera 18.00 pr.

Buick Parking Light Lenses

1941 Parking Light Lens:

Clear plastic Parking Light Lens used on the top of front fenders for 1941 Buick models.

PL41B Parking Light Lens 44.50 ea.



1955 Parking Light Lens:

For 1955 Buick Special and Century models.

'Guide F4-55' and part number 5945947 on lens.

PL55SC Parking Light Lens 20.00 ea.

PLG55CB Parking Lens Gasket 8.50 pr.



1949 Super and Roadmaster

Parking Light Lens: Clear plastic Parking Light Lens used on the top of front fenders for 1949 Buick Super and Roadmaster models.

PL49B Parking Light Lens 35.00 ea.

PLG49B Parking Lens Gasket 11.00 pr.



1955 Parking Light Lens: Clear lens for 1955 Super and Roadmaster models. Part number 5945896 and 'Guide F4A-55' on lens.

PL55B Parking Light Lens 28.50 ea.

PLG55SB Parking Lens Gasket 10.00 pr.

1950-52 Parking Light

Lens: Clear Parking Light Lens fits All 1950-52 Buick models. 'Guide F-40' and part number 5938915 on lens.

PL502B Parking Light Lens 20.00 ea.

PLG502B Parking Lens Gasket 8.50 pr.



1956-57 Parking Light

Lens: Clear plastic Parking Light Lens for All 1956-57 Buick models. 'Guide F4-56' and part number 5947045 in raised letters on lens.

PL567B Parking Light Lens 24.50 ea.

PLG567B Parking Lens Gasket 8.50 pr.



1953-54 Parking Light

Lens: Parking Light Lens used on All 1953-54 Buick models. Clear lens has 'Guide F4-53' with part number 5943810 in raised letters.

PL534B Parking Light Lens 19.50 ea.

PLG534B Parking Lens Gasket 8.50 pr.



1958 Parking Light

Lens: For All 1958 Buick models. Clear bullet shaped lens has 'Guide F4-58' on face of lens.

PL58B Parking Light Lens 28.50 ea.

PLG58B Parking Lens Gasket 8.50 pr.



Buick Back-up and License Light Lenses

1950-53 Back-up Light Lens:

Used on All 1950 models, 1951-53 Super, Roadmaster and Skylark. 'Guide B-40' and part number 5938905 on clear lens.

BL503B Back-up Light Lens 19.50 ea.
BUG503B Back Up Lens Gasket 9.50 pr.



1951-53 Back-Up Light Lens:

Clear glass Back-Up Light Lens for all 1951-53 Buick Special models. Part number printed on lens is 5938297.

BL513B Back-up Light Lens 29.50 ea.



1955 Back-up Light Lens:

Used on All 1955 Buick models. Clear round lens has part number 5946070 and 'Guide B4-55' in raised letters on front.

BL55B Back-up Light Lens 22.50 ea.
BUG55B Back Up Lens Gasket 8.50 pr.



1936 Buick Chrome Tail Light Bezel: High quality Chrome plated Tail Light Bezel for All 1936 Buick models.

TLR356 Tail Light Bezel 32.00 ea.



TLB428B



LD503

1942-48 Super & Roadmaster Chrome Tail Light Bezel: High quality Chrome plated Tail Light Bezel for All 1942-48 Buick Super and Roadmaster models.

TLB428B Tail Light Bezel 64.00 ea.

1956 Back-up Light Lens:

Clear lens for All 1956 Buick models has part number 5947192 and 'Guide B4-56' on lens per original.

BL56B Back-up Light Lens 34.50 ea.
BUG56B Back Up Lens Gasket 8.50 pr.



1957 Back-up Light Lens:



Fits All 1957 Buick models. Curved Clear lens has 'Guide B4-57' on front of lens.

BL57B Back-up Light Lens 39.50 ea.
BUG57B Back Up Lens Gasket 9.50 pr.



1956 Buick License Lamp Lens: Clear plastic Lens molded with 'Guide L5-60' and 5945916 part number per original.

5945916 License Lamp Lens
 1956 All models 25.00
LLG558 License Lens Gasket
 1956 All models 5.00



1959 Buick License Lamp Lens: Clear rectangle lens has 'Guide L4-59' in raised letters on bottom and center ribbed section.

LL59B License Lamp Lens 52.00
 1959 All

1950-52 Tail Lamp

Chrome Bezel: Cast Chrome Bezel used on All 1950 Buick models and 1951-52 Super and Roadmaster models.

TLB502B Tail Lamp Bezel 42.00 ea.



1950-52 Parking Light/Back-Up Light Chrome Bezel: Chrome plated Bezel used for Parking Lights on All 1950-52 Buick models. Also used as a Back-Up Light Bezel on All 1950 Buicks and 1951-52 Super and Roadmaster models.

LD503 Parking/Back-Up Bezel 20.00 ea.

Wheel Trim Rings: For all 1934-53 15 or 16 inch wheel rims with small hub caps. 1949-53 Models originally used a 3 rib trim ring. Both trim rings we offer have a smooth design with no ribs. Although not correct for 1949-53 15 inch wheels, the smooth design does have an excellent appearance and is correct for 16 inch wheels. Highly polished Stainless Steel. Sold individually.

WTR15	Wheel Trim Ring 15 inch wheel	1940 90, 1941-53 All	39.50 ea.
WTR16	Wheel Trim Ring 16 inch wheel	1934-48 All	39.50 ea.



HC390B



HC410B



WTR16



HCC55B

1939-50 Buick Hub Caps: Stainless Steel reproduction Hub Caps have machine stamped 'BUICK' letters painted Black.

HC390B	Single Hub Cap	1939-40 all exc. Limited	72.00 ea.
HC390B4	Set of 4 Hub Caps	1939-40 all exc. Limited	279.00 set
HC410B	Single Hub Cap	1941-50 exc. 1941 Series 90	72.00 ea.
HC410B4	Set of 4 Hub Caps	1941-50 exc. 1941 Series 90	279.00 set

HCC567B



1955-58 Buick Hub Cap Inserts: Round plastic Hub Cap Inserts are Red with a ribbed background and Chrome 'Buick' lettering for 1955 and 1956-57 models.

HCC55B	Hub Cap Insert	1955 All	24.00 ea.
HCC567B	Hub Cap Insert	1956-57 All	24.00 ea.

1935-60 Wheel Stud Bolts: New Wheel Stud Bolts used on Buick models from 1935-1960. Five used per wheel. WB350B measures 1-1/2" overall length with approximate 1" thread length. WB570 measures 1-13/16" overall with 1-1/4" thread length.

WB350B	Wheel Stud Bolts	1935-56 All models front 1957-60 front except Aluminum Drums 1941-58 All models rear	4.50 ea.
---------------	------------------	--	----------

WB570	Chrome Wheel Stud Bolts	1957-60 with Wire Wheels or Aluminum Drums	9.25 ea.
--------------	-------------------------	---	----------



WB350B



WB570

Stainless Capped Lug Nuts: Wheel lug nuts with Stamped Stainless caps used on 1963-75 Buicks. Sold individually or in a set of 20.

WN714	Capped Lug Nuts (set of 20)	1963-75 All	49.00 set
WN714A	Capped Lug Nut (individual)	1963-75 All	3.00 ea.



1968-69 Gas Door Assembly: New stamped steel item manufactured to exact OEM specifications. Includes tension springs and bolts to rear bumper. Tilts down to allow access to fuel tank filler.

GD680	Gas Door Assembly	1968-69 All exc. Wagons & Riviera	55.00
8418-89	License Plate Fasteners	1961-75 All	3.00 pr.



1964-65 Riviera Wheel Center Caps: Chrome plated Center Caps with plastic 'R' emblem insert are available in 2" and 2-1/8" diameters.

WC645R	2" Wheel Center Cap	1964-65 Riviera	39.50 ea.
WC645RB	2 1/8" Wheel Center Cap	1964-65 Riviera	39.50 ea.



1964-65 Riviera Wheel Cap Inserts: Plastic insert with Black background and Chrome 'R' logo is used in all 1964-65 Riviera center caps for both 2" and 2-1/8" caps.

WP645R	Wheel Cap Insert	1964-65 Riviera	20.00 ea.
---------------	------------------	-----------------	-----------

1966-70 Center Cap Retaining Clips: Spring steel clips bolt into the Mag Wheel Center Caps used on 1966-70 models. Attaches cap onto rim and holds the plastic insert in place. Available for 2" and 2-1/8" rim opening sizes size.

WCR650S	2" Center Cap Retaining Clip		
	1966-70 with 2" hole in rim	7.00 ea.	
WCR650	2 1/8" Center Cap Retaining Clip		
	1966-70 with 2-1/8" hole in rim	7.00 ea.	




1966-70 Mag Wheel Center Caps: Features bright Chrome plating with Black highlights in ribbed section work with 1966-70 Mag Wheels having 2" or 2-1/8" opening in center. Same center cap can be used for multiple models. However, plastic insert (listed below) differs with each model. Retaining clips listed above.

WC660	Mag Wheel Chrome Center Cap	1966-70	39.50 ea.
--------------	-----------------------------	---------	-----------

1966-70 Mag Wheel Center Cap Inserts: Plastic Center Cap Inserts used with the above Mag Wheel Center Caps for 1966-70 Buick models. Retaining clips WCR650 or WCR650S used to secure the insert into the center cap.

WP660R	Riviera Plastic Center Cap Insert	1966-70 Riviera	18.00 ea.
WP660W	Wildcat Plastic Center Cap Insert	1966-70 Wildcat	18.00 ea.
WP660T	Tri-Shield Plastic Center Cap Insert	1966-70 LeSabre & Electra	18.00 ea.



1971-81 Riviera Chrome Wheel Center Caps: Chrome plated Wheel Center Cap with Silver 'R' logo insert used on 1971-1981 Riviera models. Available for two wheel hole sizes with 2" and 2-1/8" diameter.

WC714R	2" Wheel Center Cap	1971-81 Riviera	39.50 ea.
WC714RB	2-1/8" Wheel Center Cap	1971-81 Riviera	39.50 ea.



Accessory Exhaust Deflectors: The 982511 deflector can be used on many models up to 1953, will fit onto a 1-1/2" diameter tail pipe. The 1954-55 deflector is a chrome plated tubular extension design.


982511	Stainless Exhaust Deflector	models up to 1953	65.00
ED545B	Tubular Exhaust Deflector	1954-55 All	21.00 ea.



1948-55 Buick Hood And Trunk Emblem Plastic Inserts

1948 Plastic Hood Insert: Plastic Insert for Hood Emblem on All 1948 models. Red background with Chrome and Blue checkerboard pattern.


HE48B Hood Emblem Insert 89.00



HE48B

1949 Plastic Hood Insert: Plastic Hood Emblem Insert for 1949 Buick Super and Roadmaster models. Red ribbed background with Silver and Blue checkerboard pattern.

HE49B Hood Emblem Insert 86.00



HE49B




HE50B

1950 Plastic Hood Insert: Hood Emblem Insert used on All 1950 Buick models. Red ribbed background with Chrome and Blue checkerboard pattern.

HE50B Hood Emblem Insert 86.00

1939-41 Trunk Emblem Badge: Chrome plated Badge Emblem used in center of trunk ornament on 1939-41 Buicks. Bright Red background with Blue checkerboard and Yellow highlights.


TEB391B Trunk Emblem Badge
1939-41 All 37.50



HE512B

1951-52 Plastic Hood Insert: Fits All 1951-52 Buick models for Chrome hood emblem. Background is Red, checkerboard section is Chrome and Blue.

HE512B Hood Emblem Insert 86.00




HE53B

1953 Plastic Hood Insert: Plastic Insert used on All 1953 Buick models. Red ribbed background with Chrome and Blue checkerboard pattern.

HE53B Hood Emblem Insert 86.00

1939-41 'Buick Eight' Trunk Letter Set: Small Chrome letters install into the recessed areas of red lenses on the trunk emblem. **BUICK EIGHT**

TLS391B Buick Eight Letter Set
1939-41 All models 21.00 set



1941 'Buick Eight' Trunk Emblem Lenses: Bright Red lenses with areas for TLS391B Chrome letter set, sold separately. Installs into Chrome trunk emblem.

TEL41B Buick Eight Trunk Lenses
1941 All models 43.50 pr.

1942-48 Buick Trunk Emblem Chrome Base:

Bright Chrome finish Trunk Emblem Base uses TEL428B Lenses and TE429B Badge Emblem. All pieces sold separately.

TEB428B Trunk Emblem Base
1942-48 All models 83.50



1942-48 All, 1949 Special Trunk Emblem Badge:

Bright Chrome emblem with Red background, Blue checkerboard and Yellow highlights.

Attaches to the TEB428B Chrome Emblem Base.

TE429B Trunk Emblem Badge
1942-48 All, 1949 Special 43.50



1942-48, 1949 Special 'Buick Eight' Trunk Emblem Lenses: Dark Red lenses with Chrome letters, installs into Chrome trunk ornament on All 1942-48 models and 1949 Special models.

TEL428B 'Buick Eight' Trunk Lenses
1942-48 All, 1949 Special 73.50 pr.



1948 'Dyna Flow' Trunk Emblem Lenses: Dark Red lenses with Chrome plated 'Dyna Flow' letters. Used on 1948 models equipped with a Dynaflow.

TEL48B 'Dyna Flow' Trunk Lenses
1948 w/ Dynaflow 86.00 pr.



1949 'Dyna Flow' Trunk Emblem Lenses: Red lenses with Chrome letters spelling 'Dyna Flow'. For trunk ornament on all 1949 models with Dynaflow.

TEL49B 'Dyna Flow' Trunk Lenses
1949 with Dynaflow 132.00 pr.



1950-52 'Dyna Flow' Trunk Emblem Lenses:

Chrome plated letters on bright Red lenses, for 1950-52 models equipped with the Dynaflow transmission.

TEL502B 'Dyna Flow' Trunk Lenses
1950-52 with Dynaflow 97.50 pr.



1950-52 'Buick Eight' Trunk Emblem Lenses:

Bright Red lenses with Chrome letters for All 1950-52 8 cylinder models not equipped with Dynaflow.

TEL502SB 'Buick Eight' Trunk Lenses
1950-52 8 cylinder 130.00 pr.



1953 'Buick Eight' Trunk Emblem Lenses: Bright Red lenses with Chrome plated letters install in trunk ornament on All 1953 Buick models.

TEL53B 'Buick Eight' Trunk Lenses
1953 All models 69.00 pr.



1955 Buick Plastic Trunk Emblem Insert:

Chrome and Black Plastic Trunk Emblem Insert with Red and Blue highlights in the badge. Used on All 1955 Buick models.

TEL55B Plastic Trunk Emblem Insert
1955 All models 72.50

1949 Buick Front Bumper Emblems: Chrome plated Metal Emblem insert for the center of the front bumper on All 1949 Buick Super and Roadmaster models. Red painted highlights in lettering.

FBE49S 1949 Buick Front Bumper 'Super' Emblem 43.00
FBE49R 1949 Buick Front Bumper 'Roadmaster' Emblem 43.00



1953 Buick Front Bumper Plastic Emblems: Plastic emblem installs in the center of the front bumper on All 1953 Super, Special or Roadmaster models. Metal backing plate has threaded stud.

FBE53SU 1953 Front Bumper 'Super' Emblem 112.50
FBE53SP 1953 Front Bumper 'Special' Emblem 112.50
FBE53RM 1953 Front Bumper 'Roadmaster' Emblem 112.50

FBE53SP



FBE53SU

FBE53RM



1955 Buick Grille Ornaments: Chrome plated Grille Ornament used on 1955 Buick Special, Super & Century models. Features Red, White and Blue highlights around outer ring with Black center circle. 1955 Roadmaster ornament has same coloring with Gold colored plating.

GO55B Chrome Grille Ornament 1955 40-50-60 Series 75.00
GO55BR Gold Grille Ornament 1955 Roadmaster 92.50



GO55B



HO558B

1955 Buick Hood Ornaments, 1958 Buick Front Fender Ornaments: Round, Chrome plated stand up 'V' ornament used on the hood of 1955 models and on each front fender for 1958 Buick models. Also available in Gold plating for 1955 Roadmasters.

HO558B Hood & Fender Ornaments 1955 Hood, 1958 Fenders 79.50 ea.
HOB55 Hood Ornament Chrome Base 1955 Buick 79.50
HO55R Hood Ornament, Gold Plating 1955 Roadmaster 97.50



Buick Hood Letter Sets, Scripts and Emblems

1941 'Buick Eight' Hood Letter Set: Individual Chrome plated letter set spells 'Buick Eight' on the front edge of the hood.

HLS41B Hood Letter Set 1941 Eight Cylinder Models 43.00 set

BUICK EIGHT

HLS41B

1954 Hood Letter Set: Chrome plated 'Buick' letter set used on the hood of All 1954 Buick models.

HLS54B Hood Letter Set 56.00 set

BUICK

HLS54B

1955-56 Hood Letter Set: Individual Chrome letter set spells 'Buick' on the hood of 1955 and 1956 models except for Roadmaster.

HLS556B Hood Letter Set 56.00 set

BUICK

HLS56B

1955-56 Buick Roadmaster Hood Letters:

Individual letter set in Gold colored plating for the hood of 1955 and 1956 Roadmaster models

HLS556G 'Buick' Hood Letters 73.00 set

BUICK

1955 Buick 'Roadmaster' Grille Script:

Small 'Roadmaster' Script used on the grille in 1955.

Correct Gold colored plating per original

BE55GR 'Roadmaster' Grille Script 59.00

Roadmaster

1955 Roadmaster Door Badge Emblem: Located on door near the rear-view mirror on 1955 Buick Roadmaster models. Correct Gold colored plating per original.

BE55DR Door Badge Emblem 39.00 ea.



1957 Hood Letter Set: Individual chrome plated letter set includes 'arrows' used on All 1957 Buick models.

HLS57B Hood Letter Set 56.00 set

BUICK

HLS57B

1958 Hood Letter Set: Chrome letter set spells out 'Buick' for All 1958 models.

HLS58B Hood Letter Set 56.00 set

HLS58B

BUICK

1964-65 Buick Hood Letter Set: Chrome plated letter set for the front of the hood on All 1964-65 Buicks.

HLS645B Hood Letter Set 55.00 set

BUICK

HLS645B

1966, 1968-70 Buick Hood Letter Set: Chrome plated individual letter set used on the front of hood for All 1966 and 1968-70 Buick models.

HLS670B Hood Letter Set 68.00 set

BUICK

HLS670B

1948-50 Buick 'Super' Script: Chrome 'Super'

fender script for All 1948-50 Buick 50 Series.

BE480S 'Super' Script 29.75 ea.

Super

1948-50 Buick 'Roadmaster' Script:

Chrome plated 'Roadmaster' fender script used on All 1948-50 70 Series Buicks.

BE480R 'Roadmaster' Script 39.50 ea.

Roadmaster

1948-52 Buick 'Dynaflow' Script: Chrome

'Dynaflow' fender script for All 1948-52 models equipped with the Dynaflow Transmission.

BE482 'Dynaflow' Script 36.00 ea.

Dynaflow

1955 & 1956 Buick 'Special' Scripts:

Chrome plated 'Special' script used on rear fenders or rear doors for 1955 or 1956 Buick Special models.

BE55S 'Special' Script 59.50 ea.

BE56S 'Special' Script 59.50 ea.

Special

1956 Buick 'Century' Script: Chrome plated

'Century' script used on rear fenders or rear doors for 1956 Buick Century models .

BE56C 'Century' Script 59.50 ea.

Century

1956 Buick 'Super' Script: Chrome plated 'Super'

script used on rear fenders or rear doors for 1956 Buick Super models .

BE56U 'Super' Script 59.50 ea.

Super

1957 Buick Roadmaster Trunk Letter Set:

Individual Chrome plated letter set for the trunk lid of 1957 Roadmaster models.

TLS57BR 'Roadmaster' Trunk Letters 129.00

ROADMASTER

1959 Buick Front Fender Scripts: Chrome plated emblems for front fenders on 1959 Buick Electra, Electra 225 and Invicta models. For Electra 225 models, order one BE59BE and one BE59B for each fender.

BE59BE 'Electra' Front Fender Script 1959 Electra 34.50 ea.

BE59B '225' Front Fender Numbers 1959 Electra 225 19.50 ea.

BE59BI 'Invicta' Front Fender Script 1959 Invicta 34.50 ea.

ELECTRA

225

Invicta

Emblem Fasteners: Winged speed nuts and rubber cushions used to attach various 1950's Hood Letters, Scripts, Medallions, and emblems. Sold in a package of 40 pcs (20 clips, 20 cushions)

EF58L Emblem Fasteners 45.00 pkg.



1966 'Wildcat' Hood Emblem: Chrome plated stand-up Hood Emblem with Black background behind 'Wildcat' script. For All 1966 Wildcat models.

BUF010 1966 'Wildcat' Hood Emblem 52.00

1967 'Wildcat' Quarter Panel Letter Set: Chrome plated individual letters spell out 'Wildcat' on the rear quarter panels. Two sets needed per car.

BUF57 1967 'Wildcat' Letter Set 59.00 ea.

1967 'Wildcat' Trunk Letter Set: Chrome plated letter set for trunk lid on 1967 Wildcat models.

BUF67 1967 'Wildcat' Trunk Letter Set 59.00

1969 'Wildcat' Front Fender Script:

Chrome plated 'Wildcat' script with black background. For front fenders on all 1969 Wildcat models.

BUF49 1969 'Wildcat' Fender Script 42.00 ea.

1969 'Wildcat' Trunk Script:

Chrome plated 'Wildcat' script with black background used on the trunk lid of All 1969 Wildcat models.

BUF69 1969 'Wildcat' Trunk Script 42.00

1963 Riviera Hood Spear Insert: Small plastic insert for the hood spear on 1963 Riviera models. Tri-colored shields on a Black background.

HE63R Hood Spear Plastic Insert 1963 Riviera 35.00

1964-65 'Riviera' Hood Emblem: Chrome plated stand-up 'R' hood ornament for All 1964-65 Buick Riviera.

BUR010 1964-65 Hood Emblem 45.00

1963-67 'Riviera' Front Fender Script: Chrome plated 'Riviera' script used on front fenders for 1963-67 models. Also used on the hood of 1967 Riviera models.

BE637R 1963-67 'Riviera' Front Fender Script 34.50 ea.

1965 'Riviera' Rear End Panel Script: Chrome plated 'Riviera' script used on the rear end panel for 1965 Riviera models.

BUR65 1965 'Riviera' Rear End Panel Script 38.00

1966-67 'Riviera' Rear End Panel Script: Chrome plated 'Riviera' script used on 1966-67 Riviera trunk lid.

BUR25 1966-67 'Riviera' Trunk Lid Script 32.50

1966, 1968-69 Hood Letter Set: Chrome plated individual letters spell 'Riviera' across the front edge of the hood on 1966 and 1968-69 Riviera models.

BUR8 1966, 1968-69 'Riviera' Hood Letter Set 69.00

1966-67 'By Buick' Trunk Emblem: Chrome plated emblem with Black highlights for the trunk lid on All 1966-67 Riviera models.

BUR66 1966-67 'By Buick' Trunk Emblem 29.00



WILDCAT

WILDCAT

Wildcat

Wildcat



Riviera



Riviera

Riviera

RIVIERA



Firewall Grommets: High quality rubber firewall grommets available for many late 1930 to late 1950 Buick models.

FG377	Firewall Grommet	coil wire, 1937-48 All	13.50
FG349B	Firewall Grommet	oil, temp & vacuum line, 1939-40 Super, Century, Roadmaster & Limited, 1941-42 All, 1946-48 Special, 1949 All	18.00
FG379B	Firewall Grommet	wiring harness, 1937-48 All, 1949 Special	35.00
FG374	Firewall Grommet	vent control cable, 1950 All, 1951-52 50-70 Series 1953 All Series except Skylark	6.00
FG503B	Firewall Grommet	oil, temp or vacuum lines, 1950-53 All	15.00
FG503BWH	Firewall Grommet	windshield washer hose, 1950-53 All	15.00
FG508	Firewall Grommet	park brake cable, 1950-53 Super, Roadmaster, Skylark, 1954-56 All	15.00
FG508B	Firewall Grommet	oil and temp lines, 1950-58 most models	7.50
FG508BVL	Firewall Grommet	vacuum lines, 1950-58 most models	9.50
FG530B	Firewall Grommet	wiring harness, 1953 All models	58.00
FG546BOT	Firewall Grommet	oil and temp lines, 1954-56 All models	24.00
FG546BS	Firewall Grommet	speedometer cable, 1954-56 All models	24.00
FG546BV	Firewall Grommet	vacuum lines and ignition resistor wire, 1954-56 All	24.00
FG546BPB	Firewall Grommet	parking brake cable, 1954-56 All models	28.00
FG546BMW	Firewall Grommet	main wiring harness, 1954-56 All models	30.00



Cowl Lacing Strips: Seals across the top of the firewall to the underside of hood.

CL30	Cowl Lacing	1928-39 All	11.00 ft.
CL538B	Cowl Lacing	1953 50-70 Series, 1954-58 most models	39.50
CL590B	Cowl Lacing	1959-60 All models	42.00




CL51F	Cowl Lacing Fasteners	1953-60 All	3.50 ea.
CB491	Cowl Rubber Bumpers	1949-60 All	11.00 pr.
CLP538	Cowl Lacing Plugs	1953-58 All	2.50 ea.



Hood Bumpers and Rubber Rest Pads:

HB379B	Hood Rest Pad	1937-38 (uses 6) 1939-49 (up to 12 per car)	7.75 ea.
HB41	Hood Bumper	1939-40 All (uses 6)	7.50 ea.
HB429B	Hood to Cowl Bumper	1942-49 All	17.00 ea.
HB459B	Hood to Fender and Hood Rail Bumper	1942-49 All	4.00 ea.
HB48B	Hood to Grille Bumper	1948 50-70 Series	4.00 ea.
HB50	Hood to Fender Bumper	1948-54 All	5.00 ea.
HB490B	Hood to Fender Bumper	1949 50-70 Series	8.00 ea.
HB493B	Hood Corner Bumper at Shroud	1949-53 All	21.50 ea.
HB495B	Hood to Grille Bumper	1949 Super & Roadmaster 1950-55 All models	7.50 ea.
HB502B	Hood Side to Fender Ledge Bumper	1950 All models 1951-52 Super & Roadmaster	17.00 ea.
HB535B	Hood to Fan Shroud Bumper	1953-55 most models	4.00 ea.
HB558B	Hood to Fender Bumper	1955-58 All models	6.00 ea.
HB459B	Hood to Radiator Side Panel Bumper	1956-59 All	4.00 ea.
HB194B	Hood Side on Fender Ledge Bumper	1958 All models	21.50 ea.
HB54	Hood Adjuster Bumper & Stud	1958-67 All	12.50 ea.
HB489B	Hood to Fender Bumper	1959-61 All models	15.00 ea.
HB635B	Hood to Fender Bumper	1963 All, 1964-65 Riviera	9.00 ea.
HB652B	Hood to Fender Bumper	1965 exc. Riviera, 1966-72 All	9.00 ea.
HB74	Hood Adjuster Bumper & Stud	1968-75 All	8.50 ea.



Door to Body Rubber Bumpers:

DB328B	Door Bumper	1937-48 All closed models	10.00 ea.
DB45	Door Center Post Bumper	1936-39 closed models	3.00 ea.
DB383	Door Side Bumper	1937-53 Hardtop & Convertible	21.50 ea.
DB50	Door Bumper w/ Screw	1941-60 some models	3.50 ea.
DB45	Door Bumper	1941-60 exc, Convertible	3.00 ea.
DB65	Flat Door Bumper	1937-56 some models	3.50 ea.
DB490B2	Lower Door Bumper	1949 Super & Roadmaster 2-Door	27.00 ea.
DB490B4	Upper Door Bumper	1949 Super & Roadmaster	57.00 pr.
DB80	Door Bumper (2 tabs)	1949-60 All	4.00 ea.
DB60	Rectangle Door Bumper	1957-60 most 4-Doors	5.00 ea.
DB59	Rectangle Door Bumper	1959-64 All, 1" x 1/2" x 1"	5.50 ea.
DB59A	Rectangle Door Bumper	1959-64 All, 1" x 5/8" x 11/16"	5.00 ea.
DB85	Rectangle Door Bumper	1963-66 some models 1-1/16" x 5/8" x 3/4"	4.50 ea.
DB66	Door Bumper	1967-70 Riviera	4.50 ea.
DB41	Door Bumper	1967-70 All	4.00 ea.
DB90	Door Bumper	1971-75 All	3.50 ea.



Door Bottom Drain Hole Seal: Rubber seal covers drain holes in door bottom, DHS578 is also used on 1957-58 Buick Wagons in the bottom of the tailgate.

DHS546	Drain Hole Seal	1954-56 40-60, 1954 Skylark	8.00 ea.
DHS578	Drain Hole Seal	1957-58 All	5.50 ea.
DHS591	Drain Hole Seal	1959-61 All	8.00 ea.
DHS66	Drain Hole Seal	1964 LeSabre, Wildcat, Electra & Riviera, 1965 All exc. Riviera	4.50 ea.



Cowl Vent Gasket: Molded rubber gasket seals around the cowl vent opening.

CV378	Cowl Vent Gasket	1937 40-60 Series, 1938-40 all, 1941 40-50-70 Series	53.00
--------------	------------------	---	-------



GB10



GB15

Gas Door Bumpers:

GB10	Gas Door Bumper	1939-53 All exc. 1950-53 40 Series	2.00 ea.
GB15	Gas Door Bumpers	1950-53 40 Series, 1954-56 All	7.50 pr.
GDB57	Gas Door Bumpers	1957 All models	14.50 pr.



GDB57

Trunk Lid Bumpers: Rubber bumpers used to cushion the trunk lid.

TB61	Trunk Lid Bumper, 7/8" diam. 1/4" thick	1949-68	3.00 ea.
TB69	Trunk Lid Bumper, 7/8" diam. 3/8" thick	1969-75	3.00 ea.



TB61

TB69

Rubber Bumper Fillers: Molded Black rubber Fillers used in outer corners of bumpers to fill the gap between body and bumper. Sold in pairs only except where noted.

BI635R	Front Bumper Bracket Insulators	1963-65 Riviera	18.00 pr.
BG635R	Front Bumper Grommets	1963-65 Riviera	13.50 pr.
BF635	Rear Bumper Filler Seals	1963-65 Riviera	34.50 pr.
FF64B	Front Bumper Filler (same both sides)	1964 LeSabre, Electra, Wildcat	17.00 ea.
FF667R	Front Bumper Fillers	1966-67 Riviera	25.75 pr.
RF667R	Rear Bumper Fillers	1966-67 Riviera	22.50 pr.
RF689R	Rear Bumper Fillers	1968-69 Riviera	23.75 pr.
FF70R	Front Bumper Fillers	1970 Riviera	23.50 pr.
RF712R	Rear Bumper Fillers	1971-72 Riviera	21.50 pr.



BI635R



BG635R



BF635



FF64B



FF667R



RF667R



RF689R



FF70R



RF712R

Bumper Bar Rubber Grommet: Rubber grommets seal area in body where the bumper bars pass through sheetmetal. Sold in pairs for front or rear bumper.

BF378FB	Front Bumper Bar Grommets	1937-38 40-60 Series	79.00 pr.
BF390FB	Front Bumper Bar Grommets	1939 40-60 Series & 1940-41 40-50-60-70 Series	79.00 pr.
BF379RB	Rear Bumper Bar Grommets	1937 40-60 Series & 1939 40-60 Series	75.00 pr.
BF400RB	Rear Bumper Bar Grommets	1940 40-50-60-70 Series	78.00 pr.



BF390FB



BF400RB

Trunk Ornament Mounting Pads

1939-56 Trunk Ornament Rubber Mounting Pads: Correctly reproduced molded rubber mounting pads for 1939-56 Buick Trunk Lid Ornaments.

MP112B	Trunk Ornament Pad	1940 40-50-70 Series	79.00
MP113B	Trunk Ornament Pad	1941 All	85.00
MP114B	Trunk Ornament Pad	1942-48 50-70 Series	81.00
MP076B	Trunk Ornament Pad	1949 some 50-70 Series	85.00
MP103B	Trunk Ornament Pad	1950-51 All, 1952 All 40 Series & 1952 Series 59R & 79R	84.00
MP110B	Trunk Ornament Pad	1953 All models	79.00
MP185B	Trunk Ornament Pad	1954 All models (may need slight hole modification on some models)	109.00
MP202B	Trunk Ornament Pad	1955 40, 50, 60 Series	85.00
MP122B	Trunk Ornament Pad	1956 All models	125.00



MP113B



MP076B



MP103B



MP110B



MP185B




MP202B



MP122B

Buick Hood Insulation Pads: Computer die cut Hood Insulation Pads for popular Buick models listed.

HI53B	Hood Insulation	1953 Super & Roadmaster	79.00
HI54B	Hood Insulation	1954 Skylark, Special & Century	79.00
HI556B	Hood Insulation	1955-56 All	69.00
HI57B	Hood Insulation	1957 Super & Roadmaster	69.00
HI58B	Hood Insulation	1958 All	69.00
HI59B	Hood Insulation	1959 All	69.00
HI60B	Hood Insulation	1960 All	59.00
HI635RB	Hood Insulation	1963-65 Riviera (3-pc set)	59.00
HI66LB	Hood Insulation	1966 LeSabre & Wildcat	69.00
HI667RB	Hood Insulation	1966-67 Riviera (5-pc set)	59.00
HI67B	Hood Insulation	1967 Wildcat, LeSabre & Electra	69.00
HI68LB	Hood Insulation	1968 LeSabre & Wildcat (5-pc set)	69.00
HI690EB	Hood Insulation	1969-70 Electra 225 (5-pc set)	69.00



HI635RB

Convertible Top Parts: Pumps, Cylinders, and Hoses

Convertible Top Handle: Chrome Top Handles include mounting bolt and spring washer. Available for All 1949-60 Buick Convertible models.

CTH453	Convertible Top Handle	1949-53 Convertible	75.00
CH546	Convertible Top Handle	1954-56 Convertible	109.00
CTH57	Convertible Top Handles	1957-60 Convertible	109.00 pr.

1957-60 Convertible Top Handle Striker Plates: Chrome plated striker plates attach to the windshield frame and allow the top handle to lock into place.

CTS57	Convertible Striker Plates	1957-60 Convertible	98.00 pr.
--------------	----------------------------	---------------------	-----------

Convertible Top Cylinders: New cylinders available for all models listed.

TC1	Convertible Top Cylinder	1946-53 exc. 1953 Special	159.00 ea.
TC6	Convertible Top Cylinder	1953 Buick Special	159.00 ea.
TC7	Convertible Top Cylinder	1954-56 Buick	159.00 ea.
TC13	Convertible Top Cylinder	1957-58 Special & Century	159.00 ea.
TC14	Convertible Top Cylinder	1957-58 Super, Roadmaster, Limited	159.00 ea.
TC15	Convertible Top Cylinder	1959-60 Buick	159.00 ea.
TC26	Convertible Top Cylinder	1961 LeSabre, Invicta & Electra	159.00 ea.
TC27	Convertible Top Cylinder	1962 LeSabre, Invicta, Electra, Wildcat	159.00 ea.
TC28	Convertible Top Cylinder	1963-64 LeSabre, Invicta, Electra, Wildcat	159.00 ea.
TC46	Convertible Top Cylinder	1965-70 LeSabre, Invicta, Electra, Wildcat	159.00 ea.

Convertible Top Pump Motors: 1954-56 Buick used a vertical mounted Top Pump, 1954-55 OEM pumps had hose ports located at the pump top area. 1956 OEM pump ports were located on the pump sides. All replacement pumps have hose ports located on the side of the pump. Order CTH546 Top Hoses for All 1954-56 replacement pumps.

TP2V	Convertible Top Pump Motor	1954-56 Buick (vertical)	375.00
TP1	Convertible Top Pump Motor	1957-62 Buick	375.00
TP634	Convertible Top Pump Motor	1963-64 Buick	375.00
TP7	Convertible Top Pump Motor	1965-70 Buick	375.00

Convertible Top Hoses: High quality Convertible Hoses are complete with correct 'T fitting' in center and 90 degree or straight fittings on ends. In 1954-55 the hose ports are on the top of the OEM motors; for 1956 the ports are on the side of the motor. If installing a replacement top pump (TP2V), you will need to order the CTH546 hoses. If your original vertical pump has the hose ports on top, order the CTH561 hoses.

CTH546	Convertible Top Hoses	1954-56 with side ports	119.00 pr.
CTH561	Convertible Top Hoses	1954-55 with top ports, 1957-61 Buick Convertible	119.00 pr.
CTH627	Convertible Top Hoses	1962-70 Buick Convertible	119.00 pr.



1961-64 Convertible Top Latches: New Chrome Convertible Top Latches for All 1961-64 Buick Convertibles except Skylark. Includes chrome Top Hooks.

CTL614L	Convertible Top Latch, left side	1961-64 Convertible	165.00
CTL614R	Convertible Top Latch, right side	1961-64 Convertible	165.00



Convertible Top Hooks: Chrome hooks thread into Convertible Top Latch.

CX614	Convertible Top Hook	1961-64 Convertible	16.50 ea.
CX642	Convertible Top Hook	1965-70 Convertible	8.50 ea.


Convertible Top Latch Assemblies: New Convertible Top Latch assemblies complete with Chrome Top Hook. Applies to 1966-70 Electra Convertibles, 1967-70 LeSabre and Wildcat Convertibles, and 1971-75 Centurion and LeSabre Convertibles.

CTL660L	Left Side Top Latch	1966-70 Convertible	119.00
CTL660R	Right Side Top Latch	1966-70 Convertible	119.00
CTL716L	Left Side Top Latch	1971-75 Convertible	139.00
CTL716R	Right Side Top Latch	1971-75 Convertible	139.00



Convertible Top Tension Cables: New Convertible Top Hold Down Tension Cables run down both sides of the roof to keep the convertible top tight along the roof rail when top is in up position. Sold in pairs.

614BM	Convertible Top Cables	1961-64 LeSabre, Invicta, Wildcat	54.50 pr.
614CM	Convertible Top Cables	1961-64 Electra	54.50 pr.
6570A	Convertible Top Cables	1965-70 LeSabre & Wildcat	54.50 pr.
6570B	Convertible Top Cables	1965-70 Electra	54.50 pr.
1971BC	Convertible Top Cables	1971 Centurion & LeSabre	54.50 pr.
7276	Convertible Top Cables	1972-75 Centurion & LeSabre	65.00 pr.



1971-75 Centurion & LeSabre Convertible Top Motor: New Scissor Top Motor includes electrical pigtail and proper electrical connectors.

STM716	Convertible Scissor Top Motor	1971-75 Centurion & LeSabre	259.00
---------------	-------------------------------	-----------------------------	--------

1971-75 Centurion & LeSabre Convertible Scissor Top Parts:

CAB716	Convertible Top Actuator Bolt/Lock Washer	1971-75 Convertible	14.00
CFB716	Convertible Frame Bushing Set (16 pcs)	1971-75 Convertible	60.00
CBG716	Convertible 3rd Bow Plastic Guide	1971-75 Convertible	63.00
CTR716	Convertible Top Relay	1971-75 Convertible	63.00
CDC716BK	Convertible Drive Cable (Black, pass side)	1971-75 Convertible	65.00
CDC716BL	Convertible Drive Cable (Blue, driver side)	1971-75 Convertible	65.00
CGW716	Convertible Top Rain Gutter Wires	1971-75 Convertible	59.00
CSA716	Convertible Top Glass Support Arms and Bushings	1971-75 Convertible	99.00
HGP716	Convertible Header Bow Guide Pins	1971-75 Convertible	14.00 pr.



1946-48 Bakelite Power Top Control Valve: A rebuild service for power top valves is available for 1946-1949 Buick Convertibles. Valve mounts on firewall and is controlled by the push-pull top switch rod. Send original valve to us for rebuilding service.

CTV460 Power Top Control Valve 1946-49 Convertible 289.00



Power Convertible Top Switch Repair Kit: All new internal parts to service the push-pull convertible top switch used on 1951-54 Buick convertible models.

4600800 Power Top Switch Kit 1951-54 Convertible 119.00



Convertible Top Frame Assembly Hardware:

Complete hardware kits to replace all nuts, bolts, bushings, washers and screws used to assemble the Convertible top frames. Each section is bagged separately and detailed instruction sheet is included.

CBK001 Convertible Top Frame Bolt Kit 1953-56 Convertibles 199.00 kit

CBK402 Convertible Top Frame Bolt Kit 1957-58 Convertibles 199.00 kit

CBK401 Convertible Top Frame Bolt Kit 1959-60 Convertibles 199.00 kit



Convertible Top Cylinder Mounting Hardware:

Special bolts, washers and pins used for attaching the Convertible Top Cylinders to the Top Frame and lower mounting supports. These kits are included with the Top Frame Hardware packages or can be ordered seperately.

CTCU460 Top Cylinder Upper Mounting Hardware
1949-60 Convertibles 21.00 kit

CTCL466 Top Cylinder Lower Mounting Hardware
1946-56 Convertibles 13.00 kit

CTCL570 Top Cylinder Lower Mounting Hardware
1957-60 Convertibles 13.00 kit



1954-56 Convertible Rear of Quarter Window Molded Weatherstrip:

Intricate rubber weatherstrip with metal insert. Original GM part #s are 4638120 (RH) and 4638121 (LH). Sold in pairs.

RQW546C 1954-56 Special & Century, 1954 Skylark 89.50 pr.



Convertible Top Frame Bumpers: Rectangular rubber bumper with metal insert attaches to convertible top frame with a screw. Sold in pairs.

CTRB537 1953 Special, 1954 All Conv., 1955-56 40-50-70 Series Conv. 66.00 pr.



Convertible Top Motor Grommets: Rubber mounting grommets used to secure the Convertible Top Pump. 3 or 4 used per car.

TMG642 Top Motor Grommet 1954 40-60 Series, 1955-72 All 4.50 ea.



Hydraulic Pump Mount: Rubber bushing with threaded studs on top and bottom.

TMG454 Hydraulic Pump Mount 1946-53 All,
1954 Super & Skylark 27.00 ea.

1959-60 Convertible Header Bows: New sheetmetal Convertible Header Bows ideally replace damaged or rusted originals.

CHB590	Convertible Header Bow	1959-60 Convertible	459.00
---------------	------------------------	---------------------	--------



1954-56 Buick Convertible Top Hold Down Strap and Footman Loop: Leather strap with Brass buckle used to secure the convertible top when in down position. Small chrome ‘Footman’ Loops are used to retain the leather strap; one is mounted on the body and the other is attached to the top frame.

4631033	Leather Strap	1954 Skylark, 1954-56 Special & Century Conv.	28.50
4667402	Footman Loop	1955-56 All Conv.	27.50 ea.



1950-57 Buick Windshield Wiper Transmission Chrome Escutcheons:

Reproduction wiper escutcheons have a bright Chrome finish. 1954-57 escutcheons include chrome washer nozzles and metal tube inserted into back of 1957 models to attach the wiper hoses. All are sold in pairs.

WWE503	Chrome Wiper Escutcheons	1950 All, 1951-53 Super & Roadmaster, 1953 Skylark	45.00 pr.
WWE540	Chrome Wiper Escutcheons	1954 Super & Roadmaster	95.00 pr.
WWE556	Chrome Wiper Escutcheons	1955 Roadmaster, 1956 Super & Roadmaster	95.00 pr.
WWC556	Windshield Wiper Cam-o-matic cams	1955-56 All with Cam-o-matic	45.00 pr.
WWE57SC	Chrome Wiper Escutcheons	1957 Special & Century	84.50 pr.



Wiper Transmission Chrome Nuts: Chrome plated nuts used to secure the Chrome Wiper Escutcheons onto the wiper transmission.

WWT503	Wiper Transmission Nuts	1950 All, 1951-53 Super & Roadmaster, 1953 Skylark	18.50 pr.
WWT546	Wiper Transmission Nuts	1954-57 All	16.50 pr.
WWT547	Wiper Transmission Nuts	1958 All	18.50 pr.
GM053	Wiper Nut Tool	1954-57 All	24.50

WWT547

Glass Windshield Washer Fluid Jar: New glass Washer Fluid Jar for All 1951-58 Buick models.

WWJ508 Glass Washer Jar 1951-58 All 65.00




WJC507



1951-58 Washer Jar Caps and Pump Rebuild Kits:

New Washer Jar Caps are available to fit 1951-56 and 1957-58 Buick. Quality cap replaces original. Washer Pump Rebuild kits include new rubber seals, screws and rivets.

WJC507	Washer Jar Metal Cap	1951-55 All	65.00
WJC580	Washer Jar Metal Cap	1956-58 All	75.00
D9	GM Washer Jar Cap Decal	1941-58 All	5.00
D9A	Trico Washer Jar Cap Decal	1941-58 All	4.50
WPRK507	Washer Pump Rebuild Kit	1951-55 All	79.50



WJC580



WPRK507



D9



D9A

1963-75 Washer Pump Repair Kit: Contains the necessary parts to rebuild your inoperative washer pump. Original style and application pumps are no longer available. This kit is a viable alternative to replacing the entire wiper motor and washer pump assembly.

WPRK638 Washer Pump Repair Kit 1963-75 All Models 24.50 ea.



Optikleen Glass Bottle: Triangular glass jar includes cap and Optikleen decal. Accessory used on 1959-67 Buick models. Metal bracket mounts to firewall.

OKB647	Optikleen Triangular Glass Bottle, Cap and Decal	37.50
OB647	Optikleen Bottle Metal Bracket	27.00
OKBC647	Optikleen Metal Cap	8.50
DC47	Optikleen Decal (paper decal, wet back to adhere)	8.50



Plastic Washer Fluid Jar: Translucent White plastic washer fluid jar has 'Buick' logo in raised letters. Used on 1963-64 LeSabre, Wildcat and Electra and 1965-70 Buick Riviera. Includes Black plastic snap on cap.

WJ630B Washer Fluid Jar 1963-64 LeSabre, Wildcat & Electra 39.50
1965-70 Riviera




Cam-O-Matic Wiper Arm Plastic Shoe: Black plastic insert snaps into place on the underside of Cam-O-Matic wiper arms. Used on 1959-60 Buick models equipped with the Cam-O-Matic option arms.

1472783 Wiper Arm Plastic Insert 1959-60 models 29.50 pr.



Windshield Wiper Transmission Mounting Pads: Rubber mounting pads seal underneath the windshield wiper escutcheons. Sold in pairs.

WW378	1937-38 40-60 Series	19.00 pr.
WW400	1940 50-70 Series, 1941 40 Series, 1946-49 40 series	20.00 pr.
WW428	1942-48 50-70 Series	17.00 pr.
WW512	1950 All, 1951-53 50-70 Series	20.00 pr.
WW513	1951-53 40 Series	14.00 pr.
WW546	1954 Skylark, 1954-56 40-60 Series	14.00 pr.



Windshield Wiper Arms and Blades:

WWN390	Wiper Arm Chrome Nut	1936-40 All	5.50 ea.
WWA320	Wiper Arm	1936-40 All	21.50 ea.
WWA418	Wiper Arm	1941-48 All, 1949 Special	22.50 ea.
WWA493	Wiper Arm	1949 50-70 Series, 1950-53 All	65.00 pr.
WWA556	Wiper Arm	1955-56 except Cam-o-matic	65.00 pr.
WWA578	Wiper Arm	1957-58 40-50-60 Series except Cam-o-matic	65.00 pr.
WWA590	Wiper Arm	1959-60 except Cam-o-matic	69.00 pr.
TAU-8	Wiper Blade (8 inch)	1932-38 All	15.00 ea.
TAU-9	Wiper Blade (9 inch)	1939-48 All, 1949 Special	15.00 ea.
WB493	Wiper Blade	1949 50-70 Series, 1950-53 exc. Skylark	29.00 ea.
WB546	Wiper Blade	1953 Skylark, 1954-56 some models	29.00 ea.
WB546A	Wiper Blade	1954-56 some models	49.00 ea.
WB578	Wiper Blade	1957-58 All	29.00 ea.
WB590	Wiper Blade	1959-60 All	29.00 ea.
1481285	Wiper Blade (18" satin finish)	1961-75 All	26.50 ea.
WWN540	Windshield Wiper Nozzles	1954 Skylark, 1954-56 40-60 Series, 1957-59 All	13.50 pr.
4460	Windshield Washer Hose to Pump & Filter	1961-75 All	2.00 per foot
4457	Windshield Washer Hose to Nozzles	1961-75 All	2.00 per foot
WJF6421	Windshield Washer Jar Filter, inside jar	1964-75 All	5.50



WWN540



WJF6421



Ignition, Door, Trunk and Glove Box Locks & Keys:

New lock assemblies available for Door, Ignition, Glove Box & Trunk. All locks supplied with two keys.

Ignition Lock Cylinders and Keys:

IC513B	1951-53 40 Series	29.50
IC3565	1957-60 All models	23.50
IC614B	1961-62 All exc. Special, 1963 All, 1964 All exc. Special	29.50
IC3565	1965 All models	23.50
IC68	1968 All models	27.50
IC6978	1969-78 All models	27.50



Door Lock Cylinders and Keys:

DL54	1954 40-60-80 Series, 1955-56 40-60 Series exc. 4439 & 4639	73.00 pr.
DL556	1955-56 Series 4439 & 4639	73.00 pr.
DL590	1959 2-Door Sedan	73.00 pr.
DL656	1959 All exc. 2-Door Sedan	39.50 pr.
DL614C	1960 All 2-Door, 1961-64 series 4411-37-67-69, 4637-67-69, 4719-37-67	47.00 pr.
DL556	1961-64 4439-4639, 4729-39, 4829-39	73.00 pr.
DL656	1965-66 exc. 66 Riviera	39.50 pr.
DL614C	1966-68 Riviera	47.00 pr.
DL678	1967 4-Door Htop & Sedan 39-69 models, 1967 2-Door Htop & Conv. 57-67-87 models, 1968 All exc. Riviera	39.00 pr.
DL7181T	1969-73 All exc. Riviera	26.50 pr.



Glove Box Lock Cylinders with Keys:

GB492	1941-53 All, 1955 All	49.00
GB546B	1954 All, 1956 All	29.50
GB624	1959 All	49.00
GB616B	1961-66 All exc. Riviera	26.50
GB667B	1966-67 Riviera	26.50
GB683B	1968-73 All	19.50

Trunk Lock Cylinders with Keys:

TL55	1955-58 All	38.00
TL667T	1959-60 All exc. wagon, 1965 Wildcat & LeSabre	29.50
TL678	1961 All, 1963-64 Riviera, 1965-66 exc. Riviera, 1967-68 All exc. 1968 Riviera	29.00
TL613	1966 Riviera, 1968 Riviera	38.00
TL680B	1969-70 Riviera	23.00
TL673	1969-73 All exc. Riviera & Electra	23.00
GT712RB	1971-72 Riviera & Electra (Trunk & Glove Box Set)	69.00

Ignition & Door Key Blanks:

3694624	Octagon	1937-66	5.50
7033454	Octagon 'A'	1967	5.50
7034680	Octagon 'C'	1968	5.50
7025014	Square 'E'	1969 & 1973	5.50
7025282	Square 'J'	1970 & 1974	5.50
7027275	Square 'A'	1971 & 1975	5.50
7024229	Square 'C'	1972 & 1976	5.50

Trunk & Glove Box Key Blanks:

7002238	Round	1937-66	5.50
7033455	Round 'B'	1967	5.50
7034702	Round 'D'	1968	5.50
7025019	Oval 'H'	1969 & 1973	5.50
7025288	Oval 'K'	1970 & 1974	5.50
7027281	Oval 'B'	1971 & 1975	5.50
7024235	Oval 'D'	1972 & 1976	5.50



Power Steering Pump and Gearbox Rebuilding Kits

5682664	Power Steering Pump Rebuild Kit	1953-55 All	59.50
5683483	Power Steering Pump Rebuild Kit	1956-57 All	69.50
5685766	Power Steering Pump Rebuild Kit	1958 All exc. Air Ride	69.50
5688065	Power Steering Pump Rebuild Kit	1959-67 All	65.00
5688044	Power Steering Pump Rebuild Kit	1968-77 All	59.50
1391413	Power Steering Gearbox Rebuild Kit	1953-55 All	129.00
5685033	Power Steering Gearbox Rebuild Kit	1956 All	129.00
5685263	Power Steering Gearbox Rebuild Kit	1957-58 All	129.00
5687179	Power Steering Gearbox Rebuild Kit	1959-77 All	129.00



5688044



5685263

1956-64 Power Steering Rag Joint: Flexible coupling between power steering gearbox and steering shaft.

PSC560 Power Steering Rag Joint 1956-64 All 22.50



Fusick



PSP-545V



PSP-545S



PSP-580



PSP-614

1952-67 Power Steering Pump Rebuilding Service: We offer restoration service on all 1952-67 Power Steering Pumps. Service includes degreasing plus replacement of all seals and gaskets, restoration of the metal surfaces and paint application. A new decal is applied if required. Pump Bearings available as an extra charge. Most Power Steering Pumps are in stock. **Core Charge for pumps shipped in advance of your units return is 250.00. Charge will be refunded upon return of original.**

PSP-523V	Power Steering Pump Rebuild Service, Vickers pump	1952-53 All	329.00
PSP-545V	Power Steering Pump Rebuild Service, Vickers pump	1954 All	329.00
PSP-55VB	Power Steering Pump Rebuild Service, Vickers pump	1955 All	329.00
PSP-545S	Power Steering Pump Rebuild Service, Saginaw pump	1954 All	329.00
PSP-55SB	Power Steering Pump Rebuild Service, Saginaw pump	1955 All	329.00
PSP-560	Power Steering Pump Rebuild Service, Saginaw pump	1956 All	329.00
PSP-570	Power Steering Pump Rebuild Service, Saginaw pump	1957 All	329.00
PSP-580	Power Steering Pump Rebuild Service, Saginaw pump	1958 All	329.00
PSP-590	Power Steering Pump Rebuild Service, Saginaw pump	1959-60 All	329.00
PSP-614	Power Steering Pump Rebuild Service, Saginaw pump	1961-64 exc. Special	249.00


1952-63 Rebuilt Power Steering Gear Boxes: Rebuilding service for Power Steering Gearboxes available for 1952-63 Buicks originally equipped with power steering. All 1952-63 gearbox units will need to be sent to us in advance for rebuilding, please contact us for information. Allow 3-4 weeks for rebuild time.

***1952-55 units will require an additional 100.00 shipping surcharge due to the large size.**

PSGB-525B	Power Steering Gearbox Rebuild Service	1952-55 All	1500.00
PSGB-568B	Power Steering Gearbox Rebuild Service	1956-58 All	1150.00
PSGB-593B	Power Steering Gearbox Rebuild Service	1959-63 All	499.00



PSGB-525B



PSGB-568B

Vacuum Wiper Motor Rebuilding Service: Rebuilt using all new seals, gaskets and screws. Each unit is bench tested before shipping. Most wiper motors require customer to send us the core in advance for rebuilding. Please call for availability. **Core Charge on wiper motors sent in advance of receiving core is 100.00.**

WM-CHM10-5	Vacuum Wiper Motor 1949 Super-Roadmaster, 1950 All, 1951-53 Super-Roadmaster, 1953 Skylark	169.00
WM-CHM10-41	Vacuum Wiper Motor 1951 Buick Special	169.00
WM-CPM12-9	Vacuum Wiper Motor 1952-53 Buick Special	169.00
WM-CPH10-29	Vacuum Wiper Motor 1954 40-60-100 Series early design, 1954 50-70 Series, 1955 Super	169.00
WM-CPH10-31	Vacuum Wiper Motor 1954 40-60-100 Series late design, 1955 40-60 Series	169.00
WM-CPD1-1	Vacuum Wiper Motor 1955 Roadmaster	169.00
WM-CPH10-41	Vacuum Wiper Motor 1956 40-60 Ser. exc. Cam-o-matic	169.00
WM-CPD1-7	Vacuum Wiper Motor 1956 40-60 Ser. with Cam-o-matic	169.00
WM-CPH10-39	Vacuum Wiper Motor 1956 50 Ser. without Cam-o-matic	169.00
WM-CPD2-5	Vacuum Wiper Motor 1956 50-70 Ser. Cam-o-matic (early)	169.00
WM-CPD2-7	Vacuum Wiper Motor 1956 50-70 Ser. Cam-o-matic (late)	169.00
WM-CPD2-15	Vacuum Wiper Motor 1957 with Cam-o-matic	169.00
WM-CPH10-11	Vacuum Wiper Motor 1957-58 All exc. Cam-o-matic	169.00
WM-CPD2-21	Vacuum Wiper Motor 1958 Special, Super & Century with cam-o-matic	169.00
WM-CPDM2-21	Vacuum Wiper Motor 1958 Roadmaster Limited	169.00



CHM10-5



CPH10-29



CPH10-39

Wiper Motor Coordinator Rebuilding Service: Round valve controls windshield washer operation and is used on 1956-58 Buick models. We are the only company that offers wiper motor coordinator rebuilding service.

WMC568	Wiper Motor Coordinator Rebuild Service	1956-58 All	69.00
---------------	---	-------------	-------



Wiper Control Rebuilding Service: Wiper control regulates vacuum to the wiper motor. Rebuild service includes cleaning and replacement of seals.

WC568	Wiper Control Rebuild Service	1956-58 All	69.00
--------------	-------------------------------	-------------	-------



Fuel Pump Repair Kits: Includes necessary seals, valves and gaskets to rebuild your existing Buick Fuel Pump. Early Buicks use a dual action fuel pump, which provides vacuum to engine in addition to fuel. In 1957 Buick changed to a single action fuel pump.

FPA70	Fuel Pump Kit (dual action)	1940-51 All	95.50
FPA202	Fuel Pump Kit (dual action)	1952 All, 1953 40 Series	95.50
FPA219	Fuel Pump Kit (dual action)	1953 50-70 Series, 1954-55 All exc. late 1955	105.50
FPA231	Fuel Pump Kit (dual action)	late 1955, 1956 All	95.50
FPA236	Fuel Pump Kit (single action)	1957-58 All	71.50
FPA250	Fuel Pump Kit (single action)	1959-63 All exc. Special 1964 401 & 425 engine	71.50





FPA219

Rebuilt Buick Fuel Pumps: Rebuilt using modern materials to withstand today's gasoline formulas. Most applications will require a core to be shipped in advance for rebuilding.

Core charge on in stock pumps is 175.00.

FP-529	Rebuilt Fuel Pump	1941-51 40-50 Series	229.00
FP-530	Rebuilt Fuel Pump	1941-51 60-70-90 Series	229.00
FP-9761	Rebuilt Fuel Pump	1952 40-50 series, 1953 40 Series	229.00
FP-9762	Rebuilt Fuel Pump	1952 70 Series	229.00
FP-9763	Rebuilt Fuel Pump	1953 50-70 Series, 1954-55 All exc. late 1955	229.00
FP-4304	Rebuilt Fuel Pump	late 1955, 1956 All	229.00
FP-4399	Rebuilt Fuel Pump	1957-58 All	229.00
FP-4706	Rebuilt Fuel Pump	1959-63 All exc. Special 1964 401 & 425 engines	229.00



Carburetor Rebuilding Service: Carburetor rebuilding service requires original cores be sent in advance. We are currently limited on in stock rebuilt carburetors. Call ahead for availability. Typical turn around time for rebuilding is 3-4 weeks. Any 2 or 4 barrel Carter, Rochester or Stromberg carburetor used on Buicks from 1936-1967 can be serviced.

RC2367B	Rebuild Service, Carter 2 barrel	1936-67 All	569.00
RC4367B	Rebuild Service, Carter 4 barrel	1936-67 All	599.00
RR4566B	Rebuild Service, Rochester 4 barrel	1955-66 All	599.00
RS2370B	Rebuild Service, Stromberg 2 barrel	1937-60 All	569.00
RS4370B	Rebuild Service, Stromberg 4 barrel	1937-60 All	599.00



2 Barrel Carburetor Base Gaskets:

CBP350B	Base Gasket, 1/2" thick, 3-hole	1935-39 Special, 1940-49 Special & Super	17.50
CBP360B	Base Gasket, 7/16" thick, 4-hole	1936-39 320 engine, 1950-53 Special, 1950-52 Super, 1954-55 All 2 Barrel	17.50

CBP350B



CBP360B



854444

Carburetor Base Plate Stainless Shim: Stainless Steel Shim used on some 1954-56 models with a Carter WCFB 4 Barrel carburetor.

186-8	Carter Carburetor Base Shim 1954-56 Carter WCFB 4 Barrel	25.50
--------------	--	-------


Fuel Pump to Carburetor Inline Filter Assembly: Installs in steel lines from fuel pump up to carburetor. Includes replacement style paper fuel filter.

854444	Fuel Filter Assembly	1957-60 All	39.00
GF124	Replacement Fuel Filter for glass bowl		19.00



1952-56 Rochester 4 Brl Carburetor Float: New Rochester 4 Barrel Carburetor Floats available for 1954-56 Rochester Carburetors, two floats used per carburetor.

7017488	Rochester 4 Barrel Carburetor Float 1954-56 All	59.50 ea.
----------------	---	-----------



1936-67 Carter Carburetor Rebuild Kits: Numbers stamped after 1937 located on bottom of throttle body.

101B	Carter WDO 2-Brl Kit	1936-40 All, #s 419-440-448-474	56.50
103B	Carter WCD 2-Brl Kit	1941-42 40-90 series, #s 487-549-551	56.50
105B	Carter WCD 2-Brl Kit	1941-42 with Dual Carbs (one kit services both carburetors)	79.50
107B	Carter WCD 2-Brl Kit	1946-49 40-50-70 Series, #s 608-609-663-664	56.50
109B	Carter WCD 2-Brl Kit	1950-51 70 Series, #s 725-726-882-883-2017-2081-2179	56.50
		1950-54 40-50 Series, #s 725-726-882-883-2017-2081	
109AB	Carter WCD 2-Brl Kit	1955 40-50 Series, #2179	56.50
113B	Carter WCFB 4-Brl Kit	1952-53 70 Series, #s 894-996-2053-2083	58.50
		1954-56 50-100 Series, #s 2082-2197-2347-2358	
115B	Carter WGD 2-Brl Kit	1956-60 Special & LeSabre All carb #s	58.50
119B	Carter AFB 4-Brl Kit	1957-67 All carb #s	59.50

1955-66 Rochester Carburetor Rebuild Kits: Numbers located on triangle brass tag.

118B	Rochester 4GC 4-Brl Rebuild Kit	1955 All, #s 7006200-7009100	53.50
120B	Rochester 4GC 4-Brl Rebuild Kit	1956 All, # 7009200	56.50
124B	Rochester 4GC 4-Brl Rebuild Kit	1957-58 All, #s 7010070-7011570-7011600	58.50
130B	Rochester 4GC 4-Brl Rebuild Kit	1959-62 All exc. 215 V8, 1963-66 401 V8 #s 7013044-7015040-7019040-7020040-7020041	56.50

1937-60 Stromberg Carburetor Rebuild Kits: Number stamped on top bowl cover from 1939 and up.

2000B	Stromberg AA 2-Brl Rebuild Kit	1937-49 40-50 Series, #s 7-12, 7-17, 7-19, 7-24, 7-74, 7-75, 7-79, 7-31, 7-32, 7-66, 7-69, 7-81, 7-82	62.50
2001B	Stromberg AA 2-Brl Rebuild Kit	1937-51 60-70-80-90 Series, #s 7-13, 7-15, 7-18, 7-20, 7-36, 7-22, 7-23, 7-33 1953-55 40-50 Series, #s 7-57, 7-70, 7-77, 7-80, 7-89 7-91, 7-95, 7-96, 7-102, 380150	62.50
2010B	Stromberg AA 2-Brl 2x2 Rebuild Kit	1941-42 All with Dual Carbs (one kit services both carburetors)	86.50
2002B	Stromberg AA 2-Brl Rebuild Kit	1950-52 40-50 Series, 1953 40 Series, #s 7-88, 7-90	62.50
2013B	Stromberg 4A 4-Brl Rebuild Kit	1952-54 70 Series & Skylark, #s 7-92, 7-94, 7-98	69.50
2003B	Stromberg WW 2-Brl Rebuild Kit	1955-56 40 Series, #s 7-103, 7-104, 7-105	62.50
2007B	Stromberg WW 2-Brl Rebuild Kit	1957 40 Series with Dynaflow, #7-106	62.50
2005B	Stromberg WW 2-Brl Rebuild Kit	1958-60 Special & LeSabre	76.50

1940-56 Flexible Fuel Line: Rubber fuel hose used between steel fuel lines located at the frame to fuel pump.

GL403	Fuel Line Hose	1940-53 Straight 8 engines	21.50
11215	Fuel Line Hose	1953-56 V8 engines	36.50



1948-55 Accelerator Pedal Return Spring: Long spring used to help return the accelerator pedal.

AS483B	Accelerator Pedal Spring	1948-52 All, 1953 40 Series, 1954-55 All	10.00
---------------	--------------------------	--	-------



Fuel Tank Vent Tube Filter and Hoses: Plastic vent with inner foam filter used to vent the fuel tanks on all 1968-70 Buick models except Riviera and Station Wagons. Includes two hoses and clamps for installation.

GTF690K	Fuel Tank Vent with Hoses	1968-70	37.50
----------------	---------------------------	---------	-------



1957 Buick Fuel Tank: New reproduction fuel tank for all 1957 Buick models including wagons. Original tanks had a fuel filter that attached to the drain plug/fuel outlet and be inside the tank. The new tanks require installation of an inline fuel filter on the hose fuel outlet.

FT570B	Fuel Tank	1957 All	549.00
FTS578B	Fuel Tank Straps	1957-58 All	65.00 pr.
FTB578B	Fuel Tank Bolt Kit	1957-58 All	18.00 pr.

Oversize shipping surcharge of 50.00 on all tanks



FTB578B

FT570B



FTS578B



1958 Buick Fuel Tank: New reproduction fuel tank for all 1958 Buick models except wagons. Roadmaster and Limited models have a shorter neck that requires cutting and rewelding or installation of a gas neck hose.

FT580B	Fuel Tank	1958 exc. Wagon	549.00
FTS578B	Fuel Tank Straps	1957-58 exc. Wagon	65.00 pr.
FTB578B	Fuel Tank Bolt Kit	1957-58 exc. Wagon	18.00 pr.

Oversize shipping surcharge of 50.00 on all tanks



Original Style Gas Caps: Reproduction Cadmium plated original style gas caps used on all 1938-56 & 1957-59 Buick models. Non vented design caps are used on 1957-62 Buicks.

511124	Original Style Gas Cap	1938-56 All	27.50
GC5762	Non Vented Gas Cap	1957-58 All	45.00
		1959 exc. Wagons, 1960-62 All	




Fuel Tank Sending Units: New Fuel Tank Sending Units available for 1939-59 Buicks. Sending Units include float, fuel pick-up line (exc. 1957 models) and rubber mounting gasket.

GTU3956B	Fuel Tank Sending Unit	1939-56 All	79.00
GTU57B	Fuel Tank Sending Unit	1957 All	89.50
GTU58B	Fuel Tank Sending Unit	1958 All	89.50
FTU590	Fuel Tank Sending Unit	1959 no A/C	99.50

GTU3956B

GTU57B



Fuel Sending Unit Filters: Sock type filter used on fuel pick up line on the sending unit inside the fuel tank.

FF390	Sending Unit Filter for 5/16" tube	11.50
FF577	Sending Unit Filter for 3/8" tube	15.00



GTU58B

FF390

1938-49 Gas Door Springs: Sold in a pair for all 1938-49 Buick models.

GDS389	Gas Door Springs	1938-49 All	9.75 pr.
---------------	------------------	-------------	----------



GDS389

Gas Filler Neck Rubber Grommet: Molded Rubber Grommet seals around gas filler neck where it passes through rear fender.

GF37B	Gas Filler Neck Grommet	1937 40-60 Series	68.00
--------------	-------------------------	-------------------	-------



GF37B



1939-55 Valve Cover Nuts and 1953-56 Spark Plug Cover Nuts:

Special nuts used on Rocker Covers or Spark Plug Covers. Fiber washers are used under nuts for cushion and to prevent oil seepage.

RCN396B	Valve Cover/ Spark Plug Cover Nuts	3.50 ea.
W6	Valve Cover/ Spark Plug Cover Washer	.50 ea.



1957-60 Valve Cover Bolt Grommets: Small grommets used to seal around the valve cover bolts on all 1957-60 Buick models.

VCG570B	Valve Cover Bolt Grommet	1957-60 All	3.50 ea.
----------------	--------------------------	-------------	----------



A/C Oil Filler Breather Cap: Reproduction twist on Oil Filler Breather Cap for all 1939-67 Buick models has 'A/C' and 'OIL' in raised letters on top. Proper steel wool mesh inserted to filter debris.

OC397	Oil Filler Breather Cap, Painted	1939-67 All	39.00
OC397CH	Oil Filler Breather Cap, Chrome	1939-67 All	49.00


**Oil Filter Elements:**

P112	Oil Filter Element	1939-47 All	23.50
P115	Oil Filter Element	1948 40-50 Series, 1948 70 series with Dynaflow	24.50
P127	Oil Filter Element	1948 70 series with Hydraulic Lifters, 1949-52 All, 1953 Special	19.50
PF122	Oil Filter Element	1953-58 All V8 engines	22.50



Exhaust Manifold Lock Washers: Stamped-steel Exhaust Manifold Lock Washers install on the exhaust manifold studs. Tabs bend over to lock nut in place.

EML536B	Exhaust Manifold Lock Washers	1953-56 V8	3.50 ea.
EML572B	Exhaust Manifold Lock Washers	1957-62 V8	4.00 ea.
EML626B	Exhaust Manifold Lock Washers	1962-66 V8	3.00 ea.




Upper and Lower Muffler Clamps: Limited supply of new old stock muffler clamps used on 1937-38 40-50-60 & 70 series, 1946-52 all series, 1953-54 40-60 & 70 series and 1954 Skylark (100 series). Sold in a pair.

1302878	Muffler Clamps	1937-54 models listed	13.50 pr.
----------------	----------------	-----------------------	-----------



1936-66 Engine Overhaul Gasket Sets: Complete Gasket Set includes all necessary items for an engine rebuild.

RS518G	Engine Gasket Set	1936-53 233 & 248 straight 8 cyl. engines	249.00 set
RS576BS	Engine Gasket Set	1948-53 263 straight 8 cyl. with Dynaflow	249.00 set
RS519G	Engine Gasket Set	1936-52 320 straight 8 cyl. engine	249.00 set
RS567G	Engine Gasket Set	1953-56 264 & 322 V8 engines	249.00 set
RS597G	Engine Gasket Set	1957-66 364-400-401-425 V8 engines	249.00 set



567G

1936-66 Buick Head Gaskets:

518G	Head Gasket	1936-53 233 & 248 straight 8 cyl. engines	99.00
576BS	Head Gasket	1948-53 263 straight 8 cyl. with Dynaflow	79.00
567G	Head Gaskets	1953-56 264 & 322 V8 engines	99.00 pr.
597G	Head Gaskets	1957-66 364-400-401-425 V8 engines	99.00 pr.



7281E

1937-67 Buick Intake and Exhaust Gaskets:

10008	Intake and Exhaust Gaskets	1937-53 233 & 248 straight 8 cylinder, 1948-53 263 straight 8 cyl. with Dynaflow	34.50 set
11023	Intake and Exhaust Gaskets	1937-52 320 straight 8 cylinder	34.50 set
15017E	Intake Manifold Gaskets	1953-56 264 & 322 V8 engines	29.00 set
15031E	Intake Manifold Gaskets	1957-66 364-400-401-425 V8 engines	29.00 set
7281E	Exhaust Manifold Gaskets	1953-56 264 & 322 V8 (4 pc. set)	25.50 set
3708E	Exhaust Manifold Gaskets	1957-66 364-400-401-425 V8 (8 pc. set)	25.50 set
7350E	Exhaust Manifold Gaskets	1957-66 364-400-401-425 V8 (4 pc. set)	25.50 set
3974E	Exhaust Manifold Gaskets	1964-67 300-340 V8 engines	25.50 set



3208E

1936-67 Buick Oil Pan Gaskets:

34000	Oil Pan Gasket Set	1936-53 233 & 248 straight 8 cylinder, 1936-53 263 straight 8 cyl. with Dynaflow	32.50 set
36068	Oil Pan Gasket Set	1936-52 320 straight 8 cylinder	32.50 set
23006E	Oil Pan Gasket Set	1953-56 264 & 322 V8 engines	32.50 set
23008E	Oil Pan Gasket Set	1957-66 364-400-401-425 V8 engines	32.50 set



23006E

1937-66 Buick Push Rod/Valley Cover Gasket Sets:

30005E	Push Rod Cover Gasket Set	1937-49 Super, 1940-50 Special 233-248-263	25.00 set
30007E	Push Rod Cover Gasket Set	1950-52 Super, 1951-53 Special 233-248-263	25.00 set
33002E	Push Rod Cover Gasket Set	1937-52 320 straight 8 cylinder	25.00 set
21006E	Valley Pan Gasket Set	1953-56 264 & 322 V8 engines	22.50 set
21013E	Valley Pan Gasket Set	1957-66 364-400-401-425 V8 engines	22.50 set



30007E




21007E

1934-66 Buick Valve Cover Gaskets:

32009E	Valve Cover Gasket	1934-53 233 & 248 straight 8 cylinder 1950-53 263 straight 8 cylinder with Dynaflow	35.00
34002E	Valve Cover Gasket	1936-52 320 straight 8 cylinder	35.00
21007E	Valve Cover Gaskets	1953-56 264 & 322 V8 engines, 1957-66 364-400-401-425 V8 engines	28.50 pr.

1936-67 Rear Main Seals: Available in either original style graphite rope seal or modern rubber replacement seal.

5143	Rear Main Seal (rope)	1936-53 233 & 248 straight 8 cylinder,	29.00
		1950-53 263 straight 8 cylinder with Dynaflo,	
		1936-52 320 straight 8 cylinder,	
		1957-66 364-400-401-425 V8 engines	
3764	Rear Main Seal (rubber)	1940-53 233 & 248 straight 8 cylinder,	69.00
		1940-53 263 straight 8 cyl. with Dynaflo	
4424	Rear Main Seal (rope)	1953-56 264 & 322 V8 engines	29.00
3A29S	Rear Main Seal (rubber)	1957-66 364-400-401-425 V8 engines,	59.00
		1964-67 300 & 340 V8 engines	




1936-66 Timing Cover Gasket Sets:

GS13022	Timing Cover Gasket and Seal Set	1936-53 233-248-263 straight 8 cylinder	35.00 set
GS12060	Timing Cover Gasket and Seal Set	1953-56 264 & 322 V8 engines,	35.00 set
		1957-66 364-400-401-425 V8 engines	

Engine Parts

Freeze Plug Kits: Complete engine freeze plug kits for all 1939-60 Buick straight 8 and V8 engines.

FPK4	Engine Freeze Plug Kit	1939-53 straight 8	55.00 kit
FPK5	Engine Freeze Plug Kit	1953-60 All V8	55.00 kit



Camshafts: New camshafts available for 1953-61 V8 engines.

CM314	Camshaft	1953-55 322 V8 50-60-70 Series,	349.00
		1954-55 264 V8 40 Series,	
		1956 322 V8 all Series,	
CM564	Camshaft	1957-61 364 & 401 V8	349.00



Cam Bearing Sets: New cam bearings available for following 1937-61 Buick engines.

CBS145	Cam Bearing Set	1937-53 248 & 263 straight 8 40 Series,	109.00 set
		1937-52 248 & 263 straight 8 50 Series,	
CBS317	Cam Bearing Set	1953-56 322 V8 50-60 & 70 Series,	89.00 set
		1954-55 264 V8 40 Series,	
		1956 322 V8 40 Series	
CBS361	Cam Bearing Set	1957-61 364 & 401 V8 engines	89.00 set



Valve Lifters: We recommend installing new lifters with all camshaft replacements.

VL1H	Hydraulic Valve Lifter	1948-53 straight 8 cylinder	21.00 ea.
VL2	Hydraulic Valve Lifter	1953-55 322 V8 50-60 & 70 Series,	14.50 ea.
		1954-55 264 V8 40 Series	
VL5	Hydraulic Valve Lifter	1956-61 322, 364 & 401 V8 engines	14.50 ea.

Rocker Arm Shafts:

RAS42000	Rocker Arm Shaft	1953-61 264, 322, 364 & 401 V8	49.00 ea.
-----------------	------------------	--------------------------------	-----------



Push Rods: Pre 1953 Buick straight 8's used many different length Push Rods. They are available on a special order basis, we will need the length of original push rods at time of order.

PR48004	Push Rod	1953-55 322 V8 50-60-70 Series, 1954-55 264 V8 40 Series	11.00 ea.
PR48000	Push Rod	1956 322 V8 engine	11.00 ea.
PR48001	Push Rod	1957-58 364 V8 all Series, 1959-61 364 V8 LeSabre	11.00 ea.



Rocker Arms: Sold in a complete set of 16 Rocker Arms. Buick V8 engines use two types of rocker arms on each engine. The four left rear arms match the four right front arms and the four right rear arms match the four left front arms.

RA44000/1	Rocker Arm Set	1953-56 322 V8, 1954-55 264 V8 40 Series	229.00 set
RA44002/3	Rocker Arm Set	1957-61 364 & 401 V8	229.00 set



Intake & Exhaust Valve Guide Sets:

VG384	Valve Guide Set	1937-53 248 & 263 straight 8 40 Series, 1937-52 248 & 263 straight 8 50 Series	80.00 set of 16
VG733	Valve Guide Set	1953-61 264, 322, 364 & 401 V8	69.00 set of 16



Intake Valves:

IV944	Intake Valve	1936-53 248 & 263 straight 8 40 Series, 1936-52 248 & 263 straight 8 50 Series	24.50 ea.
IV2010	Intake Valve	1953 322 V8 50-60-70 Series	19.50 ea.
IV2044	Intake Valve	1954-56 322 V8 engine, 1954-55 264 V8 40 series	19.50 ea.
IV2226	Intake Valve	1957-58 364 V8 engine	19.50 ea.
IV2274	Intake Valve	1959-63 364 & 401 V8 engines	19.50 ea.



Exhaust Valves:

EV837	Exhaust Valve	1936-53 248 & 263 straight 8 40 Series, 1936-52 248 & 263 straight 8 50 Series	21.00 ea.
EV407	Exhaust Valve	1936-52 320 straight 8 60 & 70 Series	21.00 ea.
EV2009	Exhaust Valve	1953 322 V8 50-60-70 Series	21.00 ea.
EV2043	Exhaust Valve	1954 264 & 322 V8 engines	21.00 ea.
EV2088	Exhaust Valve	1955-56 264 & 322 V8 engines	21.00 ea.
EV2225	Exhaust Valve	1957-58 364 V8 engine	21.00 ea.
EV2404	Exhaust Valve	1959-63 364 & 401 V8 engines	21.00 ea.

Outer Valve Springs:

VS594	Outer Valve Spring	1937-47 All, 1948-49 248 straight 8 40 & 50 Series, 1950-53 263 straight 8 40 Series with Dynaflow, 1950-52 263 straight 8 50 Series with Dynaflow, 1948-52 320 straight 8 60 & 70 Series	9.00 ea.
VS862	Outer Valve Spring	1953-61 264, 322, 364 & 401 V8	9.00 ea.

Inner Valve Springs:

VS595	Inner Valve Spring	1949 248 straight 8 40 & 50 Series, 1950-53 263 straight 8 40 Series with Dynaflow, 1950-52 263 straight 8 50 Series with Dynaflow, 1949-52 320 straight 8 60 & 70 Series	9.00 ea.
VS815	Inner Valve Spring	1953-61 264, 322, 364 & 401 V8	9.00 ea.

Piston and Pin Sets: Replacement pistons sold in a set of eight. Available in standard size and over-size .020, .030, .040 and .060. Specify correct size when ordering.


PST989A	Piston and Pin Set	1953 322 V8	329.00 set
PST1040A	Piston and Pin Set	1954-56 322 V8	329.00 set
PST1042A	Piston and Pin Set	1954-55 264 V8	529.00 set
PST2008A	Piston and Pin Set	1957-58 364 V8 50-60-70 Series, 1959-61 364 V8 LeSabre	329.00 set



PST989A

Piston Ring Sets: Complete Piston Ring Sets available in standard and oversize .020, .030, .040, and .060. Specify correct size when ordering.

RNG1105C	Piston Ring Set	1937-50 248 straight 8	199.00 set
RNG8325C	Piston Ring Set (cast iron)	1953-56 322 V8	71.50 set
RNG7678C	Piston Ring Set (cast iron)	1957-61 364 V8	99.00 set



Timing Chain & Gear Sets: Includes Timing Chain, Crank Gear and Cam Gear.

483/37/38	Timing Chain and Gear Set	1950 248 straight 8, 1950-53 263 straight 8	209.00 set
493/59/60	Timing Chain and Gear Set	1953-56 322 V8, 1954-55 264 V8	209.00 set
493/04/76	Timing Chain and Gear Set	1957-61 364 V8, 1959-61 401 V8	129.00 set



Rod Bearing Sets: Rod Bearing Sets available in standard and undersize .010, .020, .030 and .040. Specify correct size when ordering.

RB349	Rod Bearing Set	1950-53 263 straight 8	179.00 set
RB314	Rod Bearing Set	1949-52 320 straight 8	179.00 set
RB426	Rod Bearing Set	1953-56 322 V8, 1954-55 264 V8	179.00 set
RB517	Rod Bearing Set	1957-61 364 V8, 1959-61 401 V8	129.00 set



Main Bearing Sets: Main Bearing Sets available in standard and undersize .010, .020, .030, and .040. Please specify correct size when ordering.

MBS306	Main Bearing Set	1949-52 320 straight 8	219.00 set
MBS1555	Main Bearing Set	1953-56 322 V8, 1954-55 264 V8	219.00 set
MBS1811	Main Bearing Set	1957-61 364 V8	219.00 set



Oil Pump Rebuild Kits:

OPK51991	Oil Pump Rebuild Kit	1940-50 248 straight 8, 1950-53 263 straight 8	109.00
OPK51005	Oil Pump Rebuild Kit	1953-56 322 V8, 1954-55 264 V8	109.00
OPK51003	Oil Pump Rebuild Kit	1957-58 364 V8	109.00
OPK51004	Oil Pump Rebuild Kit	1959-61 364 & 401 V8	109.00



OPK51003

1948-60 Dynaflow Transmission Rebuild Kits and Parts:

We can supply Master Rebuilding Dynaflow Transmission Kits and many individual kits and parts to maintain your Buick. Master overhaul kits include gaskets, seals, rings, friction plates and steel plates. Bushings, washer kits and transmission bands are sold separately.


We do not have 1958-59 Buick Triple Turbine Flight Pitch parts at this time.

D102-1	Dynaflow Master Rebuild Kit	1948-54 All	389.00
D102A-1	Dynaflow Master Rebuild Kit	1955-60 All	429.00
D102B-1	Dynaflow Master Rebuild Kit	1961-63 All	429.00
D102-4	Dynaflow External Seal & Gasket Kit	1948-54 All	125.00
D102A-4	Dynaflow External Seal & Gasket Kit	1955-60 All	125.00
D102B-4	Dynaflow External Seal & Gasket Kit	1961-63 All	125.00
KD106	Dynaflow Bushing Kit	1948-54 All	129.00
KD106A	Dynaflow Bushing Kit	1955-63 All	139.00
KD111	Dynaflow Washer Kit	1948-54 All	109.00
KD111A	Dynaflow Washer Kit	1955-63 All	129.00
D110-9A	Dynaflow Torque Ball Retainer	1948-60 All	129.00
(replacement fits all 1948-60 Dynaflow Transmissions. Does not have lip, dust boot rests against retainer)			
D110-9B	Dynaflow Torque Ball Seal Kit	1948-52 All	149.00
D110-9C	Dynaflow Torque Ball Seal Kit	1953-60 All	149.00
(Includes D110-9A, rear seal and shims)			
16010E	Dynaflow Transmission Pan Gasket	1948-63 All	18.50
13073E	Dynaflow Flight Pitch Transmission Pan Gasket	1958-59 All	18.50
12090E	Super Turbine 300 (2 speed) Transmission Pan Gasket	1964-69 All	21.50
1334298	Dynaflow Torque Ball Boot	1948 Roadmaster, 1949-52 All	79.00
1170199	Dynaflow Torque Ball Boot	1953-55 All	79.00
Note: Some 1953 Buicks use the 1334298 boot. Check shape of boot before ordering.			



Buick Engine Paint: Enamel Engine Paint is computer matched from original color samples. Sold in 11-fluid-ounce aerosol cans.

EP20	Turquoise Engine Paint	1942-53 All straight 8	19.50 can
EP30	Aqua Engine Paint	1953-67 All V8 engines	19.50 can



Buick Engine Mounts:

MM347B	Engine Mounts	1934-35 40 Series, 1936 All exc. Conv, 1937-38 All	145.00 pr.
M2112/3	Engine Mounts	1953-56 All V8	109.00 pr.
M2165	Engine Mounts	1957-58 All	149.00 pr.
M2166	Engine Mounts	1959-60 All	109.00 pr.

Buick Transmission Mounts:

M1029	Transmission Thrust Mount	1948-56 All Dynaflow	55.00
M2069	Transmission Thrust Mount	1948-56 All standard transmission	55.00
M2145	Transmission Thrust Mount	1957-59 All exc. Flight Pitch trans.	55.00
M2070	Dynaflow Transmission Mount	1948-58 exc. 1953 Dynaflow	49.00



Motor Mount and Transmission Mount Bolt Kits: Complete new hardware kits available for Buick Motor Mounts and Transmission Mounts.

MMB4856B	Motor Mount Bolt Kit	1948-56 All	17.00
TMB4059B	Transmission Mount Bolt Kit	1940-59 All	19.00



Driveshaft Center Bearings and Support Mounts:

Replacement part needed to eliminate driveshaft vibration.

Support Mounts include bearing retaining clips. Bearing is sold separately.

BS619B	Driveshaft Bearing Support	1961-64 All	94.50
BS658B	Driveshaft Bearing Support	1965-68 LeSabre, Wildcat & Electra	65.00
6908	Driveshaft Center Support Bearing	1961-68 All	99.50



Buick Air Filter Elements: Many AC Delco filters have been discontinued, however we supply the available AC Delco filters, but substitute with other replacement brands when necessary.

A212CW Air Filter Element 1968 All 4-Barrel. & 1969 Riviera GS, 18.00
1970-76 4-Barrel. Wildcat, Centurion, Electra & Riviera



Air Filter to Valve Cover Breather Tubes: Molded rubber tubes install between the valve cover and the air cleaner assembly on V8 engines equipped with 4 Barrel Carburetor.

VT689B Breather Tube 1968-69 350-400-430 4-Barrel 19.50 ea.
VT704B Breather Tube 1970-71 All V8, 1972 455 V8 18.00 ea.

Crankcase to Carburetor Molded Vent Hose: Rubber hose attaches between the Crankcase and the 4 Barrel Carburetor on 350 & 455 V8 engines.

VH725B Vent Hose 1971-75 350-455 V8 21.75

1936-59 Buick Bypass Hoses: Short straight hose used as a bypass between water pump and the bottom of the thermostat housing on 1936-1959 Buick engines.

1298610 Bypass Hose 1936-49 All 4.50
1340851 Bypass Hose 1950-59 All 4.50



Black Ribbed Heater Hose: Available in 3/4" i.d. or 5/8" i.d. with correct 5-rib design. Sold by the foot for various Buick applications.

HH5/8 Ribbed Heater Hose, 5/8" 5.50 per foot
HH3/4 Ribbed Heater Hose, 3/4" 5.50 per foot



5/8" Water Outlet Nipple: Water Outlet Nipple used on 1937-58 Buicks for water pump or block applications.

WPN340 Water Outlet Nipple 1937-58 All 11.00



1950-53 Heater Control Valve Hose: Curved heater hose from Heater Control valve to the defroster inlet for All 1950-53 Buick models.

1341781 Heater Control Valve Hose 1950-53 All 16.50

1951-53 Heater Control Valve Foam Seal: High quality foam rubber seal designed to cushion heater control valve and seal out water and noise on All 1951-53 Buick models.

1342597 Heater Control Valve Seal 1951-53 All 30.00



Whittek 'Tower' Style Hose Clamps: Available in popular sizes for heater hoses and radiator hoses used on 1949-60 Buick models.

HC54 Wittek Hose Clamp, 1-1/16" 4.00 ea.
HC55 Wittek Hose Clamp, 1-1/4" 5.00 ea.
HC62 Wittek Hose Clamp, 2-1/16" 5.00 ea.
HC78 Wittek Hose Clamp, 2-1/4" 5.50 ea.



Buick Radiator Hoses: Correctly molded, Buick number stamped Radiator Hoses. All hoses are stamped with the original GM part number and have the proper bends for easy installation.

Upper Radiator Hoses:

1303682	Upper Radiator Hose	1936-38 All, 1939-40 80-90 Series	31.50
1309316	Upper Radiator Hose	1939-40 40-50-60-70 Series	45.00
1321616	Upper Radiator Hose	1941 40-50 Series	45.00
1390727	Upper Radiator Hose	1947 w/ #3119868 rad, 1948-49 40-50 Ser.	45.00
1339068	Upper Radiator Hose	1948 70 Series	45.00
1337134	Upper Radiator Hose	1949 70 Series	45.00
1390726	Upper Radiator Hose	1950-52 40-50 Series, 1953 40 Series	45.00
1339966	Upper Radiator Hose	1950-52 70 Series	45.00
1318716	Upper Radiator Hose	1953 V8 exc. Super w/ man trans, no A/C	45.00
1163095	Upper Radiator Hose	1954-56 All models	45.00
1173211	Upper Radiator Hose	1957 All models	45.00
1180759	Upper Radiator Hose	1958 All models	45.00
1186272	Upper Radiator Hose	1959 All models	45.00
1193220	Upper Radiator Hose	1960 All models	45.00

Fusick



1163095

Lower Radiator Hoses:

1394876	Lower Radiator Hose	1936-38 60-80-90 Ser, 1939-40 80-90 Ser	45.00
1394877	Lower Radiator Hose	1939-40 40 Series, 1940 50 Series	45.00
1393064	Lower Radiator Hose	1941 40-50 Series	45.00
1390724	Lower Radiator Hose	1942-47 41-41SE-46-46S-46SSE-49, 1942-47 50-60 70-90 Series, 1948 All, 1949 70 Series	45.00
1393976	Lower Radiator Hose	1949 40-50 Series	45.00
1390299	Lower Radiator Hose	1950-52 40-50 Series, 1953 40 series	45.00
1390300	Lower Radiator Hose	1950-52 70 Series	45.00
1391165	Lower Radiator Hose	1953 50-70 Series, 1954-56 All	45.00
1392922	Lower Radiator Hose	1957 All models	45.00
1388374	Lower Radiator Hose	1958 All models	45.00
1388584	Lower Radiator Hose	1959 All models	45.00
1199313	Lower Radiator Hose	1960 All models	45.00

Fusick



1391165

Heater Control Valve Rebuild Service: Rebuilding service for all Ranco and Harrison Heater Control Valves. Most valves require your rebuildable core in advance for service. Many Buick valves use long capillary tubes. These tubes must be intact in order to rebuild units. **Core charge on in stock Rebuilt Heater Valves is 150.00** which is refunded upon receipt of your **rebuildable core**. Missing parts, broken capillary tubes and collapsed capillary bags will be deducted from the core charge refund.

HCV-1342540	Heater Control Valve	1942-50 All	165.00
HCV-1343735	Heater Control Valve	1951-53 All	165.00
HCV-1163846	Heater Control Valve	1954-55 All	165.00
HCV-1175397	Heater Control Valve	1956 All	165.00
HCV-1178563	Heater Control Valve	1957 All	165.00
HCV-1181344	Heater Control Valve	1958 All	165.00
HCV-1189168	Heater Control Valve	1959 All with automatic heater	165.00
HCV-3146294	Heater Control Valve	1959 All with manual heater	165.00
HCV-3147318	Heater Control Valve	1960 All	165.00
HCV-3150613	Heater Control Valve	1961-62 All exc. Special	165.00
HCV-3151404	Heater Control Valve	1961-63 All Special & Skylark	165.00




1343735



1175397





3131115



3135076



3141027



3144756

Rebuilt Heater Cores: Rebuilding service on original Buick heater cores, check with us on availability. Some will require original unit to be sent in for service. **Core charge of 250.00** on all rebuilt units sent in advance of re-buildable core being sent in to us.

HC-3123864	Rebuilt Heater Core	1950-53 All models	425.00
HC-3131115	Rebuilt Heater Core	1954-55 All models	425.00
HC-3135076	Rebuilt Heater Core	1956-57 All models	425.00
HC-3141027	Rebuilt Heater Core	1958 All models	425.00
HC-3144756	Rebuilt Heater Core	1959-62 All exc.Special/Skylark	425.00



RC1R



RC6R



RC15R




RC27

Radiator Caps: Correctly reproduced AC Radiator Caps.

RC1R	AC Radiator Cap	1949-56 All exc. 1955-56 with A/C	36.50
RC6R	AC Radiator Cap	1955-56 All with A/C	39.50
RC15R	AC Radiator Cap	1957-64 All exc. Special & Skylark	36.50
		1965-68 All, 1969-70 without coolant recovery	
RC27	AC Radiator Cap	1970-72 with coolant recovery	36.50

Reproduction Thermostat Housings: Cast Aluminum replacement Thermostat Housings available for 1954-666 Buick models. Mounting gasket sold separately.

1186342	Thermostat Housing	1954-57 V8 engines	26.50
1350825	Thermostat Housing	1962-66 401-425 engines	32.50



1186342

1350825

Thermostats and Thermostat Housing Gaskets:

300-160	160 degree Thermostat	1937-53 Straight 8,	14.50
		1964-66 300 & 340 V8, 1967-68 All V8	
300-180	180 degree Thermostat	1937-53 Straight 8,	14.50
		1964-66 300 & 340 V8, 1967-68 All V8	
300-195	195 degree Thermostat	1937-53 Straight 8,	14.50
		1964-66 300 & 340 V8, 1967-68 All V8	
33036	160 degree Thermostat	1953-66 264, 322, 364, 401 & 425 V8	14.50
33038	180 degree Thermostat	1953-66 264, 322, 364, 401 & 425 V8	14.50
2172	Thermostat Housing Gasket	1934-40 233, 248, 263	5.00
2173	Thermostat Housing Gasket	1936-49 320, 1941-49 248, 263	5.00
TG578	Thermostat Housing Gasket	1949-53 Straight 8 Cylinder	5.50
33625	Thermostat Housing Gasket	1953-66 264, 322, 364, 401 & 425 V8	5.00



33036



33621



TG578



33625



Rebuilt Original Buick Water Pumps: Rebuilding service available for all 1936-66 Buick models listed. Most applications will require the core be sent in advance for rebuilding. If we do have a unit in stock there will be an additional **150.00 core charge** that will be refunded upon return of original pump.

WP-1328454	Rebuilt Water Pump	1934-39 40 Series, 1940 40-50 Series	295.00
WP-1393739	Rebuilt Water Pump	1936-40 60-70-80-90 Ser, 1941-49 All	295.00
WP-1341508	Rebuilt Water Pump	1950-53 Straight 8	295.00
WP-1392632	Rebuilt Water Pump	1953-55 V8	295.00
WP-1392637	Rebuilt Water Pump	1956 All	295.00
WP-1396560	Rebuilt Water Pump	1957 All	295.00
WP-1350016	Rebuilt Water Pump	1958 All exc. A/C	295.00
WP-1396561	Rebuilt Water Pump	1958 All with A/C	295.00
WP-1396562	Rebuilt Water Pump	1959-60 All,	295.00
		1961 exc. A/C and Special	
WP-1396348	Rebuilt Water Pump	1962-66 exc. A/C,	295.00
		exc. Special & Skylark	
WP-1399641	Rebuilt Water Pump	1962-66 with A/C	295.00
		exc. Special & Skylark	



1341508



1396562

1396876	NOS Water Pump, sold as is, no warranty	1965-67 225, 300, 340, 1968-70 350	159.00
1396879	NOS Water Pump, sold as is, no warranty	1967-72 400, 430, 455	159.00
1247080	NOS Water Pump, sold as is, no warranty	1973-76 455	159.00

Buick Water Pumps: Reproduction replacement water pumps available for 1936-49 Straight 8 and 1953-61 V8 Buick engines. Pumps do not have part numbers or markings cast into housing. Water pumps include a new mounting gasket.

W3649B	Reproduction Water Pump	1936-49 248, 322 Straight 8	185.00
W503B	Reproduction Water Pump	1950-53 248, 263, 320 Straight 8	185.00
W535B	Reproduction Water Pump	1953-55 322 V8	185.00
W496B	Reproduction Water Pump	1956 322 V8	185.00
W528B	Reproduction Water Pump	1957-58 364 V8	185.00
W560B	Reproduction Water Pump	1959-61 exc. 61 with A/C	185.00



W535B



W496B



W528B



W560B

Buick Fan Belts:

454	Fan Belt	1936-39 40 Series	36.50
692	Fan Belt	1937-39 60-80-90 Series	36.50
562	Fan Belt	1940 40-50 Series (47 5/8")	36.50
625	Fan Belt	1940 60-70-80-90 Series (51")	39.50
660	Fan Belt	1941-49 40-50 Series (49 1/2")	36.50
625	Fan Belt	1941-49 60-70 Series 320 engine (52")	39.50
454	Fan Belt	1950 40-50 Series 248-263 engines	36.50
686	Fan Belt	1950 60-70 Series 320 engine	36.50
7435	Fan Belt	1951-52 40-50 Series 248-263 engines	27.50
7541	Fan & Generator Belt	1953 50-70 Series V8	27.50
7541	Power Steering Belt	1953 50-70 Series V8	27.50
7530	Fan & Generator Belt	1954-56 All exc. A/C, 1957 early exc. A/C	27.50
7650	Fan, Generator & A/C Belts	1955 All (uses two belts)	27.50 ea.
7530	Power Steering Belt	1954 All	27.50
7555	Power Steering Belt	1955-56 All	27.50
7530	Fan & Generator Belt	1957 late, 1958 All	27.50
7545	Power Steering Belt	1957 early, 1958 All exc. A/C	27.50
7541	Power Steering Belt	1957 late, 1958 All with A/C	27.50
7575	Air Conditioning Belt	1957 early	27.50
7580	Air Conditioning Belts	1958 All with A/C (uses two belts)	27.50 ea.
7495	Fan & Power Steering Belt	1959-60 All	27.50



Note: 1957 Buicks used both early and late belt lengths. We would need your existing belt number for proper identification.

Ignition Wire Sets: Fully tailored (except where specified), high quality Ignition Wire sets are made using original GM blueprints. Date coded for the 1st quarter of each year for 1961-72 Ignition Wire Sets.

RC313B	Ignition Wire Set	1931-53 Straight 8, Tan/Black cloth, semi-tailored	53.50
RS313B	Ignition Wire Set	1931-53 Straight 8, Black rubber semi-tailored	53.50
RS493B	Ignition Wire Set	1937-53 Straight 8 cylinder	85.00
RS536B	Ignition Wire Set	1953-56 V8, Black rubber	85.00
LS536B	Ignition Wire Set	1953-56 V8, Lacquered cloth, semi-tailored	53.50
RS578B	Ignition Wire Set	1957-58 V8 engine	89.50
RS590B	Ignition Wire Set	1959-60 V8 engine	89.50

**Buick Spark Plug Wire Retainers:**

WH363	Ignition Wire Retainers (4 pcs)	1937-52 All, 1953 40 Series	30.00 set
WH546B	Ignition Wire Retainer	1954-56 All	7.00 ea.
WH578B	Ignition Wire Retainer	1957-58 All	7.00 ea.
WR683	Ignition Wire Retainer	1967-72 All	4.00 ea.



Positive Battery Cable Retainer: Black plastic clip used to secure the positive battery cable.

WR672	Battery Cable Retainer	1967-72	3.25 ea.
--------------	------------------------	---------	----------



Factory Rebuilt Distributors: Complete rebuilding service includes rebuilt vacuum advance, new points, condenser, rotor and distributor cap. Please check with us for availability, not all units will be in stock. A **150.00 core charge will be added to rebuilt distributors sent in advance, refunded upon receipt of old unit.** Rebuilding service available for distributors prior to 1946, please contact us for information.

DIS-1110801	Rebuilt Distributor	1946-48 All, 1949 Special	379.00
DIS-1110815	Rebuilt Distributor	1949 50-70 Series, 1950-52 All	379.00
DIS-1110838	Rebuilt Distributor	1953 Special	379.00
DIS-1110827	Rebuilt Distributor	1953 Super, Roadmaster & Skylark	379.00
DIS-1110849	Rebuilt Distributor	1954-55 All	379.00
DIS-1110861	Rebuilt Distributor	1956 All	379.00
DIS-1110870	Rebuilt Distributor	1957 All, 1958 some models (check tag number)	379.00
DIS-1110934	Rebuilt Distributor	1958 some models (check tag number)	379.00
DIS-1110959	Rebuilt Distributor	1959 with automatic transmission	379.00
DIS-1110993	Rebuilt Distributor	1960-63 All exc. Special, 1964 Electra & Riviera, 1965 425 V8 Wildcat, Electra & Riviera, 1966 425 engines	379.00



1110827

Distributor Vacuum Advance: Rebuilt Distributor Vacuum Advances for all 1937-59 Buicks.

All units require an additional core charge of 95.00 if sent in advance of receiving core.


VC6	Distributor Vacuum Advance	1937-52 All	89.00
VC7	Distributor Vacuum Advance	1953 40 Series	89.00
VC63	Distributor Vacuum Advance	1953 50-70 Series, 1954-56 All	89.00
VC20	Distributor Vacuum Advance	1957-59 All	89.00
1917246	Vacuum Advance Gasket	1953-56 All	3.00



VC6

Distributor Lead Wires:

1879140	Distributor Ground Wire	1934-52 All, 1953 40 Series	4.00
1865978	Distributor Lead Wire	1937-56 All	18.50
1942518	Distributor Lead Wire w/ grommet	1957-70 All	22.50
1932023	Distributor Lead Wire grommet	1957-70 All	4.00



1879140

1942518

Delco-Remy Distributor Tag with Rivets: New distributor tags include fastening rivets. Number stamping process available upon request.

DT35	Delco-Remy Distributor Tag	1935-55 All	9.50
-------------	----------------------------	-------------	------



Voltage Regulators: 'D' prefix for part # indicates A/C Delco, 'VR' prefix indicates Standard Ignition.

D601	Voltage Regulator (6 volt)	1940-51 All	112.00
VR8R	Voltage Regulator (6 volt)	1952 All, 1953 Special	112.00
D618	Voltage Regulator (12 volt)	1953 Super & Roadmaster, 1954-55 All, 1956 with generator #1102008	133.00
D621	Voltage Regulator	1956 with generator #1102051 & 112053, 1957 All, 1958-62 exc. A/C	112.00
VR24R	Voltage Regulator	1958-61 with A/C, 1962 with generator and A/C	145.00
D635	Voltage Regulator	1962 with alternator, 1963-65 exc. 62A alternator, 1966-67 exc. Riviera & 62A alternator, 1968 All exc. 62A & 63A alternator	103.50
D632	Voltage Regulator	1966-67 Riviera	69.50



D601



D632



Distributor Caps, Rotors, Points and Condensors:

DR196	Distributor Cap	1937-52 All, 1953 40 Series	37.50
DR427	Distributor Cap	1953 50-70 Series, 1954-56 All	29.50
D308R	Distributor Cap	1957-74 All	26.50
DR142	Distributor Rotor	1937-50 All	15.00
DR307	Distributor Rotor	1951-52 All, 1953 40 Series	13.50
DR306	Distributor Rotor	1953-56 All V8	29.50
DR426R	Distributor Rotor	1957-74 All	15.00
DR2236P	Ignition Points Set	1937-52 All, 1953 40 Series	29.50
DR2437P	Ignition Points Set	1953 50-70 Series, 1954-56 All	29.50
D106PS	Ignition Points Set	1957-74 All	29.50
D203	Ignition Condensor	1937-56 All	18.50
D204	Ignition Condensor	1957-74 All	13.50

Tune Up Kits: Contains Distributor Cap, Rotor, Points and Condensor.

TK2	Tune Up Kit	1937-50 All	95.00
TK2B	Tune Up Kit	1951-52 All, 1953 40 Series	89.00
TK4B	Tune Up Kit	1953 50-70 Series, 1954-56 All	89.00
TK5	Tune Up Kit	1957-74 All	79.00

AC Delco Spark Plugs: Genuine A/C Delco plugs.

R45	Spark Plug	1938-58 with 14 mm plugs	4.50 ea.
R45S	Spark Plugs	1959-66 400, 401, 425, set of 8	36.00
		1965-57 300 & 340	
R44TS	Spark Plug	1967-71 400, 430, 455, 350 GS	4.50 ea.
R45TS	Spark Plug	1968-71 350 exc. GS, 1972-74 All	4.50 ea.

Horn Relays:

HR114	Horn Relay	1940-52 All, 1953 40 Series	36.00
U1738	Horn Relay	1953 50-70 Series, 1954-56 All	39.50
HR117	Horn Relay	1957-58 All	29.50
HR125	Horn Relay	1959-60 All	37.50
R203	Horn Relay	1961-67 All	79.50

Headlight Switches: New headlight switches available for the following models.

1995031	Headlight Switch, 6 volt	1949 Super & Roadmaster	76.50
1995031-12V	Headlight Switch, 12 volt	1949 Super & Roadmaster	76.50
DS155	Headlight Switch	1967 All models	49.50

Headlight Dimmer Switch: High-Low Headlight Dimmer Switch located on left side of drivers floor board.

DS40	Headlight Dimmer Switch	1934-58 All	49.50
DS590	Headlight Dimmer Switch	1959-60 All exc. Guidematic	28.50
D808	Headlight Dimmer Switch	1963-67 All exc. Guidematic	23.50

Positive Battery Cable Strap: Metal strap used to secure the positive battery cable to the starter on 1954-58 models.

PCHD5458	Positive Battery Cable Strap	1954-58 All	22.50
-----------------	------------------------------	-------------	-------



Ignition Coils: New Ignition Coils for 1939-60 Buicks, 1939-52 and 1953 Special are 6 volt units, while 1953 Super & Roadmaster and All 1954-60 models use a 12 volt coil. Ignition coils are A/C Delco replacements when available or a comparable quality.

337164	6 Volt Ignition Coil	1949-52 All, 1953 40 Series	85.00
337166	12 Volt ignition Coil	1953 50-70 Series, 1954-72 All	85.00

Starter Solenoid Switches:

SS201	Starter Solenoid Switch	1954-56 All	98.50
SS200	Starter Solenoid Switch	1957-75 All	75.00
SPB567	Starter Solenoid Plunger Boot	1951-56 All	20.00



Starter Drive Assemblies:

SDN73	Starter Drive Assembly	1949-53 All	69.50
SDN8	Starter Drive Assembly	1954-56 All	63.00
SDN7	Starter Drive Assembly	1957-60 All, 1961 361 & 401	89.50
SDN1A	Starter Drive Assembly	1964-74 All	36.50

Generator Oil Fill Caps: Two sizes used on all 1935-62 Buick Generators.

21-430	Generator Oil Fill Cap (1/4" diam. on end frame side)	1935-62 All	7.50
21-431	Generator Oil Fill Cap (3/16" diam. pulley drive side)	1935-62 All	6.50



Starter and Generator Inspection Cover Bands: Metal bands wrap around starter and generator to cover the inspection holes. Starter band used on all 1935-50 models and generator band used for all 1938-51 models,

817114	Starter Inspection Cover Band	1935-50 All	16.50
816340	Generator Inspection Cover Band	1938-51 All	16.50



Starter and Generator Brush Sets and Generator End Bearings: Necessary maintenance items for any Starter or Generator rebuilding process. Each set services one unit.

RX60	Starter Brush Set	1937-52 All, 1953 40 Series, 1954-75 All models	11.50 set
RX45	Starter Brush Set	1953 50-70 Series	11.50 set
RX46	Generator Brush Set	1934-39 All	11.50 set
RX63	Generator Brush Set	1940-62 All	13.50 set
3203	Generator End Bearing	1937-62 All	19.50



Generator and Starter I.D. Tags with Rivets: Replace your deteriorated tags with these new reproductions. Available for 6 volt (Black) and 12 volt (Red) systems. Includes two rivets for installation. Number stamping process is available upon request.

GTB35	Black 6 Volt Generator & Starter Tag	1937-52 All, 1953 40 Series	9.50
GTR53	Red 12 Volt Generator & Starter Tag	1953 exc. 40 Series, 1954-62 All	9.50



GTB35
Fusick



GTR53
Fusick

1937-60 Fuse Packages: The fuses listed are sold in packages of 5 at 5.50 per package.

AGA-1	1 Amp Fuse	5.50	AGC-20	20 Amp Fuse	5.50	AGA-2	2 Amp Fuse	5.50
AGA-3	3 Amp Fuse	5.50	AGC-25	25 Amp	5.50	SFE-4	4 Amp Fuse	5.50
AGA-5	5 Amp Fuse	5.50	AGC-30	30 Amp Fuse	5.50	SFE-9	9 Amp Fuse	5.50
AGC-2	2 Amp Fuse	5.50	AGW-4	4 Amp Fuse	5.50	SFE-14	14 Amp Fuse	5.50
AGC-15	15 Amp Fuse	5.50	SFE-7 1/2	7 1/2 Amp Fuse	5.50	SFE-20	20 Amp Fuse	5.50

1953-60 Buick Horn Restoration and Recalibration Service: Restoration service available for 1953-60 Buick original 12 volt High and Low Note Horn Assemblies. No service available for 6 volt horns.

Restored horn assemblies include the center attaching and mounting bracket. Rebuilt units sent out in advance of originals will be charged a **250.00 core charge**, Returned cores need to be complete with bracket and not have any broken castings or excessive pitting in order for a full core refund to be issued.

H536HL	High-Low Horn Assembly	1953 50-70 Series, 1954-55 All	379.00 pr.
H560HLB	High-Low Horn Assembly	1956 All	379.00 pr.
H570HLB	High-Low Horn Assembly	1957 All	379.00 pr.
H580HLB	High-Low Horn Assembly	1958 All	379.00 pr.
H590HLB	High-Low Horn Assembly	1959 All	379.00 pr.
H600HLB	High-Low Horn Assembly	1960 All	379.00 pr.



1954-62 Power Options Relay: New electrical relay used for all power options on 1954-62 Buick models.

1116895	Power Options Relay	1954 All models, 1955-57 All except Special 2 Dr Sedan, 1961-62 Special, 1962 LeSabre, Invicta & Electra	95.00
----------------	---------------------	--	-------

1116895
Fusick



Ignition Ballast Resistor: Used on all 1954-59 Buicks.

1957154	Ignition Ballast Resistor	1954-59 All	43.50
----------------	---------------------------	-------------	-------

1957154



40 Amp Circuit Breaker: Power window and power seat control 40 Amp Circuit Breaker for All 1970 Buick Convertibles except Electra models.

4849847	Power Options Circuit Breaker		32.00
----------------	-------------------------------	--	-------



4849847

Oil Pressure and Temperature Sending Units:

TS15	Temperature Sending Unit	1960-63 exc. Special, 1964-68 400-401-425-430 V8	45.00
PS12	Oil Pressure Sending Unit	1960-66 exc. Special	27.50
PSB12	Oil Sending Unit Rubber Boot	1960-66 exc. Special	6.50



Wire Harness Straps: Metal snap-in straps secure wiring harness to inner fender wells. Check your car for quantity and style needed.

WHF03	Harness Strap	1957-60	5.50 ea.
WHF04	Harness Strap	1957-60	5.50 ea.
WHF04A	Harness Strap	1957-60	5.50 ea.



Headlight Bucket Rubber Wiring Grommet: Used on 1949-57 models where wiring passes through the back of the headlight bucket. Fits 7/8" hole.

LG507	Headlight Wiring Grommet	1949-57 Buick	8.50 ea.
--------------	--------------------------	---------------	----------



Headlight Terminal Junction Boards: Small board attaches to top of radiator support providing a connection point between headlight bucket wires and main wiring harness.

1314627	Terminal Board, 8 connectors	1940-51 All	24.50 ea.
1998763	Terminal Board, 4 connectors	1952-55 All	39.00 ea.



Battery Cables and Ground Straps:


G9	Negative Ground Strap	1936-37 All, 1950-51 Special & Super, 1953 Special	47.50
31005	Negative Battery Cable	1954-56 All, 1958-60 All, 1962 Electra, Invicta, LeSabre	49.50
31020	Negative Battery Cable	1957 All models	49.50



HD53B



HD557B



HD602B



31005

Battery Hold Downs:

HD53B	Battery Hold Down Cover	1953 All V8	65.00
HD557B	Battery Hold Down	1955-57 All	51.50
HD602B	Battery Hold Down	1960-62 All exc. Special	34.50
HD635B	Battery Hold Down	1963 All, 1963-65 Riviera	28.50
HD657B	Battery Hold Down	1965-66 full size	27.50
HD667BR	Battery Hold Down	1966-67 Riviera	26.50
HD670B	Battery Hold Down	1967 full size, 1968-70 Riviera	27.50
BHC54	Hold Down Corner Cushions	1953-58 All	7.00 ea.
BK393	Hold Down Bolt Kit (includes grommets)	1939-53 straight 8	14.50 kit
BK579	Hold Down Bolt Kit	1954-58 All	17.50 kit
HDB005	Hold Down Bolt	1965-67 All, 1968-70 Riviera	11.00 ea.



BHC54

Fusick



HDB005

Fusick

Positive Battery Cable Rubber

Boot: Rubber boot used from 1937-60 to protect the positive battery cable where it attaches to the battery.

BCC36 Battery Cable Boot 12.50



Fusick

Starter Cable Rubber Boot:

Used on 1932-66 All models. Rubber boot protects end of the battery cable at starter.


SCC46 Starter Cable Boot 12.50



Fusick

Rubber Body Mount Pads and Insulators:

BM409B	Body Mount Insulator to Frame	2" square, 1/2" thick, 1940-49 up to 20 per car	15.00 ea.
BM518	Body Mount Assembly	2" square with steel collar, washer and plate 1941-58 All, up to 20 per car	17.50 ea.



BM409B



Fusick

BM518

Interior and Exterior Light Bulbs

6 Volt Bulbs: 1940-52 & 53 Buick Special models were a 6 volt system. Check your existing bulbs for correct applications and numbers.

6006	Headlight Sealbeam Bulb	26.50 ea.
63	Park & License Light Bulb	5.00 ea.
1154	Park & Tail Light Bulb	5.00 ea.
55	Dash Instruments & Courtesy Light Bulb	4.00 ea.
51	Dash Indicator Light Bulb	4.00 ea.
82	Interior Dome Light Bulb	5.00 ea.



12 Volt Bulbs: 1953 (exc. Special) and newer years use a 12 volt system, check existing bulbs for correct numbers and application needed.

53	Dash Instrument & Indicator Light Bulb	1954-56, 1961	4.00 ea.
57	Dash Instrument Light Bulb	1953-60	4.00 ea.
67	License Light Bulb	1953-63	4.00 ea.
89	Interior Courtesy Light Bulb	1954-75	4.00 ea.
90	Interior Dome Light Bulb	1954-67	4.00 ea.
1004	Interior Dome & Courtesy Light Bulb	1954-75	4.00 ea.
1073	Tail Light Bulb	1957	5.00 ea.
1157	Park/Turn Signal Light, Stop/Tail/Turn Light Bulb	1964-75	5.00 ea.
1157NA	Park/Turn Signal Bulb (Amber)	1965-75	5.00 ea.
6014	Headlight Sealbeam Bulb	1953 Super & Roadmaster, 1954-57 All	19.75 ea.
4000	Headlight Sealbeam Bulb (low)	1958-75	18.50 ea.
4001	Headlight Sealbeam Bulb (high)	1958-75	18.50 ea.
97	License Light Bulb	1964-73	4.00 ea.
161	Dash Instrument Bulb	1964-74	3.00 ea.
168	Dash Instrument Bulb	1971-75	3.00 ea.
194	Dash Instrument Bulb	1961-75	3.00 ea.
194	Side Marker Light Bulbs	1968-75	3.00 ea.
211	Interior Dome Light Bulb	1967-75	4.00 ea.
212	Interior Dome Light & Courtesy Light Bulb	1970-75	4.00 ea.
1156	Back Up Light Bulb	1964-75	4.00 ea.

Speedometer Cables:

Complete Speedometer Cable assembly with correct braided casing and threaded end fittings.

CC1	Speedometer Cable and Casing (69 1/2")	1937-41 40 Series, 1937-40 60 Series, 1938 80 & 90 Series, 1940 70 Series, 1940-41 50 Series, 1942-49 40-50-70 Series, 1950-53 40 Series, 1950-52 50 & 70 Series, 1953 50 Series with standard trans., 1954 100 Series, 1954-55 40 & 60 Series A/T, 1966 & 68 Wildcat with 3-speed Manual Trans.	55.00
CC2	Speedometer Cable and Casing (74")	1954-55 50 Series with M/T, 1956-58 all series	55.00
CC7	Speedometer Cable and Casing (59 1/2")	1955 40-60 Series with Manual Trans 1961 with Manual Trans, 1962 All Series, 1963-64 All exc. Speed Control, 1966 All A/T exc. Riviera or Speed Control, 1966 All 4-speed M/T, 1967 All with TH400 A/T, 1968 All exc. Speed Control	55.00



Wheel Bearings and Grease Seals:

909001	Front Outer Wheel Bearing	1937-39 40-60 Series, 1940 40-50-60-70 Series	59.50 ea.
909025	Front Outer Wheel Bearing	1941-42 exc. 80-90 Series, 1946-57 All Series	59.50 ea.
909065	Front Outer Wheel Bearing	1958 All	66.50 ea.
909073	Front Outer Wheel Bearing	1959-60 All	59.50 ea.
S3	Front Outer Wheel Bearing	1961-70 All	33.50 ea.
909052	Front Inner Wheel Bearing	1937-39 40-60 Series, 1940 40-50-60-70 Series	89.00 ea.
909062	Front Inner Wheel Bearing	1941-42 exc. 80-90 Series 1946-56 All Series	95.00 ea.
909072	Front Inner Wheel Bearing	1957 All	66.50 ea.
909066	Front Inner Wheel Bearing	1958-60 All	95.00 ea.
S5	Front Inner Wheel Bearing	1961-70 All	33.50 ea.
20118	Front Wheel Grease Seal	1941-56 All	29.50 ea.
20115	Front Wheel Grease Seal	1957-60 All	24.50 ea.
19852	Front Wheel Grease Seal	1961-70 All	24.50 ea.
C1502	Rear Axle Wheel Bearing	1937-55 All	79.50 ea.
IR1502	Inner Bearing Race (used with C1502 bearing)	1937-55 All	14.50 ea.
RW509ER	Rear Axle Wheel Bearing	1956-62 All exc. 1961-62 Special	99.50 ea.
88128R	Rear Axle Wheel Bearing	1963-64 All, 1965-67 Wildcat, Electra & Riviera	74.50 ea.
88131R	Rear Axle Wheel Bearing	1968-70 Wildcat, Electra & Riviera except Estate Wagon	79.50 ea.
18704	Outer Axle Oil Seal	1937-39 40-60 series, 1940-55 All	24.50 ea.
21070	Axle Oil Seal	1956-60 All	24.50 ea.
15592	Axle Oil Seal	1961-62 All exc. Special	24.50 ea.
51098	Axle Oil Seal	1963-70 Wildcat, Electra & Riviera	24.50 ea.

Front Wheel Dust Caps: Steel Dust Caps for front wheels fits 1934-36 Special, 1937-40 Special & Century and 1940 Super & Roadmaster

405999 Front Wheel Dust Cap 1934-40 All 21.00 ea.

Dust Cap Static Collectors: Brass coils that install inside the front wheel dust cap to cut down on radio interference.

WBSC412	Static Collector	1940-60 All	25.00 ea.
WBSC612	Static Collector	1961-66 All	25.00 ea.

Differential Housing Cover Gasket:

11064E	Differential Cover Gasket	1934-55 All exc. 1936-42 Limited	18.50
---------------	---------------------------	----------------------------------	-------

Differential Carrier Gaskets:

11028E	Differential Carrier Gasket	1937-55 All exc. 1936-42 Limited	18.50
13059E	Differential Carrier Gasket	1956-65 All exc. 1961-65 Special	18.50

Differential Vent Valve and Aluminum Posi Tag: Plastic valve used to vent the rear differential. Aluminum tag for cars equipped with a posi rear end has 'Use limited slip diff. lube only' in raised letters. Attaches to differential using one of the cover bolts.

DIF64	Differential Vent Valve	1965-77 All	8.50
DT642	Differential Posi Tag	1964-75 with posi	6.00

**909062****IR1502****909073****88128R****WBSC412****WBSC612**

Power Brake Unit Rebuilding Service: Rebuilt Power Brake Booster/Master Cylinder combination for 1955-64 Bendix and Moraine systems. Buick used two suppliers of brake units from 1955-64. 1957-59 Bendix master cylinders are cast aluminum while 1955-59 Moraine master cylinders are cast iron. Easiest method to distinguish 1960-64 Bendix unit is the back plate to booster canister is attached with screws. Moraine back plate to booster canister is a twist on/off installation. Please check your brake unit for Bendix or Moraine before placing an order. Please be aware that 1956 Buick Power Brake Units have an external in-line check valve that must be included with the unit for proper rebuilding process. **Core charge for Power Brake Units sent in advance is \$325.00.** Special note: We do not have a rebuilding service for 1953-54 Buicks equipped with Kelsey Hayes Power Brake Units. Sources suggest using a 1955 Buick Power Brake Unit in place of Kelsey Hayes assemblies. Accordingly, they will attach and function correctly.

PBB570B	Rebuilt Bendix Power Brake Unit	1957 All	695.00
PBB580B	Rebuilt Bendix Power Brake Unit	1958 All	695.00
PBM550B	Rebuilt Moraine Power Brake Unit	1955 All	695.00
PBM560B	Rebuilt Moraine Power Brake Unit	1956 All	959.00
PBM570B	Rebuilt Moraine Power Brake Unit	1957 All	749.00
PBM580B	Rebuilt Moraine Power Brake Unit	1958 All	749.00
PBM590B	Rebuilt Moraine Power Brake Unit	1959 All	749.00
PBM601B	Rebuilt Moraine Power Brake Unit	1960-61 All	749.00
PBM620B	Rebuilt Moraine Power Brake Unit	1962 All	649.00
PBM630B	Rebuilt Moraine Power Brake Unit	1963 All	649.00
PBM640B	Rebuilt Moraine Power Brake Unit	1964 All	649.00



1958 Moraine



1956 Moraine



1960-61
Moraine

Please Read: A newly rebuilt Power Brake Unit will not always guarantee a solution to your problem. Other areas to check are a lack of vacuum caused by a bad check valve, or a pin hole in the vacuum reserve tank. Air in the brake lines, deteriorated vacuum hoses or poorly functioning wheel cylinders are areas of concern as well. **NEVER use silicone brake fluid.**

Power Brake Master Cylinder Rebuild Kits: Rebuild kits are now available for 1955-59 Delco Moraine Power Brake units and 1956-59 Bendix Power Brake Units, commonly called Treadle-Vac. Kits include all seals and gaskets needed to rebuild your master cylinder. Rubber push rod boot, leather booster seal and brake plunger rod are sold separately.

MPBK55B	Moraine Power Brake Master Cylinder Kit	1955 All	99.00 kit
BPBK539	Bendix Power Brake Master Cylinder Kit	1956 All	89.00 kit
MPBK56B	Moraine Power Brake Master Cylinder Kit	1956 All	99.00 kit
MPBK57B	Moraine Power Brake Master Cylinder Kit	1957 All	99.00 kit
BPBK578B	Bendix Power Brake Master Cylinder Kit	1957-58 All	89.00 kit
MPBK58B	Moraine Power Brake Master Cylinder Kit	1958 All	99.00 kit
MPBK59B	Moraine Power Brake Master Cylinder Kit	1959 All	99.00 kit
BPBK59B	Bendix Power Brake Master Cylinder Kit	1959 All	89.00 kit
BPRB539	Brake Booster Rubber Push Rod Boot	1956-59 All	28.50
PBK376004	Power Brake Booster Leather Seal	1955-59 All	45.00
BBP539	Bendix Power Brake Plunger Rod	1957-59 Bendix	52.50



BPBK539



BPRB539

BBP539

Power Brake Booster Rebuild Kits: Rebuild kits available for the Power Brake Boosters listed below. Kits only service the booster canisters, not the master cylinder . Check our website for complete contents.

62-603	Moraine Booster Kit	1955 Buick All models	259.00
62-604	Moraine Booster Kit	1956 Buick All models	259.00
62-533	Moraine Booster Kit	1960 Electra, Invicta & LeSabre	259.00
62-535	Bendix Booster Kit	1960-61 Electra, Invicta, LeSabre & Special booster canister uses 8 screws	259.00
62-631	Moraine Booster Kit	1961-62 Electra, Invicta, LeSabre & Special for Delco Moraine units with air cleaner tube	259.00
62-655	Moraine Booster Kit	1963-66 Electra, Invicta, LeSabre, Special, Wildcat & Riviera for Delco Moraine units with a 5" deep canister	259.00
62-280	Moraine Booster Kit	1964-66 Electra, Invicta, LeSabre, Special, Wildcat & Riviera for Delco Moraine units with 9" diameter canister	259.00
62-463	Bendix Booster Kit	1964-66 Electra, Invicta, LeSabre, Special, Wildcat & Riviera for Bendix units with 9" diameter canister	259.00
62-281	Moraine Booster Kit	1967-69 Electra, Invicta, LeSabre, Special, Wildcat & Riviera for Delco Moraine units with 11" diameter canister	259.00




New Power Brake Master Cylinders: Reproduction replacement master cylinders for following applications. May differ in appearance from originals.

35027	Power Brake Master Cylinder	1960-61 LeSabre, Invicta & Electra	159.00
36115	Power Brake Master Cylinder	1962 LeSabre, Invicta & Electra	159.00
36134	Power Brake Master Cylinder	1963-66 LeSabre, Wildcat & Electra 1965 Riviera	139.00
36236	Power Brake Master Cylinder	1967-70 LeSabre, Wildcat, Electra & Riviera with Bendix power drum brakes	119.00
36234	Power Brake Master Cylinder	1967-70 LeSabre, Wildcat, Electra & Riviera with Moraine power drum brakes	159.00
36306	Power Brake Master Cylinder	1971-76 LeSabre, Centurion, Electra, Estate Wagon & Riviera with Moraine power disc brakes 1973-76 LeSabre, Centurion, Electra, Estate Wagon & Riviera with Bendix power disc brakes	119.00



Power Brake System Vacuum Hose and Clamps:

H1451	Brake Vacuum Hose	4.00 per foot
H6	Vacuum Hose Clamp	5.50 ea.



MANUAL Brake Master Cylinders: Master Cylinders listed are new reproduction units. Rebuilt units require your original core in advance.

4647	New Master Cylinder 1939-40 exc. Limited, 1941-49 All	209.00
10032	New Master Cylinder 1950-52 50-70 series, 1950-53 40 series	209.00
MC-19896	Rebuilt Master Cylinder 1954-55 All without power brakes	399.00
MC-22819	Rebuilt Master Cylinder 1956 All without power brakes	699.00



MANUAL Brake Master Cylinder Rebuild Kit: Includes necessary rubber seals, spring, valve, plunger and clips to rebuild your manual brake master cylinder.

3626	Master Cylinder Kit 1937-40 exc. Limited,	35.00
	1941-55 All with manual brakes	



Brake Stoplight Switches:

SLS24	Stoplight Switch	1937-40 All	33.50
SLS27	Stoplight Switch	1941-55 All	29.50
SLS30	Stoplight Switch	1956-63 All	26.50
SLS66	Stoplight Switch	1964-70 All	23.50
9795358	Park Brake Warning Light Switch	19.50	
	1969-72 LeSabre, Wildcat, Electra, Centurion & Riviera		



Drum Brake Shoe Sets: One set of brake shoes will service either both front drums or both rear drums.

BS29	Front Brake Shoe Set	1937-51 Special, 1940-51 Super (1-3/4" width)	75.00 set
340PG	Front Brake Shoe Set	1937-39 Century	75.00 set
197PG	Front Brake Shoe Set	1940-42 Century, 1940-51 Roadmaster, 1952-57 Special & Super, late 1952-57 Roadmaster, 1953-57 Century, 1961-62 LeSabre, Invicta, Electra, 1963-70 LeSabre, Invicta, Wildcat, Electra, Riviera	75.00 set
BS65	Front Brake Shoe Set	early 1952 Roadmaster, 1958-60 All models	75.00 set
BS29	Rear Brake Shoe Set	1937-55 Special, 1940-52 Super (exc. 1952 wagon)	75.00 set
197PG	Rear Brake Shoe Set	1940-42 Century, 1940-57 Roadmaster, 1952 Special & Super Wagon, 1953-57 Super, 1954-57 Century, 1956-57 Special, 1958-60 All models	75.00 set
340PG	Rear Brake Shoe Set	1937-39 Century, 1961-70 LeSabre, Invicta, Wildcat, Electra, Riviera	75.00 set

Drum Brake Shoe Hold Down Kits and Springs: Kits include brake return springs and brake shoe hold-down hardware. One kit services one axle.


BHK1	Front Brake Hold Down Kit	1937-42 Century, 1937-51 Special 1940-51 Super and Roadmaster	27.50
BHK3	Front Brake Hold Down Kit	1952-58 Roadmaster	27.50
BHK2	Front Brake Hold Down Kit	1952-57 Special and Super, 1954-57 Century, 1958 All exc. Roadmaster, 1959-60 All models	27.50
BHK4	Front Brake Hold Down Kit	1961-62 LeSabre, Invicta & Electra	27.50
BHK6	Front Brake Hold Down Kit	1963-70 LeSabre, Invicta, Wildcat, Electra and Riviera with front drums	27.50
BHK1	Rear Brake Hold Down Kit	1937-42 Century, 1937-55 Special, 1940-51 Roadmaster, 1940-52 Super	27.50
BHK2	Rear Brake Hold Down Kit	1952-57 Roadmaster, 1953-57 Super, 1954-57 Century, 1956-57 Special 1958-60 All models	27.50
BHK5	Rear Brake Hold Down Kit	1963-70 LeSabre, Invicta, Wildcat, Electra and Riviera	27.50

Drum Brake Inspection Hole Covers: Small metal cover snaps into inspection hole on brake drums. Sold in a set of four.

C3460	Brake Inspection Hole Covers	1937-60 All	11.00 set of 4
--------------	------------------------------	-------------	----------------

BHK2

BHS562



Brake Adjuster Screw Assembly:

BHS562	Front or Rear Brake Adjuster Screw	1956-62 All models exc. 61-62 Special & Skylark	21.50 ea.
80551	Left Front or Rear Brake Adjuster Screw	1963-70 LeSabre, Invicta, Wildcat, Electra & Riviera	18.50 ea.
80552	Right Front or Rear Brake Adjuster Screw	1963-70 LeSabre, Invicta, Wildcat, Electra & Riviera	18.50 ea.

Wheel Cylinder Rebuild Kits: Contains new spring and rubber seals and cups.

19386	Front Wheel Cylinder Kit	1937-41 Special & Century, 1940-41 Super, Roadmaster & Limited 1942 Limited	14.50 ea.
13620	Front Wheel Cylinder Kit	1942-57 All exc. 1942 Limited 1957-66 All, 1967 Riviera with 1-1/8" bore	14.50 ea.
WK237	Front Wheel Cylinder Kit	1967-70 LeSabre, Wildcat, Electra, & Riviera, 1967 Riviera with 1-13/16" bore	14.50 ea.
3600	Rear Wheel Cylinder Kit	1938-39 Special & Century, 1940 All except Limited 1941-49 All, 1950 Special with 3/8" lines	14.50 ea.
19325	Rear Wheel Cylinder Kit	1950 Special with 5/16" lines, 1951-70 All models	14.50 ea.



Front Wheel Cylinders:

6090	Left Front Wheel Cylinder	1937-41 Special & Century, 1940-41 Super, Roadmaster, Limited 1942 Limited	55.00
6091	Right Front Wheel Cylinder	1937-41 Special & Century, 1940-41 Super, Roadmaster, Limited 1942 Limited	55.00
7536	Left Front Wheel Cylinder	1942-57 All except 1942 Limited	55.00
7537	Right Front Wheel Cylinder	1942-57 All except 1942 Limited	55.00
14493	Left Front Wheel Cylinder	1958-60 All models	55.00
14494	Right Front Wheel Cylinder	1958-60 All models	55.00
32071	Left Front Wheel Cylinder	1961 with horizontal mounting bolts	55.00
32072	Right Front Wheel Cylinder	1961 with horizontal mounting bolts	55.00
37017	Left Front Wheel Cylinder	1961 with diagonal pattern bolts, 1962-66 All	55.00
37018	Right Front Wheel Cylinder	1961 with diagonal pattern bolts, 1962-66 All	55.00
37097	Left Front Wheel Cylinder	1967-68 LeSabre, Wildcat & Electra	55.00
37098	Right Front Wheel Cylinder	1967-68 LeSabre, Wildcat & Electra	55.00



Rear Wheel Cylinders:

6092	Rear Wheel Cylinder, both sides	1938-39 Special & Century, 1940-41 All, 1942 Limited	55.00 ea.
7563	Left Rear Wheel Cylinder	1942-49 All, 1950 Special with 3/8" lines	55.00
7564	Right Rear Wheel Cylinder	1942-49 All, 1950 Special with 3/8" lines	55.00
13387	Left Rear Wheel Cylinder	1950 Special with 5/16" lines, 1951-70 All except 1967-69 Riviera	55.00
13388	Right Rear Wheel Cylinder	1950 Special with 5/16" lines, 1951-70 All except 1967-69 Riviera	55.00
37017	Left Rear Wheel Cylinder	1967-69 Riviera with 1-1/8" cylinder bore	55.00
37018	Right Rear Wheel Cylinder	1967-69 Riviera with 1-1/8" cylinder bore	55.00



Front Brake Hoses:

4497	Front Brake Hose	1936 All, 1937-40 80-90 Series	46.00 ea.
7600	Front Brake Hose	1937-38 40-60 Series	46.00 ea.
5433	Front Brake Hose	1939 Special & Century, 1940-49 All, 1950 Special with 3/8" lines	39.00 ea.
13589	Front Brake Hose	1950 Special with 5/16" lines, 1950 Super & Roadmaster 1951-56 All exc. 1953 Conv.	39.00 ea.
35009	Front Brake Hose	1957-61 All, 1965 Riviera	46.00 ea.
36611	Front Brake Hose	1962-64 LeSabre, Invicta, Wildcat & Electra	39.00 ea.
36582	Front Brake Hose	1969-70 LeSabre, Wildcat & Electra 1967-70 Riviera with front disc 1969-70 Riviera with front drum	39.00 ea.



Rear Brake Hoses:

26960	Rear Brake Hose	1937-39 Special & Century, 1941 Special, Super & Roadmaster	46.00
20996	Rear Brake Hose	1940 All, 1941-42 Century, 1942-49 Special Super & Roadmaster, 1950 Special with 3/8" lines	46.00
10595	Rear Brake Hose	1950 Special with 5/16" lines, 1951-55 Special 1950-55 Super & Roadmaster exc. 1953 Conv. & Wagon	46.00
23057	Rear Brake Hose	1956-58 All models	46.00
8553	Rear Brake Hose	1959-60 All models	46.00
36005	Rear Brake Hose	1962-66 LeSabre, Invicta, Wildcat & Electra 1965-66 Riviera	46.00
36692	Rear Brake Hose	1968 LeSabre, Wildcat & Electra	46.00



Parking Brake/Emergency Brake Cables: All brake cables are quality manufactured in USA using correct connectors and coil wrapped sheathing for an original fit and appearance.

Front Parking/Emergency Brake Cables:

1660B	Front Parking Brake Cable	1953 All exc. Super & Roadmaster 4-Door Sedan	85.00
1907B	Front Parking Brake Cable	1954-56 Special, Century & Skylark	85.00
1908B	Front Parking Brake Cable	1954-55 Super & Roadmaster	85.00
1955B	Front Parking Brake Cable	1956 Super & Roadmaster	85.00
1974B	Front Parking Brake Cable	1957-58 Special & Century with Dynaflow trans	85.00
1975B	Front Parking Brake Cable	1957-58 Super, Roadmaster & Limited	85.00
2062B	Front Parking Brake Cable	1959 LeSabre & Invicta	85.00
2063B	Front Parking Brake Cable	1959 Electra	85.00
2098B	Front Parking Brake Cable	1960 LeSabre & Invicta	85.00
2099B	Front Parking Brake Cable	1960 Electra	85.00
2149B	Front Parking Brake Cable	1961 LeSabre, Invicta & Electra	85.00
2238B	Front Parking Brake Cable	1963 Riviera	85.00
2331B	Front Parking Brake Cable	1964-65 Riviera	85.00
2630B	Front Parking Brake Cable	1968 LeSabre, Wildcat & Electra with auto trans	85.00

Intermediate Parking/Emergency Brake Cables:

2461B	Intermediate Parking Brake Cable	1963-64 Riviera	49.00
2384B	Intermediate Parking Brake Cable	1965-68 LeSabre, Wildcat & Electra with auto trans	49.00

Rear Parking/Emergency Brake Cables:

1696B	Rear Parking Brake Cable	1953 Special	89.00
1887B	Rear Parking Brake Cable	1954-56 Special, Century & Skylark	89.00
1888B	Rear Parking Brake Cable	1954-56 Super & Roadmaster	89.00
1973B	Rear Parking Brake Cable	1957-58 Special, Super, Roadmaster & Limited 1957-58 Century with Dynaflow Transmission	89.00
2064B	Rear Parking Brake Cable	1959 LeSabre, Invicta & Electra	89.00
2072B	Rear Parking Brake Cable	1960 LeSabre, Invicta & Electra	89.00
2150B	Rear Parking Brake Cable	1961-63 Electra (two per car)	79.50 ea.
2239B	Rear Parking Brake Cable	1963 Riviera	89.00
2327B	Rear Parking Brake Cable	1964 LeSabre & Wildcat (two per car)	79.50 ea.
2329B	Rear Parking Brake Cable	1964-65 Riviera	89.00
2328B	Rear Parking Brake Cable	1964 Electra (two per car)	79.50 ea.

Front and Rear Knee Action Shocks: Rebuilding service on the Knee Action Shocks for all 1937-53 Buicks in front and 1937-55 Buicks in rear. Please call ahead for availability on rebuilt shocks.

Core charge on shocks sent out in advance is 150.00 per shock, shocks that are frozen or have excessive side to side play are not rebuildable.

1947A/B	Front Knee Action Shocks	1937-38 40-60 Series	579.00 pr.
1948A	Front Knee Action Shocks	1939 40-60 Series, 1940 40-50-60-70 Series 1941-42 90 Series, 1942-53 All	579.00 pr.
1713A/B	Rear Knee Action Shocks	1937 40-60 Series	429.00 pr.
2103AB/EF	Rear Knee Action Shocks	1939 40-60 Series (specify either A/B or E/F)	429.00 pr.
2105A/B	Rear Knee Action Shocks	1940 40-50-60-70 Series	429.00 pr.
2105C/D	Rear Knee Action Shocks	1941 exc. 90 Series, 1942-53 All	429.00 pr.
2105X/Y	Rear Knee Action Shocks	1954-55 All Series	429.00 pr.



1948A



2105C/D



RSL39B



RSL413B

Rear Shock Link Kits:

RSL39B	Rear Shock Links	1939 All, 1940 80-90 Series	60.00 pr.
RSL40B	Rear Shock Links	1940 40-50-60-70 Series	60.00 pr.
RSL413B	Rear Shock Links	1941-50 All, 1951-53 50-70 Series 1954-55 50-70 Series	55.00 pr.
RSL515B	Rear Shock Links	1951-53 40 Series 1954-55 40-60-100 Series	55.00 pr.



50140G



50155G



50093G



50135G



50211G

Tubular Shock Absorbers:

Custom made gas charged tubular shock absorbers for all 1954-70 Buicks. Designed as exact mechanical replacements for discontinued original shock absorbers. Shocks are sold in pairs.

50140G	Front Shock Absorber	1957 All	149.00 pr.
50155G	Front Shock Absorber	1958 exc. Air Ride	149.00 pr.
50093G	Rear Shock Absorber	1959-60 exc. Air Ride	149.00 pr.
50135G	Rear Shock Absorber	1961-64 All, 1963-65 Riviera	149.00 pr.
50211G	Rear Shock Absorber	1966-70 Riviera	149.00 pr.

1937-76 Buick Coil Springs: We supply new coil springs for most 1937-76 Buick models. Front and Rear Coil Springs were used on all 1937-76 models. Since there are a large amount of coil spring applications, we do not stock the springs. All spring orders will be filled on a special order basis. You must provide a complete description of your car when ordering (year, model, engine size, air conditioning, sedan, hardtop, or convertible). Please allow 2-3 weeks for delivery time. No Rear Coil Springs are available at this time for 1961-64 Buicks.

Please note: Special order springs can not be shipped outside the US

FCS496B	Front Coil Springs	1937-1976 All except Convertible	259.00 pr.
FCS496CB	Front Coil Springs	1937-1976 All Convertible	259.00 pr.
RCS496B	Rear Coil Springs	1937-60, 1965-76 All except Convertible	259.00 pr.
RCS496CB	Rear Coil Springs	1937-60, 1965-76 All Convertible	259.00 pr.



1939-60 Front Coil Spring Insulators: Flat rubber pads used to insulate the front coil springs on all 1939-60 Buick models.

B35835	Front Coil Insulators	1939-53 All	39.00 pr.
SI381B	Front Coil Insulators	1954-60 All	24.50 pr.

1938-58 Rear Coil Spring Clamp Insulator: Molded flat rubber insulator for the rear coil spring clamp used on 1938-57 all models and 1958 models except with air ride.

B30455	Rear coil Spring Clamp Insulator	1938-58 All	21.50 pr.
SI380B	Rear Coil Spring Insulator	1938-60 All	39.00 pr.

Idler Arm Bracket and Bushing:

K75	Idler Arm Bracket and Bushing	1954-56 All	127.00
18531	Idler Arm Bracket and Bushing	1957-60 All	149.00

Outer Tie Rod Ends and Adjusting Sleeves:

ES140R	Outer Tie Rod	1949-52 40-50 series 1953-58 All	53.50 ea.
ES500S	Tie Rod Adjusting Sleeve	1950-58 All, 1962-68 All	33.50 ea.
TRE302RL	Outer Tie Rod	1959-60 All, 1961 w/ Saginaw	109.00 ea.
TRE638S	Tie Rod Adjusting Sleeve	1959-61 All	21.00 ea.
6160	Tie Rod End Rubber Boot	1939-60 All	5.00 ea.

Upper & Lower Control Arm Shafts: New Control Arm Shaft Packages contain bushings, rubber seals, grease fittings and shaft.

SK13090A	Upper Control Arm Shaft	1954-56 All	109.00 ea.
SK13117A	Upper Control Arm Shaft	1957-60 All	109.00 ea.
SK13027B	Lower Control Arm Shaft	1940 All exc 80-90 series 1941-42 All series	269.00 ea.
SK13002A	Lower Control Arm Shaft	1937-38 40-60 series 1946-57 All	109.00 ea.
SK13130A	Lower Control Arm Shaft	1958-60 All	119.00 ea.
6167	Lower Control Shaft Seals	1937-60 All	4.00 ea.

King Pin Kit: Contains all necessary parts to replace worn original king pins.

KPK89	King Pin Kit	1934-36 40 series, 1937-56 exc. 80-90 series	119.00 kit
--------------	--------------	---	------------

Upper and Lower Pivot Pin Kits:

K60	Upper Outer pivot Pin Kit	1937-39 40-60 series, 1940-56 All	79.50 ea.
K50	Lower Outer Pivot Pin Kit	1941-50 40-50 ser., 1951-56 All	69.00 ea.
K102	Lower Outer Pivot Pin Kit	1937-39 40-60 series, 1940 exc. 80-90 series, 1941 60-70-80-90 series	65.00 ea.
6166	Lower Pivot Pin Seals	1937-60 All	4.00 ea.
6178	Upper Pivot Pin Seals	1937-60 All	4.00 ea.

Driveshaft U-Joints:

534G	U-Joint, Saginaw- Inner lock rings	1957-60 All rear, 1961-75 All positions	59.50 ea.
354	U-Joint, Spicer- Outer lock rings	1957-60 All rear, 1961-62 All front and 2 center locations	59.50 ea.
355	U-Joint, Spicer-Outer lock rings	1961-62 All rear	54.50



1957 Buick Upper & Lower Ball Joint Rebuilding Service: Rebuilding service for 1957 Buick ball joints. **Core charge of 195.00 per ball joint.** Please call ahead for availability, originals may need to be sent in advance for rebuilding service.

10291	Left Lower Ball Joint	1957 only	495.00
10290	Right Lower Ball Joint	1957 only	495.00
10289	Left Upper Ball Joint	1957 only	395.00
10288	Right Upper Ball Joint	1957 only	395.00



Upper & Lower Ball Joints: New Upper and Lower Ball Joints available for all 1958-70 Buick models.

BJ10115	Upper Ball Joint	1958-60 All	159.00 ea.
BJ10139	Upper Ball Joint	1961-62 All	179.00 ea.
BJ10202	Upper Ball Joint	1963-70 All	99.00 ea.
BJ10116	Lower Ball Joint	1958-60 All	159.00 ea.
BJ10140	Lower Ball Joint	1961-62 All	179.00 ea.
BJ10198	Lower Ball Joint	1963-70 All	89.00 ea.



BJ10115

BJ10116



FB526B

41143

Upper and Lower Control Arm Rubber Bumpers:

FB125B	Lower Control Arm Bumper	1937-39 40-60 series 1940 40-50-60-70 exc 50-70 Conv.	83.00 pr.
411143	Lower Control Arm Bumper	1940 50-70 series Conv, 1941-56 All	27.50 ea.
FB526B	Lower Control Arm Bumper	1957-60 All	99.00 pr.
1298323	Upper Control Arm Bumper	1937-56 All	21.00 ea.
FB573B	Upper Control Arm Bumper	1957-60 All	14.50 ea.



FB573B

Upper and Lower Control Arm Bushings:

BU12055	Lower Control Arm Bushings	1940-60 All	109.00 set of 4
BU12215	Lower Control Arm Bushings	1961-70 All	79.00 pair
BU12126	Upper Control Arm Bushings	1954-65 All	79.00 set of 4
BU12185	Upper Control Arm Bushings	1966-70 All	79.00 set of 4



BU12055

Rear Axle Rubber Bumpers:

AB371B	Rear Axle Bumpers	1941 50-60-70 series, 1942 40-60 series, 1946-48 40 series, 1949-57 All	199.00 pr.
AB638B	Rear Axle Bumpers	1958 All exc. Air Ride	199.00 pr.
AB388B	Rear Axle Radius Rod Bushings	1938-58 All	59.00 set of 4
SB560B	Rear Axle Strut Rod at Driveshaft Tube Bushings	1956-60 All series	32.00 pr.



BU12215

AB371B

AB638B

Stabilizer Bar End Link Kits: Complete Stabilizer Bar End Link Kits include threaded rods, rubber bushings, washers, spacers and bolts. Sold in pairs.

18001	Front Stabilizer Link Kit	1937-53 All	29.50 pr.
SK18027	Front Stabilizer Link Kit	1954-56 All	26.50 pr.
SK18038	Front Stabilizer Link Kit	1957-60 All	26.50 pr.
18001	Rear Stabilizer Link Kit	1940-41 All	29.50 pr.



18001

411392

Fusick

411142

K5227

Front Stabilizer Bar Rubber Bushings:

411392	Front Stabilizer Bar Bushings	1948-57 All	26.00 pr.
411142	Front Stabilizer Bar Brackets	1948-57 All	16.50 ea.
K5227	Front Stabilizer Bar Bushings	1958-60 All	23.50 pr.
K8204	Front Stabilizer Bar Bushings	1961-66 exc. Special	25.00 pr.

Windshield and Rear Window Channel, Door, Vent Window, Quarter Window and Roof Rail Weatherstrips

1937-49 Division Bar Gaskets and Pinchweld Seal: Used in combination with the Windshield Channels, Division Bar Gaskets seal the two pieces of glass in center of windshield. Pinchweld Seal installs around the perimeter of the windshield to secure reveal moldings. Sold in a 12' length..

PS418	Pinchweld Seal	1941-49 for windshield and rear window, as required	71.00
WR104A	Division Bar Gasket	1937-38 Special & Century	84.00
WP373	Division Bar Seal	1940 Super & Roadmaster, 1941-48 All, 1949 Special	47.00

1937-64 Rubber Windshield Channel:

WR105	Windshield Channel	1937-38 Special & Century convertible without reveal molding, use with WR104A Division Bar Gasket	147.00
WR104	Windshield Channel	1937-38 Special & Century closed models without reveal molding, use with WR104A Division Bar Gasket	176.00
WR175	Windshield Channel	1940-48 Super & Roadmaster 4-Dr sedan (models 51&71) 1940-42 Super & Roadmaster coupes (models 56, 56S, 76S) 1946-48 Super & Roadmaster Estate Wagons (models 59 & 79) use with PS418 pinchweld seal and WP373 Division Bar Seal	240.00
WR523B	Windshield Channel	1940-41 Super & Roadmaster convertible use with PS418 pinchweld seal and WP373 Division Bar Seal	237.00
WR113	Windshield Channel	1941-42 Special (41, 41SE, 46, 46S, 46SSE), 1941-42 Century and Limited (60 & 90 series), 1946-49 Special All models use with PS418 pinchweld seal and WP373 Division Bar Seal	188.00
WR112	Windshield Channel	1941-42 Special (44, 44C, 44S, 47 118" wheelbase) use with PS418 pinchweld seal and WP373 Division Bar Seal	130.00
WR113	Windshield Channel	1949 Special 2-Dr Sedanet & 4-Dr Sedans	188.00
WR490C	Windshield Channel	1949 Super & Roadmaster Convertible	508.00
WR120C	Windshield Channel	1950-51 Super 4-Dr Sedan (4569) & 2-Dr Sedanet 1950 Roadmaster 4-Dr Sedan (4769) 1950-53 Super & Roadmaster Estate Wagon	322.00
WR121C	Windshield Channel	1950-53 Super & Roadmaster Conv. & Riviera 2-Dr Htop	323.00
WR120	Windshield Channel	1951-53 Special 2 & 4-Dr Sedans	171.00
WR121	Windshield Channel	1951-53 Special Conv. & Riviera 2-Dr Htop	171.00
WR122	Windshield Channel	1954 All Special, Century & Skylark 1955-56 Special & Century Convertibles	216.00
WR122C	Windshield Channel	1954-55 Super & Roadmaster Conv. & Riviera 2-Dr Htop 1956 Super & Roadmaster Conv. & Riviera 2 & 4-Dr Htop	231.00
WR123	Windshield Channel	1955-56 Special & Century closed models including hardtops and wagons	236.00
WR124	Windshield Channel	1957-58 Special, Century, Super, Roadmaster & Limited Convertibles	240.00
WR125	Windshield Channel	1957-58 All closed models except Super, Roadmaster, & Limited 4-Dr Htops (4539, 4739, 4739X,-DX,-SX, 4839X)	233.00



Rubber Windshield Channel continued:

WR126	Windshield Channel	1959-60 All models	179.00
WR055	Windshield Channel	1961 LeSabre, Invicta & Electra closed models including Hardtops and Wagons 1962 LeSabre, Invicta & Electra closed models except 2-Dr Htop (4447, 4647, 4847) and Electra 225 4-Dr Htop (4 window)	194.00
WR858	Windshield Channel	1961-62 LeSabre, Invicta & Electra Convertibles	171.00
WR793	Windshield Channel	1962 LeSabre, Invicta & Electra 2-Dr Htop, Electra 225 4-Dr Htop (4 window-model 4839)	183.00
WR286	Windshield Channel	1963-64 LeSabre, Invicta, Wildcat & Electra 2 & 4-Dr Sedans & Station Wagons 1963-64 Electra 225 4-Dr Sedan (6 window hardtop-4829)	229.00
WR731	Windshield Channel	1963-64 LeSabre, Wildcat & Electra 2-Dr Htop 1963-64 Electra 225 4-Dr Htop (4 window-4839)	157.00
WR788	Windshield Channel	1963-64 LeSabre & Wildcat 4-Dr Htop	163.00
WR851	Windshield Channel	1963-64 LeSabre, Wildcat & Electra Convertibles	165.00

Rear Window Division Bar Gasket and Pinchweld Seal:

PS418	Pinchweld Seal	1941-49 for rear window and windshield, as required	71.00
--------------	----------------	---	-------

1937-64 Rubber Rear Window Channel: Molded Rubber Gasket used to secure rear glass into body.

RW104	Rear Window Channels	1937-38 Special & Century, sold as a pair, models 41, 46, 46S, 48, 61, 66S, 68	165.00 pr.
RW107	Rear Window Channel	1939-49 Special closed models with reveal molding 1939-42 Century closed models 1942-48 Super & Roadmaster Sedanets (56S, 76S) 1949 Special 4-Dr Sedan (1941-49 uses PS418 Pinchweld Seal)	173.00
RW109C	Rear Window Channel	1949 Super & Roadmaster 2-Dr Sedanet	245.00
RW113A	Rear Window Channel	1951-52 Special 2 & 4-Dr Sedan	403.00
RW113	Rear Window Channel	1953 Special 4-Dr Sedan & Special Riviera 2-Dr Htop	196.00
RW114B	Rear Window Channel	1954-56 Special & Century Riviera 2-Dr Htop	279.00
RW115	Rear Window Channel	1954-56 Special & Century 2 & 4-Dr Sedan	234.00
RW122C	Rear Window Channel	1954-56 Super & Roadmaster Riviera 2-Dr Htop	215.00
RW116	Rear Window Channel	1955-56 Special & Century Riviera 4-Dr Htop	198.00
RW117	Rear Window Channel	1957 Special & Century Riviera 2-Dr Htop	299.00
RW118	Rear Window Channel	1957 Special & Century 2 & 4-Dr Sedan & Riviera 4-Dr Hardtop	299.00
RW121	Rear Tailgate Window Channel	1957-58 Special & Century Estate Wagon	352.00
RW125C	Rear Window Channel	1957 Super & Roadmaster Riviera 2-Dr Htop	229.00
RW119	Rear Window Channel	1958 Special & Century closed models	229.00
RW120	Rear Window Channel	1959-60 LeSabre, Invicta & Electra 4-Dr Htop with panoramic rear window	313.00
RW122	Rear Window Channel	1959-60 LeSabre, Invicta & Electra 4-Dr Sedans with inside garnish molding	215.00
RW126C	Rear Window Channel	1959-60 LeSabre, Invicta & Electra 2-Dr Htop	205.00

Rubber Rear Window Channel continued:

RW634	Rear Window Channel	1961 LeSabre & Invicta 2-Dr Htop	191.00
RW387	Rear Window Channel	1961-62 Electra 4-Dr Sedan & 4-Dr Htop (6 window)	226.00
RW823	Rear Window Channel	1961 Electra 2-Dr Htop	225.00
RW507	Rear Window Channel	1962-64 LeSabre & Wildcat 2 & 4-Dr Sedan	177.00
RW559	Rear Window Channel	1962-64 LeSabre & Wildcat 2-Dr Htop	157.00
RW816	Rear Window Channel	1962-64 Electra 2-Dr Htop & 4-Dr Htop (4 window)	225.00

Front Door Vent Window Weatherstrips:

VR8	Vent Weatherstrip	1937-38 Special & Century closed models	129.00 pr.
VR7	Vent Weatherstrip	1937-38 Special & Century Convertible Coupes	119.00 pr.
VR19	Vent Weatherstrip	1941-42 Special 41, 41SE, 46, 46S, 46SSE (121" wheel base) 1941-42 Century closed models, 1946-49 Special	191.00 pr.
VR17	Vent Weatherstrip	1941-42 Special 44, 44S, 47 (118" wheel base)	186.00 pr.
VR18	Vent Weatherstrip	1941-42 Special Convertible	196.00 pr.
VR22	Vent Weatherstrip	1949 Super Conv., Roadmaster Conv. & Riviera 2-Dr Htop	218.00 pr.
VR046C	Vent Weatherstrip	1949 Super 2-Dr Sedanet & Roadmaster Sedanet 1950 Special, Super 4-Dr Sedans (4569), 2-Dr Sedanet & Estate Wagon 1950 Roadmaster 4-Dr Sedans (4769), 2-Dr Sedanet & Estate Wagon 1951 Super 4-Dr Sedans (4569), 2-Dr Sedanet & Estate Wagon 1951 Roadmaster Estate Wagon 1952-53 Super Estate Wagon, Roadmaster Estate Wagon	220.00 pr.
VR24C	Vent Weatherstrip	1950-53 Super & Roadmaster Conv & Riviera 2-Dr Htop	247.00 pr.
VR25	Vent Weatherstrip	1951-52 Special 2 & 4-Dr Sedan & Coupe (4327) 1953 Special 4-Dr Sedan	196.00 pr.
VR26	Vent Weatherstrip	1951-53 Special Conv. & Riviera 2-Dr Htop	313.00 pr.
VR27	Vent Weatherstrip	1954-56 Special & Century Conv. & Riviera 2-Dr Htop 1954 Skylark Convertible	221.00 pr.
VR28	Vent Weatherstrip	1954-56 Special 2 & 4-Dr Sedan & Estate Wagon 1954-55 Century 4-Dr Sedan & Estate Wagon 1956 Century Estate Wagon	178.00 pr.
VR093C	Vent Weatherstrip	1954-56 Super & Roadmaster 4-Dr Sedan (4519, 4719)	200.00 pr.
VR064C	Vent Weatherstrip	1954-56 Super & Roadmaster Conv. & Riviera 2 & 4-Dr	317.00 pr.
VR29	Vent Weatherstrip	1955-56 Special & Century Riviera 4-Dr Htop	215.00 pr.
VR30	Vent Weatherstrip	1957-58 Special & Century Conv. & Riviera 2-Dr Htop	240.00 pr.
VR30A	Vent Weatherstrip	1957 Special & Century Riviera 4-Dr Htop 1957-58 Special & Century Riviera Hardtop Wagon	252.00 pr.
VR30B	Vent Weatherstrip	1957 Special 2 & 4-Dr Sedan, 1957 Century 4-Dr Sedan 1957-58 Special Estate Wagon (post car)	247.00 pr.
VR30C	Vent Weatherstrip	1958 Special 2 & 4-Dr Sedan, 1958 Century 4-Dr Sedan	252.00 pr.
VR30D	Vent Weatherstrip	1958 Special & Century Riviera 4-Dr Hardtop	252.00 pr.
VR074C	Vent Weatherstrip	1957-58 Super & Roadmaster Conv. & Riviera 2-Dr Htop	253.00 pr.
VR31	Vent Weatherstrip	1959-60 LeSabre & Invicta 2 & 4-Dr Htop & Conv. 1959-60 Electra 2 & 4-Dr Hardtop (4-Window) & Conv.	150.00 pr.
VR32	Vent Weatherstrip	1959 LeSabre & Invicta 2 & 4-Dr Sedan and Estate Wagon 1959 Electra 4-Dr Sedan	158.00 pr.
VR100C	Vent Weatherstrip	1959-60 Electra 6 window 4-Door Hardtop	227.00 pr.



VR33	Vent Weatherstrip	1960 LeSabre & Invicta 2 & 4-Dr Sedan and Estate Wagon	162.00 pr.
		1960 Electra 4-Dr Sedan	
VR612	Vent Weatherstrip	1961 LeSabre 2 & 4-Dr Sedan & Wagon,	183.00 pr.
		1961 Electra 4-Dr Sedan	
		1962 LeSabre 2 & 4-Dr Sedan, 1962 Invicta Wagon,	
		1962 Electra 225 4-Dr Sedan	
VR614B	Vent Weatherstrip	1961-62 LeSabre, Invicta & Electra 2 & 4-Dr Htops & Convs.	149.00 pr.
VR634	Vent Weatherstrip	1963 LeSabre, Wildcat & Electra 225 2-Dr Htops & Convs.,	159.00 pr.
		1964 LeSabre & Wildcat 2-Dr Htop & Conv.,	
		1964 Electra 225 2 & 4-Dr Htop & Conv.	
VR634C	Vent Weatherstrip	1963-64 LeSabre & Wildcat 4-Dr Htop	226.00 pr.
VR634S	Vent Weatherstrip	1963 LeSabre 2 & 4-Dr Sedans & Wagons,	149.00 pr.
		1963 Invicta Station Wagon	
		1964 LeSabre 4-Dr Sedan & Wagon,	
		1964 Wildcat & Electra 225 4-Dr Sedan	
VR595	Vent Weatherstrip	1965-68 Electra 4-Door Sedan	238.00 pr.

Vent Window Seals: Vertical seal located on the leading edge of division bar. Seals back side of the vent window glass.

VS791	Vent Seals	1937-38 Special & Century closed models &	64.00 pr.
		1940-41 Super & Roadmaster Convertibles including Phaeton	
VS800B	Vent Seals	1939-40 Special & Century closed models	64.00 pr.
VS411	Vent Seals	1941-42 Special Convertible	64.00 pr.
VS924C	Vent Seals	1949 Super & Roadmaster Conv. & 2-Door Hardtop	64.00 pr.
VS502	Vent Seals	1951 All Special models, 1952-53 Special Conv. & 2-Dr Hardtop	74.00 pr.
VS503	Vent Seals	1950-53 Super & Roadmaster Conv. & 2-Door Hardtop	64.00 pr.
VS504	Vent Seals	1954-56 Special & Century Conv. & 2-Door Hardtop	64.00 pr.
		1954 Skylark Convertible	
VS091C	Vent Seals	1954-56 Super & Roadmaster Convertible	61.00 pr.
		1958 Special & Century 4-Door Hardtop	
VS703C	Vent Seals	1954-56 Super & Roadmaster 2-Door Hardtop	64.00 pr.
		1956-58 Super & Roadmaster 4-Door Hardtop	
VS505	Vent Seals	1955-56 Special & Century 4-Door Hardtop	64.00 pr.
VS507	Vent Seals	1957-58 Special & Century Conv. & 2-Door Hardtop	64.00 pr.
VS508	Vent Seals	1957-58 Super, Roadmaster & Limited Conv & 2-Door Hardtop	64.00 pr.
VS509	Vent Seals	1957 Special & Century Hardtop Wagon	62.00 pr.
		1958 Special & Century Hardtop Wagon	
VS510	Vent Seals	1957 Special & Century 2 & 4-Dr Sedan & Estate Wagon	64.00 pr.
		1958 Special Estate Wagon (post model)	
VS506	Vent Seals	1958 Special & Century 2 & 4-Door Sedan	65.00 pr.
VS511	Vent Seals	1959-60 LeSabre & Invicta 2 & 4-Door Hardtop	61.00 pr.
		1959-60 Electra Conv., 2-Door Hardtop & 4-Door Hardtop (4 window)	
VS30	Vent Seals	Rubber section only, no metal insert, for all models not listed	18.50 pr.

1954-56 Vent Window Assembly Base Gasket: Molded rubber gasket installed under the vent window frame assembly. Used on 1954-56 Special & Century 2-Door Hardtops and Convertibles, and 1954 Buick Skylark.

VWG546	Vent Window Base Gasket	1954-56 Buick	65.00 pr.
---------------	-------------------------	---------------	-----------



Rear Quarter Vent Window Weatherstrips:

Molded rubber weatherstrips for Vent Windows in the rear on body of car.

VR295C	Rear Quarter Vent Weatherstrips	1954 Super & Roadmaster 4-Door Sedan (4519, 4719)	249.00 pr.
VR094C	Rear Quarter Vent Weatherstrips	1955-56 Super & Roadmaster 4-Door Sedan (4519, 4719)	257.00 pr.

Fixed Rear Quarter Window Weatherstrips: Rubber weatherstrip for fixed rear quarter windows.

RQW379	Quarter Window Channels	1937-38 Special & Century Sport and Business Coupe (46, 46S, 66S)	145.00 pr.
RQW390	Quarter Window Channels	1939-40 Special & Century business coupe (46, 66)	145.00 pr.
RQW545	Quarter Window Channels	1954-56 Special 4-Dr Sedan (4469, 4469D)	223.00 pr.

**Convertible Roof Rail Weatherstrips:**

RR490C	Roof Rail Weatherstrips	1949 Super & Roadmaster Convertibles (header bow seal sold separately; order HBS49C listed below)	495.00 6 pc set
HBS49C	Header Bow Seal	1949 Super & Roadmaster Convertibles	249.00
RR501	Roof Rail Weatherstrips	1950-53 Super & Roadmaster Convertibles	554.00 8 pc set
RR530	Roof Rail Weatherstrips	1953 Special Convertibles	435.00 7 pc set
RR546	Roof Rail Weatherstrips	1954 Skylark, 1954-56 Special & Century Convertibles	689.00 7 pc set
RR546C	Roof Rail Weatherstrips	1954-56 Super & Roadmaster Convertibles	633.00 9 pc set
RR570	Roof Rail Weatherstrips	1957-58 Special & Century Convertibles	639.00 7 pc set
RR578C	Roof Rail Weatherstrips	1957-58 Super & Roadmaster Convertibles	631.00 9 pc set
RR590B	Roof Rail Weatherstrips	1959-60 Special & Invicta Convertibles	455.00 7 pc set
RR590C	Roof Rail Weatherstrips	1959-60 Electra Convertibles	455.00 7 pc set
RR614C	Roof Rail Weatherstrips	1961-64 Electra Convertibles	521.00 7 pc set
RR614B	Roof Rail Weatherstrips	1961-62 LeSabre & Invicta Convertibles (first type for 1962 6-5/8" between center section studs)	309.00 7 pc set
RR614	Roof Rail Weatherstrips	1962-64 LeSabre, Invicta & Wildcat Convs. (second type for 1962 5-3/8" between center section studs)	309.00 7 pc set
RR656	Roof Rail Weatherstrips	1965 LeSabre & Wildcat Convertibles (with molded corners on front side rail)	329.00 7 pc set
RR650	Roof Rail Weatherstrips	1965-70 Electra Convertibles	349.00 7 pc set
RR670	Roof Rail Weatherstrips	1966-70 LeSabre & Wildcat Convertibles	349.00 7 pc set
RR715	Roof Rail Weatherstrips	1971-75 LeSabre & Centurion Convertibles	209.00 5 pc set



Windshield Pillar Weatherstrips:

WP49C	Windshield Pillar Weatherstrips	1949 Super & Roadmaster Riviera 2-Door Hardtop & 1949 Super & Roadmaster Convertibles	167.00 pr.
WP530C	Windshield Pillar Weatherstrips	1950-53 Super & Roadmaster Convertibles 1953 Skylark	214.00 pr.
WP546C	Windshield Pillar Weatherstrips	1954-56 All Convertibles	51.00 pr.
WP95S	Windshield Pillar Weatherstrips	1957-58 All Convertibles	78.00 pr.
WP59	Windshield Pillar Weatherstrips	1959-60 All Convertibles	172.00 pr.
WP630	Windshield Pillar Weatherstrips	1963-64 LeSabre, Wildcat & Electra Convs.	84.50 pr.
WP650	Windshield Pillar Weatherstrips	1965 LeSabre, Wildcat & Electra Convs.	84.50 pr.
WP668	Windshield Pillar Weatherstrips	1966-68 LeSabre, Wildcat & Electra Convs.	84.50 pr.
WP690	Windshield Pillar Weatherstrips	1969-70 LeSabre, Wildcat & Electra Convs.	84.50 pr.
WP715	Windshield Pillar Weatherstrips	1971-75 LeSabre & Centurion Convs.	84.50 pr.

**2-Door Hardtop Roof Rail Weatherstrips:**

RR49C	Roof Rail Weatherstrips	1949 Roadmaster Riviera 2-Dr Hardtop	509.00 pr.
RR763C	Outer Roof Rail Seal at Qtr Window	1954-56 Special & Century, 1957-58 Super & Roadmaster	38.00 pr.
RR578M	Roof Rail Weatherstrips	1957-58 Special & Century Riviera 2-Dr Hardtop	227.00 pr.
RW59	Roof Rail Weatherstrips	1959-60 LeSabre, Invicta, Electra 2-Dr Hardtop	222.00 pr.
RR62	Roof Rail Weatherstrips	1962 LeSabre & Invicta 2-Dr Hardtop	89.00 pr.
RR63	Roof Rail Weatherstrips	1963-64 LeSabre, Wildcat, Electra 2-Dr Hardtop	89.00 pr.
RR426B	Roof Rail Weatherstrips	1963-65 Buick Riviera	186.00 pr.
RR65	Roof Rail Weatherstrips	1965-66 LeSabre, Wildcat, Electra 2-Dr Hardtop	173.00 pr.
RR66ET	Roof Rail Weatherstrips	1966-70 Buick Riviera	89.00 pr.
RR690B	Roof Rail Weatherstrips	1969-70 LeSabre & Wildcat 2-Dr Hardtop	89.00 pr.
RR713B	Roof Rail Weatherstrips	1971-73 LeSabre & Centurion 2-Dr Hardtop	206.00 pr.
RR716	Roof Rail Weatherstrips	1971-74 Electra 2-Dr Hardtop, 1974-76 LeSabre 2-Dr Hardtop	193.00 pr.

4-Door Hardtop Roof Rail Weatherstrips:

RR558M	Roof Rail Weatherstrips	1955-56 Special & Century Riviera 4-Dr Hardtop with metal core	695.00 pr.
RR568A	Roof Rail Weatherstrips	1957 Special & Century Riviera 4-Dr Hardtop 1957-58 Special & Century Hardtop Wagon	225.00 pr.
RR568B	Roof Rail Weatherstrips	1958 Special & Century Riviera 4-Dr Hardtop	225.00 pr.
RR590A	Roof Rail Weatherstrips	1959-60 LeSabre & Invicta 4-Dr Hardtop	253.00 pr.
RR590D	Roof Rail Weatherstrips	1959-60 Electra 4-Dr Hardtop	245.00 pr.
RR612	Roof Rail Weatherstrips	1961-62 LeSabre & Invicta 4-Dr Hardtop	210.00 pr.
RR634	Roof Rail Weatherstrips	1963-64 LeSabre & Wildcat 4-Dr Hardtop	89.00 pr.
RR634C	Roof Rail Weatherstrips	1963-64 Electra 4-Dr Hardtop (4 window)	240.00 pr.



4-Door Hardtop Roof Rail Weatherstrips continued:

RR634CS	Roof Rail Weatherstrips	1963-64 Electra 4- Dr Hardtop (6 window)	199.00 pr.
RR656B	Roof Rail Weatherstrips	1965-66 LeSabre & Wildcat 4-Dr Hardtop	195.00 pr.
RR6904B	Roof Rail Weatherstrips	1969-70 LeSabre, Wildcat & Electra 4-Dr Hardtop	89.00 pr.
RR714B	Roof Rail Weatherstrips	1971-74 LeSabre & Centurion 4-Dr Hardtop	286.00 pr.
RR714C	Roof Rail Weatherstrips	1971-74 Electra 4-Dr Hardtop	272.00 pr.

2-Door Models and Convertible Door Weatherstrips: Quality foam rubber door weatherstrips with correctly molded ends and push-in tabs where originally needed. Other weatherstrips without tabs are glued into place. All door weatherstrips are sold in pairs.

DW116B	Door Weatherstrips	1950-53 Super & Roadmaster Conv. & 2-Dr Hardtop	699.00 pr.
DW51	Door Weatherstrips	1951-53 Special Conv. & Riviera 2-Dr Hardtop	359.00 pr.
DW54	Door Weatherstrips	1954-55 Special & Century Conv. & Riviera 2-Dr Hardtop	209.00 pr.
		1954 Buick Skylark Convertible	
DW838C	Door Weatherstrips	1954-56 Super & Roadmaster Riviera 2-Dr Hardtop	209.00 pr.
DW893C	Door Weatherstrips	1954-56 Super & Roadmaster Convertible	209.00 pr.
DW56	Door Weatherstrips	1955-56 Special & Century Riviera 2-Dr Hardtop	209.00 pr.
DW57A	Door Weatherstrips	1957 Special 2-Door Sedan	209.00 pr.
DW58	Door Weatherstrips	1957-58 Special & Century Convertible	209.00 pr.
DW457B	Door Weatherstrips	1957-58 Super & Roadmaster 2-Dr Hardtop	209.00 pr.
DW58S	Door Weatherstrips	1958 Special 2-Door Sedan	209.00 pr.
DW59	Door Weatherstrips	1959-60 LeSabre, Invicta, Electra Conv. & 2-Dr Hardtop	109.00 pr.
DW61	Door Weatherstrips	1961-62 LeSabre, Invicta, Electra Conv. & 2-Dr Hardtop	93.00 pr.
DW63	Door Weatherstrips	1963-64 LeSabre, Wildcat, Electra 2-Dr Hardtop & Conv	93.00 pr.
DW66	Door Weatherstrips	1965-66 LeSabre, Wildcat, Electra Conv. & 2-Dr Hardtop	93.00 pr.
DW66ET	Door Weatherstrips	1966-70 Buick Riviera	93.00 pr.
DW67BC	Door Weatherstrips	1967-68 LeSabre, Wildcat, Electra Conv. & 2-Dr Hardtop	93.00 pr.
DW69BC	Door Weatherstrips	1969-70 LeSabre, Wildcat, Electra Conv. & 2-Dr Hardtop	93.00 pr.
DW715	Door Weatherstrips	1971-76 LeSabre, Centurion, Electra Conv. & 2-Dr Hardtop	93.00 pr.
DW716E	Door Weatherstrips	1971-73 Buick Riviera	89.50 pr.

4-Door Models and Station Wagon Door Weatherstrips: Quality foam rubber door weatherstrips with correctly molded ends and push-in tabs where needed. Other weatherstrips without tabs are glued into place.

DW54F	Front Door Weatherstrips	1954 Special, Century, Super & Roadmaster	149.00 pr.
		4-Door Sedans, 1954 Special & Century Wagon, glue on type	
DW54FP	Front Door Weatherstrips	1954-56 Special & Century 4-Dr Sedan & Wagon	149.00 pr.
		models with push in tabs	
DW55F	Front Door Weatherstrips	1955-56 Special & Century Riviera 4-Dr Hardtop	212.00 pr.
DW55R	Rear Door Weatherstrips	1955-56 Special & Century Riviera 4-Dr Hardtop	225.00 pr.
DW556R	Rear Door Weatherstrips	1954-56 Special & Century 4-Dr Sedan	149.00 pr.
DW57F	Front Door Weatherstrips	1957-58 Special & Century Riviera 4-Dr Hardtop	253.00 pr.
		and Hardtop Wagon	
DW57R	Rear Door Weatherstrips	1957 Special & Century Riviera 4-Dr Hardtop	235.00 pr.
		and Hardtop Wagon	
DW805C	Front Door Weatherstrips	1957-58 Super & Roadmaster 4-Dr Hardtop	319.00 pr.
DW571C	Rear Door Weatherstrips	1958 Super & Roadmaster 4-Dr Hardtop	258.00 pr.
DW58R	Rear Door Weatherstrips	1958 Special & Century Riviera 4-Dr Hardtop	258.00 pr.
		and Hardtop Wagon	
DW58SF	Front Door Weatherstrips	1958 Special & Century 4-Door Sedan	262.00 pr.
DW58SR	Rear Door Weatherstrips	1958 Special & Century 4-Door Sedan	199.00 pr.

4-Door Models and Station Wagon Door Weatherstrips: Continued from previous page.

DW59F	Front Door Weatherstrips	1959-60 LeSabre & Invicta 4-Dr Sedan & Wagon	188.00 pr.
DW59R	Rear Door Weatherstrips	1959-60 LeSabre, Invicta, Electra 4-Door Sedan	205.00 pr.
DW845	Front Door Weatherstrips	1959-60 Electra 4-Dr Hardtop	193.00 pr.
DW59HF	Front Door Weatherstrips	1959-60 LeSabre & Invicta 4-Dr Hardtop	193.00 pr.
DW59HR	Rear Door Weatherstrips	1959-60 LeSabre, Invicta, Electra 4-Dr Hardtop	199.00 pr.
DW59SWR	Rear Door Weatherstrips	1959-60 LeSabre & Invicta Station Wagons	219.00 pr.
DW1787	Front Door Weatherstrips	1959-60 Electra 4-Door Sedan	212.00 pr.
DW61SDF	Front Door Weatherstrips	1961-62 LeSabre, Invicta, Electra 4-Dr Hardtop	209.00 pr.
DW61SDR	Rear Door Weatherstrips	1961-64 LeSabre, 1961-62 Invicta 4-Dr Hardtop	179.00 pr.
		1963-64 Wildcat 4-Dr Hardtop	
DW614SDF	Front Door Weatherstrips	1961-64 LeSabre 4-Dr Sedan & Wagon,	119.00 pr.
		1962-63 Invicta 4-Dr Sedan & Wagon,	
		1961-64 Electra 4-Dr Sedan, 1964 Wildcat 4-Dr Sedan	
DW614SDR	Rear Door Weatherstrips	1961-64 LeSabre & Electra 4-Dr Sedan,	89.00 pr.
		1964 Wildcat 4-Dr Sedan	
DW614SWR	Rear Door Weatherstrips	1961-64 LeSabre & Invicta Station Wagon	129.00 pr.
DW656F	Front Door Weatherstrips	1965-66 LeSabre & Wildcat 4-Dr Sedan	89.00 pr.
DW67SDF	Front Door Weatherstrips	1965-68 LeSabre, Wildcat, Electra 4-Dr Hardtop	199.00 pr.
DW690CF	Front Door Weatherstrips	1969-70 Electra 4-Dr Sedan	230.00 pr.
DW153	Front Door Weatherstrips	1969-70 LeSabre, Wildcat, Electra 4-Dr Hardtop	273.00 pr.
DW154	Rear Door Weatherstrips	1969-70 LeSabre & Wildcat 4-Dr Hardtop	279.00 pr.
DW213	Rear Door Weatherstrips	1969-70 Electra 4-Dr Hardtop	241.00 pr.
DW716	Front Door Weatherstrips	1971-76 LeSabre, Centurion, Electra 4-Dr Hardtop	295.00 pr.



Quarter Window Chrome Sash Channels: Chrome molding attaches to the leading edge of the rear quarter window glass on 2 Door Hardtop and Convertible models. Includes a strip of glass setting channel to attach molding onto quarter glass.

SC682L	Left Chrome Sash Channel	1969-70 2-Door except Riviera	42.00
SC682R	Right Chrome Sash Channel	1969-70 2-Door. except Riviera	42.00
SC716L	Left Chrome Sash Channel	1971-73 LeSabre & Centurion 2-Dr Hardtop	42.00
		1971-75 LeSabre & Centurion Convertible	
SC716R	Right Chrome Sash Channel	1971-73 LeSabre & Centurion 2-Dr Hardtop	42.00
		1971-75 LeSabre & Centurion convertible	



2-Door Hardtop & Convertible Quarter Window Vertical Weatherstrips:

QW50	Quarter Window Weatherstrips	1949-56 All Conv. & 2-Dr Hardtop	26.50 pr.
		1957-58 Super, Roadmaster & Limited 2-Door Hardtop	
		1957-58 Special & Century Conv. & 2-Dr Hardtop	
		1959-60 Conv. & 2-Dr Hardtop exc. Electra 2-Dr Hardtop (4737)	
QW427C	Quarter Window Weatherstrips	1957-58 Super, Roadmaster & Limited Convertible	65.00 pr.
QW815C	Quarter Window Weatherstrips	1959-60 Electra 2-Dr Hardtop (4737)	64.00 pr.
QW614C	Quarter Window Weatherstrips	1961-64 Electra Convertible (4867)	67.00 pr.
QW614B	Quarter Window Weatherstrips	1961-64 LeSabre, Invicta, Wildcat Convertible (4467, 4667)	67.00 pr.
QW614E	Quarter Window Weatherstrips	1961 LeSabre, Invicta, Electra 2-Door Hardtop (4437, 4637, 4737)	65.00 pr.
QW614D	Quarter Window Weatherstrips	1962-64 Electra 2-Door Hardtop (4847)	67.00 pr.
QW614A	Quarter Window Weatherstrips	1962-64 LeSabre, Invicta & Wildcat 2-Door Hardtop (4467, 4647)	64.00 pr.
QW428B	Quarter Window Weatherstrips	1963-65 Buick Riviera	42.00 pr.
QW656B	Quarter Window Weatherstrips	1965-66 Electra Conv. & 2-Dr Hardtop (8237, 8437, 8467)	97.00 pr.
QW656C	Quarter Window Weatherstrips	1965-66 LeSabre & Wildcat Convertibles & 2-Door Hardtops	95.00 pr.
QW678B	Quarter Window Weatherstrips	1967-68 LeSabre & Wildcat 2-Dr Hardtops	97.00 pr.
QW678C	Quarter Window Weatherstrips	1967-68 LeSabre, Wildcat & Electra Conv.	32.50 pr.
QW670T	Quarter Window Weatherstrips	1966-70 Buick Riviera	43.00 pr.
QW8485	Quarter Window Weatherstrips	1969-70 LeSabre, Wildcat & Electra Convertibles & 2-Door Hardtops	23.50 pr.
QW715C	Quarter Window Weatherstrips	1971-74 Electra 2-Door Hardtop	80.00 pr.
QW715	Quarter Window Weatherstrips	1971-75 LeSabre & Centurion Convertibles & 2-Door Hardtops	59.50 pr.
QW714E	Quarter Window Weatherstrips	1971-73 Buick Riviera	97.00 pr.



1957-64 Station Wagon Rear Side Glass Weatherstrip Channels:

WSG328	Wagon Side Glass Channels	1957-58 Special & Century Hardtop Wagon (hardtop wagons only, will not fit post models)	351.00 pr.
WSG279	Wagon Side Glass Channels	1959-60 LeSabre & Invicta Station Wagon	325.00 pr.
WSG874	Wagon Side Glass Channels	1961-64 LeSabre & Invicta Station Wagon	275.00 pr.



Body Pillar Weatherstrip Seals: Located at top corner of door jamb.

BP545	Body Pillar Weatherstrips	1954-56 Special & Century Conv., 1954 Skylark	62.00 pr.
BP546	Body Pillar Weatherstrips	1954-56 Special & Century 2-Dr Hardtop	103.00 pr.
BP269C	Body Pillar Weatherstrips	1954-56 Super & Roadmaster 2-Dr Hardtop	92.00 pr.
BP581	Body Pillar Weatherstrips	1957-58 Special & Century Convertible, 1959-60 All Convertible	71.00 pr.
BP580	Body Pillar Weatherstrips	1957-58 Special & Century 2-Dr Hardtop	89.00 pr.
BP729C	Body Pillar Weatherstrips	1957-58 Super, Roadmaster & Limited Conv.	97.00 pr.
BP923C	Body Pillar Weatherstrips	1957-58 Super, Roadmaster & Limited 2-Dr Hardtop	90.00 pr.
BP907	Body Pillar Weatherstrips	1958 4-Dr Hardtop & Hardtop Wagon (rear doors)	79.00 pr.
BP5804	Body Pillar Weatherstrips	1958 Special & Century 4-Dr Hardtop & Hardtop Wagons (front doors)	67.00 pr.
BP591	Body Pillar Weatherstrips	1959-60 LeSabre, Invicta, Electra 4-Door Hardtop (rear doors)	90.00 pr.
BP941	Body Pillar Weatherstrips	1959-60 LeSabre, Invicta, Electra 4-Door Hardtop (front doors)	72.00 pr.
BP590	Body Pillar Weatherstrips	1959-60 LeSabre, Invicta & Electra 2-Dr Hardtop	67.00 pr.
BP571	Body Pillar Weatherstrips	1961 LeSabre, Invicta & Electra Conv., 1962 Invicta & Electra Conv.	73.00 pr.
BP834	Body Pillar Weatherstrips	1961-64 LeSabre, Invicta, Wildcat, Electra 4-Door Hardtop (front doors)	21.50 pr.
BP837	Body Pillar Weatherstrips	1961-64 LeSabre, Invicta, Wildcat, Electra 4-Door Hardtop (rear doors)	69.00 pr.
BP877	Body Pillar Weatherstrips	1962-64 LeSabre, Invicta, Wildcat, Electra 2-Door Hardtop	69.00 pr.
BP571	Body Pillar Weatherstrips	1963-64 LeSabre, Invicta, Electra Conv.	73.00 pr.
BP844	Body Pillar Weatherstrips	1965-66 LeSabre, Wildcat, Electra Convertible & 2-Door Hardtop	64.50 pr.
BP816	Body Pillar Weatherstrips	1965-68 LeSabre, Wildcat, Electra 4-Door Hardtop (rear doors)	65.00 pr.
BP667T	Body Pillar Weatherstrips	1966-70 Buick Riviera	43.00 pr.
BP939	Body Pillar Weatherstrips	1967-68 LeSabre & Wildcat Convertible 1967-68 Electra Conv. & 2-Dr Hardtop 1968 LeSabre & Wildcat 2-Dr Hardtop (4-3/4" long)	94.00 pr.
BP690	Body Pillar Weatherstrips	1969-70 LeSabre, Wildcat, Electra Convertible & 2-Door Hardtop	46.50 pr.
BP715	Body Pillar Weatherstrips	1971-73 LeSabre, Centurion, Electra, Riviera Convertible & 2-Door Hardtop	43.50 pr.



BP269C



BP844



BP939



BP982C



BP877



BP715



4-Door Hardtop Rear Door Vertical Weatherstrips: Installs into vertical chrome molding on the leading edge of rear door glass. Seals between the two side windows on All 4-Door Hardtop models.

QW090C	Rear Door Vertical Weatherstrips	1956 Super & Roadmaster Riviera Sedan 4-Door Hardtop	65.00 pr.
QW891C	Rear Door Vertical Weatherstrips	1957 Super & Roadmaster Riviera Sedan 4-Door Hardtop	62.00 pr.
QW904C	Rear Door Vertical Weatherstrips	1958 Super & Roadmaster 4-Door Hardtop	66.00 pr.
QW614E	Rear Door Vertical Weatherstrips	1961-62 LeSabre & Invicta 4-Door Hardtop (4439, 4639)	65.00 pr.
QW786	Rear Door Vertical Weatherstrips	1965-70 LeSabre, Wildcat, Electra 4-Door Hardtop	74.00 pr.
QW716C	Rear Door Vertical Weatherstrips	1971-76 Electra 4-Door Hardtop	95.00 pr.
QW716B	Rear Door Vertical Weatherstrips	1971-76 LeSabre & Centurion 4-Door Hardtop	97.00 pr.

1957 Convertible Rear Quarter Window Drain Tube: Located in the rear quarter of 1957 convertibles under the rear quarter windows. These parts often deteriorate. Oval tubes are molded with the correct shape and are used along with the Drain Tube Grommets. Tubes and Grommets each sold separately, as pairs.

DH57CV	Quarter Window Drain Tubes	1957 Special & Century Convs.	49.50 pr.
DHG57CV	Drain Tube Grommets	1957 Special & Century Convs.	28.50 pr.

1957 All Convertibles Body Lock Pillar Molded Weatherstrip: Complex molded rubber pillar lock seal with steel insert. These previously unavailable pieces perfectly replace original GM numbers 4695400/01. Weatherstrip is mounted on the rear quarter under the rear window on All 1957 convertibles. Sold in pairs.

QW57BP	Body Lock Pillar Molded Weatherstrip	1957 All Convertibles	89.50 pr.
---------------	--------------------------------------	-----------------------	-----------

1957-58 Rear Window Gutter Drain Tube: Molded rubber Drain Tube fits most 1957-58 2 & 4-Door Sedan models at rear window gutter area.

RWD578	Rear Gutter Drain Tube	1957-58 most models	52.50 pr.
---------------	------------------------	---------------------	-----------

1957-58 All Models Windshield Channel at Firewall to Fender Drain Tubes: 20" long tube is self-retaining. Oval end and grommet to prevent chafing against sheet metal. Sold in pairs.

WDT578	Windshield Channel to Fender Drain Tubes	1957-58 All	57.50 pr.
---------------	--	-------------	-----------



Auxiliary Door Weatherstrip & Misc. Weatherstrips:

RR523C	Roof Rail Weatherstrip above vent window	1954-56 Super & Roadmaster 2-Dr Hardtop	109.00 pr.
DW90	Auxiliary Door Weatherstrips wrap around front upper hinges	1954 Special, Century & Skylark	79.00 pr.
DW90A	Auxiliary Door Weatherstrips wrap around front upper hinges	1955-56 Special & Century	78.00 pr.
RR763C	Roof Rail Weatherstrips at quarter window	1954-56 Super & Roadmaster 1957-58 Special, Century, Super, Roadmaster & Limited	38.00 pr.
DW90B	Auxiliary Door Weatherstrips wrap around front upper hinges	1959-60 LeSabre, Invicta & Electra	75.00 pr.
RR711C	Upper Vertical Weatherstrips on rear body lock pillars	1959-60 Electra 4-Dr Hardtop (4829)	155.00 pr.

MOLDED RUBBER WEATHERSTRIPPING

Outstanding quality extruded Black closed cell sponge rubber or molded solid rubber weatherstrip used on All 1935-75 Buick models. All extruded weatherstrips are a glue-on design. Many models from 1949-53 use a split trunk weatherstrip, which has one piece in the body gutter across top of trunk opening and the remainder is needed on the trunk lid. Please check applications carefully.

DOOR WEATHERSTRIP

DW60 All 1936-38 models for door bottom only.

DW60 Door W/Strip



8.00 ft.

DW65 1937-38 All models. DW70 can be used as a substitute for DW65 if desired.

DW65 Door W/Strip



9.00 ft.

DWC73 Clip for DW65

4.00 ea.

DW70 1939-48 All exc. 1948 Roadmaster, on top and sides of door.

DW70 Door W/Strip



3.75 ft.

DW75 Fits 1948 Roadmaster, and most 1949-53 models.

DW75 Door W/Strip



5.00 ft.



Body Hinge Pillar to Door Sealing Strips: Die-cut original material with thread reinforcement. Fits 1950-53 All models. Sold in pairs.

FS491

39.50 pr.

DW80 1951-55 models not using DW75 or DW85A door weatherstripping. Check your door for proper usage.

DW80 Door W/Strip



3.75 ft.

DW85A 1955-60 models using push-in tab type. Used where molded ends are not available.

DW85A Door W/Strip



4.00 ft.

TRUNK WEATHERSTRIP

TW20 Trunk weatherstrip for all 1939-40 40-60 Series

Coupes & Conv.

Black Sponge 15/16" x 7/16".

TW20 Trunk W/Strip 4.50 ft.



TW25 1937-39, 1940 40-60-80-90 Series 2 & 4-Door Sedans, available in 15 foot lengths.

TW25 Trunk W/Strip 129.00 lgth.



TW35 Trunk weatherstrip for All 1941-48 Special models.

TW35 Trunk W/Strip



4.50 ft.

TW45 Trunk weatherstrip for 1942-48 Super & Roadmaster. Available in 15 foot lengths only.

TW45 Trunk W/Strip 79.00 lgth.



TWL50 Trunk weatherstrip for 1949-51 Special in trunk gutter. Usually 6 ft. per car.

TWL50 Trunk W/Strip 5.00 ft.



TWL50A Trunk weatherstrip for All 1949-51 Super & Roadmaster, 1952-53 All models in gutter.

Uses 7 ft. per car.

TWL50A Trunk W/Strip 7.00 ft.

TWU66 Trunk weatherstrip for 1949-51 All,

1952-53 Special, and All 1954-56 models on trunk lid. 1949-53 cars use 9 ft per car. 1954-56 cars use 18 ft per car.

TWU66 Trunk W/Strip 7.00 ft.



TWU70 Trunk weatherstrip for all 1950-53 Super & Roadmaster on trunk lid.

Requires 9 ft. per car.

TWU70 Trunk W/Strip 4.00 ft.



TW650C Trunk weatherstrip in gutter on 1954-56 Super & Roadmaster models.

TW650C Trunk W/Strip 11.00 ft.



TWL75 Trunk weatherstrip for All 1957-76 models, sold in an 18 foot piece. Molded to fit into channel around perimeter of trunk.

TWL75B-18 1957-70 36.00

TWL75E-18 1971-76 36.00



3M Weatherstrip Adhesive:

Black rubber to metal cement supplied by 3M. Sold in a 5 oz. tube.

8008 3M Adhesive 13.50 tube



Side Window Channel

Preformed pieces are not available for any Buick model. We supply sufficient measurements in our complete kits to re-channel one car, or you can purchase channel strips individually. In all cases, a certain amount of trimming and bending is required. For rigid channels, rivets are used and sweepers use staples or clips.

Kits do not include windshield, rear window, or vent window rubber. Each kit services one car.

CK100	Window Channel Kit	1937-53 4-Door Sedans and Station Wagons	275.00
		(does not include rear sliding window channel)	
CK100A	Window Channel Kit	1954-60 4-Door Sedan and Post Wagons	275.00
CK200	Window Channel Kit	1937-60 2-Door Post Coupe and Sedans	275.00
		(Specify sliding or roll up rear windows)	
CK300	Window Channel Kit	1937-53 2-Door Conv, 1949-53 Riviera Coupes	135.00
CK300A	Window Channel Kit	1954-56 Convertibles & Riviera Coupes	230.00
CK300B	Window Channel Kit	1957 Convertibles & Riviera Coupes	185.00
CK300C	Window Channel Kit	1958-60 Convertibles & Riviera Coupes	185.00
CK500	Window Channel Kit	1955-60 4-Dr Riviera Hardtop & Hardtop Wagons	255.00

625C Sweeper Clip: Used in attaching outer flexible sweeper. For use on All 1949-60 models. Two doors usually require 12 clips, 4 doors require 26.

625C Window Sweeper Clip 2.00 ea.



Front Door Window Adjuster Bumper Cushion:

This small part, when worn, can cause scratched side glass. Attaches to window adjuster studs inside doors. Up to 8 used per car.

WB408 Window Bumper Cushion 3.50 ea.
1940-58 Conv, 1949-58 Riviera Hardtop

C101 Flexible Window Glass Channel: Mohair lined, cloth covered channel with Stainless Steel bead. Fits 1933-60 2 and 4-door Sedan side windows.

C101 Flexible channel (6 ft) 49.00 ea.

C202 Rigid Upper Division Bar: Mohair lined with stainless steel bead. Used on front and rear door window channel above belt line. Fits 1933-60 models in vent window frame.

C202 Upper Division Bar (2- 18" lengths) 45.00 pr.

C303 Rigid Lower Division Bar: Mohair lined, no bead. Used on front and rear door window channel inside door. Fits all 1940-60 models.

C303 Lower Division Bar (2- 18" lengths) 45.00 pr.

C404 Flexible Sweeper: For inner and outer beltline, used on all cranking and sliding glass. 1933-60 All models. Specify year and inner or outer use.

C404 Flexible Sweeper (64" length) 39.50 ea.


6114 Mohair Channel Liner: All 1954-58 2 Door Hardtops and Convertibles in rear of front door glass and rear quarter window channel.

6114 Mohair Liner Sold by the foot 5.00 ft.

Side Window Run Clips: Two styles used on 1939-53 models. Check existing clips for style and quantity.


514C Side Window Clip 1939-53 4.00 ea.

515C Side Window Clip 1939-53 4.00 ea.



Engine Compartment Decals: Valve cover, oil filter and air filter decals.

BD10	1936-37 'Buick Valve in Head Silent Oil Cushion' Valve Cover Decal	13.00
BD11	1938 'Buick 8 Dynafash Oil Cushion' Valve Cover Decal	13.00
BD12	1939-40 Special & Super 'Buick 8 Dynafash' Valve Cover Decal	13.00
BD027	1942-48 'Buick Valve in Head Fireball Dynafash Eight' Blue Print Valve Cover Decal	13.00
BD001	1948-53 'Buick Valve in Head Fireball Dynafash Eight' Red Print Valve Cover Decal	13.00
BD003	1948-53 Buick 'Hydraulic Lifter' Valve Cover Decal	5.50
BD004	1950-53 Buick 263 Straight 8 Valve Cover Decal, Series 40 & 50	5.50
BD032	1953-55 Buick V8 Valve Cover Decals	8.00 pr.
D1	1937-53 Buick Straight 8 Oil Filler Cap Decal	5.00
D2	1953-60 Buick V8 Oil Filler Cap Decal	5.00
BD095	1950-53 Buick Orange PF127 Oil Filter Cannister Decal	5.50
D19	1953-58 Buick Black PF122 Oil Filter Cannister Decal	6.00
BD34	1953-58 Buick Orange PF122 Oil Filter Cannister Decal	6.00
D3	1937-46 Buick Oil Bath Air Filter Maintenance Decal	5.00
D6	1946-53 Buick Straight 8 Dry Element Air Filter Maintenance Decal	5.00
D5	1947-53 Buick Straight 8 Oil Bath Air Filter Maintenance Decal	5.00
D7W	1953-58 Buick V8 White Oil Bath Air Filter Maintenance Decal	5.00
D7O	1953-58 Buick V8 Orange Oil Bath Air Filter Maintenance Decal	5.00
BD260	1954-56 Buick 2 Barrel Air Filter Maintenance Decal	5.00
BD187	1957-58 Buick 2 Barrel Oil Bath Air Filter Maintenance Decal	5.00
BD188	1958 Buick 2 Barrel Dry Element Air Filter Maintenance Decal (A63C)	5.00
BD245	1958 Buick 4 Barrel Dry Element Air Filter Maintenance Decal (A63C)	5.00
BD189	1958 Buick 4 Barrel with Air Ride Dry Element Air Filter Maintenance Decal (A63C)	5.50
BD246	1959-60 Buick 4 Barrel Dry Element Air Filter Side Decal (A86C)	5.00
D27	1937-62 Buick Generator Warning Tag	3.50
D9	1941-58 Buick 'GM' Windshield Washer Jar Lid Decal (Yellow)	5.00
D9A	1941-58 Buick 'Trico' Windshield Washer Jar Lid Decal (Red)	5.00
BD175	1941-58 Buick 'GM' Windshield Washer Jar Bracket Decal	5.00
BD330	1941-58 Buick 'GM' Windshield Washer Jar Bracket Decal	5.00
BD144	1946-60 Buick Antifreeze Tag	5.00
BD372	1956-60 Buick Cooling System Decal	5.00
BD450	1953-69 Buick A/C Compressor Freon Charge Tag	5.00
BD253	1955-61 Buick 'Harrison' A/C Evaporator Box Decal	6.50
BD168	1955-63 Buick A/C Compressor Warning Decal	5.50
D20	1952-55 Buick Power Steering Pump Lid Decal	13.00



Interior Decals and Tags:

BD039	1939-47 Buick Tire Pressure Glove Box Decal	5.00
BD035	1948-50 Buick Tire Pressure Glove Box Decal	5.00
BD043	1951-53 Buick Tire Pressure Glove Box Decal	5.00
BD040	1937-58 Buick Glove Box Key Instruction Decal	3.50
BD373	1959-60 Buick Glove Box Key, Oil, Tire Pressure Decal	5.50
BD307	1937-54 Buick New Car Break-in Instrument Panel Tag	5.50
BD326	1953-63 Buick 'Air Conditioned by Buick' Window Decal	6.00
BD393	1954-63 Buick Electric Antenna Instruction Tag	5.50

Trunk Compartment Decals and Tags:

BD105	1938-41 Buick Jack Instructions Trunk Decal	5.50
BD106	1942-48 Buick Jack Instructions Trunk Decal	5.50
BD104	1955 Buick Jack Instructions Trunk Decal	5.50
BD045	1956 Buick Jack Instructions, Tire Pressure Decal	5.50
BD409	1956-57 Buick Jack Instructions Trunk Tag	6.00
BD046	1957 Buick Jack Instructions, Tire Pressure Decal	5.50
BD103	1958 Buick Jack Instructions, Tire Pressure Decal	5.50
BD333	1959 Buick Jack Instructions, Tire Pressure Decal	5.50
BD343	1960 Buick Jack Instructions, Tire Pressure Decal	6.00

BD035



BD373



BD045

Buick Body Manuals:

Reprinted GM Body Manuals pertain exclusively to body oriented repairs. For example, glass and window channel installation, door and trunk alignment and repair, wind and water leaks and weatherstripping.

BF33	1933-36 Body Manual	29.50
BF37	1937-38 Body Manual	29.50
BF40	1939-40 Body Manual	29.50
BF41	1941-42 Body Manual	24.50
BF46	1946-47 Body Manual (also use for 1948)	35.00
FBM66	1966 Fisher Body Manual	46.50
FBM67	1967 Fisher Body Manual	46.50
FBM68	1968 Fisher Body Manual	46.50
FBM69	1969 Fisher Body Manual	46.50
FBM70	1970 Fisher Body Manual	46.50
FBM71	1971 Fisher Body Manual	46.50
FBM72	1972 Fisher Body Manual	46.50
FBM73	1973 Fisher Body Manual	46.50
FBM74	1974 Fisher Body Manual	46.50
FBM75	1975 Fisher Body Manual	46.50
FBM76	1976 Fisher Body Manual	46.50



Convertible Top Guide: Book containing many articles, installation tips, maintenance information and much more helpful material pertaining exclusively to Convertible Tops.

B716	Convertible Top Guide	19.95
-------------	-----------------------	-------



HARDWARE PACKAGES, SPECIALTY BOLTS AND FASTENERS

Sheetmetal Attaching Bolts: Special bolt with a square captured lock washer, use to attach sheetmetal panels and other applications on 1950-63 Buick models.

5063B	Square Lock Washer Bolt	1950-63	5.00 ea.
5063BSET	Pack of 25 Bolts	1950-63	109.00 pkg.



Rear Bumper Gravel Deflector Fastener Package:

Attaches Rear Bumper Gravel Deflector to Rear Body sheetmetal on all 1941-53 models. Package includes 8 self tapping screws and 8 washers.

RGD413	Rear Gravel Deflector Fasteners	1941-53 All	11.50 pkg.
---------------	---------------------------------	-------------	------------



Trunk Hinge Bolts: Special Hex Head Bolt with lock washers used to attach trunk lid to hinges. Used on all 1950-60 Buick models.

THB500	Trunk Lid to Hinge Bolts	1950-60 All	21.00 set of 4
---------------	--------------------------	-------------	----------------



Trunk Lid Latch Cover and Guide Pin Screw Package:

Used on All 1950-58 models. Attaches Trunk Latch to the underside of trunk lid. Kit also includes the two screws used to install the guide pin to underside of trunk lid.


TLL506	Trunk Latch Screw Package	1950-58 All	8.50 pkg.
---------------	---------------------------	-------------	-----------



Trunk Latch Striker Plate Screw Kit:

Hardware kit used to attach Trunk Lid Striker Plate to lower section on body. Four piece kit comes with two hex head machine screws and two lock washers.

TLS506	Trunk Latch Striker Plate Screws	1949-58 All	4.50 kit
---------------	----------------------------------	-------------	----------



Door Hinge to Body Pillar Bolts: Phillips countersunk flat head bolt with lock washer used on All 1946-60 models. Measures 5/16-24 x 1". Used to attach door hinge to body pillar. Package of five services one door.

DHP420	Door Hinge to Body Bolts	1949-60 All	14.50 pkg of 5
---------------	--------------------------	-------------	----------------



Door Hinge to Door Bolts: Hex head bolt with washer, 5/16"-24 x 1 5/8". Attaches door hinge to the doors on All 1949-60 models. Package of six services one door.

DHD480	Door Hinge to Door Bolts	1948-60 All	18.00 pkg of 6.
---------------	--------------------------	-------------	-----------------



Door Latch to Door Mounting Screws: Chrome Phillips head countersunk screws with lock washers that attach the door latch assembly into door. Package of six services two doors.

DLD490	Door Latch to Door Screws	1949-60 All	12.50 pkg.
---------------	---------------------------	-------------	------------



Door Striker to Door Jamb Screw package: Three screws used per door striker on all 1949-60 models to mount into door jamb. Silver oxide finish 5/16-24 x 1-3/16" phillips flat head countersunk screws with lock washers. Package of six services two doors.

DSJ493	Door Striker Mounting Screws	1949-53 All	12.50 pkg.
---------------	------------------------------	-------------	------------

DSJ540	Door Striker Mounting Screws	1954-60 All	12.50 pkg.
---------------	------------------------------	-------------	------------



Door and Quarter Window Chrome Frame Assembly Screw Package: Used for assembly of Chrome window frames on All 1949-60 2 Door Hardtop and Convertible models. Sold in a 30 piece kit.

DQW490	Chrome Window Frame Assembly Screws	1949-60 2 Door Hardtop & Convertibles	18.50 kit
---------------	-------------------------------------	---------------------------------------	-----------



Vent Window Assembly Screw Kit: 68 piece kit provides the screws, bolts and washers needed to reassemble your vent window frame assemblies.

Applies to All 1949-60 models.

VWA490 Vent Window Screw Package 1949-60 26.50 kit




Quarter Window Adjuster and Pivot Bolt Kit: Bolt, nut and washer set for the adjustment and pivot point of the rear quarter windows. Kit applies to 1952-53 2-Door Hardtop and convertible models and 1954-60 convertibles. One kit services one side.

QWB520 Quarter Window Pivot Kit 1952-60 32.00 kit



Door and Quarter Window Inspection Cover Screw Kit: Bolt kit attaches the inspection covers onto doors and quarters. Used on 1940-60 All models.

DQC400 Inspection Cover Screw package 1940-60 All 18.50 kit



Holiday Coupe Roof Rail 'Flipper Molding' Screw Kit: Hardware kit covers All 1951-58 2-Door Hardtop models with Flipper Moldings at roof rail area. Sold in a package of 40 assorted size pieces.

RFMS518 Roof Flipper Molding Screw Kit 1951-58 Hol. Cpe 16.50 kit



Front Crossmember Brake Line Clip Set: Clips used to hold the front brake lines where they cross over the front crossmember on the frame. Used on All 1949-60 models regardless of power or manual brakes.

FBL490 Front Crossmember Brake Line Clips 1949-60 All 11.00 kit



Headlight Bucket to Fender Mounting Screws and Clip Kit: Sold in a 32 piece kit. Used for mounting the headlight buckets into the front fenders on All 1940-54 models.

HAF414 Headlight Bucket to Fender Mounting Kit 1940-54 All 18.50 kit



Headlight Retaining Adjuster Screws: Used for headlight adjustments and attaching headlight retaining ring to buckets on all 1940-60 models. Sold in a set of four.

HLS400 Headlight Adjuster Screws 1940-60 All 11.00 set of 4



Headlight Retaining Ring Springs: Used with the Adjuster Screws on 1958-60 all models.

HRS580 Headlight Retaining Ring Springs 1958-60 All 4.50 ea.



Interior Sheet Metal Screw Assortment: 100 pieces with 5 different sizes of chrome plated sheet metal screws. For all Models.

2860 Interior Screw Package 1935-60 All 24.50 pkg.



Tire Valve Stems: New Tire Valve Stem replacements for damaged or cracked originals.

10192 Valve Stem 1967-75 All models 8.50 each

Slotted Valve Stem Caps: Applies to all Buicks through 1960. Chrome plated as original.

5716 Valve Stem Caps, set of 5 9.50 set



ASSORTED HARDWARE AND FASTENERS

Inside Door Handle and Window Crank Handle Retaining Clips:

- 11A** Fits All 1939-50 Buicks.
Clip package of 10 7.50
- 2451A** Fits All 1951-60 Buicks
Clip Package of 10 8.50

Door Panel Repair Tab: Fits All 1935-56 Buicks. **7585A** Package of 25 16.50

Nut and Bolt Rubber Insulators: Used as a cushion under steel washers to eliminate water damage and prevent paint chips. Fits All models. 48 pc set

- RP80** Rubber Insulator Set 16.00

Fender Washers: Correct 1-1/4" diameter to accommodate Fender Bolt 5451 (below). Used on All 1928-53 models.

- 768A** Washer package of 50 29.00

Fender Bolt: Correct 1" X 5/16" zinc-plated chromate bolts.

- 5451** Bolt package of 25 16.00

Fender Well Anchor Nut with Tab:

Used mainly on rear body to rear fender area. Fits 1949-53 models.

- 332** Fender Anchor Nut 5.50 ea.

Sheet Metal J Clip: Used with the 2219 & 2972 Tapping Screws on All 1940-60 front end sheet metal, aprons, fenders and inner wheel wells.

- 2057** J Clip pkg. of 25 11.00 pkg.

Phillips Head Tapping Screw: Used on front fender and radiator sheet metal area. Fits All 1940-60 models.

- 2219** Tapping Screw (25 pkg) 28.50

Hex Head Tapping Screws: Used to attach various front and rear sheet metal parts. Fits all models.

- 2972** Screw Package of 50 15.00

1949-54 Vent Window Rivet: Used on pivot points for vent windows.

- R7402** Vent Window Rivet 3.00 ea.

License Plate Bolt and Nut: Fits All models. Set of two bolts and two nuts will service one plate.

- 1313** License Plate Fasteners 6.00 4 pc set

Suspension Grease Fittings:

New grease fittings for control arms, ball joints, tie rods, idler arm, etc. Sold in 10 piece packages.

- 9262A** 3/8" diam. fitting 13.50 pkg.

- 9257A** 1/4" diam. fitting 12.50 pkg.

Wire Harness Straps: Brass strap used to attach accessory wiring to main harness.

- WHS400** Wire Harness Strap 3.00 ea.

1954-56 Under Hood Wire Retaining Clip: This is the clip used in the engine compartment to retain battery cables & wiring harness. Uses 3-4 clips per car.

- 2008** Wire Retaining Clip 1954-56 All 5.00 ea.

Brake and Fuel Line Clips

1935-60 Fuel and Brake Line Fasteners: Used to attach lines to the frame where one 3/8" line exists.

- 3888J** Brake and Fuel Line clips 3.50 ea.

1935-60 Fuel and Brake Line Clips:

For models using 2 parallel steel lines that are 1/4" and 5/16" diameter.

- 1012** Fuel and Brake Line Clip 4.00 ea.

1935-60 Fuel and Brake Line Clips:

For models using 2 parallel steel lines that are both 5/16" diameter.

- 1012A** Fuel and Brake Line Clip 4.00 ea.

1935-60 Fuel and Brake Line Clips:

For models using two parallel steel lines that are 1/4" and 3/8" diameter.

- 1013** Fuel and Brake Line Clip 4.00 ea.

MOLDING CLIPS AND FASTENERS

Rear Quarter Fin Peak Molding Clips: Special design clip used to retain the chrome fin moldings on top of rear quarters.

1026	Rear Fin Molding Clip	1959 All	4.00 ea.
1027	Rear Fin Molding Clip	1960 All	4.00 ea.



Rocker Panel Molding Clips: Metal clips used to install the rocker panel moldings.

RMC580B	Rocker Molding Clip	1958 Roadmaster & Limited	3.00 ea.
RMC60B	Rocker Molding Clip	1960 All models	3.00 ea.
RMC612B	Rocker Molding Clip	1961-62 Electra & Electra 225	4.00 ea.



RMC580B



RMC60B



RMC612B



2356

Universal Molding Clips: Universal flat clip with threaded stud, can be used for moldings as wide as 2-1/2" or as small as 3/4", when cut to molding size.

2356	Universal Molding Clip	All years	3.50 ea.
-------------	------------------------	-----------	----------



1304863

New Old Stock Molding Clips: We have a large quantity of the following original (new old stock) molding clips.

1304863	Running Board Molding Clips	1938 All models	2.50 ea.
4762566	Rocker Panel Molding Clips	1959 All models	3.50 ea.



4762566

Bumper Bolts: Chrome plated or Stainless-capped Bumper Bolts for many 1942-60 Buick models.

BB429B	Chrome Bumper Bolt	1942-48 All front and rear, 1949 Special front	8.00 ea.
BB493B	Stainless Capped Bumper Bolt	1949 Super & Roadmaster front, 1950-53 All models front, 1951-53 Super, Roadmaster & Skylark rear	7.75 ea.
BB490B	Stainless Capped Bumper Bolt	1949 Super & Roadmaster rear, 1954-60 All models front and rear	3.00 ea.



BB429B



BB493B



BB490B



Index

A

Accelerator Pedals	11
Accessories	10
Air Filter Elements	54
Antenna Masts	19
Ash Tray, rear armrest	8

B

Back Up Light Lenses	23
Back Up Lens Gaskets	23
Ball Joints	74
Battery Cables	63
Battery Hold Down Parts	63
Bearings, Engine	49, 51
Bearings, Wheel	65
Belts, Engine	58
Body Mount Pads	63
Booster, Power Brake	66
Brake Parts	66-71
Brake Master Cylinder	67-68
Brake Pedal Pads	11
Brake Stoplight Switches	68
Bulbs	64
Bumper Bolts	93
Bumper Emblem Inserts	27
Bumper Grommets, Rubber	34

C

Carburetor Base Gaskets	44
Carburetor Rebuild Kits	45
Carburetor Rebuild Service	44
Carpet Sets	13
Center Caps, Wheel	25
Coil Springs	72
Convertible Top Cylinders	35
Convertible Top Handles	35
Convertible Top Hoses	35
Convertible Top Latches	36
Convertible Top Motors	35
Courtesy Light Bezels	4-5
Courtesy Light Lenses	4-5
Cowl Lacing	31
Cowl Vent Gasket	33
Curb Feelers	10
Cylinders, Brake Wheel	70

D

Decals	88-89
Distributors	59
Dome Light Lenses	4-5
Dome Light Bezels	4-5
Door Bumpers, Rubber	32
Door Lock Knobs	7
Door Jamb Light Switch	4, 15
Door Jamb Strikers	15
Door Jamb Wiring Boot	3
Door Sill Plates	14
Door Handles, Exterior	19
Door Handles, Interior	6
Driveshaft Bearing Support	53

E

Electrical Components	58-64
Engine Gaskets	48-49
Engine Mounts	53
Engine Paint	53
Engine Parts	49-51
Exhaust Deflector	25

F

Fasteners	90-92
Fender Portholes	17
Fender Welt	16
Firewall Grommets	31
Fisher Body Manuals	89
Fisher Body Plates	14
Floor Mats	14
Floor Pan Plug Set	16
Freeze Plug Kits	49
Front Bumper Inserts	27
Fuel Line Hoses & Filter	45
Fuel Pumps	44
Fuel Pump Kits	43
Fuel Tanks	46
Fuel Tank Sending Units	46
Fuses	61

G

Gas Caps	46
Gas Door Bumpers	33
Gas Filler Door Assembly	24
Generator Parts	61
Glove Box Insert	12
Grommets, Bumper Bar	34
Grommets, Firewall	31

H

Header Bow, Convertible	38
Headlight Bezels	20
Headlight Retaining Ring	20
Headlight Terminal Board	62
Heater Control Valve	55
Hardware Kits	90-92
Hood Bumpers	32
Hood Ornament, 1955	27
Hood Emblem Inserts	26
Hood Insulation	34
Hood Letter Sets	28
Hood Release Cables	20
Horn Assemblies, Rebuilt	62
Horn Relay	60
Hose Clamps	54
Hoses, Radiator	54
Hub Caps	24
Hub Cap Inserts	24

I-J

Ignition Coil	61
Ignition Parts	58-61
Ignition Wire Sets	58
Inside Door Handles	6
Interior Chrome Parts	1-10
Jar, Glass Washer Fluid	39



K		R		V-W-X-Y-Z	
Kick Panels	12	Radiator Caps	56	Vacuum Wiper Motors	43
Kit, Hardware	90-92	Radiator Hoses	55	Visor Supports	9
Kit, Carburetor Rebuild	45	Rearview Mirror, Inside	9	Visor Vanity Mirrors	10
Kit, Engine Gasket	48	Rear Shock Links	72	Voltage Regulator	59
Kit, Fuel Pump Rebuild	43	Rear Window Channel	76-77	Water Pumps	57
Kit, Transmission Rebuild	52	Relay, Power Options	62	Weatherstrip, by the foot	86
Kit, Tune Up	60	Rocker Molding Clips	93	Weatherstrip, Body Pillar	84
Kit, Window Channel	87			Weatherstrip, Door	81-82
Key Blanks	41	S		Weatherstrip, Quarter Window	83
Knee Action Shocks	72	Scripts	28-30	Weatherstrip, Roof Rail	80-81
L		Seals, Wheel Grease	65	Weatherstrip, Vent Window	77-78
Letter Sets	28-30	Seat Back Bumpers	8	Wheel Bearings & Seals	65
License Lamp Lens	23	Shock Absorbers	72	Wheel Lug Nuts & Studs	24
License Plate Frame	10	Speedometer Cable	64	Window Channel Kits	87
Literature	89	Starter Parts	61	Windshield Rubber Channel	75-76
Lock Cylinders	41	Steering Column Floor Plates	12	Windshield Washer Parts	38-39
M-N		Suspension Bumpers	74	Windshield Wiper Blades	40
Manual, Fisher Body	89	Suspension Parts	72-74	Wiper Escutcheons	38
Molding Clips	93	Switches, Power Window	1	Window Crank Handles	6
O-P-Q		Switches, Power Seat	1-2		
Oil Filters	47	T-U			
Outside Mirrors	18	Tail Lamp Wiring Boots	16		
Park Light Lenses	22	Tail Lens Gaskets	21		
Park Lens Gaskets	22	Tail Light Bezels	23		
Parking Brake Cables	71	Tail Light Lenses	21		
Pedal, Accelerator	11	Tire Valve Stems	91		
Pedal Pads, Brake	11	Tissue Dispenser	10		
Pistons and Pin Sets	51	Thermostats	56		
Piston Ring Sets	51	Thermostat Housings	56		
Porthole, Fender	17	Top Latch, Convertible	36		
Power Brake Booster	66	Torque Ball Rubber Boots	52		
Power Seat Switches	1-2	Transmission Mounts	53		
Power Steering Rebuild	42	Transmission Rebuild Kits	52		
Power Steering Kit	42	Trunk Lid Bumpers	33		
Power Window Motors	3	Trunk Mats and Material	16		
Power Window Switch	1-2	Trunk Emblem Chrome Base	26		
Quarter Window Sash Mld.	82	Trunk Ornament Lenses	26-27		
		Trunk Ornament/Handle Pads	34		
		Tune Up Kits	60		

