

CATALOG #29BC



Fusick **Automotive Products Inc.**

21 Thompson Road
East Windsor, CT 06088-0655
Fax 1-860-623-3118
Email: sales@fusick.com
www.fusickautomotiveproducts.com

SINCE 1971

Phone: 1-860-623-1589
Phone: 1-860-623-1583
M-Th 8:00 AM to 5:30 PM
Fri 8:00 AM to 5:00 PM
Sat 9:00 AM to 12:00 Noon



Welcome Oldsmobile Enthusiasts,

Fusick Automotive has been in business since 1971 serving 1935-77 Oldsmobile owners worldwide. During this time, we have developed a large inventory of aftermarket and reproduction parts.

We hope this catalog will meet some of your restoration needs. The uncertainty and spiraling costs of raw materials, labor, and out of control freight charges have necessitated price increases in this catalog. These increases reflect just the new increases of goods within the last year.

For those restoring a 1961-77 Cutlass, 442, or H/O, we offer a catalog listing hundreds of items for enthusiasts. We also offer a catalog for 1935-60 Oldsmobile enthusiasts. This catalog has a large variety of reproduction items, suspension parts, rubber parts and decals to aid in your restoration. As always, catalogs are no charge with an order or you may download the complete pdf file on our website fusickautomotiveproducts.com for free.

Please read our policies and procedures on the opposite page before ordering. Remember, we constantly maintain a large stock of parts in order to offer same day shipping. We appreciate your mail-in, faxed, emailed or web site order to help eliminate needless communication errors. Enjoy the catalog and we look forward to assisting you with your Oldsmobile restoration in the near future.

Sincerely for Oldsmobile,

Office Personnel

Jason Jutras
Jason@fusick.com

Kevin McMahon
Kevin@fusick.com

Brandon Smith
BSmith@fusick.com

Michael Catania
MCatania@fusick.com

Warehouse Personnel

James Hemingway
James Hemingway

Terrance Chase
Terrance Chase
Terrance@fusick.com

Scott Spremulli
Scott Spremulli

Matt Sprenulli
Matt Sprenulli

Mike Fusick
Michael Fusick



Revision Date: May 1, 2023

SCRIPTS & EMBLEMS

We have reproduced many of the hard-to-find Scripts and Emblems for Starfire and Toronado. Quality of casting and chrome finish is excellent. All scripts and emblems are inspected, approved and licensed by General Motors.

1961-66 Starfire Scripts

1961 'Starfire' Scripts: The 1961 Starfire uses the same script on both front fenders and trunk. Quality cast chrome script licensed by General Motors.

Fasteners included.

SE6241T 'Starfire' Script, 1961 Starfire 56.50 ea.



1962 'Starfire' Scripts: The 1962 Starfire used 2 different scripts for trunk and fenders. Scripts are quality cast chrome and licensed by General Motors. Includes fasteners.

SE6274 1962 'Starfire' Fender Script 55.50 ea.

SE6241T 1962 'Starfire' Trunk Script 56.50

1963 'Starfire' Scripts: 1963 Starfire scripts are quality cast chrome plated and licensed by GM. Includes fasteners. SE6320 is used on 1963 Starfire Convertibles while the SE63RP Roof Panel script is used on 1963 Starfire Coupes.

SE6320 1963 'Starfire' Convertible Front Fender Script 55.50 ea.

SE6361T 1963 'Starfire' Trunk Script 56.50

SE63RP 1963 'Starfire' Coupe Roof Panel Script 55.50 ea.



1964 'Starfire' Scripts: The 1964 Starfire used 2 different scripts. Cast chrome plated and licensed by General Motors. Includes fasteners.

SE6423 1964 'Starfire' Fender Script 55.50 ea.

SE6477T 1964 'Starfire' Trunk Script 56.50



1965-66 'Starfire' Scripts: 1965-66 Starfires used two different scripts for fender and trunk. Licensed and approved by GM. Includes fasteners.

SE6541 1965-66 'Starfire' Fender Script 55.50 ea.

SE6558T 1965-66 'Starfire' Trunk Script 56.50

1966-67 Toronado Scripts and Emblems

The 1966-67 Toronado Scripts and Emblems are all licensed and approved by General Motors. Quality casting with excellent chrome finish and correct painted highlights per originals.



GM Restoration Parts

1966-67 Toronado Front End Panel

Rocket Emblem: Cast chrome plated emblem with correct 'claret poly' (maroon) color in body and black highlights around edges. Licensed by General Motors. Emblem is 5" tall and has two mounting studs, includes fasteners. Mounts on front end panel over the 'Oldsmobile' letters.

SE6694 1966-67 Rocket Emblem 52.00



GM Restoration Parts

1966-67 'Toronado' Front Fender Script:

Cast chrome plated 'Toronado' scripts are licensed by General Motors. Correct dark grey highlights in center of letters. Script has five mounting studs and includes fasteners.

SE6656 1966-67 'Toronado' Fender Script 52.00 ea.



GM Restoration Parts

'Oldsmobile' Front End Panel Letter Set:

Expensive tooling was used to bring these quality letters to the enthusiast. Set of 10 letters has correct grey highlights in the center of letters and is licensed by General Motors. Correct angle on all the letters to conform to the angle of the front end panel. Includes all fasteners.

L667T 1966-67 'Oldsmobile' Letter Set 72.00 set



GM Restoration Parts

1967 'Toronado' Grille Script: Cast chrome grille script with correct grey highlights in center of letters. Script has three mounting studs with fasteners included. Inspected and licensed by General Motors.

SE6777G 1967 'Toronado' Grille Script 52.00



GM Restoration Parts

1966-67 'Toronado' Trunk Script:

Cast chrome plated script, licensed by General Motors. Correct grey color highlights in letters as original.

SE6602 1966-67 'Toronado' Trunk Script 52.00

1966-67 Toronado 'by Oldsmobile'

GM Restoration Parts

Trunk Nameplate: Cast chrome nameplate has brushed finish on face and correct white 'BY OLDSMOBILE' letters as original. Licensed by General Motors.

SE6603 1966-67 'by Oldsmobile' Nameplate 42.00
SE97G

'Oldsmobile' Grille Scripts

'Oldsmobile' Grille Scripts: Quality chrome plated cast Grille Scripts for 1968-69 88 & 98 models and 1972 98 models. All mounting hardware included.

SE97G 1968-69 88 & 98 Grille Script 40.00

SE25G 1972 98 Grille Script 40.00



GM Restoration Parts



SE25G

GM Restoration Parts

OUTSIDE REAR VIEW MIRRORS

Excellent reproductions of selected mirrors used on 1961-71 Full Size Oldsmobiles. Applications listed are the only mirrors available at this time.



SM6170L Left only Outside Standard Chrome Mirror. Includes mounting bracket and molded plastic gasket. Fits **1961-62** all models 89.50



SM6308B Outside Standard Chrome Mirror, fits both sides. Base has a v-shape in the bottom to mount onto the body line. Mounting bracket and molded plastic gasket included. Fits **1963-64** all models. 84.50 ea.



1965 88-98-Starfire Outside Standard Chrome Mirror. Includes mounting bracket and molded plastic gasket.

SM6365L Left Outside Chrome Mirror 89.50

SM6365R Right Outside Chrome Mirror 89.50



SM6667B Outside Standard Chrome Mirror, fits both sides. With mounting bracket and molded plastic gasket. Fits **1966** all models including Toronado. 84.50 ea.



1968-70 Toronado left and right Outside Standard Chrome Mirrors. Includes mounting screws and molded plastic gasket.

SM7050L Left Mirror 1968-70 Toronado 75.00

SM7050R Right Mirror 1968-70 Toronado 75.00

SM7050P Pair of 1968-70 Toronado mirrors 139.00 pr.



1968-70 88-98 Left and right Standard Chrome Outside Mirrors. With mounting screws and molded plastic gasket.

SM6865L Left Outside Mirror 75.00

SM6865R Right Outside Mirror 75.00

SM6865P Pair of 1968-70 Chrome mirrors 139.00 pr.

Mirror Gaskets: The following side view mirror gaskets are available in the original plastic material. Will fit either passenger or driver side.

MGS670	Mirror Gasket	1967 standard mirrors	9.00
MGS670R	Mirror Gasket	1967 LH remote mirror	11.00
MGS682	Mirror Gasket	1968-69 all exc. Toronado.	9.50
MGS702	Mirror Gasket	1968-69 Toro, 1970 88-98	9.00



1969-70, 1971-76 Rear Quarter Window Chrome Sash Channels:

Chrome plated molding attaches to leading edge of quarter window and accepts the Quarter Window Weatherstrips. Fits 1969-70 88 & 98 Holiday Coupes and Convertibles and 1971-76 Delta 88 Royale Holiday Coupe and Convertible. Mounts to glass with window setting channel which is included.

SC682L	Left Chrome Sash Channel	1969-70 88-98 Hol. Cpe. & Conv.	42.00
SC682R	Right Chrome Sash Channel	1969-70 88-98 Hol. Cpe. & Conv.	42.00
SC716L	Left Chrome Sash Channel	1971-76 Delta 88 Royale Hol.Cpe & Conv	42.00
SC716R	Right Chrome Sash Channel	1971-76 Delta 88 Royale Hol.Cpe & Conv	42.00

1961-62 88-98 Outside Door Opening Handle Set: Complete handle package comes with push button assemblies and mounting hardware. Handles fit all 1961-62 Oldsmobile 88 & 98 two door models and front doors only on 1961-62 88 & 98 four door models.

DH612BC Outside Door Handles 1961-62 all models 79.50 set



ORIGINAL T3 HEADLAMPS

T3 Headlamps: New T3's to fit all 1961-71 Oldsmobiles. Made under license from General Motors and produced by an OEM manufacturer, these T3's cannot be distinguished from original. Sold in pairs of one low beam and one high beam only.

T3607	T3 Headlamps	1961-67 all models (1 high, 1 low)	98.50 pr.
T36871	T3 Headlamps	1968-71 all models (1 high, 1 low)	98.50 pr.

1965-66 and 1968-70 Headlight Buckets: New stamped sheetmetal headlight buckets available for all 1965-66 88-98-Starfire and 1968-70 88 & 98 models. Sold in a set of four only. 1967 models differ from other years and are not available at this time.

HLB656	Headlight Bucket Set	1965-66 88-98-Starfire	125.00 set
HLB678	Headlight Bucket Set	1968 88-98 models	125.00 set
HLB692	Headlight Bucket Set	1969-70 88 & 98 models	125.00 set

Headlight Adjuster Screws: Uses eight per car, two per headlight. Allows adjustment for proper alignment of headlights. Two different types available, 67-3110 is a self retaining design that snaps into a rectangular hole and 68-3249 uses included pop rivets to install.

67-3110	Headlight Adjuster Screw, self retaining	4.50 ea.
68-3249	Headlight Adjuster Screw, pop-riveted	4.50 ea.

Headlight Bulb Retaining Rings: Uses four per car, Stainless Steel Ring used to hold Headlight Bulbs into Headlight Buckets listed above.

HRR61	Headlight Bulb Retaining Ring	1965-66, 1968-69	29.50 ea.
HRR702	Headlight Bulb Retaining Ring	1970-72	29.50 ea.

1969 88 & 98 Hood Release Handle: New plastic Hood Release Handle includes retaining clip. Fits all 1969 88 & 98 models.


HRH690	Hood Release Handle	1969 88-98	21.50
HRHC692	Hood Release Handle Clip		1.50

1966-68 Toronado Chrome Exhaust Tips: Chrome plated exhaust tips used on 1966, 1967 & 1968 Toronado. Tips for the 1966 models have the bracket attached on top. Previously discontinued, we have re-tooled the chrome tips and reintroduced them back to the market.


EE66T	Chrome Exhaust Tips	1966 Toronado	159.00 pr.
EE67T	Chrome Exhaust Tips	1967 Toronado	159.00 pr.
EE68T	Chrome Exhaust Tips	1968 Toronado	189.00 pr.



GD647



GD680




GD712

1964-72 License Plate Holder/ Gas Door Assemblies: New item manufactured to exact OEM specifications. Stamped steel construction, includes tension springs. Holds rear license plate, bolts to rear bumper and tilts down to allow access to fuel tank filler neck.

GD647	Gas Door Assembly	1964-67 88-98, 1964-66 Starfire, 1966-67 Toronado	55.00
GD680	Gas Door Assembly	1968-70 88, 1969-70 98 models	55.00
GD712	Gas Door Assembly	1971-72 88 & 98, 1973 Delta 88 & Delta 88 Royale	55.00
8418-89	License Plate Fasteners	1961-75 all	3.00 pr.



EE66T



EE67T



EE68T



Back-Up Light Lenses: Vulnerable lenses located in the rear bumper, used on 1966-67 Toronado and 1967-68 Ninety Eight. Our lenses are the correct clear lens and are licensed by GM. Sold in pairs only.

BU0102	Back-up Lenses	1966-67 Toronado, 1967-68 98	64.50 pr.
BUG0102	Back Up Gaskets	1966-67 Toronado, 1967-68 98	10.00 pr.

1967 88 Back-Up Lenses and Housings: Clear plastic back-up lenses for 1967 Oldsmobile 88 models. New metal back-up housings are sold complete with wiring pigtail and connector. Chrome screws have the correct collar on them to prevent over tightening.

BU7090B	Back-Up Lens	1967 88 models	29.50 ea.
BUH702	Back-Up Housing	1967 88 models	52.00 ea.
BUG702	Lens Gasket	1967 88 models	5.00 ea.
BLS702	Lens Screws	1967 88 models	4.50 pr.

1969 88 & 98 Parking Light Housings: Cast metal housing includes wire pigtail and bulb socket.

PLA697L	Left Park Light Assembly	1969 88 & 98	73.00
PLA697R	Right Park Light Assembly	1969 88 & 98	73.00
PLG690	Park Light Gaskets	1969 88 & 98	5.00 ea.
PLS690	Park Lens Screws	1969 88 & 98	4.50 pr.

License Lamp Lenses: New License Lamp Lenses available for 1961-63 and 64 wagons, and 1966-72 some models (see listing below). Clear lens with 5957401-2 GUIDE 35 SAE L 66 for 1966-72.

LL614	License Lamp Lens	1961-63, 1964 Wagons	16.50
LL6801	License Lamp Lens	1966 88s, 1968-70 all exc. 1968 98, 1971-72 88-98 exc. wagons	13.50
LLG6801	License Lens Gasket for LL6801 Lens		3.50

License Lamp Assembly: Complete assembly ready to install includes lens, gasket, housing, wire pigtail with end connector and bulb. Replaces GM part number 916271 and fits 1969-70 Toronado models.

LLA6801	License Lamp Assembly	1969-70 Toronado	45.00
----------------	-----------------------	------------------	-------

BU0102



BUH702



PLA697L



BU7090B



LL614



LL6801



ANTENNA PARTS



Power Antenna Chrome Nut: Threaded chrome nut used on all 1961-68 Oldsmobiles.

PAN619	Antenna Chrome Nut	34.50
---------------	--------------------	-------

Power Antenna Mounting Pad: Fits all 1961-66 with power antenna exc. Toronado.

MAG619A	Antenna Mount Pad	7.50
----------------	-------------------	------



Manual Antenna Mounting Pad: Fits all 1961-70 with manual antenna exc. Toronado.

MAG619	Antenna Mount Pad	7.00
---------------	-------------------	------

Manual Antenna Black Plastic Nut: Fits 1961-62 88/98/Starfire models with manual antenna.

AN586	Manual Antenna Nut	1961-62 all	14.50
--------------	--------------------	-------------	-------

Manual Antenna Black Plastic Antenna Nut: Fits 1963-70 88/98 with Manual Antenna only.

AN679	Manual Antenna Nut	1963-70 88-98	13.00
--------------	--------------------	---------------	-------



Manual Antenna Mast:

New Manual Antenna Masts are now available, correct three piece mast with small ball tip. Original base which antenna presses into must be re-used. Applies to 1961-62 all models equipped with a manual antenna, will not work for factory equipped power antennas.

569310	Manual Antenna Mast	1961-62	65.00
---------------	---------------------	---------	-------

Manual Antenna Mast: Elliptical (oval) three piece, manual antenna mast with bullet tip. Presses into existing antenna base on 1969-70 88 and 98 models.

402253	Elliptical Antenna Mast	1969-70 88 & 98	139.00
---------------	-------------------------	-----------------	--------

1961-70 Convertible Top Motors and Cylinders:

Leaking or inoperative cylinders will need replacement. We offer new (not rebuilt) cylinders and motors with a One year warranty against defects.

TC26	Top Cylinder	1961 all	159.00 ea.
TC27	Top Cylinder	1962 all	159.00 ea.
TC28	Top Cylinder	1963-64 all	159.00 ea.
TC46	Top Cylinder	1965-70 all	159.00 ea.
TP2	Top/Pump Motor	1961-63 all	339.00
TP3	Top/Pump Motor	1964 all	339.00
TP7	Top/Pump Motor	1965-70 all	339.00
TMG642	Top Motor Grommet all models		3.50 ea.



Convertible Top Hooks: Threaded rod with chrome plated hooks. Replacement for an often broken part.

CX614	Convertible Top Hook	1961-63	16.50 ea.
CX642	Convertible Top Hook	1965, 67-70	8.50 ea.

1966-70, 1971-75 Convertible Top Latch Assemblies: New Convertible Top Latch assembly replaces damaged originals on all 1966-70 98 Convertibles and 1967-75 88 Convertibles. Assemblies include the chrome Top Hook.

CTL660L	Left Top Latch	1966-70 98, 1967-70 88 Conv.	119.00
CTL660R	Right Top Latch	1966-70 98, 1967-70 88 Conv.	119.00
CTL716L	Left Top Latch	1971-75 88 Conv.	139.00
CTL716R	Right Top Latch	1971-75 88 Conv.	139.00

1961-62 Convertible Top Switch: New electrical switch with polished stainless steel button for convertible top operation on 1961-62 88, 98 & Starfire Convertible. Original chrome bezel must be re-used. New clips included with switch.

4634122	Convertible Top Switch	1961-62 Conv.	85.00
----------------	------------------------	---------------	-------

1967-68 Convertible Top Switch & Power Antenna Switch: New Convertible Top Switch available for all 1967-68 88-98 Convertible models. Same switch is also used for the Power Antenna option. Chrome finish with black highlights on push button.

CTS667	Convertible Top & Power Antenna Switch	1967-68 88-98	83.00
---------------	--	---------------	-------

Convertible Top Cables:

For 1961-75 Models, except 1971. These cables have a tendency to break after a period of years and should be replaced when installing a new top.



614BM	1962-64 88 and Starfire Top Cables	54.50 pr.
614CM	1961-64 98 Convertible Top Cables	54.50 pr.
6570A	1965-70 88 and Starfire Top Cables	54.50 pr.
6570B	1965-70 98 Convertible Top Cables	54.50 pr.
7276	1972-75 88 Convertible Top Cables	65.00 pr.

Convertible Top Hoses: Fit 1961-70 all models from cylinders to motor and pump assembly. Manufactured to accommodate many models. Surplus lines should be coiled and retained at the pump. Lines are rubber for 1961, and plastic from 1962-1970.

CTH561	Rubber Top Hoses	1961 all	119.00 pr.
CTH627	Plastic Top Hoses	1962-70 all	119.00 pr.

1961-64 Convertible Top

Latches: New chrome convertible top latch assemblies replace broken or worn out originals. Fit all 1961-64 Convertible models.

CTL614L	Top Latch, left side	1961-64	165.00
CTL614R	Top Latch, right side	1961-64	165.00



1971-75 Oldsmobile 88 Convertible Top Motor: New Scissor Top Motor for all 1971-75 88 convertibles includes electrical pigtail wires and connector.

STM716	Convertible Top Motor	1971-75 Convertible	259.00
---------------	-----------------------	---------------------	--------



1971-75 88 Convertible Scissor Top Parts:

CAB716	Convertible Top Actuator Bolt/Lock Washer	1971-75 88 Convertible	14.00
CFB716	Convertible Frame Bushing Set (16 pcs)	1971-75 88 Convertible	60.00
CBG716	Convertible 3rd Bow Plastic Guide	1971-75 88 Convertible	63.00
CTR716	Convertible Top Relay	1971-75 88 Convertible	63.00
CDC716BK	Convertible Drive Cables (black-pass. side)	1971-75 88 Convertible	65.00
CDC716BL	Convertible Drive Cables (blue-driver side)	1971-75 88 Convertible	65.00
CGW716	Convertible Top Rain Gutter Wires	1971-75 88 Convertible	59.00
CSA716	Convertible Top Glass Support Arms and Bushings	1971-75 88 Convertible	99.00
HGP716	Convertible Header Bow Guide Pins	1971-75 88 Convertible	14.00 pr.




Convertible Top Guide: Book contains many articles, installation tips, maintenance information and much more helpful information pertaining exclusively to convertible tops.
B716 Convertible Top Guide 21.50



1961-75 Power Window Motors:

New Power Window Motors for all 1961-1975 2 and 4 Door Oldsmobiles equipped with power windows. These motors have a square body and replace original worn motors perfectly.

M3898	Right Power Window Motor (passenger side)	1961-75 all	149.00 ea.
M3899	Left Power Window Motor (driver side)	1961-75 all	149.00 ea.



Power Window Door Jamb Wiring Conduit/Rubber Boot: Located at front door hinge area. Two used per car. Fits all 1965-68 models, and 1969-1970 Toronado models equipped with power windows and/or power door locks.

EWC6670	Wiring Rubber Conduit	1965-68 all, 1969-70 Toronado	55.00 ea.
----------------	-----------------------	-------------------------------	-----------



HOOD INSULATION PADS

All Hood Insulation Pads are manufactured using the same material as original, but without the embossments for hood braces or air filters. 1961-63 Insulations are yellow, 1964-75 Insulations are dark gray. In all cases the smooth side faces the hood. Check your original for quantity of Hood Insulation Fasteners needed. Models earlier than 1964 use an adhesive to hold the insulation onto underside of hood. 1964 and newer used a combination of push-in fasteners and adhesive. We recommend 3M Spray Trim Adhesive or a similar quality product.



HI612



HI667T	Hood Insulation Pad	1966-67 Toronado	53.50
HI680T	Hood Insulation Pad	1968-70 Toronado	53.50
HI612	Hood Insulation Pad	1961-62 all	53.50
HI630	Hood Insulation Pad	1963 all	53.50
HI640	Hood Insulation Pad	1964 all	53.50
HI650	Hood Insulation Pad	1965 all	53.50
HI660	Hood Insulation Pad	1966 88-98	53.50
HI670	Hood Insulation Pad	1967 88-98	53.50
HI680	Hood Insulation Pad	1968 88-98	53.50
HI690	Hood Insulation Pad	1969-70 88-98	53.50
HI715	Hood Insulation Pad	1971-75 88-98	53.50
HI760	Hood Insulation Pad	1976 88-98	53.50
11129	Square Hood Insulation Fastener	1964-70 All	1.50 ea.
11130	Round Hood Insulation Fastener	1971-75 All	1.50 ea.

Hood 'Pop-Up' Spring: Made from spring steel, bolts to radiator support. Causes the hood to pop up when pulling the hood release.

HS682F Hood Pop Up Spring 1968-69 all, 1970 Toro 13.50

COWL TO HOOD LACING STRIPS

Molded rubber or foam rubber strip installs in engine compartment across the top of the cowl to seal under the back side of the hood.

CL61	Cowl Lacing Strip	1961-63 all models	47.00
CL64	Cowl Lacing Strip	1964-67 all models	16.50
CL68	Cowl Lacing Strip	1968-70 all models	16.50
CL716	Cowl Lacing Strip	1971-76 all models	65.00




INNER FRONT FENDER A-FRAME SEALS

A Frame Seals are die cut from the original style, black masticated rubber using all original samples for correct fit and shape. Original style olive green metal fasteners, part number 3774, are sold separately.

FCD19	A-Frame Seals (uses 34 clips)	1961 all	42.50 pr.
FCD20	A-Frame Seals (uses 26 clips)	1962 all	42.50 pr.
FCD21	A-Frame Seals (uses 38 clips)	1963-64 88-98-Starfire	36.50 set
FCD22	A-Frame Seals (uses 18 clips)	1965-66 88-98-Starfire	32.50 pr.
FCD23	A-Frame Seals (uses 24 clips)	1967-68 88-98	32.50 pr.
FCD24T	A-Frame Seals	1966-70 Toronado	29.50 pr.
FCD25	A-Frame Seals	1969-70 88-98	32.50 pr.


Olive Green Metal Push-In Fasteners: Correct, 5/8" x 1/2" rectangular head push in metal fasteners painted flat olive green, used on A-Frame seals, cowl lacing, and various other areas under the hood.

3774 Original Style Olive Green Metal Fasteners 1961-70 all models 1.50 ea.




TRUNK COMPARTMENT

1962-75 Trunk Compartment Cardboard Side Panels and Mats: We have the 1962-63-64 Starfire die cut trunk cardboards and die cut trunk mats available. The 1962 Starfire version is available in blue and maroon only. The 1963-64 Starfire version is available in black, blue and maroon. Other Trunk Mats listed from 1966-75 are made from the closest matched materials available. We no longer have available the foam backed, tan Trunk Material for 1961-65 88, 1965-66 98, and 1966 Toronados.



TRM672



houndstooth
pattern

1962 Starfire Convertible
Trunk Cardboards



75.00 shipping surcharge on trunk cardboard kits sent to a U.S. address

TCK61CV	Trunk Cardboard Set (Maroon, Blue or Black)	1961 Starfire Convertible	159.00
TCK62CM	Trunk Cardboard Set (Maroon)	1962 Starfire Coupe	173.00 2 pc.
TCK62CVM	Trunk Cardboard Set (Maroon)	1962 Starfire Convertible	173.00 4 pc.
TCK62CB	Trunk Cardboard Set (Blue)	1962 Starfire Coupe	173.00 2 pc.
TCK62CVB	Trunk Cardboard Set (Blue)	1962 Starfire Convertible	173.00 4 pc.
TM62CM	Trunk Mat Set (die cut Maroon felt)	1962 Starfire Coupe	299.00 7 pc.
TM62CVM	Trunk Mat Set (die cut Maroon felt)	1962 Starfire Convertible	299.00 7 pc.
TM62CB	Trunk Mat Set (die cut Blue felt)	1962 Starfire Coupe	299.00 7 pc.
TM62CVB	Trunk Mat Set (die cut Blue felt)	1962 Starfire Convertible	299.00 7 pc.
TCK634C	Trunk Cardboard Set (black)	1963-64 Starfire Holiday Coupe	173.00 2 pc.
TCK634CV	Trunk Cardboard Set (black)	1963-64 Starfire Convertible	173.00 4 pc.
TM634C	Trunk Mat (die cut black felt material)	1963-64 Starfire Holiday Coupe	299.00 7 pc.
TM634CV	Trunk Mat (die cut black felt material)	1963-64 Starfire Convertible	299.00 7 pc.
TM634CBL	Trunk Mat Set (Blue felt)	1963-64 Starfire Coupe	299.00 7 pc.
TCK634CBL	Trunk Cardboard Set (Blue)	1963-64 Starfire Coupe	173.00 2 pc.
TM634CVBL	Trunk Mat Set (Blue felt)	1963-64 Starfire Convertible	299.00 7 pc.
TCK634CVBL	Trunk Cardboard Set (Blue)	1963-64 Starfire Convertible	173.00 4 pc.
TM634CM	Trunk Mat Set (Maroon felt)	1963-64 Starfire Coupe	299.00 7 pc.
TCK634CM	Trunk Cardboard Set (Maroon)	1963-64 Starfire Coupe	173.00 2 pc.
TM634CVM	Trunk Mat Set (Maroon felt)	1963-64 Starfire Convertible	299.00 7 pc.
TCK634CVM	Trunk Cardboard Set (Maroon)	1963-64 Starfire Convertible	173.00 4 pc.
TM65HT	Trunk Mat (die cut rubber aqua houndstooth)	1965 88 Hol. Cpe & Conv.	99.00
TM65C	Trunk Mat (die cut rubber aqua houndstooth)	1965-66 98 Convertible	93.00 3pc.
TM66B	Trunk Mat (die cut vinyl houndstooth)	1966 88-Starfire Holiday Coupe and Conv.	79.50
TM67B	Trunk Mat (die cut vinyl houndstooth)	1967-68 88 Holiday Coupe and Convertible	79.50
THC678	Trunk Hinge Box Covers (aqua houndstooth)	1967-68 88 Convertible	43.00 pr.
TM68C	Trunk Mat (die cut black felt material)	1967-68 98 Holiday Coupe and Convertible	89.50
TM69B	Trunk Mat (die cut gray green material)	1969-70 88 Holiday Coupe and Convertible	79.50
TM70C	Trunk Mat (die cut black felt material)	1969-70 98 Holiday Coupe and Convertible	89.50
TM70E	Trunk Mat (die cut black felt material)	1970 Toronado	89.50 7pc.
TM715B	Trunk Mat (die cut black felt material)	1971-75 Delta 88 Holiday Coupe and Conv.	98.50

1965-70 88-98 Accessory Rubber Trunk Mat:

Accurate reproduction of an accessory which is highly desired by collectors. This mat has the correct ribbed pattern and the word 'OLDSMOBILE' molded into the rubber. Available in black only. Pictured at top of page.

TRM672 Accessory 'Oldsmobile' Rubber Trunk Mat 1965-70 88-98 189.00

Trunk Weatherstrip, Trunk Lid Bumpers, Spare Tire & Jack Parts

Trunk Weatherstripping: We offer the finest quality black sponge rubber weatherstrip available. No unsightly splice marks or oversize extrusions that make closing the trunk lid a difficult task. All 1961-75 2 doors use 18 feet, 1961-75 4 doors use 15 feet and 1966-75 Toronados use 12 feet.

TWL75B-18	Trunk Weatherstrip	1961-70 88-98-Starfire (18 foot piece)	36.00
TWL75E-18	Trunk Weatherstrip	1971-76 88-98 (18 foot piece)	36.00
TWL75	Trunk Weatherstrip	1961-75 4 Dr models & Toronado	2.00 ft.



TB65

TLG61	Trunk Lock Gasket	1961-68 all	3.50
TLG68	Trunk Lock Gasket	1969-70 88	3.50



TB61	Trunk Lid Bumper	1961-68 all	3.00 ea.
TB69	Trunk Lid Bumper	1969-75 all	3.00 ea.



TB63



Trunk Floor Rubber Plugs: Two different designs, both fit 1" hole in sheetmetal.

TB63	Floor pan plug	1963-69 all	4.50 ea.
TB65	Floor pan plug	1969-75 all	5.00 ea.

Jack Shaft Insulator and Jack Lift Pad:

JRI68	Jack Shaft Rubber Insulator	1968-72 88-98	12.50
JLP682	Rubber Jack Lift Pad	1968-72 88-98	13.50



Hold-Down Parts for Spare Tire:


ST6693	Spare Tire Threaded Retaining Rod (cut to length)	1966-75 all	12.00
ST6516	Spare Tire Retaining Wing Nut	1965-75 all	9.50



ST6516

Spare Tire Cover and Retainer: Pressboard cover with aqua and black houndstooth pattern. Fits 1963-64 Starfire Convertible and 1965-68 all Convertibles. Does not match the felt 1963-66 Trunk Material.

STC61	Pressboard Spare Tire Cover, houndstooth	29.50
ST618	Spare Tire Cover Retainer, Cadmium plated as original	24.50



ST618

Washer Fluid Jars and Related Parts

Correct triangle glass bottle comes complete with metal cap and GM Optikleen decal. Used on all 1961-67 models. Translucent white plastic fluid jar for 1971-77 models includes the black cap.



WJ7393



OKB647	Optikleen Triangular Glass Bottle with cap and decal	1961-67 all	37.50
OKBC647	Optikleen Bottle Metal Cap only	1961-67 all	8.50
OB647	Optikleen Bottle Metal Bracket	1961-67 all	27.00
DC47	Optikleen Decal for glass jar (moisten back to stick)	1961-67 all	8.50
WJ7393	Plastic Washer Fluid Jar with Cap	1971-77 all models	29.50
WJC6894	Windshield Washer Jar Cap	1966-75 all models	5.50
WJF6421	Windshield Washer Jar Filter	1964-75 all models	5.50
4460	Windshield Washer Hose to Pump and Filter	1961-75 all models	2.00 ft.
4457	Windshield Washer Hose to Nozzles	1961-75 all models	2.00 ft.



1963-75 Washer Pump Repair Kit: Contains the necessary parts to rebuild your inoperative washer pump. The correct style and application pumps are no longer available, and this is a viable alternative to changing the entire wiper motor and washer pump assembly.

WPRK638	Washer Pump Repair Kit	1963-75 all models	24.50 kit
----------------	------------------------	--------------------	-----------



RUBBER PARTS

HB59 Hood to Fender Bumper:

1961-62 all models 5.00 ea.



HB65 Hood to Fender Bumper:

1963-66 all, 67 Toronado 4.50 ea.



HB68 Hood to Fender Bumper:

1968-70 Toronado, 1969 88-98 4.50 ea.



HB68A Hood to Fender Bumper:

1968 88-98 5.00 ea.



HB70 Hood to Fender Bumper:

1970-75 all 4.50 ea.



HB73

HB73 Hood Bumper & Adjusting Stud:

(Front) 2 per car 1961-67 all 9.50 ea.



HB74 Hood Bumper & Adjusting Stud:

(Front) 2 per car. 1968-75 all 9.50 ea.

DB59 Door Lock Pillar Bumper:

1961-64 all 2 Doors Uses 4 per car. 5.00 ea.



DB66 Door Lock Pillar Bumper:

1966-70 Toronado 4.50 ea.



DB90 Door Lock Pillar Bumper:

1965-75 all exc 1966-70 Toronado. 3.50 ea.



DB41 Door Lock Pillar Bumper:

Same shape as DB90 but larger. Fits many 1965-70 models. 4.00 ea.

Fender Skirt Rubber: Correct extrusion and lengths for the following applications.

FS12 Fender Skirt Rubber 1963-64 98 79.00 pr.

FS13 Fender Skirt Rubber 1965-66 98 83.00 pr.

FS15 Fender Skirt Rubber 1971-76 98 39.00 pr.



Door Jamb Light Switch Rubber Boot:

Fits 1961-64 88-98-Starfire, most 2 & 4 door models. Uses 2 or 4 per car.

DJB614 Light Switch Boot 6.00 ea.



Door Handle and Door Lock Cylinder Gaskets:

Die cut per original. One set will service two handles.

DH612 Door Handle Gasket (4 pc)

1961-70 all exc. 1969-70 Royale 6.50 set

DH716 Door Handle Gasket (4 pc)

1971-76 all models 9.50 set

DCG61 Door Lock Cylinder Gasket

Fits 1961-77 all models 3.50 ea.



DHS66 Bottom Drain Hole Sealing Strip:

Fits 1962-72 all models. 2 used per door. 4.50 ea.



RPC64 Rocker Panel Inner Rubber Cover:

For 1964-68 all models. Used as a drain hole cover in rear wheel well. 5.00 ea.



Fuel Tank Door Bumpers: Reproduced exactly as original for the correct application.

GB35 Bumper 1966-67 Toronado and 1967-68 98 (uses one only) 3.50

GB40 Bumpers 1965-67 all 88's 9.00 pr.

GB50 Bumpers 1966 98, 1968-70 88's, 1969-70 98 9.00 pr.



Headlight Bucket to Body Bumper Stop:

For 1966-67 Toronado.

Uses 4 per car.

HL66T Rubber Stop 3.50 ea.



Seat Back Bumpers: Fits 1961-72.

SB65 Oval Seat Bumper 7.00 ea.

SB61 Round Seat Bumper 6.50 ea.



1961-75 RUBBER WEATHERSTRIPPING

Convertible Roof Rail Weatherstrips: 1961-75 Convertible Roof Rail Weatherstrips and Windshield Pillar

Weatherstrips are available to seal your convertible top. Roof Rail Weatherstrips are compression molded rubber with steel framing and have a better than original fit and appearance.

RR614	Roof Rail Weatherstrip (7 piece set)	1961-64 88-Starfire Convertibles	309.00 set
RR614C	Roof Rail Weatherstrip (7 piece set)	1961-64 98 Convertibles	521.00 set
RR656	Roof Rail Weatherstrip (7 piece set)	1965-66 88-Starfire Convertibles	329.00 set
RR650	Roof Rail Weatherstrip (7 piece set)	1965-70 98 Convertibles	349.00 set
RR670	Roof Rail Weatherstrip (7 piece set)	1967-70 88 Convertibles	349.00 set
RR715	Roof Rail Weatherstrip (5 piece set)	1971-75 88 Convertibles	229.00 set
WP620	Windshield Pillar Weatherstrip	1961-62 All Convertibles	84.50 pr.
WP630	Windshield Pillar Weatherstrip	1963-64 All Convertibles	84.50 pr.
WP650	Windshield Pillar Weatherstrip	1965 All Convertibles	84.50 pr.
WP668	Windshield Pillar Weatherstrip	1966-68 All Convertibles	93.00 pr.
WP690	Windshield Pillar Weatherstrip	1969-70 All Convertibles	84.50 pr.
WP715	Windshield Pillar Weatherstrip	1971-75 All 88 Convertibles	84.50 pr.



2 Door Hardtop Roof Rail Weatherstrips:

Correct ready-to-install weatherstrips that include inserted tabs and molded ends for accurate installation.

RR61	Roof Rail Weatherstrip	1961 88 Holiday Coupes	203.00 pr.
RR62	Roof Rail Weatherstrip	1962 88-Starfire Holiday Coupes	89.00 pr.
RR63	Roof Rail Weatherstrip	1963-64 88 Holiday Coupes	89.00 pr.
RR63C	Roof Rail Weatherstrip	1963-64 98 Holiday Coupe	177.00 pr.
RR634SF	Roof Rail Weatherstrip	1963-64 Starfire & Jetstar 1 Hol.Cpe	203.00 pr.
RR65	Roof Rail Weatherstrip	1965-66 88-Starfire Holiday Coupes	173.00 pr.
RR65C	Roof Rail Weatherstrip	1965-68 98 Holiday Coupes	89.00 pr.
RR67B	Roof Rail Weatherstrip	1967-68 88 Holiday Coupes	89.00 pr.
RR690B	Roof Rail Weatherstrip	1969-70 88 Holiday Coupes	89.00 pr.
RR713B	Roof Rail Weatherstrip	1971-73 88 Holiday Coupes	206.00 pr.
RR716	Roof Rail Weatherstrip	1971-74 98 HC, 1974-76 88 HC	193.00 pr.
RR756C	Roof Rail Weatherstrip	1975-76 98 Holiday Coupes	115.00 pr.
RR66ET	Roof Rail Weatherstrip	1966-70 Toronado	89.00 pr.



2 Door Hardtop and Convertible Molded Door Weatherstrips:

All weatherstrips are like the originals with molded ends and inserted retaining clips.

DW61	Door Weatherstrips	1961-62 All Hol. Cpe and Conv.	93.00 pr.
DW63	Door Weatherstrips	1963-64 All Hol. Cpe and Conv.	93.00 pr.
DW66	Door Weatherstrips	1965-66 All Hol. Cpe.and Conv.	93.00 pr.
DW66ET	Door Weatherstrips	1966-70 Toronado	93.00 pr.
DW67BC	Door Weatherstrips	1967-68 All Hol. Cpe. and Conv.	93.00 pr.
DW69BC	Door Weatherstrips	1969-70 All Hol. Cpe and Conv.	93.00 pr.
DW715	Door Weatherstrips	1971-75 88 Hol. Cpe. and Conv.	93.00 pr.



Door Body Pillar Sealing Strips:

Located directly under the Quarter Window Vertical Weatherstrips on the rear door jamb area.

BP571	Pillar Sealing Strips	1961-64 88-98-Starfire Convertibles	73.00 pr.
BP877	Pillar Sealing Strips	1961-64 88-98-Starfire Holiday Coupes	69.00 pr.
BP844	Pillar Sealing Strips	1965-66 88-98-Starfire Holiday Coupes and Conv.	64.50 pr.
BP667T	Pillar Sealing Strips	1966-67 Toronado	43.00 pr.
BP939	Pillar Sealing Strips	1967-68 88-98 Holiday Coupes and Convertibles	94.00 pr.
BP690	Pillar Sealing Strips	1969-70 88-98 Holiday Coupes and Convertibles	46.50 pr.
BP715	Pillar Sealing Strips	1971-75 88-98 Holiday Coupes and Convertibles	43.50 pr.



2 Door Hardtop and Convertible Quarter Window Weatherstrips:

Fits vertical leading edge of quarter window. Metal inserted rubber as original equipment.

QW614A	Quarter Window Weatherstrips	1962 88-Starfire Holiday Coupes, 1963-64 88 Holiday Coupes	64.00 pr.
QW614B	Quarter Window Weatherstrips	1961-64 88-Starfire Convertibles	67.00 pr.
QW614C	Quarter Window Weatherstrips	1961-64 98 Convertibles	67.00 pr.
QW614D	Quarter Window Weatherstrips	1962-64 98 Holiday and Sport Coupes	67.00 pr.
QW614E	Quarter Window Weatherstrips	1961 88-98 Holiday Coupes, 1961-62 88 Holiday Sedans, 1963-64 Starfire-Jetstar I Holiday Coupes	65.00 pr.
QW656B	Quarter Window Weatherstrips	1965-66 98 Coupes and Conv., 1965-66 Starfire-Jetstar I Holiday Coupes	97.00 pr.
QW656C	Quarter Window Weatherstrips	1965-66 88 Holiday Coupes and Convertibles 1965 Starfire Convertible	95.00 pr.
QW670T	Quarter Window Weatherstrips	1966-70 Toronado	43.00 pr.
QW678B	Quarter Window Weatherstrips	1967-68 88 Holiday Coupes	97.00 pr.
QW678C	Quarter Window Weatherstrips	1967-68 88-98 Convertibles	32.50 pr.
QW8485	Quarter Window Weatherstrips	1969-70 88-98 Holiday Coupes and Convertibles	23.50 pr.
QW715	Quarter Window Weatherstrips	1971-75 88 Holiday Coupes and Convertibles	59.50 pr.
QW715C	Quarter Window Weatherstrips	1971-75 98 Holiday Coupes	80.00 pr.

4 Door Hardtop Roof Rail Weatherstrips (no center post):

RR612	Roof Rail Weatherstrips	1961-62 88 Holiday Sedans	210.00 pr.
RR938	Roof Rail Weatherstrip	1961 98 4 window 4 Door Hardtop	231.00 pr.
RR634	Roof Rail Weatherstrips	1963-64 88 Holiday Sedans	89.00 pr.
RR634C	Roof Rail Weatherstrips	1963-64 98 4 Window Holiday Sedans	240.00 pr.
RR634CS	Roof Rail Weatherstrips	1963-64 98 6 Window Holiday Sedans	199.00 pr.
RR656B	Roof Rail Weatherstrips	1965-66 88 Holiday Sedans	195.00 pr.
RR6904B	Roof Rail Weatherstrip	1969-70 88 & 98 4 Door Hardtop	89.00 pr.
RR658	Roof Rail Weatherstrips	1965-66 98 Holiday Sedans	99.00 pr.
RR714B	Roof Rail Weatherstrip	1971-74 88 Holiday Sedans	286.00 pr.
RR714C	Roof Rail Weatherstrips	1971-74 98 Holiday Sedans	272.00 pr.
RR146	Roof Rail Weatherstrip	1975-76 98 Holiday Sedans	297.00 pr.

4 Door Hardtop (no post) Molded Door Weatherstrip:

DW61SDF	Front Door Weatherstrip	1961-62 88 & 98 Holiday Sedans	209.00 pr.
DW937R	Rear Door Weatherstrip	1961 98 Sport Sedan (style 3839)	223.00 pr.
DW61SDR	Rear Door Weatherstrip	1961-64 All 88 Holiday Sedans	179.00 pr.
DW61CSDR	Rear Door Weatherstrip	1961-62 All 98 Holiday Sedans (not Sport Sedan)	213.00 pr.
DW63SDF	Front Door Weatherstrip	1963-64 88 & 98 Holiday Sedan	125.00 pr.
DW63CSDR	Rear Door Weatherstrip	1963-64 All 98 Holiday Sedans (not Sport Sedan)	159.00 pr.
DW67SDF	Front Door Weatherstrip	1965-68 All 88 & 98 Holiday Sedans	199.00 pr.
DW656HSR	Rear Door Weatherstrip	1965-66 98 Holiday Sedan	227.00 pr.
DW153	Front Door Weatherstrip	1969-70 88 & 98 4 Door Hardtop	273.00 pr.
DW154	Rear Door Weatherstrip	1969-70 88 4 Door Hardtop	279.00 pr.
DW213	Rear Door Weatherstrip	1969-70 98 4 Door Hardtop	241.00 pr.
DW716	Front Door Weatherstrip	1971-76 88 & 98 4 Door Hardtop	295.00 pr.
DW852	Rear Door Weatherstrip	1971-74 98 4 Door Hardtop	249.00 pr.
DW406	Rear Door Weatherstrip	1975-76 98 4 Door Hardtop	245.00 pr.
DW781	Rear Door Weatherstrip	1971-74 88 4 Door Hardtop	249.00 pr.
DW782	Rear Door Weatherstrip	1975-76 88 4 Door Hardtop	250.00 pr.



2 and 4 Door Sedan (With Post) Door Weatherstrip:

Molded door weatherstrips available for the following 2 and 4 door sedans. Due to limited demand, not all applications will be in stock. Please keep this in mind when ordering and allow approximately 2 weeks for delivery. For applications not listed here, order part number **DW85A**. DW85A is molded in the correct configuration with nylon push-in tabs pre-inserted. Two door models require approximately 28 feet, while 4 door models use approximately 28 feet for the front doors and 26 feet for the rear doors.

DW85A	Door Weatherstrip	1961-75 Models Using Push-in Tab Type	4.00 ft.
DW61PC	Door Weatherstrip	1961 2 Door Sedans	149.00 pr.
DW614SDF	Front Door Weatherstrip	1961-64 88-98 4 Door Sedans and 88 Wagons	119.00 pr.
DW614SDR	Rear Door Weatherstrip	1961-64 88-98 4 Door Sedans	89.00 pr.
DW614SWR	Rear Door Weatherstrip	1961-64 88 Wagons	129.00 pr.
DW656F	Front Door Weatherstrip	1965-66 88 4 Door Sedans	89.00 pr.
DW656R	Rear Door Weatherstrip	1965-66 88 4 Door Sedans	89.00 pr.
DW705	Front Door Weatherstrip	1965-66 98 4 Door Sedans	217.00 pr.
DW552	Rear Door Weatherstrip	1965-66 98 4 Door Sedans	209.00 pr.
DW678F	Front Door Weatherstrip	1967-68 88 4 Door Sedans	100.00 pr.
DW678R	Rear Door Weatherstrip	1967-68 88 4 Door Sedans	106.00 pr.
DW690SDF	Front Door Weatherstrip	1969-70 88 4 Door Sedans	179.00 pr.
DW690SDR	Rear Door Weatherstrip	1969-70 88 4 Door Sedans	203.00 pr.
DW690CF	Front Door Weatherstrip	1969-70 98 4 Door Sedans	230.00 pr.
DW716SDF	Front Door Weatherstrip	1971-76 88 4 Door Sedans and Custom Cruiser	89.00 pr.
DW714SDR	Rear Door Weatherstrip	1971-74 88 4 Door Sedans	89.00 pr.
DW756SDR	Rear Door Weatherstrip	1975-76 88 4 Door Sedans	161.00 pr.
DW716SWR	Rear Door Weatherstrip	1971-76 Custom Cruiser	89.00 pr.

DW85A



WINDOW CHANNEL / SWEEPERS

Universal Window Sweepers: These sweepers can be used where kits are not available.

C505 sweepers have a rubber strip with a chrome bead and metal backing, trim to fit.

C667T has a round black bead with metal backing and black fuzzy material, trim to fit.

C505	Outer Window Sweepers	1961-64 All without garnish molding (4 ft. length)	29.50 ea.
C505A	Outer Window Sweepers	1961-64 All without garnish molding (2 ft. length)	18.50 ea.
C667T	Outer Window Sweepers	1966-67 Toronado (4 ft. length)	39.50 ea.

C505

C667T



Window Sweeper Kits: The following sweeper kits are now available, trimmed to correct size and ready to install.

CK6288CV	Window Sweeper Kit (8 pcs)	1962 88 convertible	162.00 kit
CK63488CV	Window Sweeper Kit (8 pcs)	1963-64 88 convertible	162.00 kit
CK65698CV	Outer Window Sweepers	1965-66 98 convertible	169.00 kit
CK66SFC	Outer Window Sweepers	1966 Starfire hardtop	169.00 kit
CK6798LS	Outer Window Sweepers	1967 98 LS 4 dr htop w/ reveal molding	169.00 kit
CK678AB4	Outer Window Sweepers	1967-68 88 convertible	169.00 kit
CK68884	Outer Window Sweepers	1968 88 4 dr htop	169.00 kit
CK6898HC	Window Sweeper Kit (8 pcs)	1968 98 holiday coupe	128.00 kit
CK6898CV	Window Sweeper Kit (8 pcs)	1968 98 convertible	128.00 kit
CK7098CV	Window Sweeper Kit (8 pcs)	1970 98 convertible	128.00 kit
CK690CV	Window Sweeper Kit (8 pcs)	1969-70 98 convertible w/ reveal molding	169.00 kit
CK690T	Outer Window Sweepers	1969-70 Toronado	169.00 kit
CK715A4	Outer Window Sweepers	1971-75 88 convertible, NO reveal molding	193.00 kit
CK715A4R	Outer Window Sweepers	1971-75 88 convertible, with reveal molding	129.00 kit



Front Windshield Rubber Channel: One piece endless ring. Due to limited demand, not all applications will be in stock. Please bear this in mind when ordering and allow for approximately 2 weeks delivery time.

WR055	Windshield Channel	1961-62 All 98 exc. Conv., 1962 4 Doors exc. 98 Sport Sedan	194.00
WR858	Windshield Channel	1961-62 88-98-Starfire Convertibles	171.00
WR793	Windshield Channel	1962 88-98-Starfire Holiday Coupes, 1962 98 Sport Sedan	183.00
WR851	Windshield Channel	1963-64 88-98-Starfire Convertibles	165.00
WR788	Windshield Channel	1963 Starfire Holiday Coupes, 1964 Starfire-Jetstar I Holiday Coupes, 1963-64 88 Holiday Sedans	163.00
WR731	Windshield Channel	1963-64 88-98 Holiday Coupes, 98 Sport Sedans (4 window)	157.00
WR286	Windshield Channel	1963-64 88 4 Door Post Sedans and Wagons, 98 4 Door Post Sedans and Luxury Sedans	229.00

Rear Window Rubber Channel: One piece endless ring. Due to limited demand, not all applications will be in stock. Please bear this in mind when ordering and allow for approximately 2 weeks delivery time.

RW823	Rear Window Channel	1961 98 Holiday Coupe	225.00
RW700	Rear Window Channel	1961 88 2 and 4 Door Post Sedans	235.00
RW634	Rear Window Channel	1961 88 Holiday Coupes	191.00
RW387	Rear Window Channel	1961-62 98 4 Door Post Sedans and Holiday Sedans	226.00
RW559	Rear Window Channel	1962 88- Starfire Holiday Coupes, 1963-64 88 Holiday Coupes	157.00
RW816	Rear Window Channel	1963-64 98 Sports Sedans (4 window) and Holiday Coupes	225.00
RW507	Rear Window Channel	1962-64 88 4 Door Post Sedans	185.00
RW067	Rear Window Channel	1963-64 Starfire Holiday Coupes	162.00

Front Door Vent Window Weatherstrip Set:

Applies to most 1961-68 Full Size Oldsmobiles. Tooled in curved molds for correct fit. Set of 4 pieces.

VR614B	Vent Weatherstrip Set	1961-62 88-98-Starfire Holiday Coupes and Conv.	149.00 set
VR612	Vent Weatherstrip Set	1961-62 88-98 2 and 4 Door Post Sedans	183.00 set
VR634	Vent Weatherstrip Set	1963-64 Starfire Convertibles, 1963-64 88-98 Holiday Coupes and Convertibles, 1963-64 98 Sports Sedans	159.00 set
VR634C	Vent Weatherstrip Set	1963 Starfire Holiday Coupes, 1964 Starfire-Jetstar I Holiday Coupes, 88 Holiday Sedans	226.00 set
VR634S	Vent Weatherstrip Set	1963-64 88-98 4 Door Sedan and Wagon	149.00 set
VR658BC	Vent Weatherstrip Set	1965-68 88-98 Holiday Coupes and Convertibles	169.00 set
VR658	Vent Weatherstrip Set	1965-68 88 4 Door Post Sedans	204.00 set
VR595	Vent Weatherstrip Set	1965-68 98 4 Dr Sedan (body style 8469 & 8669)	238.00 set



Flexible Vertical Vent Window Channel: For use in all 1965-68 2 Doors. This part is used exclusively for vent frame to front door window channeling. Sold in pairs of 35" strips that include the top molded end bumper. Trim to proper length.

C909-645	Vertical Ventilator Strip	1965 All Holiday Coupe and Convertible	49.00 pr.
C909-667	Vertical Ventilator Strip	1966-67 All Holiday Coupe and Convertible	49.00 pr.
C909-680	Vertical Ventilator Strip	1968 All Holiday Coupe and Convertible	49.00 pr.



Trunk Weatherstripping: We offer the finest quality black sponge rubber weatherstrip available. No unsightly splice marks or oversize extrusions that make closing the trunk lid a difficult task. All 1961-75 2 doors use 18 feet, 1961-75 4 doors use 15 feet and 1966-75 Toronados use 12 feet.

TWL75B-18	Trunk Weatherstrip	1961-70 88-98-Starfire (18 foot piece)	36.00
TWL75E-18	Trunk Weatherstrip	1971-76 88-98 (18 foot piece)	36.00
TWL75	Trunk Weatherstrip	1961-75 4 Dr models & Toronado	2.00 ft.



8008 3M Weatherstrip Adhesive:

Black rubber to metal cement, 5 ounce tube.

13.50 ea.



fusickautomotiveproducts.com

sales@fusick.com

RUBBER BUMPER FILLERS

1962-68 88-98-Toronado Bumper Fillers: Ornamental rubber parts located on either side of the front and rear bumpers. A necessary replacement when installing new or rechromed bumpers. Sold in pairs only.

BF62BCF	Front Bumper Fillers	1962 all models	45.00 pr.
BF62BCR	Rear Bumper Fillers	1962 all except. Station Wagon	39.50 pr.
BF63BCF	Front Bumper Fillers	1963 all models	42.50 pr.
BF63BR	Rear Bumper Fillers	1963 all except 98 and Wagons	39.50 pr.
BF63CR	Rear Bumper Fillers	1963 98	45.00 pr.
BF64BCF	Front Bumper Fillers	1964 all models	48.00 pr.
BF64CR	Rear Bumper Fillers	1964 98 models only	45.00 pr.
BF65BCF	Front Bumper Fillers	1965 all models	42.50 pr.
BF65BR	Rear Bumper Fillers	1965 all except 98	37.50 pr.
BF66BCF	Front Bumper Fillers	1966 all except Toronado	39.50 pr.
BF66BR	Rear Bumper Fillers	1966 all except Toronado and 98	41.50 pr.
BF66CR	Rear Bumper Fillers	1966 98 models only	41.50 pr.
BF66EUF	Front Upper Bumper Fillers	1966-67 Toronado only	48.00 pr.
BF66ELF	Front Lower Bumper Fillers	1966-67 Toronado only	42.50 pr.
BF66ER	Rear Bumper Fillers	1966-67 Toronado only	45.00 pr.
BF678CR	Rear Bumper Fillers	1967-68 98 models only	37.50 pr.
BF68BR	Rear Bumper Fillers	1968 88 models only	42.50 pr.



TORONADO TRUNK RUBBER DRAIN TUBES



These drain tubes fit all 1966-70 Toronados and allow the water to drain through your trunk. Missing or deteriorated Drain Tubes are the cause of most of the trunk rust problems in 1966-70 Toronados. The ends are molded as original and the drain tubes come with the proper size clamps. The lower end has been left open to allow free flow of debris. Sold in pairs only.

7630702/3 1966-70 Toronado Duct Panel Drain Tubes 85.00 pr.

We are quoting the bottom hoses used on 1966-70 Toronado in conjunction with the 7630702/3 drain tubes, please inquire.

Dome Lenses, Courtesy Lamp Lenses and Housings

CL877 Courtesy Lamp Lens at Rear Seat Arm Rest Area on 1961-70 Convertibles. Used with CLH622 Housing. Lens measures 1 1/2" X 1 1/4" 8.50 ea.




CLH622 Courtesy Lamp Housing: Located in lower rear arm rest area. Plated with bright chrome. This part is difficult to replate without losing the line detail. Fits all 1961-70 Convertibles. Companion lens is CL877 above. 28.50 ea.



DL505 Dome light Lens on side roof rail: Fits 1961-63 Super 88 Wagons on either side at side roof rail area above the side windows. Measures 3 1/2" X 1 1/2". 11.00 ea.



DL506 Center Roof Dome Light Lens: Fits All 1961-64 with a Dome Light in the center of the roof except for wagons. Opaque lens measures 4 1/2" X 2" and has a double raised line down the center. 13.50



1961-64 Side Roof Dome Light Lens: Fits 1961-64 models except conv. & wagons in roof rail area. Lens measures 6 1/4" long X 1 1/2" wide at widest point. Uses two lenses per car.

DL591 Side Roof Dome Lens 1961-64 21.50 ea.

Door Panel Courtesy Lamp Lenses:

4 to 8 lenses used per car. Lamp housing uses one red and one white lens per side. Fits 1964 Starfire-Jetstar I, 1965 Starfire-Jetstar I-98 LS, 1966 Starfire-98 LS, 1967 Delta 88 Custom-98 Conv and LS, 1968 Toronado-Delta 88 Custom-98 Conv and LS, 1969 98 Conv and LS, 1970 Delta 88 Royale-98 Convertible-Toronado Custom, 1971-75 Delta 88 Royale Coupe and Conv, 1971-74 98 Sedans, 1971-74 Toronado.

CL32W	White Courtesy Door Panel Lens	See Above	9.50 ea.
CL33R	Red Courtesy Door Panel Lens	See Above	9.50 ea.
CL30W	White Courtesy Door Panel Lens	1966-67 Toronado	9.50 ea.
CL31R	Red Courtesy Door Panel Lens	1966-67 Toronado	9.50 ea.

CL600 Courtesy Lens at rear sail panel. 1962-65 All Holiday Coupes, 1966-68 All except Toronado and Convertibles. Lens measures 2" diameter. 2 used per car. 8.50 ea.



CLH627 Courtesy Light Housing: Mounts on inside rear sail panel. Excellent chrome finish with correct ribbed section and white painted inside. Fits 1962-64 all except wagons and 98 Luxury Sedan, 1965 All except Starfire & Wagons, 1966-67 Except 98 Luxury Sedan & Toronado, 1968 88s & 98 Hol. Cpe., Hol. Sedan, Town Sedan. Companion lens is CL600. 49.50 ea.



DL68 Side Roof Dome Lens 1965 98 4 Doors, 1965-66 Starfire Hol Cpe, 1966-67 98 Luxury Sedans. Lens measures 6" x 1 1/2" and has four mounting tabs with correct lines in lens. 9.50 ea.

CL819 Courtesy Lamp Lens at Rear Upper Shelf Area: 1969-70 Delta 88-Delta 88 Custom Holiday Coupe and Holiday Sedan, 1969-70 98 Holiday Coupe, Holiday Sedan and Town Sedan, 1971-72 Delta 88-Delta 88 Custom-Delta 88 Royale Holiday Coupe and Holiday Sedan, all 1971-72 98 and Toronado models. 9.50 ea.



CL326 Courtesy Lamp Lens at Rear Seat Arm Rest Area 1971-75 Delta 88 Convertible. Opaque lens measures 2" X 1 1/4" 9.50 ea.



Interior Carpet Sets

1961-64 88 & 98 Carpet Sets: 1961-62 Dynamic 88 and Super 88 used a molded Tuxedo carpeting which is the appropriate loop carpet color with black strands interwoven into the material. 1963-64 Dynamic 88, Super 88 and 98 models were equipped with a 80/20 loop carpeting. All carpet sets are sold on a custom order basis, call or send for color samples before ordering. **NO RETURNS ON CUSTOM ORDERED CARPET SETS.**

1966-76 Toronado Carpet Sets: 1966-73 Toronados came with a 80/20 loop Carpeting while 1974-76 Toronados had pile carpeting. Colors available for the Pile Carpeting will be the same as listed below for 1965-75 88s & 98s. All carpet sets are sold on a custom order basis, call or send for color samples before ordering. **NO RETURNS ON CUSTOM ORDERED CARPET SETS.**

Tuxedo Carpeting

1961-62 Tuxedo Carpeting available in the following colors, \$ **489.00** set

Copper/Black #F-6	Green/Black #983
Blue/Black #D-4	Red/Black #C-3
Fawn/Black #1076	Turquoise/Black #B-2

80/20 Loop Carpeting

1963-64, 1966-73 Toronado 80/20 Loop carpeting available in the following colors, \$ **289.00** set

Black #01-003	Beige #11-002
Green #8-1011	Blue #16-013
Medium Green #38-1900	Medium Blue #6-016
Gray #22-893	Red #41-6364
Dark Gray #35-1956	Turquoise #5-883
Fawn #19-020	Copper #39-1966



1965-75 88, 98 & Starfire Carpet Sets: All sets include backing, harmonizing heel pad and binding. Carpets are cut to manufacturer's specifications with pressure molded floor pan areas for correct fit. Carpets are not in stock, so allow 2-3 weeks for delivery. Since carpets are a special order item, we require you to approve a color sample before we place your order. Send a self addressed stamped envelope for any carpet samples, or request samples when you place an order. **NO RETURNS ON CUSTOM ORDERED CARPET SETS.** Extra carpet material by the yard (36" X 72") is available for 55.00 per yard. Specify number of yards required and order by color number of carpet.

1965-73 88s & 98s LOOP CARPET 289.00 Set


01-003 Black	11-002 Light Saddle
41-6364 Red	12-1021 Dark Saddle
4-105 Green/Gold	13-010 Maroon
5-883 Turquoise	45-1970 Dark Green
16-013 Dark Blue	20-022 Gold
10-017 Dark Brown	

1974-76 88s & 98s PILE CARPET 249.00 Set

801 Black	875 Oxblood
819 Dark Blue	825 Maroon
807 Dark Grey	830 Buckskin
820 Saddle	810 Brown
809 Green	1804 Silver
815 Red	

Sound Deadener Package: This is the thick, tar like rubber material found between the carpet and the body floor pan. Sound Deadener should be replaced when installing new carpet.

SDM20	Sound Deadener Package	1961-64 all 88/Starfire	109.00
SDM30	Sound Deadener Package	1965-70 all 88/Starfire	109.00
SDM50	Sound Deadener Package	1971-76 all 88s	109.00



Door Panel Reflectors: Red reflective lenses with chrome trim attaches to lower door panels on many 1968-80 Oldsmobile 98 and Toronado models.

DPR702	Door Panel Reflector	1968-80 models	40.00 ea.
---------------	----------------------	----------------	-----------





1961-75 88, 98, Starfire and Toronado Sill Plates: Aluminum sill plates add the final touch to your new carpet installation. High quality aluminum stampings with correct textures and designs for most 1961-75 Oldsmobile models. New sill plates include the Fisher Body emblem and fastening screws.

SP614	Door Sill Plates	1961-64 all 2 Doors	95.00 pr.
SP6144D	Door Sill Plates	1961-64 all 88 4 Door Sedans & Wagons	129.00 set
SP6667	Door Sill Plates	1965-70 2 Doors except Toronado	95.00 pr.
SP650	Door Sill Plates	1965-70 all 4 Door models	139.00 set
SP670T	Door Sill Plates	1966-70 Toronado	119.00 pr.
SP7180	Door Sill Plates	1971-75 all 2 Doors and Toronado	129.00 pr.
1799	Door Sill Plate Screw Package	all models (pkg. of 10, included with above)	4.50 pkg.



SP614



SP670T




SP7180



1965-70 88 & 98 Rubber Floor Mats

The Rubber floor mats fit 1965-70 88 and 98 models. Mats are available in black only. Front mats have the word 'OLDSMOBILE' molded in the rubber as original, and are licensed by General Motors. Sold in pairs for front or rear, or in sets of four.

FM647S	Floor Mat Set	1965-70 88-98	219.00 set
FM647F	Front Mats (pair)	1965-70 88-98	159.00 pr.
FM647R	Rear Mats (pair)	1965-70 88-98	79.00 pr.



1966 Toronado Driver Side Rubber Floor Mat: Rubber floor mat insert is used on the front drivers side only. Installs inside chrome trim and sheetmetal pan that attaches onto the floor. Mat features correct ribbed design in black rubber and includes a die cut sheet of foam padding for the underside, also includes a hardware package to re-install assembly onto floor pan.


FM66T	Front Driver's Floor Mat	1966 toronado	179.00
--------------	--------------------------	---------------	--------



underside

1961-64 Firewall Insulators: High quality insulation bonded to a molded, textured, black plastic shell. All holes are pre-punched for steering column and heater box. Fits all 1961-64 88-98-Starfire models.

FP612	Firewall Insulator	1961-62 all models	341.00
FP634	Firewall Insulator	1963-64 all coupes	222.00
FP634CV	Firewall Insulator	1963-64 all convertibles	222.00



FP612

Manual Seat Adjuster Chrome Knob: Chrome 'T' design Seat Adjuster Knob for all 1961-64 models with manual seat adjustment. Attaches with included allen screw.

SAK614 Chrome Seat Adjuster Knob 1961-64 24.50

1967-72 Hazard Flasher Knobs: Two different styles available, check your car for proper application. Chrome knobs have the word 'Flasher' embossed into them and thread into switch on column.

HFK672A Hazard Flasher Knob 1967-72 (smaller version) 14.50

HFK672 Hazard Flasher Knob 1967-72 (larger version) 16.50



HFK672A

HFK672

1968 Toronado Dash Knobs and Bezels

New Dash Knobs and Dash Bezels are made in aluminum for lasting durability. Black anodized where applicable with silver highlights. Available for 1968 Toronado models only. Headlight Switch Knob comes complete with rod on back to insert into switch.

IB68 Ignition Lock Bezel 1968 Toronado 40.00


CDB68 Cigarette Lighter Dash Bezel 1968 Toronado 41.00

WDB68 Wiper Switch Dash Bezel 1968 Toronado 41.00

HDB68 Headlight Switch Bezel 1968 Toronado 41.00

WSK68 Wiper Switch Control Knob 1968 Toronado 35.00

HSK68 Headlight Switch Knob 1968 Toronado 35.00



IB68

CDB68

HSK68

WSK68

HDB68

1961-62 Starfire Console Gear Indicator Lens: Clear plastic with 'P' 'N' 'D' 'S' 'L' 'R' engraved letters. Fits automatic transmission consoles in all 1961-62 Starfires.

IL612A Starfire Console Indicator Lens 1961-62 Starfire 35.00



983335

GM Accessory Dash Compass: Desirable accessory originally available at GM dealers. Attaches to dash with included mounting plate.

983335 GM Accessory Dash Compass 65.00

1965-67 Chrome Arm Rest Bases and Arm Rest Pads: New chromed plastic Arm Rest Bases Fit 1965 Jetstar, Jetstar I, Super 88 2 Dr hardtop & Convertible models, 1966-67 all 88 and Starfire except 4 Dr post Sedan. Also applies to 1966-67 Standard Toronados (non Deluxe models). Bases and pads are sold in pairs, separately. Arm Rest Pads are only available in black.

AB667 Chrome Arm Rest Bases 1965-67 models listed 65.00 pr.

ARP667BL Black Arm Rest Pads 1965-67 models listed 86.00 pr.

1968 88 Arm Rest Bases and Pads: Arm rest bases and pads for 1968 Delmont 88 Holiday Coupe and convertible, 1968 Delta 88 and Delta 88 Custom Holiday Coupes. Pads measure 16 1/2" and are only available in black.

ARP680 Arm Rest Pads 1968 88 models 109.00 pr.

ARP680B Arm Rest Bases 1968 88 models 109.00 pr.

ABM680 Arm Rest Base Molding 1968 88 models 32.50 pr.



1969-70 Chrome Armrest Base Plates: Chrome Armrest Backing plates used on 1969-70 Ninety-Eight, Delta 88 & Delta 88 Custom Holiday Sedans and Town Sedan models.

AB692 Chrome Arm Rest Base Plates 1969-70 45.00 pr.

Inside Rearview Mirrors and Brackets

Rearview Mirrors: New inside rearview mirrors feature polished stainless steel backings and the day/night flip levers.

549IMS

549IMS	Inside Day/Night Mirror	1961-66 all models	85.00
IM6713	Inside Day/Night Mirror	1967-68 all models	65.00
IM6981	Inside Day/Night Mirror	1969-71 all models	65.00
IMS522	Inside Mirror to Bracket Set Screw	1961-69 all, 1970 all except Toronado	3.50



IM6713



IM6981



IM6981L

Accessory Map Light Rearview Mirror: New reproduction of the desirable rearview mirror with map light option available on 1969-71 models, can also be used on 1972 models. New mirror features polished stainless steel backing, wiring pigtail, day/night lever, map light lens and switch.

IM6981L Map Light Rearview Mirror 1969-71 models 109.50

1961-64 Convertible Interior Rear View Mirror Bracket: Applies to 1961-64 Convertible models only. Chrome plated bracket includes mirror set screw.

4757750	Interior Rear View Mirror Bracket	1961-62 Convertible	95.00
IRV634	Interior Rear View Mirror Bracket	1963-64 Convertible	79.00



4757750



IRV634

1968-69 Toronado and 1968 98 Rearview Mirror Bracket: Chrome plated support arm and mounting bracket for 1968-69 Toronado and 1969 98 all exc. convertibles.

IRV682 Inside Mirror Bracket 1968-69 Toro, 1968 98 exc. conv. 45.00



IRV682

Sun Visor Support Grommets: Rubber grommets used on the sun visor end rods to keep the visors tight in place. Worn grommets will typically cause visors to drop.

GS592	Sun Visor Rod Grommets	1961-62 Conv. models	8.50 pr.
GS6400	Sun Visor Rod Grommets	1961-75 models	8.50 set



GS592

GS6400

Glove Box Liners

We have the following die-cut Glove Boxes available. All are pre-assembled with the original style gray flocked lining.

GB61	Glove Box	1961 all	46.50
GB612	Console Glove Box	1961-62 all	42.50
GB62	Glove Box	1962 all without Air Conditioning	46.50
GB62A	Glove Box	1962 all with Air Conditioning	46.50
GB63	Glove Box	1963 all	46.50
GB64	Glove Box	1964 all	46.50
GB65	Glove Box	1965-66 all except Toronado	46.50



Glove Box Light Switch: New Light Switch available for all 1969-75 88 & 98 models. Switch is also used on 1970 88-98 & Toronado in the console box.

CLS702 Glove Box/Console Light Switch 1969-75 88-98 35.00



Power Window and Power Seat Switches

1961-72 Power Window Switch Restoration Service: Restoration service available for the 4 Button Power Window Switches located in the arm rest. Requires your original switch be sent in advance. Switches are disassembled, cleaned and restored to original working order and bench tested before returning.

PWSR614 Power Window Switch Restoration 1961-72 Oldsmobile 259.00

1961-67 Power Window Switch: Two button switch with chrome housing used on 1961-62 Starfires on the console, and 1963-67 98 models with power vent windows. Nice quality reproduction switch includes the chrome housing.

4434589 Power Window Switch 1961-67 models 130.00 ea.

1961-64 Power Window Switch Bases: Four Button Switch Base for left front door, Single Button Switch Bases for the right front door and rear door or quarters. All new electrical contacts replace often worn or inoperable switch bases. Check applications below carefully.

4723099 Left Front Power Window Switch Base (4 button)
1961-63 Dynamic & Super 88, 1961-62 98 105.00

4723098 Right Front Power Window Switch Base (1 button)
1961-63 Dynamic & Super 88, 1961-62 98 39.50

4723098 Rear Door or Rear Quarter Power Window Switch Base (1 Button)
1961-3 Dynamic & Super 88 Holiday Coupe & 4 Door 39.50

4728670 Rear Quarter Power Window Switch Base (1 button)
1961-64 Starfire & 98 2 Door models,
1963-64 Dynamic 88, Super 88, Jetstar 88 Conv. 39.50

Power Window Switch Retaining Clips: Small spring steel retaining clip used on 1961-63 power window switches.

PWSC605 Power Window Switch Retaining Clip 1961-63 Oldsmobile 4.50 ea.

Door Panel Mount Power Window Switches:

Four Button switch for driver's door and single button switches for passenger door and rear doors or quarters. Will not work on cars equipped with power window buttons on arm rests.

PWS6470 Single Button Power Window Switch 38.50 ea.
1964 88 models, 1965-70 all 88s & Starfire,
1968-69 98 Town Sedan, 1966-69 Toro w/ standard interior

PWS6471 Four Button Power Window Switch 69.50
1964 88 models, 1965-70 all 88s & Starfire,
1968-69 98 Town Sedan, 1968-69 Toro w/ standard interior

PWS7130 Single Button Switch 43.00 ea.
1971-72 all, 1973-75 all 88s

PWS7131 Four Button Switch 89.00
1971-72 all, 1973-75 all 88s

1971-75 Power Door Lock Switch: Used on 1971-75 88-98-Toronado models with power door locks and switches mounted on door panel. New Chrome switch replaces worn or broken originals.

PDL717 Power Door Lock Switch 1971-75 all 62.00 ea.



4723099



PWS6470



PWS7130



PWS7131



PDL717



Two Way Power Seat Switch Base: New electrical contacts replace worn and corroded originals. Used on 1961-64 Oldsmobile Starfire models equipped with two way power seat. Includes new retaining clips.

4728670 Two Way Power Seat Switch Base 1961-64 Starfire 39.50



Six Way Power Seat Switch Base: New electrical contacts replace worn or corroded originals. For following Oldsmobiles equipped with six way power seats; 1961-65 all models except 1965 98, 1966-72 models where buttons are on side seat panel, 1973-83 all models. Please compare your original to our photos, note pin alignment, pin bussing and notched cut out location in relation to where the word "TOP" is molded in base. If your original base differs from photos please contact us, we may be able to supply a similar base that will work for your switch.

9711651 Six Way Power Seat Switch Base 1961-81 models 122.00



Six Way Power Seat Rocker Button Assembly: New toggle lever and rocker button assembly for 1961-81 Oldsmobile models equipped with the Six Way Power Seat. Used with six way base assembly listed above.

9711696 Power Seat Button Assembly 1961-81 models 45.00




Power Seat Relay: For 4 or 6 way power seats, fits the following applications: 1965 models with 4 or 6 way except for bucket seats, 1966 Starfire, 1966-70 Toronado with 4 way buckets, 1966-72 88-98-Starfire-Toronado with 6 way seats except 1971 Toronado.

5717528 Power Seat Relay 1965-72 above models 59.95



Power Options Circuit Breaker: 40 Amp Power window and power seat control Circuit Breaker for all 1962-70 models except Toronado.

4849847 Power Options Circuit Breaker 1962-70 exc. Toro 29.50



Door Jamb Light Switch: Round Door Jamb Light Switch has a two wire connection. Can be used as a replacement on 1961-64 models but has different appearance than originals. Fits into approx. 3/4" hole in door jamb. Uses DJB614 rubber boot listed below.

4709879 Door Jamb Light Switch 1961-64 models 23.50 ea.

DJB614 Door Jamb Light Switch Rubber Boot 1961-64 models 6.00 ea.



1966-67, 1969-70 Door Jamb Light Switches: Used on all 1966-67 and 1969-70 models in the door jamb to turn on interior lights when door is open.

D7277 Door Jamb Light Switch 1966-67 all models 18.50 ea.

D6971 Door Jamb Light Switch 1969-70 all models 24.50 ea.



Door Jamb Strikers: New Door Latch Striker Bolts available for all 1968-70 and 1971-76 88-98-Toronado models.

DSA642 Door Jamb Striker 1968-70 88-98-Toronado 14.50 ea.

DSA736 Door Jamb Striker 1971-76 88-98-Toronado 19.50 ea.



Inside Door and Window Handles, Interior Parts

1961-64 Inside Door Handle: Chrome plated interior door handle used on 1961 88 models and 1962-64 88 4 door and wagon models.

IDH493 Inside Door Handle 1961-64 88 37.50 ea.



1965 Inside Door Handle: Chrome plated interior door handle used on 1965 88 4 door sedan models. Sold in a pair. Includes retaining clips.

IHD657 Inside Door Handle 1965 88 4 dr sedan 49.50 pr.



1961-67 Paddle Style Inside Door Handles:

Fits all 1961-67 88s-98s & Starfires and in the front and rear on all 1966-67 Toronados except Deluxe (model 9687). Available in two finishes, one is all chrome and the other is chrome with a brushed top surface.

IHD634 Inside Door Handles, all chrome 59.50 pr.
1961-67 most models

IHD634B Inside Door Handles, brushed finish 89.50 pr.
1961-67 most models



IHD634B

1968-72 Inside Door Opening Handles: Used on 1968-70 all 88 models, includes retaining clips. Sold in a pair for left and right.

IHD20RL Inside Door Handles 1968-70 all 88 models 49.50 pr.



IHD20RL

1961-64 Window Crank Handles: Window crank handle fits 1961-63 all models and 1964 98 front only. 4 1/2" long with double arm and chrome knob. 3 1/2" long double arm design vent window crank fits all 1961-64 models exc 64 98 Lux Sed. All handles include fastener clips.

IWH594 Window Crank Handle 1961-64 40.00 ea.

IVH594 Vent Window Crank Handle 1961-64 40.00 ea.



IVH594

1965-66 Window Crank Handles: Chrome plated, single arm Window and Vent Window Crank Handles for 1965-66 Oldsmobile models. Retaining clips included with new handles

IWH6566 Window Crank Handle 1965-66 31.50 ea.

IVH6566 Vent Window Crank Handle 1965-66 24.50 ea.



IVH6566

1967-74 Window Crank Handles: New chrome window crank handles available with either clear or black plastic knobs. Includes retaining clips.

12367 Black Knob Window Crank 1967 all exc. Toronado 21.00 ea.

12314 Clear Knob Window Crank 1968-74 88s & Toronado 18.50 ea.

12315 Black Knob Window Crank 1968-74 88s & Toronado 18.50 ea.



12367

12314

12315

Door and Window Handle Backing Plates: Thin plastic washer used in back of handles to prevent wear on door panels.

HBP647 Handle Backing Plates 4.00 ea.



1967-70, 1971-76 Turn Signal Levers and 1971-75 Tilt Wheel Lever:

Chrome plated lever with black rubber end cap. Turn Signal Levers fit all 1967-70 & 1971-76 models without cruise control and telescopic wheel.

Tilt wheel lever fits all 1971-75 models without telescopic wheel.

TSL690	Turn Signal Lever	1967-70 all exc. cruise/tele	28.50
TSL715	Turn Signal Lever	1971-76 all exc. cruise/tele	28.50
TWL715	Tilt Wheel Lever	1971-75 all exc. tele	24.50



Chrome Door Lock Buttons: Replacements for your worn or broken door lock buttons. Chrome plated plastic.

DB660	Door Lock Button	1961-66 all	7.50 ea.
DB670	Door Lock Button	1967 all	7.50 ea.
DB682	Door Lock Button	1968-70 all	7.50 ea.
DB737	Door Lock Button	1971-75 all	7.50 ea.



1961-67 Rear Arm Rest Ash Trays: Chrome plated Ash Tray located in the rear armrest on many 1961-67 2 Door 88 models and standard Toronado models. Measures 2" x 2 1/2" features a stamped knob in lid and includes the chrome bezel that attaches to the arm rest.

AT6145	Rear Arm Rest Ash Tray	1961-67 models	26.50 ea.
---------------	------------------------	----------------	-----------



1968-76 Rear Arm Rest Ash Trays: New Ash Trays for rear arm rest area. AT6869 applies to 1968-70 Standard Toronado models and 1968-76 all 4 door models except wagons. AT715 is used in 1971-75 88 Holiday Coupe and Convertible models and has a ribbed design on the lid. Two ash trays used per car.

AT6869	Rear Ash Tray Assembly	1968-70 Toro, 1968-76 all 4 Doors	35.00 ea.
AT715	Rear Ash Tray Assembly	1971-75 88 Hol Cpe & Conv	43.50 ea.



1967-68 Convertible Top Switch & Power Antenna Switch: New Convertible Top Switch available for all 1967-68 88-98 Convertible models. Same switch is also used for the Power Antenna option. Chrome finish with black highlights on push button.

CTS667	Convertible Top & Power Antenna Switch	1967-68 88-98	83.00
---------------	--	---------------	-------




Rear Shelf Package Trays

Panel between the rear seat and the rear window. Available in the following colors: Black, Red, Blue, Light Blue, Light Saddle, Dark Saddle, Gold and Green. Two styles used, either smooth plain finish or with a mesh covering.


Oversized package shipping surcharge of \$75.00 applied to all package trays

PTO-133	Mesh Package Tray	1961 88 4 Dr Htop with 1 speaker	75.00
PTO-113	Plain Package Tray	1962 Starfire Coupe, 1962-63 88 2 Dr Htop	59.00
PTO-114	Mesh Package Tray	1962 Starfire Coupe, 1962-63 88 2 Dr Htop	75.00
PTO-716	Plain Package Tray	1962-63 98 2 Dr Htop	59.00
PTO-726	Mesh Package Tray	1962-63 98 2 Dr Htop	75.00
PTO-737	Plain Package Tray	1963 88 4 Dr Htop	59.00
PTO-738	Mesh Package Tray	1963 88 4 Dr Htop	75.00
PTO-115	Plain Package Tray	1963-64 Starfire Coupe, 1964 88 2 Dr Htop	59.00
PTO-116	Mesh Package Tray	1963-64 Starfire Coupe, 1964 88 2 Dr Htop	75.00
PTO-731	Mesh Package Tray	1964 98 4 Dr Htop, no rear defroster	75.00
PTO-731D	Mesh Package Tray	1964 98 4 Dr Htop, with rear defroster	75.00
PTO-717	Plain Package Tray	1965 98 2 Dr Htop	59.00
PTO-718	Mesh Package Tray	1965 98 2 Dr Htop	75.00
PTO-117	Plain Package Tray	1966 88 4 Dr Htop	59.00
PTO-118	Mesh Package Tray	1966 88 4 Dr Htop	75.00
PTO-119	Plain Package Tray	1966 Starfire Coupe	59.00
PTO-120	Mesh Package Tray	1966 Starfire Coupe	75.00
PTO-700	Plain Package Tray	1966 98 4 Dr Sedan	59.00
PTO-701	Mesh Package Tray	1966 98 4 Dr Sedan	75.00
PTO-729	Plain Package Tray	1967-68 88 4 Dr Sedan	59.00
PTO-730	Mesh Package Tray	1967-68 88 4 Dr Sedan	75.00
PTO-730LS	Mesh Package Tray	1967-68 98 Luxury 4 Dr Sedan	75.00
PTO-702	Plain Package Tray	1968 98 2 Dr Htop	59.00
PTO-703	Mesh Package Tray	1968 98 2 Dr Htop	75.00
PTO-704	Plain Package Tray	1970 98 2 Dr Htop	59.00
PTO-705	Mesh Package Tray	1970 98 2 Dr Htop	75.00
PTO-706	Plain Package Tray	1972 88 2 Dr Htop	59.00
PTO-707	Mesh Package Tray	1972 88 2 Dr Htop	75.00
PTO-724	Plain Package Tray	1972 88 4 Dr Htop	59.00
PTO-725	Mesh Package Tray	1972 88 4 Dr Htop	75.00



Front Door Area Lower Kick Panels: Correct die cut profile in neutral white waterproof cardboard. Spray paint or color dye to match interior.

KP620	Kick Panels	1962 Dynamic & Super 88	39.50 pr.
KP621	Kick Panels	1962 98 models, no A/C	39.50 pr.
KP621A	Kick Panels	1962 98 models, with A/C	39.50 pr.
KP630	Kick Panels	1963 Dynamic & Super 88	39.50 pr.



IGNITION, DOOR, TRUNK, AND GLOVE BOX LOCKS AND KEYS

Locks are available individually or in sets. Sets are set up like original with matching key for Ignition & Door Locks and Glove Box & Trunk Lock. 1961-68 models used the smaller round and octagon style keys and 1969-76 models used the larger oval and rectangular type keys. All locks and sets supplied with 2 keys.



IC3565



IC6978

Ignition Lock Cylinders

IC3565	1961-65 all	23.50
IC667	1966-67 all	23.50
IC68	1968 all	27.50
IC6978	1969-76 all	23.50



DL614



DL7181T

Door Lock Cylinders: Door lock cylinders sold in pairs only with two keys.

DL614	1961-64 2 Door Sedan and Wagon	47.00 pr.
DL614C	1961-64 Holiday Coupes, Convertibles and 4 Doors	47.00 pr.
DL656	1965-66 all	39.50 pr.
DL678	1967-68 all	39.00 pr.
DL716	1971-76 all	43.00 pr.
DL7181T	1971-76 Toronado	26.50 pr.

Glove Box Locks: Glove box locks supplied are lock cylinder and keys only. No latch components available.

GB578L	1961 all	36.50
GB624	1962-64 all	39.00
GB656	1965-67 exc. '67 Toronado	49.00
GB67T	1967 Toronado	33.50
GB704	1969-73 all	33.50



GB578L



GB67

Console Locks: Console locks are supplied as a lock cylinder and keys only. No latch components.

CL612	1961-62 Starfire	33.00
GB67	1963-69 all	46.00
CL7071	1970-71 all	39.00



TL667T



TL673

Trunk Locks

TL613	1961-63 all	29.00
TL667T	1966-67 Toronado	29.50
TL66	1966 exc. Starfire & Toronado	29.50
TL678	1967-68 all exc. 67 Toronado	29.00
TL673	1969-73 all	23.00



DI667



DI716

Door and Ignition Lock Sets

DI614	1961-64 2 Door Sedan and Wagons	65.00
DI614C	1961-64 Holiday Coupes, Convertibles and 4 Doors	63.00
DI615	1965 all models	59.00
DI667	1966-67 all models	59.00
DI680	1968 all models	53.50
DI690	1969-70 all models	49.00
DI716	1971-76 all except Toronado	43.00
DI716T	1971-76 all Toronado	49.00



GT61



GT67

Glove Box and Trunk Lock Sets: Glove box locks supplied with kit is a lock cylinder and keys only. No latch components available.

GT61	1961 all models	59.00
GT623	1962-63 all models	49.00
GT66	1966 all exc. Toronado & Starfire	63.00
GT66T	1966 Toronado	66.00
GT67	1967 all except Toronado	62.00
GT693	1969-73 all models	43.00

Ignition, and Door Key Blanks

3694624	1961-66 (octagon)	5.50
7033454	1967 (octagon)	5.50
7034680	1968 all (octagon)	5.50
7025014	1969 & 1973 (square)	5.50
7025282	1970 & 1974 (square)	5.50
7027275	1971 & 1975 (square)	5.50
7024229	1972 & 1976 (square)	5.50

Deck Lid and Glove Box

7002238	1961-66 (round)	5.50
7033455	1967 (round)	5.50
7034702	1968 (round)	5.50
7025019	1969 & 1973 (oval)	5.50
7025288	1970 & 1974 (oval)	5.50
7027281	1971 & 1975 (oval)	5.50
7024235	1972 & 1976 (oval)	5.50



REBUILDING SERVICES

We offer rebuilding services on the following mechanical parts. All individual services require that your existing part or parts (commonly called cores) be shipped complete and unaltered for rebuilding. If you do not send a core in advance, we will require a core charge. Core charges are basically an incentive to return a part to us so that the next enthusiast may have a unit for their restoration. Please do not disassemble old units. Cores with missing or broken parts will be assessed a deduction or rejected and returned.

Carburetors: Cosmetically restored exterior with new internal parts. Superior workmanship.

Most carburetors are in stock, you will be assessed a core charge until your existing unit is sent in to us. Allow 6-8 weeks for rebuilding service on units not in stock. **Core charge on in stock carburetors is 295.00 for 4 barrel units and 245.00 for 2 barrels.**

RO610	Rebuilding service on 4 Barrel Carburetor, 1961-65 88-98	599.00
RO612	Rebuilding service on 2 Barrel Carburetor, 1961-65 88-98	539.00
RO660	Rebuilding service on 4 Barrel Carburetor, 1966-70 88-98-Toro	599.00

Dual Action Fuel Pumps:

Rebuilding 1961-62 (6585 AC), and 1963-64 (6620 AC) only. **Core charge for fuel pumps is 175.00.** These pumps are normally in stock for immediate shipment.

FP-6585	1961-62 Fuel Pump	179.00
FP-6620	1963-64 Fuel Pump, cars without air conditioning	165.00
FP-6620A	1963-64 Fuel Pump, cars with air conditioning	165.00

1961-64 Fuel Pump Repair Kits:

FPA266	Fuel Pump Kit	1961-62 (#6585 pump)	107.50
FPA271	Fuel Pump Kit	1963-64 (#6620 pump)	89.50

New Fuel Pumps for 1965-74 88-98-Toronado-Starfire:

The following fuel pumps are available new without a core charge.

40030	Fuel Pump	1965 330, 1965 425	69.50
40262	Fuel Pump	1966-67 425 with AC, 1968-69 455 with AC	69.50
40705	Fuel Pump	1968-69 455 without A/C	69.50
40713	Fuel Pump	1970-74 88-98 455 without A/C	69.50
		1970-71 Toronado 455 without A/C	69.50



Harmonic Balancers: Units are revulcanized using the latest silicon polymers, cleaned and repainted or primed. Due to a lack of core units, you may need to send your balancer to us for reconditioning. Please allow 3-4 weeks lead time for this service.

Core charge for in stock units sent in advance is 250.00.

HBR615	1961-64 Harmonic Balancer Rebuilding Service	265.00
---------------	--	--------

Water Pumps: New replacement water pumps have been increasingly difficult to obtain, and are quickly being discontinued. We can now offer rebuilding service for all 1961-75 Oldsmobile water pumps. All rebuilt water pumps carry a 1 year warranty. Most applications will require original cores sent in advance, please contact us for availability. Original GM water pumps with the correct casting numbers are used when available.

W993A	New Water Pump	1961-62 V8 no A/C	139.00
WP-555717	Rebuilt Water Pump	1961-62 V8 no A/C	189.00
WP-W994A	Rebuilt Water Pump	1961-62 V8 with A/C	229.00
WP-W996	Rebuilt Water Pump	1963-64 394 no A/C	229.00
WP-W996A	Rebuilt Water Pump	1963-64 394 with A/C	229.00
555717, W994A, W996 & W996A requires 175.00 core charge			
WP-W655GM	Rebuilt, Correct Number GM Water Pump	1965-75 all	269.00
W655GM requires 250.00 core charge			
WP-W655R	Rebuilt Replacement Water Pump	1965-75 all	199.00
W655R requires 150.00 core charge			



1966-70 Toronado Fuel Tanks: New reproduction Fuel Tanks for the 1966-1970 Toronados are now available. Due to the very large size of the fuel tanks with the necks there is an additional oversized shipping surcharge.

FT667T	Fuel Tank with Neck	1966-67 Toronado	679.00
FTS667T	Fuel Tank Straps	1966-67 Toronado	49.50 pr.
FT680T	Fuel Tank with Neck	1968 Toronado	679.00
FT690T	Fuel Tank with Neck	1969-70 Toronado	679.00
FTS680T	Fuel Tank Straps	1968-70 Toronado	49.50 pr.

Oversize shipping surcharge of \$200.00 on all Toronado Fuel Tanks

1966-70 Toronado Fuel Tank Sending Units: New replacement Fuel Tank Sending Units for the 1966-1970 Toronados.

FTU667T	Fuel Tank Sending Unit	1966-67 Toronado	SOON
FTU680T	Fuel Tank Sending Unit	1968-70 Toronado	SOON

Replacement Fuel Caps

We offer the following replacement fuel caps for 1964-72 Oldsmobile models. All fuel caps listed are non-vented, like originals.

GC64P	'PREMIUM FUEL' Fuel Cap	1964-69 all	34.50
GC70	Replacement Fuel Cap	1970 all	18.50
GC41	Replacement Fuel Cap	1971-72 all	18.50

Fuel Tank Vent Filter and Hoses: Attaches to fittings on front of fuel tank and provides ventilation in the fuel tank. Includes plastic filter valve, hoses and pinch clamps. Used on all 1969-71 Oldsmobile models except wagons, Toronado and any models equipped with evaporative emission control (E.E.C.)

GTF690K	Fuel Tank Vent Filter	1969-71 models	37.50
----------------	-----------------------	----------------	-------

Hood Hinges

New Hood Hinges available for 1965-66 88 & 98 All models, 1966-67 Toronado and 1969-70 88 & 98 All models.

Please note: The hood springs for these models are not yet available.

HH647R	Right Side Hood Hinge	1965-66 88-98, 1966-67 Toro	89.50
HH647L	Left Side Hood Hinge	1965-66 88-98, 1966-67 Toro	89.50
HH692R	Right Side Hood Hinge	1969-70 88-98	84.00
HH692L	Left Side Hood Hinge	1969-70 88-98	84.00

Sheet Metal Floor Pan Plugs: Oval sheet metal plug measures 4 1/2" x 3 3/4" overall.

Check your car for quantity needed.

DPC642	Sheet Metal Plug	1961-75 all	8.50 ea.
---------------	------------------	-------------	----------

Trunk Latch Assembly: New Trunk Latch assembly used on all 1963-69 models except wagons or vehicles equipped with a power trunk release.

TL592	Trunk Latch Assembly	1963-69 all	39.50
--------------	----------------------	-------------	-------



FT667T




FTS667T



GC64P

GC70

GC41



Thermostat Housing: New cast aluminum Thermostat Housing available for all 1965-76 V8 engines with the formed bypass hose, this can also be used in place of the housing for straight bypass hose.

574815	Thermostat Housing	1959-64 394 V8	39.50
392099	Thermostat Housing	1965-76 V8	38.50
393508	Molded Bypass Hose	1966-75 all	24.50



300-160	160 Degree Thermostat	1961-72 all	14.50
300-180	180 Degree Thermostat	1961-72 all	14.50
300-195	195 Degree Thermostat	1961-77 all	14.50

TG498	Therm. Housing Gasket	1961-64 all	5.50
TG677	Therm. Housing Gasket	1965-77 all	5.00



Reproduction AC Delco Radiator Caps: Quality reproduction of the original AC radiator caps used on 1961-76 Oldsmobiles.

RC15R	Reproduction AC Radiator Cap	1961-72 all	36.50
RC27	Reproduction AC Radiator Cap	1971-76 all models with closed coolant system	36.50

Radiator Insulators

Used between radiator support and radiator as cushion. Fits 1966-75 All Models.

RI2021	Insulator Set (4 piece)	1966-70 all	29.50 set
RI17	Insulator Set (4 piece)	1971-75 all	29.50 set



Radiator Core Support Kit: Fits 1966-70 88 & 98 Models, and includes rubber bushings, sleeves, bolts and washers.

RC662K	Core Support Kit	1966-70 88-98	45.00 kit
---------------	------------------	---------------	-----------



Radiator Overflow Hose and Clip: Cars that were not equipped with the optional overflow jar use a rubber drain hose that attaches to the tube at the radiator neck. Hose is held to the side of the radiator with a special metal clip.

ROH617	Radiator Overflow Hose (36" length)	1961-77 all	11.00
ROHC687	Radiator Overflow Hose Clip to Radiator	1968-77 all	14.50



Upper Radiator Hose Plastic Clamp: Attaches to radiator core support and keeps the upper hose secured and away from the fan.

HC19	Upper Hose Plastic Clamp	1966-70 all except 66-68 Toro	9.50
-------------	--------------------------	-------------------------------	------


Heater Fan Blower Motor: New heater blower motor for all 1964-75 88-98-Toronado with or without Air Conditioning.

5587	Heater Blower Motor	1964-75 all models	59.50
-------------	---------------------	--------------------	-------



Rebuilt Heater Cores: Rebuilding service for original heater cores require **250.00 core charge**. Check with us on rebuilding other years not listed. May require original heter core be sent in to us in advance, please check with us on inventory.

3144755	Rebuilt Heter Core	1961-63 88-98-Starfire	399.00
----------------	--------------------	------------------------	--------



Original Style Ribbed Heater Hose: Black heater hose features the 5 rib design like the hoses originally used by GM. Available in 3/4" or 5/8" inner diameter, Sold by the foot.

HH3/4	Ribbed Heater Hose, 3/4 I.D.	5.50 per ft.
HH5/8	Ribbed Heater Hose, 5/8 I.D.	5.50 per ft.



Radiator and Heater Hoses

580258

We carry most of the radiator hoses used on 1961-70 88-98-Starfire-Toronado. All hoses are stamped with correct GM part numbers and markings.



580249	Upper Radiator Hose	1961 all 2 barrel	42.50
580258	Upper Radiator Hose	1961 all 4 barrel	42.50
584294	Upper Radiator Hose	1962 all 2 barrel	42.50
584295	Upper Radiator Hose	1962 all 4 barrel	42.50
587188	Upper Radiator Hose	1963-64 2 barrel	42.50
587189	Upper Radiator Hose	1963-64 4 barrel	42.50
387577	Upper Radiator Hose	1965 all except A/C	42.50
390437	Upper Radiator Hose	1965 with A/C, 1966 except Toronado, 1967 except A/C	42.50
387577	Upper Radiator Hose	1966-67 Toronado with 3 core radiator	42.50
395056	Upper Radiator Hose	1966-67 Toronado with 4 core radiator	42.50
394884	Upper Radiator Hose	1967 88-98 with A/C, 1968 all except Toronado	42.50
399310	Upper Radiator Hose	1968-75 Toronado	42.50
402153	Upper Radiator Hose	1969-73 all 88-98	39.00
580259	Lower Radiator Hose	1961 all except A/C	43.50
586459	Lower Radiator Hose	1961 all with A/C	43.50
586511	Lower Radiator Hose	1962 all models	43.50
587144	Lower Radiator Hose	1963-64 all 394 V8	43.50
382986	Lower Radiator Hose	1964 Jetstar 88 w/ 330 V8	43.50
394883	Lower Radiator Hose	1965-68 all except Toronado	43.50
402155	Lower Radiator Hose	1966-70 Toronado, 1969-70 88-98	43.50
408617	Lower Radiator Hose	1971-72 88-98	43.50
408624	Lower Radiator Hose	1971-72 Toronado	43.50
413457	Lower Radiator Hose	1973 all 88-98	43.50
413482	Lower Radiator Hose	1973-75 Toronado	43.50
575769	Molded Heater Hose	1961-62 all Valve to Heater	34.50
581993	Molded Heater Hose	1961-62 all Pump to Heater	39.50
409042	Straight Bypass Hose	1966-75 all	9.50
393508	Molded Bypass Hose	1966-75 all	24.50



Radiator and Heater Hose Clamps

We have a complete line of original hose clamps for 1961-77 Oldsmobiles. Check your needs and application for proper usage.

HC58	Tension Spring Hose Clamp	Most 1961-70 5/8" Heater Hoses	2.50 ea.
HC59	Tension Spring Hose Clamp	Most 1961-70 3/4" Heater Hoses	2.50 ea.
HC100	Double Wire Hose Clamp	Used on all 1964-70, 1973-77 Bypass Hose	5.50 ea.
HC128	Double Wire Grip Hose Clamp	Used on 1961-70, 1973-77 Upper Hose	7.00 ea.
HC202	Double Wire Grip Hose Clamp	Used on 1961-70, 1973-77 Lower Hose at radiator	7.50 ea.
HC212	Double Wire Grip Hose Clamp	Used on 1961-70, 1973-77 Lower Hose at water pump	7.50 ea.
HC55	Post-Type Hose Clamp (Wittek)	1971-72 Heater and Bypass Hose	5.00 ea.
HC62	Post-Type Hose Clamp (Wittek)	1971-72 Radiator Hose at Radiator	5.00 ea.
HC78	Post-Type Hose Clamp (Wittek)	1971-72 Radiator Hose at Pump	5.50 ea.

Hose Clamp Kits: Includes all the clamps needed for Radiator and Heater hoses.

HCK640	Hose Clamp Kit (10 pcs)	1961-70, 1973-77 all	45.00 kit
HCK712	Hose Clamp Kit (10 pcs)	1971-72 all	40.00 kit

HCK640



Electrical Switches and Components

1966-76 Ignition Switches:

D1482A	Ignition Switch	1966-67 all	53.50
D1415B	Ignition Switch	1968 all	43.50
D1404B	Ignition Switch	1969-76 without Tilt Wheel	36.50
D1405B	Ignition Switch	1969-76 with Tilt Wheel	36.50

Headlight Switches and Headlight Dimmer Switch:

DS155	Headlight Switch	1967-69 88 & 98, 1970 88, 98 & Toro	49.50
D808	Headlight Dimmer Switch	1963-75 all except 1963-64 Guidematic	23.50

1964-75 Brake Stoplight Switches:

SLS66	Stoplight Switch	1964-75 with Power Brake, no cruise, 1966-70 Toronado	19.50
D850A	Stoplight Switch	1968-75 with Power Brake and cruise control	29.50

Parking Brake Warning Light Switch: Installs into the parking brake bracket and controls the 'brake' dash light.

9795358	Parking Brake Light Switch	1971-72 88-98	19.50
----------------	----------------------------	---------------	-------

1961-62 Turn Signal Circuit Switch: Attaches to lower steering column on all 1961-62 88s-98s-Starfires equipped with Hydramatic Transmissions.

1998138	Turn Signal Circuit Switch	1961-62 all Hydramatic	74.50
----------------	----------------------------	------------------------	-------

Turn Signal Switches: New Turn Signal Switches include the wire pigtails and cancel cam. Will not work for cars equipped with either Tilt Wheel or Cornering Lights.

D6211	Turn Signal Switch	1967-68 all models except tilt wheel or cornering lamp	59.50
D6208	Turn Signal Switch	1969-76 all models except tilt wheel or cornering lamps	54.50

Turn Signal Cancel Cams and Actuators:

TSCA68	Turn Signal Cancel Cam Actuator	1968 exc. tilt wheel	9.50
TSC68T	Turn Signal Cancel Cam	1968 with tilt wheel	14.50
TSCA694	Turn Signal Cancel Cam Actuator	1969-74 exc. tilt wheel	9.50
TSC694	Turn Signal Cancel Cam	1969-74 exc. tilt wheel	18.00

1966-67, 1969-70 Door Jamb Light Switches: Used on all 1966-67 and 1969-70 models in the door jamb to turn on interior lights when door is open.


D7277	Door Jamb Light Switch	1966-67 all models	18.50 ea.
D6971	Door Jamb Light Switch	1969-70 all models	24.50 ea.

1967-68 A/C Fan Speed Switch: New GM Air Conditioner Fan Speed Switch for all 1967-68 88 & 98 models with manual control A/C.

395168	Air Conditioner Fan Speed Switch	1967-68 88-98 with A/C	50.00
---------------	----------------------------------	------------------------	-------

Windshield Wiper Switches: New windshield wiper switches for 1961 Oldsmobile models listed, at this time these are the only applications available.

1993541	Wiper Switch	1961 88 w/ 1 speed wipers	49.50
1993543	Wiper Switch	1961 88-98-SF w/ 2 speed wipers	49.50



1961-62 Starfire Neutral Safety/Back-up Light Switch:

Used on all 1961-62 Starfires, prevents car from being started while in gear and also used to light back-up lights when in reverse.

570386 Neutral Safety/Back-up Switch 1961-62 Starfire 79.50

1964-66 Neutral Safety Switch: Neutral Safety Switch used on 1964-66 Oldsmobiles with Jetaway transmission except 1964 Jetstar 88 models with column shift.

1993659 Neutral Safety Switch 1964-66 29.50

TH400 Transmission Kick Down Switch: Switch located near accelerator pedal on all 1969-76 models equipped with a TH400 automatic transmission.

TKS690 Transmission Kick Down Switch 1969-76 TH400 39.00

Oil Pressure and Temperature Sending Units:

PS12 Oil Pressure Sending Unit 1961-75 without Dash Gauges 24.50

TS15 Temperature Sending Unit 1963-70 without Dash Gauges 42.00

1961-672 Horn Relays: R203 functions as the horn relay and positive battery cable junction. Relays mount to top of driver side inner front fender well.

R203 Horn Relay 1961-67 all models, 1968 Toronado 75.00

HR680 Horn Relay 1968 all exc. Toronado 73.00

HR692 Horn Relay 1969-72 all models 73.00

1965-72 Power Seat Relay: Available for the following applications: 1965 all with 4 or 6 way power seat except buckets, 1966 Starfire w/ 4 way bucket, 1966-67 Deluxe Toronado w/ 4 way bucket, 1966-72 88-98-Starfire & Toronado w/ 6 way power seat (exc. 1971 Toronado) and 1968-70 Toronado with 4 way bucket.

5717528 Power Seat Relay above applications 59.95

Power Options Circuit Breaker: 40 Amp Power window and power seat control Circuit Breaker for all 1962-70 models except Toronado.

4849847 Power Options Circuit Breaker 1962-70 exc. Toro 29.50

Starter Bracket and Shield: Bracket was used on all 1964-71 V8 engines, then changed to a heat shield in 1972 models to prevent starter from overheating

SBS645A Bracket 1964-72 all V8 32.00

SBS645 Shield 1972-77 exc. Toro 32.00

Starter Rebuilding Service: Rebuilding service available for original equipment starters. Most starters require originals be sent in for rebuild service, please allow 2-3 weeks. There will be a **150.00 core charge** on rebuilt units until original core is returned. We can get 1964 and newer starters rebuilt, please contact us.

STA-1107665 Starter Rebuild Service 1961-62 all 88, 1963 with low compression 279.00

STA-1107776 Starter Rebuild Service 1961-63 all with high compression 279.00


Generator Rebuild Service: Rebuilding service for 1961-62 generators. Most generators require originals be sent in for rebuild service, please allow 2-3 weeks. If we do send out rebuilt units in advance there will be a **150.00 core charge** until original core is returned.

GEN-1102217 Generator Rebuilding Service 1961 88-98 no A/C 279.00

GEN-1102187 Generator Rebuilding Service 1961 88-98 with A/C 325.00

GEN-1102276 Generator Rebuilding Service 1962 88-98 no A/C 279.00

GEN-1102277 Generator Rebuilding Service 1962 88-98 with A/C 325.00



Original Equipment Style Battery Cables: We stock original style Battery Cables for most 1961-70 88-98, and 1966-69 Toronado. Complete with part number, correct color and gauge cable, hot wire pigtail, cable insulator, etc.

Negative Battery Cables

23590	1961-62 all	69.00
28680	1963-64 all	69.00
05605	1965 all	69.00
29640	1966-68 except Toronado	69.00
30085	1966-69 Toronado	69.00
29570	1969-70 88-98 w/455	69.00

Positive Battery Cables

26880	1961 all	63.00
26895	1962 all	63.00
26885	1963-64 all	63.00
28665	1965 all	69.00
22190	1966-67 88-98-SF	69.00
28690	1966-68 Toronado	69.00
29605	1968 88-98 w/455	69.00
29565	1969 88-98 w/455	69.00
29610	1970 88-98 w/ front drum brakes	69.00



Junction Block to Starter Cable

26710	1961-62 all	69.00
27280	1963 all, 1964 all except Jetstar 88	69.00
21570	1965 all	69.00
11540	1966-67 except Toronado	69.00
28675	1966-68 Toronado	69.00



Engine Ground Strap: Goes from engine block to cowl. 10 1/2" long braided cable.
GS6560 1965-75 all models 13.00

BT6584

BT6903



HD6560



BT7577



HD6360



HD6686



HDB005

Battery Support Trays, Hold Downs, and Related Parts:

BT6584	Battery Support Tray	1965-73 88-98-SF, 1966-67 Toronado	59.00
BT6903	Battery Support Tray	1969-70 Toronado	34.50
BT7577	Battery Support Tray	1975-76 88-98, 1976-78 Toronado	69.50
HD6201	Battery Hold-down	1962 all 88-98-Starfire	34.50
HD6360	Battery Hold-down	1963-64 all 394 Engines	39.50
HD6584	Battery Hold-down	1965 88-98-Starfire	39.50
HD6680	Battery Hold-down	1966 88-98-Starfire	39.50
HD6686	Battery Hold-down	1966-67 Toronado	39.50
HD6769	Battery Hold-down	1967-68 88-98	39.50
HD6560	Battery Hold-down Clamp	1969-70 Toronado	7.50
HDB005	Battery Hold-down Bolt	1962 all, 64-75 all except 68-70 Toronado	11.00 ea.

Battery Cable Tube & Bracket: Mounts to back of the engine for correct positive battery cable routing. Used on 1968-69 88 & 98 models with auto trans, 1971-75 Toronado and 1972-74 88 & 98 models.

BCTA6874	Battery Cable Tube & Bracket	above models	49.50
-----------------	------------------------------	--------------	-------

Battery Cable Terminal Block Cover: Rubber cover used on 1964-68 models at positive battery cable junction point.

BCC648	Battery Cable Cover	1964-68 all	13.50
---------------	---------------------	-------------	-------



Ignition and Tune-Up Parts

Tune-Up Kit: For all 1961-72 V-8 Engines. Includes distributor cap, rotor, point set and condensor. (short tower cap supplied in TK5A)

TK5A	Tune-up Kit	1961-64 all 394 V8	79.00
TK5	Tune-up Kit	1965-72 all models	79.00
337166	12 Volt Ignition Coil	1961-73 all	79.00

1961-64 Distributor Assembly: Rebuilding service on the 1961-64 394 V8 distributor assemblies include a rebuilt vacuum advance, cap, rotor, points and condensor. Requires a **150.00 core charge** if rebuilt unit is shipped in advance of your original coming in.

DIS-903	Rebuilt Distributor Assembly	1961-64 394 V8	379.00
----------------	------------------------------	----------------	--------

1961-64 Distributor Vacuum Advance: Rebuilt Vacuum Advances are available for all 1961-64 394 V8. **Core charge is 95.00.**

VA903	Distributor Vacuum Advance	1961-64 394 V8	79.00
--------------	----------------------------	----------------	-------

Ignition Ballast Resistor: Used only in 1961 on 88-98-Starfire models.

1957154	Ballast Resistor	1961 only	43.50
----------------	------------------	-----------	-------

AC Spark Plug Sets: AC Delco has discontinued many of the exact replacement plugs for Oldsmobile. We have found these applications to be an excellent substitute. Plugs are sold as a set of eight.

R43S	Spark Plug Set of 8	1961-64 394 V8	36.00 set
R45S	Spark Plug Set of 8	1964 330, 65-72 V8	36.00 set

Voltage Regulators: New Voltage Regulators for 1962-76 All Models.

D632	Voltage Regulator	1962-63 all models with alternator	69.50
D663	Voltage Regulator	1964-72 all with external regulator	123.00
D680	Voltage Regulator	1969-76 all with internal regulator	43.50

Ignition Wire Sets: Correct Delco-Packard Date-Coded Wire Sets. Superior workmanship, all wire sets dated for the 1st quarter of appropriate year. *1961-64 Wire Sets require a short tower distributor cap which is available in TK5A kit.



1Q61	Ignition Wire Set*	1961 all	89.00
1Q62	Ignition Wire Set*	1962 all	89.00
1Q63	Ignition Wire Set*	1963 all	89.00
1Q64	Ignition Wire Set*	1964 all	89.00
1Q65	Ignition Wire Set	1965 all	89.00
1Q66	Ignition Wire Set	1966 all	89.00
1Q67	Ignition Wire Set	1967 all	89.00
1Q68	Ignition Wire Set	1968 all	89.00
1Q69	Ignition Wire Set	1969 all	89.00
1Q70	Ignition Wire Set	1970 all	89.00
1Q71	Ignition Wire Set	1971 all	89.00
1Q72	Ignition Wire Set	1972 all	89.00

Ignition Wire Holders: Fit 1961-75 All Models. SPR615 are different designs for left and right, as per original.

WH518	4 Wire Rubber Wire Holder	1961-64 all	8.00 ea.
SPR615	4 Wire Plastic Wire Holders	1965-75 all	14.50 pr.



Plastic Wire Harness Hold Down Straps: We have three styles of harness straps used on 1961-75 Oldsmobile models. Plastic straps attach to inner fender wells to secure wiring harnesses.

WHF05	Wire Harness Strap	1961-65 models	7.50 ea.
WHF07	Wire Harness Strap	1966-69 models	7.50 ea.
WHF06	Wire Harness Strap	1970-75 models	7.50 ea.



High and Low Note Horn Assemblies: Reproduction high and low note horns for 1961-75 all models. Sold in a pair of one high note (F note) and one low note (D note). GM parts books show the low note is originally an A note for Oldsmobiles. Includes mounting brackets. Delco-Remy on horn case per original.

H3911 Horn Assemblies 1961-75 all 129.00 pr.



Oil Filler Caps

We offer the following reproduction Oil Filler Caps for 1961-75 Oldsmobiles.

OF490	Black Oil Filler Breather Cap	1961-62 Dynamic 88 371 V8	65.00
OF490CH	Chrome Oil Filler Breather Cap	1961-62 Starfire	85.00
OF667	Black 'Top Hat' Oil Filler Cap	1966-67 88-98-Toro	35.00
OF67C	Chrome 'Top Hat' Oil Filler Cap	1966-67 88-98-Toro	40.00
OF680	Oil Filler Cap	1968-70 88-98-Toro	31.00
	with 'Engine Oil Fill and AC-FC60' imprinted on top		
OF6876	Oil Filler Cap original style with tabs	1971-75 all	25.00
OFT6877	Oil Filler Tube, presses into block	1968-75 all V8	26.50



OF490



OF490C



OF667



OF67C



OF680



OF6876



OFT6877

Air Filters and PCV Valves:

A90CW	Air Filter Element	1961-62 2 barrel, 1961-67 4 barrel except Ultra High Performance, Toronado and Jetstar 88	19.50
A85C	Air Filter Element	1962-63 Starfire 4 barrel	
		Ultra High Performance	29.50
A331C	Air Filter Element	1963-74 all 2 barrel, 1964-66 all Jetstar 88	19.50
A212CW	Air Filter Element	1966-75 Toronado, 68-76 all 4 barrel	18.00
CV679C	PCV Valve	1964-76 all	12.00
FB59	Crankcase Filter	1967 Delmont 330, 1968 all V8	7.50
FB56	Crankcase Filter	1969-76 all	18.50



Air Cleaner Vent Pipes: Metal Vent Pipe mounts into rubber grommets between the air cleaner and the valve cover breather.

399765	Air Cleaner Vent Pipe	1968 88-98 exc. A/C	37.00
399766	Air Cleaner Vent Pipe	1968 88-98 with A/C	37.50
405087	Air Cleaner Vent Pipe	1969-74 350, 1971-76 455	23.50
		1978-85 260, 307 & 350 gas engines	



399765



399766



405087

Air Filter Vacuum Hose Kit: Correct ribbed vacuum hose with a white stripe, used on all 1968-72 V8 4 barrel engines. Kit contains two pieces of hose.

AFVH682	Air Filter Vacuum Hose	1968-72 4 barrel	16.00
----------------	------------------------	------------------	-------

Carburetor Throttle Return Vacuum Tee: Rubber vacuum line union 'T' used on all 1961-64 models equipped with 4 barrel carburetor.

TVT584	Carb Throttle Return Vacuum Tee	1961-64 4 barrel	9.50
---------------	---------------------------------	------------------	------

Replacement PF7 Oil Filters: New engine oil filters available for all 1961-64 Oldsmobile V8 engines.

PF7	Engine Oil Filter	1961-64 V8 engines	21.50
------------	-------------------	--------------------	-------



PF7

Carburetor Rebuild Kits

New fresh stock that includes all parts to properly rebuild all carburetor applications listed below. All components are made from modern materials to withstand today's gasoline.

Floats and base gaskets are not included in kits.

1140	Carburetor Kit	1961-68 all 394-425-455 2 barrel	53.00
1132	Carburetor Kit	1961-65 all 4 barrel except 330 V8	66.00
1133-4	Carburetor Kit	1964-65 330 V8 4 barrel	59.00
1137	Carburetor Kit	1964-68 330-350 V8 2 barrel	53.00
370	Carburetor Kit	1966 all 4 barrel	63.00
1138	Carburetor Kit	1969-73 all 350-455 2 barrel	53.00
236	Carburetor Kit	1967-76 all 330-350-425-455 4 barrel	59.00

1961-65 4 Barrel Carburetor Base Gasket: Thick base gasket used on all 1961-65 Rochester 4 barrel carburetors.

573280	Carb Base Gasket	1961-65 Roch 4 brl	24.00
---------------	------------------	--------------------	-------

1961-64 Fuel Filter: Replacement fuel filter element for 1961-64

Oldsmobile, located in glass sediment bowl on fuel pump or in fuel line.

GF149	Fuel Filter Element	1961-64	9.50
--------------	---------------------	---------	------

1963-64 Fuel Pump Glass Bowls: New fuel pump glass bowls available for all 1963-64 Oldsmobiles using a glass bowl filter on fuel pump.

FP9	Fuel Pump Glass Bowl	1963-64 all	24.50
------------	----------------------	-------------	-------

Carburetor Choke Stoves and Choke Rods: New Choke Stoves available for 1966-67

Oldsmobiles equipped with a four barrel. Choke Rods are sold separately.

OCS66	Carburetor Choke Stove	1966 all 4 barrel	89.00
OCS67	Carburetor Choke Stove	1967 all 4 barrel	89.00
OCS66R	Carburetor Choke Rod	1966 4 barrel exc. Toro	9.00
OCS67R	Carburetor Choke Rod	1967 4 barrel exc. Toro	9.00
OCS6667R	Carburetor Choke Rod	1966-67 Toronado	9.00



OCS66R



OCS67R



OCS6667R

Throttle Cable Sleeve: Small plastic bushing used on 1966-68 Toronado where throttle cable attaches to accelerator lever on carb and 1969-72 Oldsmobile V8 applications where throttle cable attaches to accelerator pedal lever.

403929	Throttle Cable Sleeve	1966-72	9.00 ea.
---------------	-----------------------	---------	----------



403929



M2215

Engine Mounts and Transmission Mounts


We have a good supply of the following mounts in stock, including the hard to find 1961-64 Hydramatic Transmission Mounts.

Engine Mounts

M2215	Front Engine Mount	1961-64 all 88-98 except with 330 V8	65.00
M2262/3	Engine Mounts	1965-70 all except Toronado	75.00 pr.

Transmission Mounts

M2216/7	Transmission Mount	1961-64 with Hydramatic except 1963-64 Convertible	119.00 pr.
M2224	Transmission Mount	1965-70 all except Toronado	52.00



573280



FP9

OCS66

OCS67



403929



M2215



M2262/3

M2224



M2216/7

Engine Gasket Sets, Individual Gaskets



Complete Engine Overhaul Gasket Sets: Includes head, oil pan, rocker cover, valve cover, timing cover, exhaust manifold gaskets, and main bearing oil seals. Intake manifold gaskets included in 1961-64 Gasket set, order individual intake manifold gaskets for 1965-75 applications.

FS7996PT	Gasket Set	1961-64 all	285.00
FS8171PT-4	Gasket Set	1965-75 all	169.00


*Intake Manifold Gasket not included.

Individual Gaskets:

642G	Cylinder Head Gaskets	1961-64 all 394 V8	130.00 pr.
MS9549SH	Intake Manifold Gasket Set	1961-64 all 394 V8	32.00
MS9947-1	Intake Manifold Gasket Set (2 pc)	1964-72 330-350	29.50
MS96004	Intake Manifold Gasket Set	1965-72 425-455	56.00
PS12420R	Pushrod Cover Set (valley pan)	1961-64 394	25.00
MS9977	Exhaust Manifold Gasket Set	1961-64 all 394 V8	32.50
MS90021	Exhaust Manifold Gasket Set	1964-72 330-350	19.00
MS90078	Exhaust Manifold Gasket Set	1965-72 425-455	19.00
6412B	Oil Pan Gasket Set	1961-62 all	42.50
6412C	Oil Pan Gasket Set	1963-64 all	39.00
OS13419D	Oil Pan Gasket Set	1965-75 all	23.50
5145	Rear Main Bearing Seal Set (rope type)	1961-64 all	35.00
3A45	Rear Main Bearing Seal Set (rubber type)	1961-64 all	69.00
BS13927	Rear Main Bearing Seal Set	1965-75 all	23.00
12421	Rocker Arm Cover Gaskets	1961-64 all	29.50 pr.
VS13403R	Rocker Arm Cover Gaskets	1965-75 all	25.00 pr.
TCS6402-1	Timing Case Cover Seal and Gasket	1961-62 all	35.00
TCS13340	Timing Case Cover Seal and Gasket	1963-64 all	29.50
TCS13417	Timing Case Cover Seal and Gasket	1965-75 all	29.50
FPG3761	Fuel Pump Gasket	1961-63 all	5.00



MS96004



MS90078



OS13419D



TCS13417



13403

Engine Parts

1961-77 V8 Freeze Plug Kits:

FPK2	Freeze Plug Kit (28 pcs)	1961-64 394 V8	55.00 kit
FPK3	Freeze Plug Kit (16 pcs)	1965-77 all V8	29.50 kit

1961-64 394 V8 Valve Lifters: New lifters should always be installed with a new camshaft.

VL574	Valve Lifters	1961-64 394 V8	16.50 ea.
--------------	---------------	----------------	-----------

1961-64 394 V8 Push Rods:

PR525	Push Rods	1961-64 394 V8	11.00 ea.
--------------	-----------	----------------	-----------

1961-64 394 V8 Rocker Arm Shafts:

42013	Rocker Arm Shaft	1961-64 394 V8	69.00 ea.
--------------	------------------	----------------	-----------

1961-64 394 V8 Rocker Arms: 1961-64 394 V8 Engines used LH and RH rocker arms on each cylinder, 4 of each used per side.

RA591R	Right Rocker Arm	1961-64 394 V8	19.50 ea.
RA591L	Left Rocker Arm	1961-64 394 V8	19.50 ea.

1961-64 394 V8 Valve Springs: A necessary replacement with any valve job.

VS560	Valve Spring	1961-64 394 V8	9.50 ea.
--------------	--------------	----------------	----------





1961-64 394 V8 Intake and Exhaust Valves:

IV590	Intake Valve	1961 394 V8	19.50 ea.
EV560	Exhaust Valve	1961 394 V8	19.50 ea.
IV624	Intake Valve	1962-64 all 394 V8	19.50 ea.
EV624	Exhaust Valve	1962-64 all 394 V8	19.50 ea.




1961-64 394 V8 Valve Guides:

VG541	Valve Guides (set of 16)	1961 394 V8	110.00 set
VG624	Valve Guides (set of 16)	1962-64 394 V8	145.00 set



1961-64 394 V8 Timing Chain and Gears:

494/44/46	Timing Chain and Gears	1961-64 394 V8	165.00 set
------------------	------------------------	----------------	------------



1961-64 394 V8 Pistons and Rings:

Pistons and rings are available in standard, oversize .020 or oversize .030. All size pistons and rings are not in stock, allow 1-2 weeks for shipment. Specify size when ordering.

P614L	Low Compression Piston and Pin set (8.75:1)	1961-64 394 V8	495.00 set
P614H	High Compression Pistons and Pin set (10.25:1)	1961-64 394 V8	495.00 set
PRS614	Piston Ring Set	1961-64 394 V8	99.50 set



1961-64 Connecting Rod Bushing to Piston Pin: This bushing is installed on the piston end of the connecting rod.

CRB496	Connecting Rod Bushing	1961-64 394 V8	8.50 each
---------------	------------------------	----------------	-----------



1961-64 394 V8 Rod Bearing Sets: Available in standard, undersize .010, or undersize .020. Specify size when ordering.

RB590	Rod Bearing Set	1961-64 394 V8	115.00 set
--------------	-----------------	----------------	------------



1961-64 394 V8 Main Bearing Sets: Available in undersize .010, or undersize .020. Specify size when ordering.

MB8	Main Bearing Set	1961-64 394 V8	189.00 set
------------	------------------	----------------	------------



1961-64 394 V8 Cam Bearing Set:

Cam Bearings should be replaced when installing a new camshaft.

CB564	Cam Bearing Set	1961-64 394 V8	65.00 set
--------------	-----------------	----------------	-----------



EM650PR



EM692WZ



EML65

1961-64 394 V8 Camshafts: New replacement camshafts for all 1961-64 394 V8's are manufactured to original stock specifications

SOC2	Camshaft	1961-64 88-98 394 V8	349.00
SOC2HP	Camshaft	1961-64 Starfire 394 V8	349.00

1965-70 425-455 V8 Dual Exhaust Manifolds: New exhaust manifolds for 1965-70 425 and 455 88-98-Starfire models with dual exhaust. Left manifold has S casting and 384895 LH, right manifold has W casting and 389268 RH. Left manifold is available separately or sold in a pair.

EM650L	Left Side Dual Exhaust Manifold	1965-70 425-455 88-98-Starfire	269.00
EM650PR	Dual Exhaust Manifolds, pair	1965-70 425-455 88-98-Starfire	399.00 pr.
EM692WZ	Dual Exhaust Manifolds, pair	1971-73 455 88 & 98 models	299.00 pr.
EMB647	Exhaust Manifold Bolt Kit	1965-70 all	36.50 kit
EML65	Exhaust Manifold Lock Washer	1965-75 all models (4 used per car)	7.50 ea.



1966-74 350 & 455 Valve Covers:

New valve covers available for all 1966-74 88 & 98 models with 350 V8 and 455 V8 engines. D-Shaped holes for grommets and correct notches on the top rear outer sections. Sold ready to paint, in pairs only.

VC672	350 & 455 Valve Covers	1966-74 88 & 98	229.00 pr.
VCB672	Valve Cover Bolt Kit (pk of 20, grade 5)		22.00 set

1961-63 394 V8 Engine Oil Pump: Rebuilt oil pumps available for all 1961-63 Oldsmobile 371 & 394 V8 engines that use push-in type screen filter.

388203	Oil Pump Assembly	1961-63 V8 engines	149.00
---------------	-------------------	--------------------	--------


1964-77 V8 Engine Lift Hook: Attaches to left side front of intake on all 1964-77 V8 engines. Used as a lift hook for hoisting the engine from car frame.

ELH647	Engine Lift Hook	1964-77 all V8 Engines	14.50
---------------	------------------	------------------------	-------



Engine Oil Indicator Dipsticks and Tubes: New Oil Indicator Tubes and Dipsticks available for all 1968-73 350 and 455 V8 engines except Toronado.

401568	Engine Oil Indicator Tube	1968 350 w/ short tube, 1969-73 350 V8 extends approx. 9 7/8" from block	19.50
401357	Engine Oil Indicator Tube	1969-73 455 V8 exc. Toro extends approx. 11 3/4" from block	19.50
401567	Engine Oil Indicator (dipstick)	1968 350 w/ short tube, 1969-73 350 V8	33.00
419242	Engine Oil Indicator (dipstick)	1968 350 w/ long tube, 1969-73 455 V8 exc. Toro	33.00



Valve Cover Grommets: Various usage on many 1961-75 Models. Compare to pictures for correct application.

VC104 Valve Cover Grommet. 1964-75 Models, D-Shaped. 12.50

VC95 Crankcase Vent Grommet. Used on 1966-75 Most Models. 3/4" outside diameter as original 11.00


VC97 PCV Vent Pipe to Air Cleaner Grommet used on 1965 V8 w/ PCV in air cleaner and 1966-67 w/ PCV 13.50

VC44 Valve Cover Grommet used on many 1963-67 Models. 9.00

VC83 Valve Cover Grommet. Wide usage on many 1964-75 Models. Original D-shape configuration. 13.50

VC73 Vent Pipe to Air Cleaner Rubber Grommet used on all 1973-77 for the side of the air cleaner to the vent pipe 18.00

VC17 Vent Pipe to Air Cleaner Grommet. Used on all 1969-75 Models. 15.00



Engine Paint

These engine enamels are computer color-matched and are the closest to original available. To properly paint an engine 3 to 4 aerosol cans will be needed. Aerosol cans are 16 oz. Please note that we can only ship paint to addresses in the continental United States. Because of air carrier regulations we will not ship paint by air or out of the United States under any circumstances.

EP110S	Red Engine Paint	1961-69 394-425-455 Engines (exc 1966-69 Toronado)	19.50 can
EP75S	Aqua Engine Paint	1961-64 some 88 models w/ 2 barrel	19.50 can
EP74	Gold Engine Paint	1964-75 all 330-350 Engines	19.50 can
EP120S	Slate Blue Engine Paint	1966-69 Toronado	19.50 can
EP100S	Blue Engine Paint	1970-75 455 Engines	19.50 can
AF150S	Red Air Filter Assembly Paint	All Models using Red Air Filters	19.50 can



Suspension Parts

Gas Shock Absorbers: New tubular type gas shock absorbers are available to give you the quality ride and handling that you expect from your Oldsmobile. Shocks are sold in a pair.

50140G	Front Shock Absorber	1961-64 all 88-98-SF	149.00 pr.
50152G	Front Shock Absorber	1965-70 all 88-98-SF	149.00 pr.
50226G	Front Shock Absorber	1966-70 all Toronado	149.00 pr.
50185G	Rear Shock Absorber	1961-62 all 88-98-SF	149.00 pr.
50177G	Rear Shock Absorber	1963-64 all 88-98-SF	149.00 pr.
50213G	Rear Shock Absorber	1965-70 all 88-98-SF	149.00 pr.
50229G	Rear Vertical Shock Absorber	1966 Toronado	149.00 pr.
50227G	Rear Vertical Shock Absorber	1967-70 Toronado	149.00 pr.
50230	Rear Horizontal Shock Absorber	1966-70 Toronado	169.00 pr.



Upper and Lower Ball Joints: New Ball Joints available for the Oldsmobile models listed below. At this time there are no 1961-62 lower ball joints available new.

BJ10176	Upper Ball Joint	1961-64 88-98-Starfire	95.00 ea.
BJ10268	Upper Ball Joint	1971-76 88-98	49.50 ea.
BJ10142	Lower Ball Joint	1963-70 88-98-Starfire	79.50 ea.
BJ10267	Lower Ball Joint	1971-76 88-98	49.50 ea.



Upper and Lower Front Control Arm Bushings: 4 Upper Bushings (2 pair) and 4 Lower Bushings (2 pair) used per car.

5171	Upper Control Arm Bushings	1961-63 all 88-98-Starfire	103.00 pr.
6108	Upper Control Arm Bushings	1964-73 all 88-98-Starfire	59.00 set of 4
419	Lower Control Arm Bushings	1961-64 all 88-98-Starfire	69.00 pr.
5144	Lower Control Arm Bushings	1965-70 all 88-98-Starfire	89.00 set of 4



Stabilizer Bar End Link Kits and Stabilizer Bar to Frame Rubber Bushings:

K440	Front Stabilizer Link Kits	1961-70 all 88-98-SF	24.50 pr.
K446	Front Stabilizer Link Kits	1966-78 Toronado	24.50 pr.
K5227	Front Stabilizer Bushings	1961-62 all 88-98-SF	23.00 pr.
K8204	Front Stabilizer Bushings	1963-64 all 88-98-SF	25.00 pr.
K5241	Front Stabilizer Bushings	1965-76 except Toronado	23.00 pr.
K5253	Front Stabilizer Bushings	1966-78 Toronado	19.50 pr.



Rubber Suspension Bumpers:

FB4220	Upper Control Arm Bumper	1961-70 all except Toronado	24.50 pr.
FB6410	Lower Control Arm Bumper	1965-70 all except Toronado	24.50 pr.
AB6473	Axle Housing Bumper	1965-70 88-98, 1966-69 Toronado	28.50 pr.

Front Lower Control Arm Bolt Kit: New lower control arm bolts and lock nuts for all 1965-70 models except Toronado.

FCAB642	Front Lower Control Arm Bolts	1965-70 exc. Toro	29.75 kit
----------------	-------------------------------	-------------------	-----------

Rear Control Arm Bushings and Bolts:

K5161	Rear Control Arm Bushings	1965-70 all	99.00 set of 4
RCABK642	Rear Control Arm Bolt Kit	1965-70 exc. toro	59.50 set



Coil Springs and Insulators



Springs are made to order and are exact for your car. Our supplier matches the new springs to your application to ensure maintaining the proper ride height and handling. Springs are made from modern materials and as such may differ in appearance from originals. These are not the generic springs that others may offer. When ordering, we need to know year, model, body style, engine size, transmission, whether or not the car is air conditioned, and if heavy duty springs are desired. Note that heavy duty springs will likely change your car's ride quality but will not change the ride height. Springs are not in stock, allow 2-3 weeks for delivery. As coil springs are a special order item, they are not returnable.

FCS615	Front Coil Springs	1961-75 88-98-Starfire	199.00 pr.
RCS615	Rear Coil Springs	1961-75 88-98-Starfire	199.00 pr.
RSI612	Rear Coil Spring Insulator	1961-75 88-98-Starfire	9.50 ea.
562197	Front Coil Spring Insulator	1961-64 88-98-Starfire	16.50 ea.

1966-70 Toronado Rear Leaf Springs: Sold in pairs only, allow 2-3 weeks delivery.

RL660T	Rear Leaf Springs	1966-70 Toronado	425.00 pr.
---------------	-------------------	------------------	------------

Wheel Bearings and Seals, 1961-75 88-98-Starfire



909066	Front Wheel Inner Bearing	1961 88-98-Starfire	95.00 ea.
909073	Front Wheel Outer Bearing	1961 88-98-Starfire	59.50 ea.
S5	Front Wheel Inner Bearing	1962-75 except Jetstar 88 & Toronado	33.50 ea.
S3	Front Wheel Outer Bearing	1962-75 except Jetstar 88 & Toronado	33.50 ea.
S6	Front Wheel Inner Bearing	1964-66 Jetstar 88	29.50 ea.
S2	Front Wheel Outer Bearing	1964-66 Jetstar 88	29.50 ea.
20118	Front Wheel Grease Seal	1961-68 except Jetstar 88 & Toronado	29.50 ea.
17815	Front Wheel Grease Seal	1964-66 Jetstar 88	26.50 ea.
20113	Front Wheel Grease Seal	1969-70 88-98 models	23.50 ea.
88128R	Axle Bearing	1961-67 88-98 models	74.50 ea.
88131R	Axle Bearing	1968-70 88-98 models	79.50 ea.
15343	Axle Oil Seal	1961-64 88-98-Starfire	23.50 ea.
13492	Axle Oil Seal	1964-66 Jetstar 88	29.50 ea.
15376	Axle Oil Seal	1965-70 88-98-Starfire	29.50 ea.



Differential Housing Gasket: Rear end cover gaskets for 1961-70 All models except Toronados.


569569	Differential Housing Gasket	1961-64	21.50
10103E	Differential Housing Gasket	1965-70	16.50

DT642	Differential Aluminum Tag	1965-75 88-98-Starfire with Positraction	6.00
--------------	---------------------------	--	------




Differential Vent Valve: Plastic differential vent used on 1973 88 and 88 Royale all models except anti-spin differential.

DIF64	Differential Vent Valve	8.50
--------------	-------------------------	------



Axle to Rear End Housing Gaskets (A) and Brake Backing Plate to Axle Gaskets (B) (4 piece set) Die cut gaskets apply to 1961-64 All Models.

ABP390	Axle & Brake Plate Gaskets	1961-64	26.50 set
---------------	----------------------------	---------	-----------



Differential Pinion Shaft Seals: Seal located in the front of the differential where the driveshaft installs into the rear end.

19438	Differential Pinion Seal	1961-62 88-98-Starfire	31.00
19310	Differential Pinion Seal	1963-64, 1965 1st Type 88-98-Starfire	28.50

1st type seal is 2 7/8" outer diameter, 2nd type for 1965 is 2 3/4" O.D.



Driveshaft Universal Joints: For all 1961-75 88-98-Starfire Models. Same U-joint is used at front and rear of driveshaft.

1143011 Universal Joint 1961-75 all 88-98-Starfire 59.00 ea.



1961-64 Transmission Seals and Filter: New seals and filter available for 1961-64 Oldsmobiles equipped with the Roto-Hydramatic Transmission.


8619560	Transmission Front Pump Seal	1961-64 all Roto-Hydramatic	29.50
46144	Transmission Tail Shaft Seal	1961-64 all Roto-Hydramatic	26.50
TG17047	Transmission Pan Gasket	1961-64 all Roto-Hydramatic	19.50
HS750D	Transmission Filter Assembly	1961-64 all Roto-Hydramatic	119.00
H105D	Transmission Selector Shaft Seal Kit	1961-64 all Roto-Hydramatic	19.50



8619560



46144



TG17047



H105D



HS750D

1961-64 Roto Hydramatic Rebuild Kits: The 1961-64 Roto Hydramatic Overhaul Kit contains all gaskets, rubber seals, sealing rings and metal clad seals. The Master Kit contains everything in the Overhaul Kit with the addition of the friction and steel plates. The Bushing Kit, Washer Kit and transmission band are not included with the kits, these are sold separately. Transmission Band rebuilding service will require your original be sent in for service, please allow 2-3 weeks for this service.

HS102-1	Transmission Master Rebuild Kit	1961-64 Roto Hydramatic	499.00 kit
HS102-3	Transmission Overhaul Kit	1961-64 Roto Hydramatic	219.00 kit
KHS106	Transmission Bushing Kit	1961-64 Roto Hydramatic	79.50 kit
KHS111	Transmission Thrust Washer Kit	1961-64 Roto Hydramatic	109.00 kit
HS122	Transmission Band Rebuild Service	1961-64 Roto Hydramatic	93.00

Transmission Filters and Pan Gaskets: The following transmission filter kits for TH350, TH400 & TH425 automatics include a new filter, filter gasket and pan gasket.


TG18621	Transmission Pan Gasket	1965-80 TH400 Trans	18.50
TF400E	Transmission Filter Kit	1965-67 TH400 Trans	38.50 kit
TF425E	Transmission Filter Kit	1966-78 Toronado w/ TH425 Trans	47.50 kit
TF400	Transmission Filter Kit	1968-80 TH400 Trans	26.50 kit
TG18633	Transmission Pan Gasket	1969-80 TH350 Trans	18.50
TF350	Transmission Filter Kit	1969-74 TH350 Trans	26.50 kit
TF350L	Transmission Filter Kit	1975-80 TH350 Trans	26.50 kit



TF400E



TF400



TF350



TF350L



TF425E

1967-77 TH400 Transmission Dipstick and Tube: New dipstick and tube available for all 1967-77 Oldsmobiles with the TH400 automatic transmission.

TDS677 TH400 Dipstick & Tube 1967-77 Oldsmobile 39.50



1966-78 Toronado Front Wheel Bearings, Outer CV Boots and Seals

907770	Front Wheel Bearing	1966-68 Toronado	229.00 ea.
9078S	Front Wheel Bearing Seal	1966-68 Toronado	22.50 ea.
66-1005	Outer CV Boot	1966-78 Toronado	38.00 ea.
47464	Output Shaft Transmission Seal (LH only)	1966-78 Toronado	33.00



1966-78 Toronado Suspension Parts

Toronado Steering Idler Arm and Pitman Arm:

IA18737	Idler Arm	1967-78 Toronado	115.00
PIT18738	Pitman Arm	1967-74 Toronado	199.00



Toronado Tie Rod Ends and Adjusting Sleeves:

TRE361L	Outer Tie Rod End	1966-68 Toronado	69.50 ea.
TRE412L	Outer Tie Rod End	1969-78 Toronado	69.50 ea.
TRE361R	Inner Tie Rod End	1969-78 Toronado	69.50 ea.
ES2004S	Tie Rod Adjusting Sleeve	1966-74 Toronado	26.50 ea.



Front Control Arm Bushings:

BU12227	Upper Control Arm Bushings	1967-75, 77-78 Toronado	56.50 pair
BU12299	Lower Control Arm Bushings	1966-78 Toronado	135.00 set of 4



Toronado Ball Joints: New upper and lower ball joints available for Oldsmobile Toronados.

BJ10241	Upper Ball Joint (either side)	1966-70 Toronado	79.50 ea.
BJ10280	Upper Ball Joint (either side)	1971-72 Toronado	79.50 ea.
BJ10270	Upper Ball Joint (either side)	1973-75 Toronado	59.50 ea.
BJ10242	Lower Ball Joint (either side)	1966-70 Toronado	115.00 ea.
BJ10281	Lower Ball Joint (either side)	1971-78 Toronado	115.00 ea.



Power Steering Hose Kits

These kits include the pressure hose with correct fittings and the return hose with clamps.

PSH590	Power Steering Hose Kit	1961-62 88-98-Starfire	89.50 kit
35241	Power Steering Hose Kit	1963-67 98, 1965-67 88, 1965 Jetstar 1, 1965-66 Jetstar 88 & Starfire	74.50 kit
36212	Power Steering Hose Kit	1966-67 Toronado	79.50 kit
35251	Power Steering Hose Kit	1968-70 88-98	79.50 kit
PSH737	Power Steering Hose Kit	1973-77 88-98	63.50 kit



1961-77 Power Steering Pump and Gear Box Rebuilding Kits:

Kits include all gaskets and seals needed to rebuild your Power Steering Pump or Power Steering Gear Box.

5688065	Power Steering Pump Rebuild Kit	1961-67 all	59.50
5688044	Power Steering Pump Rebuild Kit	1968-77 all	59.50
5687179	Power Steering Gear Box Rebuild Kit	1961-77 all	119.00

5688044




1961-67 Power Steering Pump and Gear Box Rebuilding Services: Rebuilding service available for all 1961-67 Power Steering Pumps and Power Steering Gear Boxes. Rebuilding service requires that you send your existing units in to us to be rebuilt. Please allow 4-6 weeks.

PSP-614	Power Steering Pump Rebuilding Service	1961-64 all	299.00
PSP-657	Power Steering Pump Rebuilding Service	1965-67 all	299.00
PSGB-613	Power Steering Gearbox Rebuilding Service	1961-63 all	499.00
PSGB-970	Power Steering Gearbox Rebuilding Service	1964-76 all	219.00



PSP-614

PSGB-970



Power Steering Reservoir Cap: New replacement cap for all 1968-77 models.

PSC820	Power Steering Reservoir Cap	1968-77 all	12.50
---------------	------------------------------	-------------	-------



Brake Parts

Our brake parts section offers the best quality merchandise available. Many of the items listed are becoming difficult to obtain, so please plan ahead of actual use.

Brake Shoes: Brake shoes are sold in axle sets only. One set will service either both front or both rear wheels.

160RR	Brake Shoe Set (front)	1961-64 all except Jetstar 88	75.00 set
228RR	Brake Shoe Set (rear)	1961-64 all except Jetstar 88	75.00 set
260RR	Brake Shoe Set (front)	1966-69 Toronado, 1965-70 88-98 models except Jetstar 88	75.00 set
262RR	Brake Shoe Set (rear)	1966-69 Toronado, 1965-70 88-98 models except Jetstar 88 (2" wide)	75.00 set
242RR	Brake Shoe Set (rear)	1964-66 Jetstar 88 models	55.00 set
246RR	Brake Shoe Set (front)	1964-66 Jetstar 88 models	65.00 set
284PG	Brake Shoe Set (front)	1966-69 Toronado w/ front drum brakes	85.00 set
D52	Brake Disc Brake Pads	1969-76 88-98 models w/ front disc brakes	
		1969-73 Toronado w/ front disc brakes	49.50 set
363RR	Brake Shoe Set	1971-76 88-98 models (11"x2" rear shoes)	65.00 set



260RR

Wheel Cylinders: Replace leaky or bound up Wheel Cylinders with these new replacement units.

32071	Left Front Wheel Cylinder	1961-67 88-98-Starfire except Jetstar 88	55.00
32072	Right Front Wheel Cylinder	1961-67 88-98-Starfire except Jetstar 88	55.00
37022	Left Front Wheel Cylinder	1964-66 Jetstar 88	36.50
37023	Right Front Wheel Cylinder	1964-66 Jetstar 88	36.50
36041	Left Front Wheel Cylinder	1968-70 88-98 models	55.00
36042	Right Front Wheel Cylinder	1968-70 88-98 models	55.00
37019	Left Front Wheel Cylinder	1966-69 Toronado	55.00
37020	Right Front Wheel Cylinder	1966-69 Toronado	55.00
13387	Left Rear Wheel Cylinder	1961-70 88-98 except Jetstar 88	49.50
13388	Right Rear Wheel Cylinder	1961-70 88-98 except Jetstar 88	49.50
37021	Rear Wheel Cylinders (either side)	1964-66 Jetstar 88	29.50 ea.
37116	Rear Wheel Cylinders (either side)	1966-69 Toronado	55.00 ea.
37048	Rear Wheel Cylinder (either side)	1971-75 88-98 exc. police pkg.	49.50 ea.



32071



13387



Brake Hoses

36611	Front Brake Hoses (drum brakes)	1961-69 All Models except Toronado	39.50 ea.
35018	Rear Brake Hose	1961-62 88-98-Starfire	49.50
36692	Rear Brake Hose	1966-68 88-98-Starfire	53.00
36572	Left Front Brake Hose (drum brakes)	1966-69 Toronado	53.00
36573	Right Front Brake Hose (drum brakes)	1966-69 Toronado	53.00

Brake Hardware

Self Adjuster Screws: For 1962-70 88-98-Starfire and Toronado.

80551	Left Side Adjuster Screw	1962-70 88-98-SF, 1966-69 Toronado	18.50
80552	Right Side Adjuster Screw	1962-70 88-98-SF, 1966-69 Toronado	18.50

Brake Return Spring and Hold Down Hardware Kits:

Kits include all hold down springs and brake return springs for front and rear drum brakes.

H7124	Rear Axle Brake Spring/Hardware Kit (both sides)	1965-70 88-98-SF, 1966-69 Toronado	23.50 kit
H7125	Front Wheel Brake Spring/Hardware Kit (both sides)	1965-70 88-98-SF, 1966-69 Toronado	23.50 kit

Brake Adjuster Rubber Plugs: Fits all 1961-75 Models. Plugs adjusting hole in brake drums.

4406	Rubber Adjuster Plug (set of 4)	7.00 set
-------------	---------------------------------	----------

Parking Brake Cables: The 1961-64 cables use a different design from left to right on the rear cables, 1967-76 88 & 98 Parking Brake Cables are sold in a complete set only, no individual parts available. Sets include Front, Intermediate, and Rear Cables plus connectors and clips as needed. Toronados use one rear cable and one front cable, with no intermediate cable. Toronado cables are sold individually.

2195	Front Parking Brake Cable	1962 88-S88-Starfire	109.00
2196	Front Parking Brake Cable	1962 98	109.00
2174	Rear Parking Brake Cable	right side, 1961-62 88-98-SF	79.50
2175	Rear Parking Brake Cable	left side, 1961-62 88-98-SF	79.50
2244	Front Parking brake Cable	1963 88-S88-Starfire	109.00
2265	Front Parking Brake Cable	1963 98	109.00
2368	Front Parking brake Cable	1964 88-S88-Starfire	109.00
2332	Front Parking Brake Cable	1964 98	109.00
2245	Rear Parking Brake Cable	left side, 1963-64 88-98-Starfire	79.50
2246	Rear Parking Brake Cable	right side, 1963-64 88-98-Starfire	79.50
ERE801	Rear Parking Brake Cable	1966-68 Toronado	110.00
EFT801	Front Parking Brake Cable	1966-70 Toronado	65.00
PBC6788	Parking Brake Cable Set	1967 88 models	179.00 set
PBC6798	Parking Brake Cable Set	1967 98 models	179.00 set
PBC6888	Parking Brake Cable Set	1968-70 88 models	179.00 set
PBC6898	Parking Brake Cable Set	1968-70 98 models	199.00 set
PBC7188	Parking Brake Cable Set	1971-72 88 models	179.00 set
PBC7198	Parking Brake Cable Set	1971-72 98 models	179.00 set
PBC7388	Parking Brake Cable Set	1973-76 88 models	199.00 set
PBC7398	Parking Brake Cable Set	1973-76 98 models	179.00 set

Dust Cap Anti-Static Coil: Brass coil installs into the front wheel dust caps to cut down on radio interference.

WBSC412	Anti-Static Coil	1961-64 exc. 64 Jetstar 88	25.00
WBSC612	Anti-Static Coil	1964-65 Jetstar 88	25.00
DC6853	Front Wheel Dust Cap	1964 Jetstar 88	16.00



WBSC412



WBSC612

1961-64 Power Brake Booster/Master Cylinder Rebuild Service: Requires existing cores be sent in ahead of time for all 1961-64 Bendix or Moraine Brake Boosters. Rebuilding service available for Bendix master cylinder only, or as the master cylinder and power booster assembly. All parts are cleaned, repainted, rebuilt and bench tested. **Core charge for Power Brake Units shipped in advance is 325.00** or we can rebuild your original unit, allow 3-4 weeks delivery time.

PBM601	Moraine Booster/Master Assembly Rebuild Service	1960-61 all	725.00
PBM620	Moraine Booster/Master Assembly Rebuild Service	1962 all	725.00
PBM630	Moraine Booster/Master Assembly Rebuild Service	1963 all	725.00
PBM640	Moraine Booster/Master Assembly Rebuild Service	1964 all	725.00
PBB612	Bendix Booster/Master Assembly Rebuild Service	1961-62 all	695.00
PBB630	Bendix Booster/Master Assembly Rebuild Service	1963 all	695.00
PBB640	Bendix Booster/Master Assembly Rebuild Service	1964 all	695.00



PBM601



PBB630



PBM640



62-310



1481375



BCV642B

Power Brake Booster Check Valves:

62-310	Inline Power Brake Check Valve (universal fit)	1962-66	25.00
1481375	Bendix Power Brake Check Valve	1964-66	28.50
BCV642B	Moraine Power Brake Check Valve	1964-73 88-98-Starfire 1966 Toronado w/ disc, 1967-73 Toronado	8.50


Please Read: A fresh rebuilt Power Brake Unit will not always guarantee a solution to your problem. Other areas to check are a lack of vacuum caused by a bad check valve or pin hole in the vacuum reserve tank. Air in the brake lines, deteriorated vacuum hoses or poorly functioning wheel cylinders are areas of concern as well.

NEVER use silicone (DOT 5) brake fluid.


Replacement Master Cylinders: New Master Cylinders for 1961-69 Oldsmobile 88, 98, Starfire and Toronado with power brakes. Please note that the master cylinders are service replacements. They do not have the same appearance as the originals, but will work fine. If appearance is an issue you will need to send in your original master cylinder for rebuilding.

31999	New Master Cylinder for Moraine system 1961 88-98-Starfire (4 bolt mounting)	139.00
36137	New Master Cylinder for Moraine system 1962 88-98-Starfire (2 bolt mounting)	139.00
35026	New Master Cylinder for Bendix system 1961-63 88-98-Starfire (4 bolt mounting)	149.00
36136	New Master Cylinder for Moraine system 1963-66 88-98-SF except Jetstar 88 (2 bolt mounting)	139.00
36242	New Master Cylinder for either system 1964-66 Jetstar, 1966 Toronado	149.00
36236	New Master Cylinder for Bendix system 1967-69 88 & 98, 1967 Toronado	129.00
36234	New Master Cylinder for Moraine system 1967-69 88 & 98	159.00
36306	New Master Cylinder for either system 1971-76 88 & 98	119.00

35026



36136




36242



36234





Power Brake Booster Rebuild Kits: Available for Bendix or Moraine power brake booster units. Kits contain necessary parts to rebuild power booster units.

62-569	Major Brake Booster Repair Kit	1960-61 Bendix	229.00
62-631	Major Brake Booster Repair Kit	1961-62 Moraine	175.00
62-655	Major Brake Booster Repair Kit	1963 Moraine	175.00
62-280	Major Brake Booster Repair Kit	1964-66 Moraine 9" can	139.00
62-463	Major Brake Booster Repair Kit	1964-66 Bendix 9" can	139.00
62-436	Major Brake Booster Repair Kit	1967-69 Bendix	150.00
62-281	Major Brake Booster Repair Kit	1967-72 Moraine 11" can	139.00



Power Brake Master Cylinder Kits: Rebuild kit for original moraine power brake master cylinders.

62-474	Master Cylinder Repair Kit	1960-63 Moraine	109.00
---------------	----------------------------	-----------------	--------

1961-64 Wheel Studs and Lug Nuts: 1961-63 Oldsmobiles had left thread and right thread lug nuts and studs on opposite sides of the car, GM parts books show in 1964 they changed to right thread on both sides of car.

8743	Left Thread Lug Nut	1961-63 all	4.00 ea.
8744	Right Thread Lug Nut	1961-64 all	4.00 ea.
499908	Front Right Thread Wheel Stud	1961-64 all	11.00 ea.
499909	Front Left thread Wheel Stud	1961-63 all	11.00 ea.
499542	Rear Right Thread Wheel Stud	1961-64 all	11.00 ea.
499543	Rear Left Thread Wheel Stud	1961-63 all	11.00 ea.



Turn Signal Flashers: New 12 volt Turn Signal Flashers available for 1961-76 Oldsmobiles. Early applications could have either two or three terminals, check your car for proper flasher.

TSF550	Turn Signal Flasher 1961-63 w/ 3 terminals	7.50
TSF552	Turn Signal Flasher 1961-76 w/ 2 terminals	7.50



Fuse Packages: The fuses listed below are sold in packages of 5.

AGA-1	1 Amp Fuse	5.50	AGC-20	20 Amp Fuse	5.50	**SFE-2	2 Amp Fuse	5.50
AGA-3	3 Amp Fuse	5.50	AGC-25	25 Amp	5.50	SFE-4	4 Amp Fuse	5.50
AGA-5	5 Amp Fuse	5.50	AGC-30	30 Amp Fuse	5.50	SFE-9	9 Amp Fuse	5.50
AGC-2	2 Amp Fuse	5.50	AGW-4	4 Amp Fuse	5.50	SFE-14	14 Amp Fuse	5.50
AGC-15	15 Amp Fuse	5.50	*AGW-7 1/2	7 1/2 Amp Fuse	5.50	SFE-20	20 Amp Fuse	5.50
			* Use SFE-7 1/2			** Use AGA-2		



1961-75 Interior and Exterior Light Bulbs:

53	Dash Instrument Panel Bulb	1961-63 all	4.00 ea.
57	Dash Instrument Panel Bulb	1961-63 all	4.00 ea.
67	License Lamp Bulb	1961-63 all	4.00 ea.
90	Courtesy Lamp Bulb	1961-75 all exc Conv.	4.00 ea.
97	License Lamp Bulb	1965-75 all	4.00 ea.
161	Dash Instrument Panel Bulb	1968-75 seat belt and brake light	3.00 ea.
168	Dash Instrument Panel Bulb	1964-75 all	3.00 ea.
194	Dash and Side Marker Lamp Bulb	1964-75 all dash, 1969-75 all Front and rear Side Marker exc. 1968-69 front (uses 194A), 1963-69 all High Beam and Turn Signal Indicator	3.00 ea.
194A	Front Side Marker Lamp Bulb (Amber)	1968-69 all	3.00 ea.
211B	Dome Light Bulb	1968-75 Center Roof Dome	4.00 ea.
212	Dome Light Bulb	1968-75 Some models Center Roof Dome	4.00 ea.
563	Map Light Bulb	1968-75 all models	5.50 ea.
631	Trunk Light Bulb	1967-72 all models	5.00 ea.
1004	Dome Light Bulb	1961-67 Center Roof Dome	4.00 ea.
1073	Back-Up Light Bulb	1961-63 all	5.00 ea.
1156	Back-Up Light Bulb	1964-75 all models	4.00 ea.
1157	Park, Turn Signal and Tail Lamp Bulb (Clear)	1961-65 all Park Light, 1964-65 all, 1966-67 Toro Cornering Lamp, 1961-75 all Tail Light	5.00 ea.
1157NA	Park and Turn Signal Bulb (Amber)	1966-75 all models	5.00 ea.
1195	Cornering Lamp Bulb	1965-67 all, 1968-71 Toronado	11.50 ea.
1445	Ash Tray, Shift Indicator and Heater Controls Bulb	1961-75 all	4.00 ea.
1893	Radio and Clock Bulb	1961-75 Radio, 1965-66 Clock	3.00 ea.
1895	Glove Box Lamp Bulb	1965-68 all models	4.00 ea.



LITERATURE AND PROMOTIONAL ITEMS

NOS Uncirculated Sales Literature:

1963 All Models Pocket Color Catalog	1965 All Models Pocket Color Catalog
16 pages 3 1/2" x 8" 9.00	20 pages 3 1/2" x 8 1/2" 9.00
1963 Starfire-Jetfire Sports Model Color Catalog	1966 All Models Pocket Color Catalog
8 pages 10 1/2" x 11 1/2" 24.00	20 pages 3 1/2" x 8 1/2" 9.00
1963 All Models Color Foldout	1966 Starfire-Toronto-442 Sport Model
10 1/2" x 10 1/2" Fold in 20.00	Color Catalog 16 pages 8 1/2" x 11" 25.00
1963 All Models Prestige Color Catalog	1966 All Models Color Catalog
33 pages 10 1/2" x 10 1/2" 28.00	26 pages 8 1/2" x 11" 20.00

Oldsmobile Shop Manuals on CD-ROM: Many of the CD's contain Shop Manuals, Body Manuals and Parts Books. Check our website for a detailed description of contents for each year.


OCD1961-62	Olds CD-ROM 1961-62	49.50	OCD1968	Olds CD-ROM 1968	49.50
OCD1963	Olds CD-ROM 1963	49.50	OCD1969	Olds CD-ROM 1969	49.50
OCD1964	Olds CD-ROM 1964	49.50	OCD1970	Olds CD-ROM 1970	49.50
OCD1965	Olds CD-ROM 1965	49.50	OCD1971	Olds CD-ROM 1971	49.50
OCD1966	Olds CD-ROM 1966	49.50	OCD1972	Olds CD-ROM 1972	49.50
OCD1967	Olds CD-ROM 1967	49.50	OCD1973	Olds CD-ROM 1973	49.50

1948-63 Oldsmobile Book: Published by Brooklands Books, 172 black & white pages covering all models spanning the years 1948 through 1963. Contains Technical information, road tests, product designs, performance data and reviews.

B221 1948-63 Oldsmobile Book 39.95



LITERATURE AND PROMOTIONAL ITEMS



Owner's Manuals: High quality re-prints of the original owner's manuals.

OM61	1961 88 & 98 Owner's Manual	24.50
OM62	1962 88-98-Starfire Owner's Manual	24.50
OM64	1964 88-98-Starfire Owner's Manual	24.50
OM65	1965 88-98-Starfire Owner's Manual	24.50
OM66	1966 88-98-Starfire Owner's Manual	24.50
OM67	1967 88-98 Owner's Manual	24.50
OM68	1968 88-98 Owner's Manual	24.50
OM69	1969 88-98 Owner's Manual	24.50
OM70	1970 88-98 Owner's Manual	24.50
OM71	1971 88-98 Owner's Manual	24.50
OM72	1972 88-98 Owner's Manual	24.50
OM73	1973 88-98 Owner's Manual	24.50
OM74	1974 88-98 Owner's Manual	24.50
OM75	1975 88-98 Owner's Manual	24.50
OM76	1976 88-98 Owner's Manual	24.50
OM67T	1967 Toronado Owner's Manual	24.50
OM68T	1968 Toronado Owner's Manual	24.50
OM69T	1969 Toronado Owner's Manual	24.50
OM70T	1970 Toronado Owner's Manual	24.50



1962-68 Convertible Top Manuals: Quality re-prints of the original convertible top operation manuals that were supplied when purchasing a new Oldsmobile.


CTM62	1962 Convertible Top Manual	20.00
CTM63	1963 Convertible Top Manual	20.00
CTM64	1964 Convertible Top Manual	20.00
CTM65	1965 Convertible Top Manual	20.00
CTM66	1966 Convertible Top Manual	20.00
CTM67	1967 Convertible Top Manual	20.00
CTM68	1968 Convertible Top Manual	20.00



Shop Service Manuals:

Reprints or nice used originals of the repair manuals used by Oldsmobile mechanics.

B61RM	1961 Shop Service Manual	79.00
B61SF	1961 Starfire Supplement	24.50
B62RM	1962 Service Manual Supplement (Used in combination with 1961 Shop Service Manual for full coverage)	45.00
B63RM	1963 Shop Service Manual	85.00
B64RM	1964 Shop Service Manual (5 pc set)	109.00
B65RM	1965 Shop Service Manual	98.00
B66RM	1966 Shop Service Manual	98.00
B67RM	1967 Shop Service Manual	98.00
B68RM	1968 Shop Service Manual	98.00
B69RM	1969 Shop Service Manual	98.00
B70RM	1970 Shop Service Manual	98.00
B71RM	1971 Shop Service Manual	98.00
B72RM	1972 Shop Service Manual	98.00
B74RM	1974 Shop Service Manual	65.00
B75RM	1975 Shop Service Manual	65.00
B76RM	1976 Shop Service Manual	65.00
B77RM	1977 Shop Service Manual	65.00



Fisher Body Manuals:

Manual covers exterior body parts of all GM lines. Includes detailed coverage of the convertible top and mechanism.

FBM65	1965 Fisher Body Manual	55.00
FBM66	1966 Fisher Body Manual	55.00
FBM67	1967 Fisher Body Manual	55.00
FBM68	1968 Fisher Body Manual	55.00
FBM69	1969 Fisher Body Manual	55.00
FBM70	1970 Fisher Body Manual	55.00
FBM71	1971 Fisher Body Manual	55.00
FBM72	1972 Fisher Body Manual	55.00
FBM73	1973 Fisher Body Manual	55.00
FBM74	1974 Fisher Body Manual	55.00
FBM75	1975 Fisher Body Manual	55.00
FBM76	1976 Fisher Body Manual	55.00



FASTENERS

Bumper Bolts: With stainless steel cap as original. For 1965-75 All Front and 1964-75 All Rear.

BB131 Bumper Bolt 2.50 ea.



Bolt: Radiator Shroud and Front Fender Attaching. Bolt is 5/16"-18 X 3/4" Black Oxide finish with a 1/2" head size.

10084 Bolt 1961-75 all 1.00 ea.




Heater Hose Insulator: Used to cushion the heater hose against the alternator bracket. Fits 1968-75 All Models. One per car.

HHI68 Hose Insulator 9.50



Interior Handle Removal Tool: Used to remove clip that fastens the interior handles in place.

T16000 Handle Tool 9.50



Door Inside Handle, Window and Quarter

Window Handle Retaining Clip: For all 1961-75 Models. Package of 10.

2451A Handle Clip All Models 9.50 pkg.



12134 Door Panel Trim Tab: Fits 1964-67 All Models 11.00 pkg. of 25

11774 Door Panel Trim Tab: Fits 1968-75 all models 11.00 pkg. of 25



Interior Screw Package: 9 different shapes and sizes to service areas such as arm rest bases, door and rear trim panels, sun visors, pillar trim, etc. 80 piece package services all 1961-75 Models.

6172 Interior Screw Package 24.50



Sun Visor Support Sleeve and Rubber Grommet: Plastic sleeve that slides into visor and rubber grommet used on visor rod. Four piece set services one car. 1961-75 All Models.

GS6400 Sun Visor Grommet Set (4 pieces) 8.50 set



Deluxe Wheel Cover Retaining Clips: For installation of deluxe wheel covers on 1961-63 88-98-Starfire models. 5 clips used per wheel. 580570 is the unique shorter clip used on 1961 Models.

580570 Wheel Cover Clip 1961 all 9.00 ea.

578143 Wheel Cover Clip 1962-63 all 8.50 ea.



580570



578143

Carburetor Wing Nut: Original and aftermarket style air cleaner wing nuts for all 1964-72 Models.

3741 Aftermarket Wing Nut 2.00

3741A Original Style Wing Nut 5.50



Roof Rail Weatherstrip Fastener: Fits 1961-75 All Models.

44701 Weatherstrip Fastener .75 ea.



Door Weatherstrip Fastener: Used on most 1961-75 Models.

11120 Weatherstrip Fastener .75 ea.



Wheel Opening Molding Screw Package: Bright Zinc finish, fits all 1961-75 Models. 35 per package.

9863 Molding Screw Package 7.50 pkg.



Alternator Plastic End Cap: Red or Black plastic cap used to cover the hot wire on 1962-75 Alternators. A part missing or broken on many cars. A necessity for detailed restorations.

APC62R Red End Cap 1962-75 all 9.50

APC62B Black End Cap 1962-75 all 9.50



License Plate Fasteners: For all 1961-75 Models. Includes 2 nylon fasteners and 2 screws. One set used per plate.

8418-89 License Plate Fasteners 3.00 set




Aluminum Air Filter Plates

Air Filter Plate Chrome Retainer:

Original chrome finish. Adds a final touch to the Air Filter
Aluminum Painted Plates listed below.

FPR657	Air Filter Plate Retainer	1965-67 except Toronado	27.00
FPR680	Air Filter Plate Retainer	1968 all, 1966-72 Toronado	29.50
3741A	Original Style Wing Nut	1961-72 all	5.50



Air Filter Aluminum Plates:

Proper color stenciled plates, used on 1961-68 88-98-Starfire Models, and 1966-69 Toronado. Shipped with a protective plastic covering to prevent scratching of paint detail. Remove covering upon installation. All Plates except BC123 are GM Trademarks that have been licensed and approved.



Ultra-High Compression Plates: U-shaped plates used on 1961-64 All 4 Barrels and 1965-67 All 4 Barrels except for Toronados. 1961-64 used a red background with silver lettering and black highlights. 1965-67 has a silver background with red lettering and black highlights.

BC123B	'Ultra-High Compression' plate	1961-64 all 4 barrel	31.50
DC111A	'Ultra-High Compression' plate	1965-67 all 4 barrel exc. Toro	31.50

Starfire Air Filter Plates: 1961-64 Starfires used a red background with silver lettering and black highlights. 1965-66 Starfires used a silver background with red lettering and black highlights and 'Use Premium Fuel' printed on the left side. Both plates are 10" diam.

BS120	'STARFIRE' Aluminum Plate	1961-64 Starfires	49.50
BC124	'STARFIRE' Aluminum Plate	1965-66 Starfires	49.50



1961-64 88 and 98 Air Filter Plates: 1961-64 4 Barrels used the 'Sky Rocket' plate with a red background, silver lettering with black highlights. 10" diam. plate also has 'Use Premium Fuel' printed on the left side. 1961-64 2 Barrels use the 'Rocket' plate with a red background, silver lettering with black highlights. 7 1/2" diameter plate for smaller 2 barrel air filters.

BC121	'Sky Rocket' Aluminum Plate	1961-64 4 barrel	55.00
BC122	'Rocket' Aluminum Plate	1961-64 2 barrel	45.00

1965-67 88 & 98 Air Filter Plates: Both plates have 'Super Rocket' in red lettering on a silver background with black highlights. The 4 barrel plate is 10" diameter. The 2 barrel plate is 7 1/2" diameter with 'Ultra High Compression' printed under the word Oldsmobile. Also has the 'Use Premium Fuel' printed on the right side.

BC125	'Super Rocket' Aluminum Plate	1965-67 4 barrel	55.00
BC126	'Super Rocket' Aluminum Plate	1965-67 2 barrel	45.00



1966-69 Toronado Air Filter Plates: 1966-67 Toronado plate is a slate blue color with silver lettering. 1968-69 Toronado plate is a slate grey color with silver lettering. Both plates measure approx. 11 1/2" in diameter.

E131A	'Toronado' Aluminum Plate	1966-67 Toronado	55.00
E132A	'Toronado' Aluminum Plate	1968-69 Toronado	55.00

1968 Aluminum Air Filter Plates:

There were a number of different air filter plates available in 1968 depending on the engine size and carburetor. The 2 Barrel plates measure 8" diam while all the 4 Barrel plates measure 11" diam. All plates are perfectly reproduced with silver background, red lettering and black highlights. Shipped with a protective plastic film to prevent scratches while installing. They are held down onto the air cleaner lid with chrome retainers listed on the previous page and usually a small amount of contact cement to hold it in place.

DC106A	'Rocket 350' 4 Barrel Air Filter Plate	1968 350 4 barrel	55.00	GM Restoration Parts
BC133	'Rocket 455' 2 Barrel Air Filter Plate	1968 455 2 barrel	40.00	GM Restoration Parts
DC107A	'Rocket 455' 4 Barrel Air Filter Plate	1968 455 4 barrel	55.00	GM Restoration Parts



DC105A



DC106A



BC133



DC107A

Air Filter Decals

DC35	Air Filter Decal 'Oldsmobile Rocket 350'	1969-72 350 2 Brl	9.50
DC36	Air Filter Decal 'Oldsmobile Rocket 350'	1969-72 350 4 Brl	9.50
DC36A	Air Filter Decal 'Oldsmobile Rocket 455'	1969-72 455 4 Brl	9.50
DC36B	Air Filter Decal 'Oldsmobile Rocket 455'	1969-72 455 2 Brl	9.50
B134A	Air Filter Decal 'Oldsmobile Rocket 350'	1973-75 350 2 Brl	9.50
B134	Air Filter Decal 'Oldsmobile Rocket 350'	1973-75 350 4 Brl	9.50
B134B	Air Filter Decal 'Oldsmobile 350'	1973-75 350 4 Brl	9.50
B135	Air Filter Decal 'Oldsmobile Rocket 455'	1973-75 455 4 Brl	9.50
B135A	Air Filter Decal 'Oldsmobile 455'	1973-75 455 4 Brl	9.50
DC101	Air Filter Maintenance Decal	1966-67 All 4 Barrel	6.50
DC40	'Keep your GM car all GM' Air Filter Decal	1968-75 All	6.50



DC36



DC36A







B135A



Miscellaneous Body, Interior, and Door Jamb Decals:







D2	Oil Filler Cap Decal	1961-62 all	5.00
DC22	GM 'MARK OF EXCELLENCE' Door Jamb Decal	1966-70 all	5.00
BC21	Tire Pressure Glove Box Decal	1962 all	5.50
B22	Tire Pressure Decal	1963 all	5.50
DC23	Tire Pressure Decal	1966 all	5.00
BC23	Tire Pressure Decal	1968 88-98	5.50
BC190	Tire Pressure Decal	1970 88-98	5.50
E191	Tire Pressure Decal	1970 Toronado	5.50
DC42	Alignment Stripes for Radiator Cap	1968-75 all	4.00
DC43	Engine Cooling System Decal	1970-72 all	5.00
DC44A	GM Anti-Freeze Coolant Protection Level Decal	1961-75 all	5.00



DC141	Wheel Disc Mounting Instructions	1961-64 Models with Deluxe Wheel Discs	6.00
BC142	Superlift Air Shocks Decal	1961-72 all Models with Superlift Shocks	6.00
DC27A	Glove Box Maintenance Decal	1971-72 all Models	6.50

Trunk Compartment Decals:

BC150A	Jack Instructions Decal	1961 88-98-Starfire	7.00
BC150	Jack Instructions Decal	1962 88-98-Starfire	7.00
BC151	Jack Instructions Decal	1963 88-98-Starfire	7.00
BC152	Jack Instructions Decal	1964 88-98-Starfire	7.00
BC153	Jack Instructions Decal	1965 88-98-Starfire	7.00
BC155	Jack Instructions Decal	1966 88-98-Starfire	7.00
E159	Jack Instructions Decal	1966 Toronado	7.00
B162	Jack Instructions Decal	1967 Delta 88	7.00
BC163	Jack Instructions Decal	1967 98 Models	7.00
E166	Jack Instructions Decal	1967 Toronado	7.00
BC167	Jack Instructions Decal	1968 88 Models	7.00
BC168	Jack Instructions Decal	1968 98 Models	7.00
E170	Jack Instructions Decal	1968 Toronado	7.00
B170	Jack Instructions Decal	1969 88 Models	7.00
E173	Jack Instructions Decal	1969 Toronado	7.00
BC175	Jack Instructions Decal	1970 88 Models	7.00
BC176	Jack Instructions Decal	1970 98 Models	7.00
E177	Jack Instructions Decal	1970 Toronado	7.00
B177	Jack Instructions Decal	1971 88 Models	7.00
BC179	Jack Instructions Decal	1972 88-98-Toronado	7.00
BC180	Jack Instructions Decal	1973 88-98-Toronado	6.50
BC181	Jack Instructions Decal	1974 88-98-Toronado	6.50
BC181A	Jack Instructions Decal	1975 88-98-Toronado	6.50
BC154	Jack Stowage Decal	1965 88-98 Models	7.00
B156	Jack Stowage Decal	1966 88-98 Sedans	7.00
B157	Jack Stowage Decal	1966 88-98 Convertibles	7.00
E160	Jack Stowage Decal	1966 Toronado	7.00
BC164	Jack Stowage Decal	1967 88-98 Sedans	7.00
BC165	Jack Stowage Decal	1967 98 Convertibles	7.00
B168	Jack Stowage Decal	1968 88-98 Convertibles	7.00
BC169	Jack Stowage Decal	1968-70 88-98 Sedans	7.00
BC178	Jack Stowage Decal	1971 88-98 Sedans	7.00
BC179A	Jack Stowage Decal	1972 88-98 Sedans	7.00
BCE182	Jack Stowage Decal	1973-75 88-98 Sedans and Toronado	7.00
BC191	Jack Stowage Decal	1971-75 Delta 88 Convertibles	7.00
DC98	Jack Assembly Caution Decal	1961-75 88-98-Starfire-Toronado	6.50
E161	Jack Case Decal	1966-70 Toronado	7.00
DC97	Anti-Spin Differential Decal	1962-75 88-98-Starfire with Positraction	6.50



1960's Oldsmobile 'Owner Satisfaction' Decal: Reproduction of an Oldsmobile Service owner satisfaction decal from a 1965 Oldsmobile Service Department information package. Red and silver decal measures 4 1/4" x 4 1/4" and reads: "WE MAKE LITTLE THINGS COUNT...they add up to OWNER SATISFACTION" with the mid-60's Oldsmobile Service logo. A good spirit item for your 1960's Olds.

DC65S 'Owner Satisfaction' Decal

7.00



Fusick Automotive Gift Certificates: Available for any amount and customizable for any occasion. Always the right size and color. Contact us for details.



OLDSMOBILE CLUBS



Oldsmobile Club of America: For information on the club with over 6500 active members and 25 chapters worldwide, write: Oldsmobile Club of America, Inc., P.O. Box 80318, Lansing, Michigan 48908 or call 517-663-1811. You may also find information about the club online at the Oldsmobile Club of America website: <http://www.oldsmobileclub.org>.



National Antique Oldsmobile Club of America: For information on the club with over 2,000 active members dedicated to the preservation, restoration, and enjoyment of all Oldsmobiles built between 1897 and 1964, write to: National Antique Oldsmobile Club, Inc., c/o Jim Schultz, 121 N Railroad Street, Myerstown, PA 17067 phone 982-636-2405 or visit the website at antiqueolds.org.

OLDSMOBILE PERFORMANCE CLUB: Dedicated to Performance Oldsmobiles with a monthly e-newsletter called W-Machines Magazine that includes performance tips, historical information, technical information, parts locating, and more all geared towards performance Oldsmobiles. For information on joining contact: Olds Performance Club c/o Paul Tortorici, S&P Tees, P.O. Box 4012, South Hackensack, NJ 07606 or visit www.wildaboutcars.com for more info.



TORONADO OWNERS ASSOCIATION: We are a non-profit volunteer organization dedicated to the preservation and promotion of one of Oldsmobile's most spectacular engineering and styling feats: the Toronado. We welcome every Toronado owner or enthusiast. Ownership of a Toronado or membership in any other organization is not required. For more information visit www.toronado.org or write Toronado Owners Association, PO Box 373, Hubertus, WI 53033-0373



For various USED parts such as sheet metal, body parts, chrome, accessories, and other parts where used will sufficiently do the job, contact the following individuals. We are not responsible for delivery or pricing nor do we have any direct business ties with the individuals listed. All individuals are responsible, quality minded Oldsmobile enthusiasts.

Reproduction 61/62/63 Starfire Panels

GM Sports Inc.
2403 Stagecoach Road
Stockton, California 95215
Phone: 209-462-4300
Fax: 209-462-4303

JASWEST
3831 Line 8
Bradford Ontario
Canada L3Z 3R8
Phone: 905-775-2641
Email: stevewestlake@jaswest.com
Website: www.jaswest.com

Bill Sandy
2403 County Rt. 1
Westtown, NY 10998
Phone: 845-726-0956
Fax: 845-726-3053
billsandy1936@hotmail.com
(Literature Only, No Parts)

Various 60's NOS parts for
Toronado, 88's & 98's
Pat McMillan
phone: 618-554-4362
email: dead@mchsi.com
www.droldsmobilemuseum.com

For original seat or door panel material,
we suggest you contact:
SMS Auto Fabrics
350 South Redwood Street
Canby, Oregon 97013
Phone: 503-263-3535 Fax: 503-263-3525
www.smsautofabrics.com



Part	Page	Part	Page	Part	Page
A-B		G		R	
Antenna parts, mast, grommets	6	Gas Door Assemblies	5	Power Brake Boosters	48
Ash Trays, rear armrest	26	Gaskets, Door Handle & Lock Cylinder	12	Power Door Lock Switch	23
Back Up Lenses & Housings	6	Gaskets, Outside Mirror	4	Power Steering Pump	46
Battery Trays & Hold Down Parts	35	Gasket Sets, Engine	39	Power Window Motors	8
Bearings, Engine	40	Gasket, Trunk Lock Cylinder	11	Power Window Switches	23
Bearings, Front Wheel & Axle	43	Glove Boxes	22	Push Rods	39
Bolts, Bumper	52	Grommet, Valve Cover	41	S	
Bolts, Radiator Shroud & Fender	52	H		Radiator Cap	31
Boots, CV Inner and Outer	45	Handles, interior Door	25	Radiator Core Support Mount Kit	31
Boots, Door Jamb Wiring	8	Handles, outside Door	4	Regulator, Voltage	36
Brake Master Cylinder	48	Handles, window crank	25	Rocker Arms	39
Brake Shoes	46	Hardware, Brake	47	S	
Bulbs, Headlamp	5	Harmonic Balancer Rebuilding Service	29	Sash Channel, quarter window	4
Bulbs, Interior & Exterior	50	Headlight Buckets	5	Scripts, Body Exterior	2-3
Bumper Fillers, Front and Rear	17	Headlight Retaining Rings	5	Seal, A-Frame	9
Bumpers, Fuel Tank Door	12	Heater BlowerMotor	31	Seals, Front Wheel, Pinion, Axle	43
Bumpers, Hood, Trunk, Door Rubber	12	Hood Hinges	30	Sealing Strips, Rear Quarter Window	14
Bumpers, Suspension	42	Hood Insulation Pad	9	Seat Springs, Bucket Seat	26
Bushings, Control Arm	42, 45	Hood Release Handle	5	Shock Absorbers	42
C		Horns	37	Sound Deadener, Carpet to Floor	19
Cables, Battery	35	Hoses, Front & Rear Brake	47	Spare Tire Cover	11
Cables, Parking Brake	47	Hoses, Power Steering	45	Spare Tire Retaining Parts	11
Camshaft	40	Hoses, Radiator	32	Spark Plugs	36
Carburetor Choke Stove	38	Housings, Dome & Courtesy Lamp	18	Springs, Coil	43
Carburetor Kits	38	I-J-K		Stabilizer Links & Bushings	42
Carburetors, Rebuilding Service	29	Ignition Wire Holders	36	Straps, Wire Harness	36
Carpet Sets	19	Ignition Wire Sets	36	Sun Visor Sleeves and Grommets	22
Channel, Flexible Side Window	15	Intake Valves	40	Switch, Headlight	33
Channel, Rubber Windshield & Rear	16	Insulator, Heater Hose	52	Switch, Ignition	33
Clamps, Radiator & Heater Hose	32	Insulators, Coil Spring	43	Switch, Stoplight	33
Clips, Wheel Cover Retaining	52	Insulators, Radiator	31	Switch, Temp & Oil	34
Coil Springs	43	Jar, Windshield Washer Plastic	11	T-U-V	
Conduit/Boots, Door Jamb Rubber	8	L		Thermostat, Engine Coolant	31
Convertible Top Cables, Hoses	7	Lenses, Courtesy & Dome	18	Timing Chain and Gears	40
Convertible Top Cylinders, Pumps	7	Lenses, Back-up	6	Toronado Dash Knobs & Bezels	21
Convertible Top Latch, Switch	7	Lenses, Door Panel Lower	18	Trim Panel Tabs	52
Cowl Lacing Strips	9	Lenses, License Lamp	6	Trunk Bumpers, Rubber	11
Cylinders, Wheel Brake	46	Literature	51	Trunk Cardboards	10
D		Locks, Door, Trunk, Glove Box	28	Trunk Mats	10
Decals, Engine and Body	54-55	M		Tubes, Trunk Rubber Drain	17
Door Jamb Light Switch	24	Manifold, Exhaust	40	Tune-up Kit	36
Door Jamb Strikers	24	Manuals, Chassis Service	51	Turn Signal/Tilt Wheel Levers	26
Door Lock Buttons	26	Mats, Accessory rubber floor	20	Universal Joints	44
Door Sill Plates	20	Mats, Accessory rubber Trunk	10	Valve Covers	41
E		Mirrors, Outside Chrome	4	Valve Guides	40
Elements, Air Filter	37	Mirrors, Inside Rear View	22	Valve Lifters	39
Emblems, Body Exterior	2-3	Motor, Heater Fan	31	Valve Springs	39
Engine Parts	39-41	Mounts, Transmission	30	W-X-Y-Z	
Exhaust Tips, Chrome, Toronado	5	Mounts, Engine	30	Water Pumps	29
Exhaust Valves	40	N		Washer Jars & Parts	11
F		Nut, Power Antenna Chrome	6	Weatherstrip, Convertible Top	13
Fasteners, License Plate	5	Nut, Carburetor Wing	52	Weatherstrip, Door Body Pillar	13
Fender Skirt Rubber	12	O-P-Q		Weatherstrip, Vent Window	16
Firewall Insulation Pads	20	Oil Filler Cap	37	Weatherstrip, Windshield	16
Floor Mats, Accessory Rubber	20	Oil Filter	37	Weatherstrip, Rear Window	16
Fuel Caps	30	Package Trays	27	Weatherstrip, Windshield Pillar	13
Fuel Pumps	29	Paint, Engine	41	Weatherstrip, Door & Roof Rail	13-15
Fuel Pump Rebuild Kits	29	Pistons, Piston Rings	40	Weatherstrip, Quarter Window	14
Fuel Tank, Toronado	30	Plate, Air Filter Aluminum	53	Weatherstrip, Trunk	11
				Wire Sets, Ignition	36