

CATALOG #31BC



21 Thompson Road
East Windsor, CT 06088-0655
Fax 1-860-623-3118
Email: sales@fusick.com
www.fusickautomotiveproducts.com

SINCE 1971
Phone: 1-860-623-1589
Phone: 1-860-623-1583
M-Th 8:00 AM to 5:30 PM
Fri 8:00 AM to 5:00 PM
Sat 9:00 AM to 12:00 Noon



Welcome Oldsmobile Enthusiasts,

Fusick Automotive has been in business since 1971 serving 1935-77 Oldsmobile owners worldwide. During this time, we have developed a large inventory of aftermarket and reproduction parts.

We hope this catalog will meet some of your restoration needs. The uncertainty and spiraling costs of raw materials, labor, and out of control freight charges have necessitated price increases in this catalog. These increases reflect increases of goods within the last year.

For those restoring a 1961-77 Cutlass, 442, or H/O, we offer a catalog listing hundreds of items for enthusiasts. We also offer a catalog for 1935-60 Oldsmobile enthusiasts. This catalog has a large variety of reproduction items, suspension parts, rubber parts and decals to aid in your restoration. As always, catalogs are no charge with an order or you may download the complete pdf file on our website fusickautomotiveproducts.com for free.

Remember, we constantly maintain a large stock of parts in order to offer same day shipping. We appreciate your mail-in, faxed, emailed or web site order to help eliminate communication errors. Enjoy the catalog and we look forward to assisting you with your Oldsmobile restoration.

Sincerely for Oldsmobile,

Office Personnel






Jason Juras
Jason@fusick.com
Kevin McMahon
Kevin@fusick.com
Brandon Smith
BSmith@fusick.com
Michael Catania
MCatania@fusick.com

Warehouse Personnel






James Hemingway
Terrance@fusick.com
Terrance Chase
Matt Spemulli
Michael Fusick



Revision Date: April, 2026

SCRIPTS & EMBLEMS

We have reproduced many of the hard-to-find Scripts and Emblems for Starfire and Toronado. Quality of casting and chrome finish is excellent. All scripts and emblems are inspected, approved and licensed by General Motors.

1961-66 Starfire Scripts

1961 'Starfire' Scripts: The 1961 Starfire uses the same script on both front fenders and trunk. Quality cast chrome script licensed by General Motors.

Fasteners included.

SE6241T 'Starfire' Script, 1961 Starfire 59.00 ea.



1962 'Starfire' Scripts: The 1962 Starfire used 2 different scripts for trunk and fenders. Scripts are quality cast chrome and licensed by General Motors. Includes fasteners.

SE6274 1962 'Starfire' Fender Script 59.00 ea.

SE6241T 1962 'Starfire' Trunk Script 59.00



1963 'Starfire' Scripts: 1963 Starfire scripts are quality cast chrome plated and licensed by GM. Includes fasteners. SE6320 is used on 1963 Starfire Convertibles while the SE63RP Roof Panel script is used on 1963 Starfire Coupes.

SE6320 1963 'Starfire' Convertible Front Fender Script 59.00 ea.

SE6361T 1963 'Starfire' Trunk Script 59.00

SE63RP 1963 'Starfire' Coupe Roof Panel Script 59.00 ea.



1964 'Starfire' Scripts: The 1964 Starfire used 2 different scripts. Cast chrome plated and licensed by General Motors. Includes fasteners.

SE6423 1964 'Starfire' Fender Script 59.00 ea.

SE6477T 1964 'Starfire' Trunk Script 59.00



1965-66 'Starfire' Scripts: 1965-66 Starfires used two different scripts for fender and trunk. Licensed and approved by GM. Includes fasteners.

SE6541 1965-66 'Starfire' Fender Script 59.00 ea.

SE6558T 1965-66 'Starfire' Trunk Script 59.00

1966-67 Toronado Scripts and Emblems

The 1966-67 Toronado Scripts and Emblems are all licensed and approved by General Motors. Quality casting with excellent chrome finish and correct painted highlights per originals.



1966-67 Toronado Front End Panel Rocket Emblem: Cast chrome plated emblem with correct 'claret poly' (maroon) color in body and black highlights around edges. Licensed by General Motors. Emblem is 5" tall and has two mounting studs, includes fasteners. Mounts on front end panel over the 'Oldsmobile' letters.

SE6694 1966-67 Rocket Emblem 59.00



1966-67 'Toronado' Front Fender Script:

Cast chrome plated 'Toronado' scripts are licensed by General Motors. Correct dark grey highlights in center of letters. Script has five mounting studs and includes fasteners.

SE6656 1966-67 'Toronado' Fender Script 59.00 ea.



'OLDSMOBILE' Front End Panel Letter Set:

Expensive tooling was used to bring these quality letters to the enthusiast. Set of 10 letters has correct grey highlights in the center of letters and is licensed by General Motors. Correct angle on all the letters to conform to the angle of the front end panel. Includes all fasteners.

L667T 1966-67 'OLDSMOBILE' Letter Set 75.00 set



1967 'Toronado' Grille Script: Cast chrome grille script with correct grey highlights in center of letters. Script has three mounting studs with fasteners included. Inspected and licensed by General Motors.

SE6777G 1967 'Toronado' Grille Script 59.00



1966-67 'Toronado' Trunk Script:

Cast chrome plated script, licensed by General Motors. Correct grey color highlights in letters as original.

SE6602 1966-67 'Toronado' Trunk Script 59.00



1966-67 Toronado 'by Oldsmobile'



Trunk Nameplate: Cast chrome nameplate has brushed finish on face and correct white 'BY OLDSMOBILE' letters as original. Licensed by General Motors.

SE6603 1966-67 'by Oldsmobile' Nameplate 49.00
SE97G

'OLDSMOBILE' Grille Scripts

'Oldsmobile' Grille Scripts: Quality chrome plated cast Grille Scripts for 1968-69 88 & 98 models and 1972 98 models. All mounting hardware included.

SE97G 1968-69 88 & 98 Grille Script 45.00

SE25G 1972 98 Grille Script 45.00



SE25G



OUTSIDE REAR VIEW MIRRORS

Excellent reproductions of selected mirrors used on 1961-71 Full Size Oldsmobiles. Applications listed are the only mirrors available at this time.



SM6170L Left only Outside Standard Chrome Mirror. Includes mounting bracket and molded plastic gasket. Fits **1961-62** All models 95.00



SM6308B Outside Standard Chrome Mirror, fits both sides. Base has a v-shape in the bottom to mount onto the body line. Mounting bracket and molded plastic gasket included. Fits **1963-64** All models. 95.00 ea.



1965 88-98-Starfire Outside Standard Chrome Mirror. Includes mounting bracket and molded plastic gasket.

SM6365L Left Outside Chrome Mirror 95.00

SM6365R Right Outside Chrome Mirror 95.00



SM6667B Outside Standard Chrome Mirror, fits both sides. With mounting bracket and molded plastic gasket. Fits **1966** All models including Toronado. 95.00 ea.



1968-70 Toronado left and right Outside Standard Chrome Mirrors. Includes mounting screws and molded plastic gasket.

SM7050L Left Mirror 1968-70 Toronado 95.00

SM7050R Right Mirror 1968-70 Toronado 95.00




1968-70 88-98 Left and right Standard Chrome Outside Mirrors. With mounting screws and molded plastic gasket.

SM6865L Left Outside Mirror 95.00

SM6865R Right Outside Mirror 95.00

Mirror Gaskets: The following side view mirror gaskets are available in the original plastic material. Will fit either passenger or driver side.

| | | | |
|----------------|---------------|---------------------------|-------|
| MGS670 | Mirror Gasket | 1967 standard mirrors | 10.00 |
| MGS670R | Mirror Gasket | 1967 LH remote mirror | 10.00 |
| MGS682 | Mirror Gasket | 1968-69 All exc. Toronado | 10.00 |
| MGS702 | Mirror Gasket | 1968-69 Toro, 1970 88-98 | 10.00 |



1969-70, 1971-76 Rear Quarter Window Chrome Sash Channels:

Chrome plated molding attaches to leading edge of quarter window and accepts the Quarter Window Weatherstrips. Fits 1969-70 88 & 98 Holiday Coupes and Convertibles and 1971-76 Delta 88 Royale Holiday Coupe and Convertible. Mounts to glass with window setting channel which is included.

| | | | |
|---------------|---------------------------|--|-------|
| SC682L | Left Chrome Sash Channel | 1969-70 88-98 Hol. Cpe. & Conv. | 49.00 |
| SC682R | Right Chrome Sash Channel | 1969-70 88-98 Hol. Cpe. & Conv. | 49.00 |
| SC716L | Left Chrome Sash Channel | 1971-76 Delta 88 Royale Hol.Cpe & Conv | 45.00 |
| SC716R | Right Chrome Sash Channel | 1971-76 Delta 88 Royale Hol.Cpe & Conv | 45.00 |

1961-62 88-98 Outside Door Opening Handle Set: Complete handle package comes with push button assemblies and mounting hardware. Handles fit all 1961-62 Oldsmobile 88 & 98 two door models and front doors only on 1961-62 88 & 98 four door models.

DH612BC Outside Door Handles 1961-62 All models 79.50 set



ORIGINAL T3 HEADLAMPS

T3 Headlamps: New T3 headlight bulbs to fit all 1961-71 Oldsmobiles. Made under license from General Motors. Sold in pairs of one low beam and one high beam only.

| | | | |
|---------------|--------------|------------------------------------|-----------|
| T3607 | T3 Headlamps | 1961-67 All models (1 high, 1 low) | 85.00 pr. |
| T36871 | T3 Headlamps | 1968-71 All models (1 high, 1 low) | 85.00 pr. |



1965-66 and 1968-70 Headlight Buckets: New stamped sheetmetal headlight buckets available for all 1965-66 88-98-Starfire and 1968-70 88 & 98 models. Sold in a set of four only. 1967 models differ from other years and are not available at this time.

| | | | |
|---------------|----------------------|------------------------|------------|
| HLB656 | Headlight Bucket Set | 1965-66 88-98-Starfire | 125.00 set |
| HLB678 | Headlight Bucket Set | 1968 88-98 models | 125.00 set |
| HLB692 | Headlight Bucket Set | 1969-70 88-98 models | 125.00 set |



Headlight Adjuster Screws: Uses eight per car, two per headlight. Allows adjustment for proper alignment of headlights. Two different types available, 67-3110 is a self retaining design that snaps into a rectangular hole and 68-3249 uses included pop rivets to install.

| | | |
|----------------|--|----------|
| 67-3110 | Headlight Adjuster Screw, self retaining | 4.50 ea. |
|----------------|--|----------|



Headlight Bulb Retaining Rings: Uses four per car, Stainless Steel Ring used to hold Headlight Bulbs into Headlight Buckets listed above.

| | | | |
|---------------|---------------------------------|------------------|---------------|
| HRR61 | Headlight Bulb Retaining Ring | 1965-66, 1968-69 | 29.50 ea. |
| HRR702 | Headlight Bulb Retaining Ring | 1970-72 | 29.50 ea. |
| HLS612 | Headlight Retaining Ring Screws | | 3.50 pk of 12 |



1969 88 & 98 Hood Release Handle: New plastic Hood Release Handle includes retaining clip. Fits all 1969 88 & 98 models.

| | | | |
|----------------|--------------------------|------------|-------|
| HRH690 | Hood Release Handle | 1969 88-98 | 25.00 |
| HRHC692 | Hood Release Handle Clip | | 1.50 |




1966-68 Toronado Chrome Exhaust Tips: Chrome plated exhaust tips used on 1966, 1967 & 1968 Toronado. Tips for the 1966 models have the bracket attached on top. Previously discontinued, we have re-tooled the chrome tips and reintroduced them back to the market.


| | | | |
|--------------|---------------------|---------------|------------|
| EE66T | Chrome Exhaust Tips | 1966 Toronado | 189.00 pr. |
| EE67T | Chrome Exhaust Tips | 1967 Toronado | 189.00 pr. |
| EE68T | Chrome Exhaust Tips | 1968 Toronado | 189.00 pr. |



GD647



GD680



GD712

1964-72 License Plate Holder/ Gas Door Assemblies: New item manufactured to exact OEM specifications. Stamped steel construction, includes tension springs. Holds rear license plate, bolts to rear bumper and tilts down to allow access to fuel tank filler neck.

| | | | |
|----------------|-------------------------|---|----------|
| GD647 | Gas Door Assembly | 1964-67 88-98, 1964-66 Starfire, 1966-67 Toronado | 55.00 |
| GD680 | Gas Door Assembly | 1968-70 88, 1969-70 98 models | 59.00 |
| GD712 | Gas Door Assembly | 1971-72 88-98, 1973 Delta 88 & Delta 88 Royale | 59.00 |
| 8418-89 | License Plate Fasteners | 1961-75 All | 3.00 pr. |



Back-up Light Lenses: Vulnerable lenses located in the rear bumper, used on 1966-67 Toronado and 1967-68 Ninety Eight. Our lenses are the correct clear lens and are licensed by GM. Sold in pairs only.

| | | | |
|----------------|-----------------|------------------------------|-----------|
| BU0102 | Back-up Lenses | 1966-67 Toronado, 1967-68 98 | 65.00 pr. |
| BUG0102 | Back-up Gaskets | 1966-67 Toronado, 1967-68 98 | 12.00 pr. |

BU0102



1967 88 Back-up Lenses and Housings: Clear plastic back-up lenses for 1967 Oldsmobile 88 models. New metal back-up housings are sold complete with wiring pigtail and connector. Chrome screws have the correct collar on them to prevent over tightening.

| | | | |
|----------------|-----------------|----------------|-----------|
| BU7090B | Back-up Lens | 1967 88 models | 29.50 ea. |
| BUH702 | Back-up Housing | 1967 88 models | 52.00 ea. |
| BUG702 | Lens Gasket | 1967 88 models | 10.00 ea. |
| BLS702 | Lens Screws | 1967 88 models | 5.00 pr. |

BUH702



1969 88 & 98 Parking Light Housings: Cast metal housing includes wire pigtail and bulb socket.

| | | | |
|----------------|---------------------------|------------|-----------|
| PLA697L | Left Park Light Assembly | 1969 88-98 | 73.00 |
| PLA697R | Right Park Light Assembly | 1969 88-98 | 73.00 |
| PLG690 | Park Light Gaskets | 1969 88-98 | 10.00 ea. |
| PLS690 | Park Lens Screws | 1969 88-98 | 4.50 pr. |

PLA697L



License Lamp Lenses: New License Lamp Lenses available for 1961-63 and 64 wagons, and 1966-72 some models (see listing below). Clear lens with 5957401-2 GUIDE 35 SAE L 66 for 1966-72.

| | | | |
|----------------|-------------------------------------|---|-------|
| LL614 | License Lamp Lens | 1961-63, 1964 Wagons | 16.50 |
| LL6801 | License Lamp Lens | 1966 88s, 1968-70 All exc. 1968 98, 1971-72 88-98 exc. wagons | 15.00 |
| LLG6801 | License Lens Gasket for LL6801 Lens | | 10.00 |



License Lamp Assembly: Complete assembly ready to install includes lens, gasket, housing, wire pigtail with end connector and bulb. Replaces GM part number 916271 and fits 1969-70 Toronado models.

| | | | |
|----------------|-----------------------|------------------|-------|
| LLA6801 | License Lamp Assembly | 1969-70 Toronado | 45.00 |
|----------------|-----------------------|------------------|-------|



ANTENNA PARTS



Power Antenna Chrome Nut: Threaded chrome nut used on All 1961-68 Oldsmobiles.
PAN619 Antenna Chrome Nut 35.00

Power Antenna Mounting Pad: Fits all 1961-66 with power antenna exc. Toronado.
MAG619A Antenna Mount Pad 7.50



Manual Antenna Mounting Pad: Fits all 1961-70 with manual antenna exc. Toronado.
MAG619 Antenna Mount Pad 7.50

Manual Antenna Black Plastic Nut: Fits 1961-62 88/98/Starfire models with manual antenna.
AN586 Manual Antenna Nut 1961-62 All 16.50



Manual Antenna Black Plastic Antenna Nut: Fits 1963-70 88/98 with Manual Antenna only.
AN679 Manual Antenna Nut 1963-70 88-98 16.50



Manual Antenna Mast:

New Manual Antenna Masts are now available. Correct three piece mast with small ball tip. Original base which antenna presses into must be re-used. Applies to 1961-62 All models equipped with a manual antenna, will not work for factory equipped power antennas.

| | | | |
|---------------|---------------------|---------|-------|
| 569310 | Manual Antenna Mast | 1961-62 | 79.00 |
|---------------|---------------------|---------|-------|

Manual Antenna Mast: Elliptical (oval) three piece, manual antenna mast with bullet tip. Presses into existing antenna base on 1969-70 88 and 98 models.

| | | | |
|---------------|-------------------------|-----------------|--------|
| 402253 | Elliptical Antenna Mast | 1969-70 88 & 98 | 145.00 |
|---------------|-------------------------|-----------------|--------|

CONVERTIBLE TOP PARTS

1961-70 Convertible Top Motors and Cylinders:

Leaking or inoperative cylinders will need replacement. We offer new (not rebuilt) cylinders and motors with a One year warranty against defects.

| | | | |
|---------------|-------------------|-------------|------------|
| TC26 | Top Cylinder | 1961 All | 169.00 ea. |
| TC27 | Top Cylinder | 1962 All | 169.00 ea. |
| TC28 | Top Cylinder | 1963-64 All | 169.00 ea. |
| TC46 | Top Cylinder | 1965-70 All | 169.00 ea. |
| TP2 | Top/Pump Motor | 1961-63 All | 375.00 |
| TP3 | Top/Pump Motor | 1964 All | 375.00 |
| TP7 | Top/Pump Motor | 1965-70 All | 375.00 |
| TMG642 | Top Motor Grommet | 1961-70 All | 5.00 ea. |

Convertible Top Cables:

For 1961-75 models, except 1971.

These cables have a tendency to break after a period of years and should be replaced when installing a new top.



| | | |
|--------------|--------------------------------|-----------|
| 614BM | 1962-64 88/Starfire Top Cables | 54.50 pr. |
| 614CM | 1961-64 98 Top Cables | 54.50 pr. |
| 6570A | 1965-70 88/Starfire Top Cables | 54.50 pr. |
| 6570B | 1965-70 98 Top Cables | 54.50 pr. |
| 7276 | 1972-75 88 Top Cables | 65.00 pr. |

Convertible Top Hoses:

Fit 1961-70 all models from cylinders to motor and pump assembly. Manufactured to accommodate many models. Surplus lines should be coiled and retained at the pump. Lines are rubber for 1961, and plastic from 1962-1970.

| | | | |
|---------------|-------------------|-------------|------------|
| CTH561 | Rubber Top Hoses | 1961 All | 139.00 pr. |
| CTH627 | Plastic Top Hoses | 1962-70 All | 124.00 pr. |

TP2



TC28

CX614



CX642

CTH627



1961-64 Convertible Top

Latches: New chrome convertible top latch assemblies replace broken or worn originals.

Fit all 1961-64 Convertible models.

| | | | |
|----------------|-----------------------|---------|--------|
| CTL614L | Top Latch, left side | 1961-64 | 189.00 |
| CTL614R | Top Latch, right side | 1961-64 | 189.00 |



Convertible Top Hooks: Threaded rod with chrome plated hooks. Replacement for an often broken part.

| | | | |
|--------------|----------------------|-------------|-----------|
| CX614 | Convertible Top Hook | 1961-63 | 19.00 ea. |
| CX642 | Convertible Top Hook | 1965, 67-70 | 9.00 ea. |

1966-70, 1971-75 Convertible Top Latch Assemblies: New Convertible Top Latch assembly replaces damaged originals on all 1966-70 98 Convertibles and 1967-75 88 Convertibles. Assemblies include the chrome Top Hook.

| | | | |
|----------------|-----------------|------------------------------|--------|
| CTL660L | Left Top Latch | 1966-70 98, 1967-70 88 Conv. | 119.00 |
| CTL660R | Right Top Latch | 1966-70 98, 1967-70 88 Conv. | 119.00 |
| CTL716L | Left Top Latch | 1971-75 88 Conv. | 149.00 |
| CTL716R | Right Top Latch | 1971-75 88 Conv. | 149.00 |

CTL660L



CTL716R



1961-62 Convertible Top Switch: New electrical switch with polished stainless steel button for convertible top operation on 1961-62 88, 98 & Starfire Convertible. Original chrome bezel must be re-used. New clips included with switch.


| | | | |
|----------------|------------------------|---------------|-------|
| 4634122 | Convertible Top Switch | 1961-62 Conv. | 95.00 |
|----------------|------------------------|---------------|-------|

4634122



1971-75 Oldsmobile 88 Convertible Top Motor: New Scissor Top Motor for all 1971-75 88 convertibles includes electrical pigtail wires and connector.

STM716 Convertible Top Motor 1971-75 Convertible 259.00



1971-75 88 Convertible Scissor Top Parts:

| | | | |
|-----------------|---|------------------------|-----------|
| CAB716 | Convertible Top Actuator Bolt/Lock Washer | 1971-75 88 Convertible | 14.00 |
| CFB716 | Convertible Frame Bushing Set (16 pcs) | 1971-75 88 Convertible | 60.00 |
| CBG716 | Convertible 3rd Bow Plastic Guide | 1971-75 88 Convertible | 63.00 |
| CTR716 | Convertible Top Relay | 1971-75 88 Convertible | 63.00 |
| CDC716BK | Convertible Drive Cables (black-pass. side) | 1971-75 88 Convertible | 65.00 |
| CDC716BL | Convertible Drive Cables (blue-driver side) | 1971-75 88 Convertible | 65.00 |
| CGW716 | Convertible Top Rain Gutter Wires | 1971-75 88 Convertible | 59.00 |
| CSA716 | Convertible Top Glass Support Arms and Bushings | 1971-75 88 Convertible | 99.00 |
| HGP716 | Convertible Header Bow Guide Pins | 1971-75 88 Convertible | 14.00 pr. |



Convertible Top Guide: Book contains many articles, installation tips, maintenance information and much more. Helpful information pertaining exclusively to convertible tops.



B716 Convertible Top Guide 21.50

1961-75 Power Window Motors:

New Power Window Motors for all 1961-1975 2 and 4 Door Oldsmobiles equipped with power windows. These motors have a square body and replace original worn or inoperative motors.

M3898 Right Power Window Motor (passenger side) 1961-75 All 149.00 ea.

M3899 Left Power Window Motor (driver side) 1961-75 All 149.00 ea.



Power Window Door Jamb Wiring Conduit/Rubber Boot: Located at front door hinge area. Two used per car. Fits all 1965-68 models, and 1969-1970 Toronado models equipped with power windows and/or power door locks.

EWC6670 Wiring Rubber Conduit 1965-68 All, 1969-70 Toronado 59.00 ea.



HOOD INSULATION PADS

All Hood Insulation Pads are manufactured using gray fiberglass insulation, but without the embossments for hood braces or air filters. When installing, the smooth side faces the hood. Check your original for quantity of Hood Insulation Fasteners needed. Models earlier than 1964 use an adhesive to hold the insulation onto underside of hood. 1964 and newer used a combination of push-in fasteners and adhesive. We recommend 3M Spray Trim Adhesive or a similar quality product.



HI612

| | | | |
|---------------|---------------------|------------------------|-------|
| HI612 | Hood Insulation Pad | 1961-62 All | 69.00 |
| HI630 | Hood Insulation Pad | 1963 All | 69.00 |
| HI640 | Hood Insulation Pad | 1964 All | 69.00 |
| HI650 | Hood Insulation Pad | 1965-66 88-98-Starfire | 69.00 |
| HI670 | Hood Insulation Pad | 1967 88-98 | 69.00 |
| HI667T | Hood Insulation Pad | 1966-67 Toronado | 69.00 |
| HI680 | Hood Insulation Pad | 1968 88-98 | 69.00 |
| HI680T | Hood Insulation Pad | 1968-70 Toronado | 69.00 |
| HI690 | Hood Insulation Pad | 1969-70 88-98 | 69.00 |
| HI715 | Hood Insulation Pad | 1971-75 88-98 | 69.00 |
| HI760 | Hood Insulation Pad | 1976 88-98 | 69.00 |



| | | | |
|--------------|---------------------------------|-------------|----------|
| 11129 | Square Hood Insulation Fastener | 1964-70 All | 1.50 ea. |
| 11130 | Round Hood Insulation Fastener | 1971-75 All | 1.50 ea. |

Hood 'Pop-Up' Spring: Made from spring steel, bolts to radiator support. Causes the hood to pop up when pulling the hood release.

| | | | |
|---------------|--------------------|------------------------|-------|
| HS682F | Hood Pop Up Spring | 1968-69 All, 1970 Toro | 13.50 |
|---------------|--------------------|------------------------|-------|


COWL TO HOOD LACING STRIPS

Molded rubber or sponge rubber strip installs in engine compartment across the top of the cowl.

| | | | |
|--------------|-------------------|-------------|-------|
| CL61 | Cowl Lacing Strip | 1961-63 All | 47.00 |
| CL64 | Cowl Lacing Strip | 1964-67 All | 16.50 |
| CL68 | Cowl Lacing Strip | 1968-70 All | 19.00 |
| CL716 | Cowl Lacing Strip | 1971-76 All | 65.00 |



INNER FRONT FENDER A-FRAME SEALS



A Frame Seals are die cut from the original style, black masticated rubber using all original samples for correct fit and shape. Original style olive green metal fasteners, part number 3774, are sold separately.

| | | | |
|---------------|-------------------------------|------------------------|-----------|
| FCD19 | A-Frame Seals (uses 34 clips) | 1961 All | 49.00 pr. |
| FCD20 | A-Frame Seals (uses 26 clips) | 1962 All | 49.00 pr. |
| FCD21 | A-Frame Seals (uses 38 clips) | 1963-64 88-98-Starfire | 49.00 set |
| FCD22 | A-Frame Seals (uses 18 clips) | 1965-66 88-98-Starfire | 49.00 pr. |
| FCD23 | A-Frame Seals (uses 24 clips) | 1967-68 88-98 | 49.00 pr. |
| FCD24T | A-Frame Seals | 1966-70 Toronado | 39.00 pr. |
| FCD25 | A-Frame Seals | 1969-70 88-98 | 49.00 pr. |


Olive Green Metal Push-In Fasteners: Correct, 5/8" x 1/2" rectangular head push in metal fasteners painted flat olive green, used on A-Frame seals, cowl lacing, and various other areas under the hood.

| | | | |
|-------------|--|--------------------|----------|
| 3774 | Original Style Olive Green Metal Fasteners | 1961-70 All models | 2.00 ea. |
|-------------|--|--------------------|----------|




TRUNK COMPARTMENT

1962-75 Trunk Compartment Cardboard Side Panels and Mats: We have the 1962-64 Starfire die cut trunk cardboards and die cut trunk mats available. The 1962 Starfire version is available in Blue and Maroon only. The 1963-64 Starfire version is available in Black, Blue and Maroon. Other Trunk Mats listed from 1966-75 are made from the closest matched materials available. We no longer have available the foam backed, Tan Trunk Material for 1961-65 88, 1965-66 98, and 1966 Toronados.



TRM672



houndstooth pattern

1962 Starfire Convertible Trunk Cardboards



75.00 shipping surcharge on trunk cardboard kits sent to a U.S. address

| | | | | |
|-------------------|---|--|--------|-------|
| TCK61CV | Trunk Cardboard Set (Maroon, Blue or Black) | 1961 Starfire Convertible | 169.00 | |
| TCK62CM | Trunk Cardboard Set (Maroon) | 1962 Starfire Coupe | 169.00 | 2 pc. |
| TCK62CVM | Trunk Cardboard Set (Maroon) | 1962 Starfire Convertible | 169.00 | 4 pc. |
| TCK62CB | Trunk Cardboard Set (Blue) | 1962 Starfire Coupe | 169.00 | 2 pc. |
| TCK62CVB | Trunk Cardboard Set (Blue) | 1962 Starfire Convertible | 169.00 | 4 pc. |
| TM62CM | Trunk Mat Set (die cut Maroon felt) | 1962 Starfire Coupe | 299.00 | 7 pc. |
| TM62CVM | Trunk Mat Set (die cut Maroon felt) | 1962 Starfire Convertible | 299.00 | 7 pc. |
| TM62CB | Trunk Mat Set (die cut Blue felt) | 1962 Starfire Coupe | 299.00 | 7 pc. |
| TM62CVB | Trunk Mat Set (die cut Blue felt) | 1962 Starfire Convertible | 299.00 | 7 pc. |
| TCK634C | Trunk Cardboard Set (black) | 1963-64 Starfire Holiday Coupe | 169.00 | 2 pc. |
| TCK634CV | Trunk Cardboard Set (black) | 1963-64 Starfire Convertible | 169.00 | 4 pc. |
| TM634C | Trunk Mat Set (die cut black felt) | 1963-64 Starfire Holiday Coupe | 299.00 | 7 pc. |
| TM634CV | Trunk Mat Set (die cut black felt) | 1963-64 Starfire Convertible | 299.00 | 7 pc. |
| TM634CBL | Trunk Mat Set (Blue felt) | 1963-64 Starfire Coupe | 299.00 | 7 pc. |
| TCK634CBL | Trunk Cardboard Set (Blue) | 1963-64 Starfire Coupe | 169.00 | 2 pc. |
| TM634CVBL | Trunk Mat Set (Blue felt) | 1963-64 Starfire Convertible | 299.00 | 7 pc. |
| TCK634CVBL | Trunk Cardboard Set (Blue) | 1963-64 Starfire Convertible | 169.00 | 4 pc. |
| TM634CM | Trunk Mat Set (Maroon felt) | 1963-64 Starfire Coupe | 299.00 | 7 pc. |
| TCK634CM | Trunk Cardboard Set (Maroon) | 1963-64 Starfire Coupe | 169.00 | 2 pc. |
| TM634CVM | Trunk Mat Set (Maroon felt) | 1963-64 Starfire Convertible | 299.00 | 7 pc. |
| TCK634CVM | Trunk Cardboard Set (Maroon) | 1963-64 Starfire Convertible | 169.00 | 4 pc. |
| TM65HT | Trunk Mat (rubber aqua houndstooth) | 1965 88 Holiday Coupe and Conv. | 129.00 | |
| TM65C | Trunk Mat (rubber aqua houndstooth) | 1965-66 98 Convertible | 129.00 | 3pc. |
| TM66B | Trunk Mat (vinyl houndstooth) | 1966 88-Starfire Holiday Coupe and Conv. | 129.00 | |
| TM67B | Trunk Mat (vinyl houndstooth) | 1967-68 88 Holiday Coupe and Convertible | 129.00 | |
| THC678 | Trunk Hinge Box Covers (aqua houndstooth) | 1967-68 88 Convertible | 49.00 | pr. |
| TM68C | Trunk Mat (black felt material) | 1967-68 98 Holiday Coupe and Convertible | 129.00 | |
| TM69B | Trunk Mat (gray green material) | 1969-70 88 Holiday Coupe and Convertible | 129.00 | |
| TM70C | Trunk Mat (black felt material) | 1969-70 98 Holiday Coupe and Convertible | 129.00 | |
| TM70E | Trunk Mat (black felt material) | 1970 Toronado | 129.00 | 7pc. |
| TM715B | Trunk Mat (black felt material) | 1971-75 Delta 88 Holiday Coupe and Conv. | 129.00 | |

1965-70 88-98 Accessory Rubber Trunk Mat:

Accurate reproduction of an accessory which is highly desired by collectors. This mat has the correct ribbed pattern and the word 'OLDSMOBILE' molded into the rubber. Available in black only. Pictured at top of page.

TRM672 Accessory 'Oldsmobile' Rubber Trunk Mat 1965-70 88-98 199.00

Trunk Weatherstrip, Trunk Lid Bumpers, Spare Tire & Jack Parts

Trunk Weatherstripping: We offer the finest quality black sponge rubber weatherstrip available.

All 1961-75 2 doors use 18 feet, 1961-75 4 doors use 15 feet and 1966-75 Toronados use 12 feet.

| | | | |
|------------------|--------------------|---|-------|
| TWL75B-18 | Trunk Weatherstrip | 1961-70 88-98-Starfire (18 foot piece) | 39.00 |
| TWL75E-18 | Trunk Weatherstrip | 1971-76 88-98 (18 foot piece) | 39.00 |
| TWL75-16 | Trunk Weatherstrip | 1961-75 4 Dr & Toronado (16 foot piece) | 30.00 |



| | | | |
|--------------|-------------------|-------------|------|
| TLG61 | Trunk Lock Gasket | 1961-68 All | 3.50 |
| TLG68 | Trunk Lock Gasket | 1969-70 88 | 3.50 |



TB63

TB65

| | | | |
|-------------|------------------|-------------|----------|
| TB61 | Trunk Lid Bumper | 1961-68 All | 3.00 ea. |
| TB69 | Trunk Lid Bumper | 1969-75 All | 3.00 ea. |




Trunk Floor Rubber Plugs: Two different designs, both fit 1" hole in sheetmetal.

TB63 Floor Pan Plug 1963-69 All 5.00 ea.

TB65 Floor Pan Plug 1969-75 All 5.00 ea.

Jack Shaft Insulator and Jack Lift Pad:

| | | | |
|---------------|-----------------------------|---------------|-------|
| JRI68 | Jack Shaft Rubber Insulator | 1968-72 88-98 | 15.00 |
| JLP682 | Rubber Jack Lift Pad | 1968-72 88-98 | 15.00 |



Hold-Down Parts for Spare Tire:

| | | | |
|---------------|---|-------------|-------|
| ST6693 | Spare Tire Threaded Retaining Rod (cut to length) | 1966-75 All | 12.00 |
| ST6516 | Spare Tire Retaining Wing Nut | 1965-75 All | 9.50 |




Spare Tire Cover and Retainer: Pressboard cover with aqua and black houndstooth pattern. Fits 1963-64 Starfire Convertible and 1965-68 all Convertibles. Does not match the felt 1963-66 Trunk Material.

| | | |
|--------------|---|-------|
| STC61 | Pressboard Spare Tire Cover, houndstooth | 49.00 |
| ST618 | Spare Tire Cover Retainer, Cadmium plated as original | 29.00 |



ST6516



ST618

Washer Fluid Jars and Related Parts

Correct triangle glass bottle comes with metal cap and GM WJ7393 Optikleen decal. Used on all 1961-67 models. Translucent white plastic fluid jar for 1971-77 models includes the black cap.



WJ7393



| | | | |
|----------------|---|--------------------|-----------|
| 1481285 | 18" Silver Finish Wiper Blades | 1961-75 All | 29.50 ea. |
| OKB647 | Optikleen Triangular Glass Bottle with cap and decal | 1961-67 All | 37.50 |
| OKBC647 | Optikleen Bottle Metal Cap only | 1961-67 All | 8.50 |
| OB647 | Optikleen Bottle Metal Bracket | 1961-67 All | 29.00 |
| DC47 | Optikleen Decal for glass jar (moisten back to stick) | 1961-67 All | 8.50 |
| WJ7393 | Plastic Washer Fluid Jar with Cap | 1971-77 All models | 29.50 |
| WJC6894 | Windshield Washer Jar Cap | 1966-75 All models | 6.00 |
| WJF6421 | Windshield Washer Jar Filter | 1964-75 All models | 5.50 |
| 4460 | Windshield Washer Hose to Pump and Filter | 1961-75 All models | 2.00 ft. |
| 4457 | Windshield Washer Hose to Nozzles | 1961-75 All models | 2.00 ft. |



1963-75 Washer Pump Repair Kit: Contains the necessary parts to rebuild your washer pump. The correct style and application pumps are no longer available. This is a viable alternative to changing the entire wiper motor and washer pump assembly.

| | | | |
|----------------|------------------------|--------------------|-----------|
| WPRK638 | Washer Pump Repair Kit | 1963-75 All models | 24.50 kit |
|----------------|------------------------|--------------------|-----------|



RUBBER PARTS

HB59 Hood to Fender Bumper:
1961-62 All models 7.50 ea.

HB65 Hood to Fender Bumper:
1963-66 All models,
1966-67 Toronado 6.00 ea.

HB68 Hood to Fender Bumper:
1968-70 Toronado,
1969 88-98 6.00 ea.

HB68A Hood to Fender Bumper:
1968 88-98 6.00 ea.

HB70 Hood to Fender Bumper:
1970-75 All 6.00 ea.

HB73 Hood Bumper & Adjusting Stud:
(Front) 2 per car 1961-67 All 9.50 ea.

HB74 Hood Bumper & Adjusting Stud:
(Front) 2 per car. 1968-75 All 9.50 ea.

DB59 Door Lock Pillar Bumper:
1961-64 All 2 Doors 5.00 ea.

DB90 Door Lock Pillar Bumper:
1965-75 All models except 1966-70
Toronado. 5.00 ea.

DB66 Door Lock Pillar Bumper:
1966-70 Toronado 5.00 ea.

DB41 Door Lock Pillar Bumper:
Same shape as DB90 but larger. Fits
many 1965-70 models. 4.00 ea.

**Headlight Bucket to Body Bumper
Stop:** For 1966-67 Toronado.
Uses 4 per car.

HL66T Headlight Bumper 5.00 ea.

Fender Skirt Rubber: Correct extrusion and lengths
for the following applications.

FS12 Fender Skirt Rubber 1963-64 98 79.00 pr.

FS13 Fender Skirt Rubber 1965-66 98 83.00 pr.

FS15 Fender Skirt Rubber 1971-76 98 39.00 pr.




Door Handle and Door Lock Cylinder Gaskets:
Die cut per original. One set will service two handles.

DH612 Door Handle Gasket (4 pc)
1961-70 All exc. 1969-70 Royale 6.50 set

DH716 Door Handle Gasket (4 pc)
1971-76 All models 9.50 set

DCG61 Door Lock Cylinder Gasket
Fits 1961-77 All models 3.50 ea.




Door Jamb Light Switch Rubber Boot:
Fits 1961-64 88-98-Starfire, most 2 &
4 door models. Uses 2 or 4 per car.

DJB614 Light Switch Boot 6.00 ea.



DHS66 Bottom Drain Hole Sealing Strip:
Fits 1962-72 All models. 2 used per door. 5.00 ea.



RPC64 Rocker Panel Inner Rubber Cover:
For 1964-68 All models. Used as a drain hole
cover in rear wheel well. 5.00 ea.

**1959-64 Vacuum Hose Firewall
Grommet:** 2-7/8" wide oval with
four holes for vacuum hoses.

FG099 Vacuum Hose Grommet 37.00



Fuel Tank Door Bumpers: Reproduced exactly as
original for the correct applications.

GB35 Bumper 1966-67 Toronado and
1967-68 98 (uses one only) 5.00

GB40 Bumpers 1965-67 All 88's 10.00 pr.

GB50 Bumpers 1966 98, 1968-70 88's,
1969-70 98 10.00 pr.



Seat Back Bumpers: Fits 1961-72.

SB65 Oval Seat Bumper 7.00 ea.

SB61 Round Seat Bumper 7.00 ea.



1961-75 RUBBER WEATHERSTRIPPING

Convertible Roof Rail Weatherstrips: 1961-75 Convertible Roof Rail Weatherstrips and Windshield Pillar Weatherstrips are available to seal your convertible top. Roof Rail Weatherstrips are compression molded rubber with steel framing and have a better than original fit and appearance.

| | | | |
|---------------|--------------------------------------|----------------------------------|------------|
| RR614 | Roof Rail Weatherstrip (7 piece set) | 1961-64 88-Starfire Convertibles | 309.00 set |
| RR614C | Roof Rail Weatherstrip (7 piece set) | 1961-64 98 Convertibles | 529.00 set |
| RR656 | Roof Rail Weatherstrip (7 piece set) | 1965-66 88-Starfire Convertibles | 329.00 set |
| RR650 | Roof Rail Weatherstrip (7 piece set) | 1965-70 98 Convertibles | 349.00 set |
| RR670 | Roof Rail Weatherstrip (7 piece set) | 1967-70 88 Convertibles | 349.00 set |
| RR715 | Roof Rail Weatherstrip (5 piece set) | 1971-75 88 Convertibles | 289.00 set |
| WP620 | Windshield Pillar Weatherstrip | 1961-62 All Convertibles | 119.00 pr. |
| WP630 | Windshield Pillar Weatherstrip | 1963-64 All Convertibles | 99.00 pr. |
| WP650 | Windshield Pillar Weatherstrip | 1965 All Convertibles | 99.00 pr. |
| WP668 | Windshield Pillar Weatherstrip | 1966-68 All Convertibles | 99.00 pr. |
| WP690 | Windshield Pillar Weatherstrip | 1969-70 All Convertibles | 99.00 pr. |
| WP715 | Windshield Pillar Weatherstrip | 1971-75 All 88 Convertibles | 99.00 pr. |



RR614

2 Door Hardtop Roof Rail Weatherstrips:

Correct ready-to-install weatherstrips that include inserted tabs and molded ends for accurate installation.


| | | | |
|----------------|------------------------|--------------------------------------|------------|
| RR61 | Roof Rail Weatherstrip | 1961 88 Holiday Coupes | 203.00 pr. |
| RR62 | Roof Rail Weatherstrip | 1962 88-Starfire Holiday Coupes | 99.00 pr. |
| RR63 | Roof Rail Weatherstrip | 1963-64 88 Holiday Coupes | 99.00 pr. |
| RR63C | Roof Rail Weatherstrip | 1963-64 98 Holiday Coupe | 199.00 pr. |
| RR634SF | Roof Rail Weatherstrip | 1963-64 Starfire & Jetstar 1 Hol.Cpe | 203.00 pr. |
| RR65 | Roof Rail Weatherstrip | 1965-66 88-Starfire Holiday Coupes | 179.00 pr. |
| RR65C | Roof Rail Weatherstrip | 1965-68 98 Holiday Coupes | 99.00 pr. |
| RR67B | Roof Rail Weatherstrip | 1967-68 88 Holiday Coupes | 99.00 pr. |
| RR690B | Roof Rail Weatherstrip | 1969-70 88 Holiday Coupes | 99.00 pr. |
| RR713B | Roof Rail Weatherstrip | 1971-73 88 Holiday Coupes | 206.00 pr. |
| RR716 | Roof Rail Weatherstrip | 1971-74 98 HC, 1974-76 88 HC | 199.00 pr. |
| RR756C | Roof Rail Weatherstrip | 1975-76 98 Holiday Coupes | 115.00 pr. |
| RR66ET | Roof Rail Weatherstrip | 1966-70 Toronado | 99.00 pr. |



2 Door Hardtop and Convertible Molded Door Weatherstrips:

All weatherstrips are like the originals with molded ends and inserted retaining clips.

| | | | |
|---------------|--------------------|---------------------------------|-----------|
| DW61 | Door Weatherstrips | 1961-62 All Hol. Cpe and Conv. | 93.00 pr. |
| DW63 | Door Weatherstrips | 1963-64 All Hol. Cpe and Conv. | 93.00 pr. |
| DW66 | Door Weatherstrips | 1965-66 All Hol. Cpe.and Conv. | 93.00 pr. |
| DW66ET | Door Weatherstrips | 1966-70 Toronado | 93.00 pr. |
| DW67BC | Door Weatherstrips | 1967-68 All Hol. Cpe. and Conv. | 93.00 pr. |
| DW69BC | Door Weatherstrips | 1969-70 All Hol. Cpe and Conv. | 93.00 pr. |
| DW715 | Door Weatherstrips | 1971-75 88 Hol. Cpe. and Conv. | 93.00 pr. |



DW61

Door Body Pillar Sealing Strips:

Located directly under the Quarter Window Vertical Weatherstrips on the rear door jamb area.

| | | | |
|---------------|-----------------------|---|-----------|
| BP571 | Pillar Sealing Strips | 1961-64 88-98-Starfire Convertibles | 99.00 pr. |
| BP877 | Pillar Sealing Strips | 1961-64 88-98-Starfire Holiday Coupes | 99.00 pr. |
| BP844 | Pillar Sealing Strips | 1965-66 88-98-Starfire Holiday Coupes and Conv. | 69.00 pr. |
| BP667T | Pillar Sealing Strips | 1966-67 Toronado | 59.00 pr. |
| BP939 | Pillar Sealing Strips | 1967-68 88-98 Holiday Coupes and Convertibles | 99.00 pr. |
| BP690 | Pillar Sealing Strips | 1969-70 88-98 Holiday Coupes and Convertibles | 69.00 pr. |
| BP715 | Pillar Sealing Strips | 1971-75 88-98 Holiday Coupes and Convertibles | 85.00 pr. |



2 Door Hardtop and Convertible Quarter Window Weatherstrips:

Fits vertical leading edge of quarter window. Metal inserted rubber as original equipment.


| | | | |
|---------------|------------------------------|--|------------|
| QW614A | Quarter Window Weatherstrips | 1962 88-Starfire Holiday Coupes, 1963-64 88 Holiday Coupes | 69.00 pr. |
| QW614B | Quarter Window Weatherstrips | 1961-64 88-Starfire Convertibles | 69.00 pr. |
| QW614C | Quarter Window Weatherstrips | 1961-64 98 Convertibles | 69.00 pr. |
| QW614D | Quarter Window Weatherstrips | 1962-64 98 Holiday and Sport Coupes | 69.00 pr. |
| QW614E | Quarter Window Weatherstrips | 1961 88-98 Holiday Coupes, 1961-62 88 Holiday Sedans, 1963-64 Starfire-Jetstar I Holiday Coupes | 69.00 pr. |
| QW656B | Quarter Window Weatherstrips | 1965-66 98 Coupes and Conv., 1965-66 Starfire-Jetstar I Holiday Coupes | 119.00 pr. |
| QW656C | Quarter Window Weatherstrips | 1965-66 88 Holiday Coupes and Convertibles 1965 Starfire Convertible | 119.00 pr. |
| QW670T | Quarter Window Weatherstrips | 1966-70 Toronado | 49.00 pr. |
| QW678B | Quarter Window Weatherstrips | 1967-68 88 Holiday Coupes | 119.00 pr. |
| QW678C | Quarter Window Weatherstrips | 1967-68 88-98 Convertibles | 45.00 pr. |
| QW8485 | Quarter Window Weatherstrips | 1969-70 88-98 Holiday Coupes and Convertibles | 35.00 pr. |
| QW715 | Quarter Window Weatherstrips | 1971-75 88 Holiday Coupes and Convertibles | 69.00 pr. |
| QW715C | Quarter Window Weatherstrips | 1971-75 98 Holiday Coupes | 80.00 pr. |

4 Door Hardtop Roof Rail Weatherstrips (no center post):

| | | | |
|----------------|-------------------------|------------------------------------|-------------|
| RR612 | Roof Rail Weatherstrips | 1961-62 88 Holiday Sedans | 199.00 pr. |
| RR938 | Roof Rail Weatherstrip | 1961 98 4 window 4 Door Hardtop | 239.00 pr. |
| RR634 | Roof Rail Weatherstrips | 1963-64 88 Holiday Sedans | 239.00 pr. |
| RR634C | Roof Rail Weatherstrips | 1963-64 98 4 Window Holiday Sedans | 239.00 pr. |
| RR634CS | Roof Rail Weatherstrips | 1963-64 98 6 Window Holiday Sedans | 199.00 pr. |
| RR656B | Roof Rail Weatherstrips | 1965-66 88 Holiday Sedans | 199.00 pr. |
| RR6904B | Roof Rail Weatherstrip | 1969-70 88 & 98 4 Door Hardtop | 99.00 pr. |
| RR658 | Roof Rail Weatherstrips | 1965-66 98 Holiday Sedans | 99.00 pr. |
| RR714B | Roof Rail Weatherstrip | 1971-74 88 Holiday Sedans | 239.00 pr. |
| RR714C | Roof Rail Weatherstrips | 1971-74 98 Holiday Sedans | 239.00 pr. |
| RR146 | Roof Rail Weatherstrip | 1975-76 98 Holiday Sedans | 2997.00 pr. |

4 Door Hardtop (no post) Molded Door Weatherstrip:

| | | | |
|-----------------|-------------------------|---|------------|
| DW61SDF | Front Door Weatherstrip | 1961-62 88 & 98 Holiday Sedans | 209.00 pr. |
| DW937R | Rear Door Weatherstrip | 1961 98 Sport Sedan (style 3839) | 259.00 pr. |
| DW61SDR | Rear Door Weatherstrip | 1961-64 All 88 Holiday Sedans | 179.00 pr. |
| DW61CSDR | Rear Door Weatherstrip | 1961-62 All 98 Holiday Sedans (not Sport Sedan) | 199.00 pr. |
| DW63SDF | Front Door Weatherstrip | 1963-64 88 & 98 Holiday Sedan | 135.00 pr. |
| DW63CSDR | Rear Door Weatherstrip | 1963-64 All 98 Holiday Sedans (not Sport Sedan) | 199.00 pr. |
| DW67SDF | Front Door Weatherstrip | 1965-68 All 88 & 98 Holiday Sedans | 199.00 pr. |
| DW656HSR | Rear Door Weatherstrip | 1965-66 98 Holiday Sedan | 239.00 pr. |
| DW153 | Front Door Weatherstrip | 1969-70 88 & 98 4 Door Hardtop | 269.00 pr. |
| DW154 | Rear Door Weatherstrip | 1969-70 88 4 Door Hardtop | 279.00 pr. |
| DW213 | Rear Door Weatherstrip | 1969-70 98 4 Door Hardtop | 239.00 pr. |
| DW716 | Front Door Weatherstrip | 1971-76 88 & 98 4 Door Hardtop | 349.00 pr. |
| DW852 | Rear Door Weatherstrip | 1971-74 98 4 Door Hardtop | 299.00 pr. |
| DW406 | Rear Door Weatherstrip | 1975-76 98 4 Door Hardtop | 269.00 pr. |
| DW781 | Rear Door Weatherstrip | 1971-74 88 4 Door Hardtop | 249.00 pr. |
| DW782 | Rear Door Weatherstrip | 1975-76 88 4 Door Hardtop | 249.00 pr. |



2 and 4 Door Sedan (With Post) Door Weatherstrip:

Molded door weatherstrips available for the following 2 and 4 door sedans. Due to limited demand, not all applications will be in stock. Please keep this in mind when ordering and allow approximately 2 weeks for delivery. For applications not listed here, order part number **DW85A**. DW85A is molded in the correct configuration with nylon push-in tabs pre-inserted. Two door models require approximately 28 feet, while 4 door models use approximately 28 feet for the front doors and 26 feet for the rear doors.

| | | | |
|-----------------|-------------------------|---|-------------|
| DW85A | Door Weatherstrip | 1961-75 Models Using Push-in Tab Type | 5.00 ft. |
| DW61PC | Door Weatherstrip | 1961 2 Door Sedans | 149.00 pr. |
| DW614SDF | Front Door Weatherstrip | 1961-64 88-98 4 Door Sedans and 88 Wagons | 119.00 pr. |
| DW614SDR | Rear Door Weatherstrip | 1961-64 88-98 4 Door Sedans | 89.00 pr. |
| DW614SWR | Rear Door Weatherstrip | 1961-64 88 Wagons | 129.00 pr. |
| DW656F | Front Door Weatherstrip | 1965-66 88 4 Door Sedans | 119.00 pr. |
| DW656R | Rear Door Weatherstrip | 1965-66 88 4 Door Sedans | 119.00 pr. |
| DW705 | Front Door Weatherstrip | 1965-66 98 4 Door Sedans | 219.00 pr. |
| DW552 | Rear Door Weatherstrip | 1965-66 98 4 Door Sedans | 209.00 pr. |
| DW678F | Front Door Weatherstrip | 1967-68 88 4 Door Sedans | 119.00 pr. |
| DW678R | Rear Door Weatherstrip | 1967-68 88 4 Door Sedans | 119.00 pr. |
| DW690SDF | Front Door Weatherstrip | 1969-70 88 4 Door Sedans | 179.00 pr. |
| DW690SDR | Rear Door Weatherstrip | 1969-70 88 4 Door Sedans | 199.00 pr. |
| DW690CF | Front Door Weatherstrip | 1969-70 98 4 Door Sedans | 259.00 pr. |
| DW716SDF | Front Door Weatherstrip | 1971-76 88 4 Door Sedans and Custom Cruiser | 99.00 pr. |
| DW714SDR | Rear Door Weatherstrip | 1971-74 88 4 Door Sedans | 99.00 pr. |
| DW756SDR | Rear Door Weatherstrip | 1975-76 88 4 Door Sedans | 1491.00 pr. |
| DW716SWR | Rear Door Weatherstrip | 1971-76 Custom Cruiser | 99.00 pr. |



WINDOW CHANNEL / SWEEPERS

Universal Window Sweepers: These sweepers can be used where kits are not available.

C505 sweepers have a rubber strip with a chrome bead and metal backing, trim to fit.

The C618 sweepers do not have a stainless bead and are used on cars with the outer reveal


molding option. C667T has a round black bead with metal backing and black fuzzy material, trim to fit.

| | | | |
|--------------|-----------------------|--|-----------|
| C505 | Outer Window Sweepers | 1961-64 All without garnish molding (4 ft. length) | 39.00 ea. |
| C505A | Outer Window Sweepers | 1961-64 All without garnish molding (2 ft. length) | 19.50 ea. |
| C618 | Outer Window Sweepers | 1961-68 All with garnish molding (4 ft. length) | 39.50 ea. |
| C667T | Outer Window Sweepers | 1966-67 Toronado (4 ft. length) | 39.50 ea. |



Window Sweeper Kits: The following sweeper kits are available, trimmed to correct size and ready to install.

| | | | |
|-----------------|----------------------------|---|------------|
| CK678AB4 | Outer Window Sweepers | 1967-68 88 convertible | 169.00 kit |
| CK6898CV | Window Sweeper Kit (8 pcs) | 1968 98 convertible | 169.00 kit |
| CK7098CV | Window Sweeper Kit (8 pcs) | 1970 98 convertible | 169.00 kit |
| CK715A4 | Outer Window Sweepers | 1971-75 88 convertible, NO reveal molding | 199.00 kit |
| CK715A4R | Outer Window Sweepers | 1971-75 88 convertible, with reveal molding | 129.00 kit |



Front Windshield Rubber Channel: One piece endless ring. Due to limited demand, not all applications will be in stock. Please bear this in mind when ordering and allow for approximately 2 weeks delivery time.

| | | | |
|--------------|--------------------|---|--------|
| WR055 | Windshield Channel | 1961-62 All 98 exc. Conv., 1962 4 Doors exc. 98 Sport Sedan | 199.00 |
| WR858 | Windshield Channel | 1961-62 88-98-Starfire Convertibles | 189.00 |
| WR793 | Windshield Channel | 1962 88-98-Starfire Holiday Coupes, 1962 98 Sport Sedan | 199.00 |
| WR851 | Windshield Channel | 1963-64 88-98-Starfire Convertibles | 179.00 |
| WR788 | Windshield Channel | 1963 Starfire Holiday Coupes, 1964 Starfire-Jetstar I Holiday Coupes, 1963-64 88 Holiday Sedans | 179.00 |
| WR731 | Windshield Channel | 1963-64 88-98 Holiday Coupes, 98 Sport Sedans (4 window) | 169.00 |
| WR286 | Windshield Channel | 1963-64 88 4 Door Post Sedans and Wagons, 98 4 Door Post Sedans and Luxury Sedans | 269.00 |

Rear Window Rubber Channel: One piece endless ring. Due to limited demand, not all applications will be in stock. Please bear this in mind when ordering and allow for approximately 2 weeks delivery time.

| | | | |
|--------------|---------------------|--|--------|
| RW823 | Rear Window Channel | 1961 98 Holiday Coupe | 239.00 |
| RW700 | Rear Window Channel | 1961 88 2 and 4 Door Post Sedans | 249.00 |
| RW634 | Rear Window Channel | 1961 88 Holiday Coupes | 189.00 |
| RW387 | Rear Window Channel | 1961-62 98 4 Door Post Sedans and Holiday Sedans | 229.00 |
| RW559 | Rear Window Channel | 1962 88- Starfire Hol Cpe, 1963-64 88 Hol Cpe | 159.00 |
| RW816 | Rear Window Channel | 1963-64 98 Sports Sedans (4 window) and Hol Cpe | 229.00 |
| RW507 | Rear Window Channel | 1962-64 88 4 Door Post Sedans | 199.00 |
| RW067 | Rear Window Channel | 1963-64 Starfire Holiday Coupes | 169.00 |

Front Door Vent Window Weatherstrip Set:

Applies to most 1961-68 Full Size Oldsmobiles. Tooled in curved molds for correct fit. Set of 4 pieces.

| | | | |
|----------------|-----------------------|--|------------|
| VR614B | Vent Weatherstrip Set | 1961-62 88-98-Starfire Holiday Coupes and Conv. | 149.00 set |
| VR612 | Vent Weatherstrip Set | 1961-62 88-98 2 and 4 Door Post Sedans | 269.00 set |
| VR634 | Vent Weatherstrip Set | 1963-64 Starfire Convertibles, 1963-64 88-98 Holiday Coupes and Convertibles, 1963-64 98 Sports Sedans | 159.00 set |
| VR634C | Vent Weatherstrip Set | 1963 Starfire Holiday Coupes, 1964 Starfire-Jetstar I Holiday Coupes, 88 Holiday Sedans | 199.00 set |
| VR634S | Vent Weatherstrip Set | 1963-64 88-98 4 Door Sedan and Wagon | 159.00 set |
| VR658BC | Vent Weatherstrip Set | 1965-68 88-98 Holiday Coupes and Convertibles | 169.00 set |
| VR658 | Vent Weatherstrip Set | 1965-68 88 4 Door Post Sedans | 249.00 set |
| VR595 | Vent Weatherstrip Set | 1965-68 98 4 Dr Sedan (body style 8469 & 8669) | 269.00 set |



Flexible Vertical Vent Window Channel: For use in all 1965-68 2 Doors. This part is used exclusively for vent frame to front door window channeling. Sold in pairs of 35" strips that include the top molded end bumper. Trim to proper length.

| | | | |
|-----------------|---------------------------|---|-----------|
| C909-645 | Vertical Ventilator Strip | 1965 All Holiday Coupe and Convertible | 79.00 pr. |
| C909-667 | Vertical Ventilator Strip | 1966-67 All Holiday Coupe and Convertible | 79.00 pr. |
| C909-680 | Vertical Ventilator Strip | 1968 All Holiday Coupe and Convertible | 79.00 pr. |



Trunk Weatherstripping: We offer the finest quality black sponge rubber weatherstrip available. No unsightly splice marks or oversize extrusions that make closing the trunk lid a difficult task. All 1961-75 2 doors use 18 feet, 1961-75 4 doors use 15 feet and 1966-75 Toronados use 12 feet.

| | | | |
|------------------|--------------------|---|-------|
| TWL75B-18 | Trunk Weatherstrip | 1961-70 88-98-Starfire (18 foot piece) | 36.00 |
| TWL75E-18 | Trunk Weatherstrip | 1971-76 88-98 (18 foot piece) | 36.00 |
| TWL75-16 | Trunk Weatherstrip | 1961-75 4 Dr & Toronado (16 foot piece) | 30.00 |



8008 3M Weatherstrip Adhesive:

Black rubber to metal cement, 5 ounce tube.

15.00 ea.



sales@fusick.com


16

fusickautomotiveproducts.com

RUBBER BUMPER FILLERS

1962-68 88-98-Toronado Bumper Fillers: Ornamental rubber parts located on either side of the front and rear bumpers. A necessary replacement when installing new or rechromed bumpers. Sold in pairs only.

| | | | |
|----------------|----------------------------|---------------------------------|-----------|
| BF62BCF | Front Bumper Fillers | 1962 All models | 49.00 pr. |
| BF62BCR | Rear Bumper Fillers | 1962 All except. Station Wagon | 49.00 pr. |
| BF63BCF | Front Bumper Fillers | 1963 All models | 42.50 pr. |
| BF63BR | Rear Bumper Fillers | 1963 All except 98 and Wagons | 42.50 pr. |
| BF63CR | Rear Bumper Fillers | 1963 98 | 45.00 pr. |
| BF64BCF | Front Bumper Fillers | 1964 All models | 49.00 pr. |
| BF64CR | Rear Bumper Fillers | 1964 98 models only | 45.00 pr. |
| BF65BCF | Front Bumper Fillers | 1965 All models | 42.50 pr. |
| BF65BR | Rear Bumper Fillers | 1965 All except 98 | 42.50 pr. |
| BF66BCF | Front Bumper Fillers | 1966 all except Toronado | 42.50 pr. |
| BF66BR | Rear Bumper Fillers | 1966 All except Toronado and 98 | 42.50 pr. |
| BF66CR | Rear Bumper Fillers | 1966 98 models only | 42.50 pr. |
| BF66EUF | Front Upper Bumper Fillers | 1966-67 Toronado only | 49.00 pr. |
| BF66ELF | Front Lower Bumper Fillers | 1966-67 Toronado only | 49.00 pr. |
| BF66ER | Rear Bumper Fillers | 1966-67 Toronado only | 49.00 pr. |
| BF678CR | Rear Bumper Fillers | 1967-68 98 models only | 39.00 pr. |
| BF68BR | Rear Bumper Fillers | 1968 88 models only | 42.50 pr. |



TORONADO TRUNK RUBBER DRAIN HOSES AND TUBES



These drain hoses and tubes fit all 1966-70 Toronados and allow the water to drain through your trunk. Missing or deteriorated pieces are the cause of most of the trunk rust problems in 1966-70 Toronados. Hard Rubber Hose used on the upper, while soft rubber tubes used for the lower. The ends are molded as original and come with the proper size clamps. The lower end has been left open to allow free flow of debris. Sold in pairs only.

| | | |
|------------------|---|-----------|
| 7630704/5 | 1966-70 Toronado Duct Panel Upper Drain Hoses | 89.00 pr. |
| 7630702/3 | 1966-70 Toronado Duct Panel Lower Drain Tubes | 85.00 pr. |

Dome Lenses, Courtesy Lamp Lenses and Housings

CL877 Courtesy Lamp Lens at Rear Seat Arm Rest Area on 1961-70 Convertibles. Used with CLH622 Housing. Lens measures 1 1/2" X 1 1/4" 10.00 ea.



CLH622 Courtesy Lamp Housing: Located in lower rear arm rest area. Plated with bright chrome. This part is difficult to replate without losing the line detail. Fits all 1961-70 Convertibles. Companion lens is CL877 above. 29.00 ea.



DL505 Dome light Lens on side roof rail: Fits 1961-63 Super 88 Wagons on either side at side roof rail area above the side windows. Measures 3 1/2" X 1 1/2" 15.00 ea.



DL506 Center Roof Dome Light Lens: Fits All 1961-64 with a Dome Light in the center of the roof except for wagons. Opaque lens measures 4 1/2" X 2" and has a double raised line down the center. 15.00



1961-64 Side Roof Dome Light Lens: Fits 1961-64 models except conv. & wagons in roof rail area. Lens measures 6 1/4" long X 1 1/2" wide at widest point. Uses two lenses per car.

DL591 Side Roof Dome Lens 1961-64 36.00 ea.

Door Panel Courtesy Lamp Lenses:

4 to 8 lenses used per car. Lamp housing uses one red and one white lens per side. Fits 1964 Starfire-Jetstar I, 1965 Starfire-Jetstar I-98 LS, 1966 Starfire-98 LS, 1967 Delta 88 Custom-98 Conv and LS, 1968 Toronado-Delta 88 Custom-98 Conv and LS, 1969 98 Conv and LS, 1970 Delta 88 Royale-98 Convertible-Toronado Custom, 1971-75 Delta 88 Royale Coupe and Conv, 1971-74 98 Sedans, 1971-74 Toronado.

| | | | |
|--------------|--------------------------------|------------------|-----------|
| CL32W | White Courtesy Door Panel Lens | See Above | 10.00 ea. |
| CL33R | Red Courtesy Door Panel Lens | See Above | 10.00 ea. |
| CL30W | White Courtesy Door Panel Lens | 1966-67 Toronado | 10.00 ea. |
| CL31R | Red Courtesy Door Panel Lens | 1966-67 Toronado | 10.00 ea. |

CL600 Courtesy Lens at rear sail panel. 1962-65 All Holiday Coupes, 1966-68 All except Toronado and Convertibles. Lens measures 2" diameter. 2 used per car. 9.00 ea.



CLH627 Courtesy Light Housing: Mounts on inside rear sail panel. Excellent chrome finish with correct ribbed section and white painted inside. Fits 1962-64 all except wagons and 98 Luxury Sedan, 1965 All except Starfire & Wagons, 1966-67 Except 98 Luxury Sedan & Toronado, 1968 88s & 98 Hol. Cpe., Hol. Sedan, Town Sedan. 49.50 ea.



DL68 Side Roof Dome Lens 1965 98 4 Doors, 1965-66 Starfire Hol Cpe, 1966-67 98 Luxury Sedans. Lens measures 6" x 1 1/2" and has four mounting tabs with correct lines in lens. 10.00 ea.



CL334 Courtesy Lamp Lens at Rear Upper Shelf Area 1966-70 Toronado. Opaque lens measures 10" X 1" and has six mounting tabs that fit into housing. 39.50 ea.

CL819 Courtesy Lamp Lens at Rear Upper Shelf Area: 1969-70 Delta 88-Delta 88 and 98 Holiday Coupe, Holiday Sedan and Town Sedan, 1971-72 Delta 88-Delta 88 Custom-Delta 88 Royale Holiday Coupe and Holiday Sedan, 1971-72 98 and Toronado. 10.00 ea.



CL326 Courtesy Lamp Lens at Rear Seat Arm Rest Area 1971-75 Delta 88 Convertible. Opaque lens measures 2" X 1 1/4" 10.00 ea.



Interior Carpet Sets

1961-64 88 & 98 Carpet Sets: 1961-62 Dynamic 88 and Super 88 used a molded Tuxedo carpeting which is the appropriate loop carpet color with black strands interwoven into the material. 1963-64 Dynamic 88, Super 88 and 98 models were equipped with a 80/20 loop carpeting. All carpet sets are sold on a custom order basis, call or send for color samples before ordering. **NO RETURNS ON CUSTOM ORDERED CARPET SETS.**

1966-76 Toronado Carpet Sets: 1966-73 Toronados came with a 80/20 loop Carpeting while 1974-76 Toronados had pile carpeting. Colors available for the Pile Carpeting will be the same as listed below for 1965-75 88s & 98s. All carpet sets are sold on a custom order basis, call or send for color samples before ordering. **NO RETURNS ON CUSTOM ORDERED CARPET SETS.**

Tuxedo Carpeting

1961-62 Tuxedo Carpeting available in the following colors, \$ **489.00 set**

- | | |
|-------------------|----------------------|
| Copper/Black #F-6 | Green/Black #983 |
| Blue/Black #D-4 | Red/Black #C-3 |
| Fawn/Black #1076 | Turquoise/Black #B-2 |

80/20 Loop Carpeting

1963-64, 1966-73 Toronado 80/20 Loop carpeting available in the following colors, \$ **299.00 set**

- | | |
|-----------------------|--------------------|
| Black #01-003 | Beige #11-002 |
| Green #8-1011 | Blue #16-013 |
| Medium Green #38-1900 | Medium Blue #6-016 |
| Gray #22-893 | Red #41-6364 |
| Dark Gray #35-1956 | Turquoise #5-883 |
| Fawn #19-020 | Copper #39-1966 |



1965-75 88, 98 & Starfire Carpet Sets: All sets include backing, harmonizing heel pad and binding. Carpets are cut to manufacturer's specifications with pressure molded floor pan areas for correct fit. Carpets are not in stock, so allow 2-3 weeks for delivery. Since carpets are a special order item, we require your color sample approval before we place your order. Request samples when you place an order. **NO RETURNS ON CUSTOM ORDERED CARPET SETS.** Extra carpet material by the yard (36" X 72") is available for 55.00 per yard. Specify number of yards required and order by color number of carpet.

1965-73 88s & 98s LOOP CARPET 299.00 Set


- | | |
|--------------------------|----------------------------|
| 01-003 Black | 11-002 Light Saddle |
| 41-6364 Red | 12-1021 Dark Saddle |
| 4-105 Green/Gold | 13-010 Maroon |
| 5-883 Turquoise | 45-1970 Dark Green |
| 16-013 Dark Blue | 20-022 Gold |
| 10-017 Dark Brown | |

1974-76 88s & 98s PILE CARPET 299.00 Set

- | | |
|----------------------|---------------------|
| 801 Black | 875 Oxblood |
| 819 Dark Blue | 825 Maroon |
| 807 Dark Grey | 830 Buckskin |
| 820 Saddle | 810 Brown |
| 809 Green | 1804 Silver |
| 815 Red | |

Sound Deadener Package: This is the thick, tar like rubber material found between the carpet and the body floor pan. Sound Deadener should be replaced when installing new carpet.

- | | | |
|-------------------------------------|-------------------------|--------|
| SDM20 Sound Deadener Package | 1961-64 All 88/Starfire | 129.00 |
| SDM30 Sound Deadener Package | 1965-70 All 88/Starfire | 129.00 |
| SDM50 Sound Deadener Package | 1971-76 All 88s | 129.00 |



Door Panel Reflectors: Red reflective lenses with chrome trim attaches to lower door panels on many 1968-80 Oldsmobile 98 and Toronado models.

- | | | |
|------------------------------------|----------------|-----------|
| DPR702 Door Panel Reflector | 1968-80 models | 40.00 ea. |
|------------------------------------|----------------|-----------|





1961-75 88, 98, Starfire and Toronado Sill Plates: Aluminum sill plates add the final touch to your new carpet installation. High quality aluminum stampings with correct textures and designs for most 1961-75 Oldsmobile models. New sill plates include the Fisher Body emblem and fastening screws.

| | | | |
|----------------|-------------------------------|--|------------|
| SP614 | Door Sill Plates | 1961-64 All 2 Doors | 99.00 pr. |
| SP6144D | Door Sill Plates | 1961-64 All 88 4 Door Sedans & Wagons | 129.00 set |
| SP6667 | Door Sill Plates | 1965-70 2 Doors except Toronado | 99.00 pr. |
| SP650 | Door Sill Plates | 1965-70 All 4 Door models | 139.00 set |
| SP670T | Door Sill Plates | 1966-70 Toronado | 129.00 pr. |
| SP7180 | Door Sill Plates | 1971-75 All 2 Doors and Toronado | 149.00 pr. |
| 1799 | Door Sill Plate Screw Package | All models (pkg. of 10, included with above) | 4.50 pkg. |




SP614



SP670T



SP7180



1965-70 88 & 98 Rubber Floor Mats

The Rubber floor mats fit 1965-70 88 and 98 models. Mats are available in black only. Front mats have the word 'OLDSMOBILE' molded in the rubber as original, and are licensed by General Motors. Sold in pairs for front or rear, or in sets of four.

| | | | |
|---------------|-------------------|---------------|------------|
| FM647S | Floor Mat Set | 1965-70 88-98 | 219.00 set |
| FM647F | Front Mats (pair) | 1965-70 88-98 | 159.00 pr. |
| FM647R | Rear Mats (pair) | 1965-70 88-98 | 79.00 pr. |

1966 Toronado Driver Side Rubber Floor Mat: Rubber floor mat insert is used on the front drivers side only. Installs inside chrome trim and sheetmetal pan that attaches onto the floor. Mat features correct ribbed design in black rubber and includes a die cut sheet of foam padding for the underside, also includes a hardware package to re-install assembly onto floor pan.


| | | | |
|--------------|--------------------------|---------------|--------|
| FM66T | Front Driver's Floor Mat | 1966 toronado | 179.00 |
|--------------|--------------------------|---------------|--------|



underside

1961-64 Firewall Insulators: High quality insulation bonded to a molded, textured, black plastic shell. All holes are pre-punched for steering column and heater box. Fits all 1961-64 88-98-Starfire models.

| | | | |
|----------------|--------------------|--------------------------|--------|
| FP612 | Firewall Insulator | 1961-62 All models | 349.00 |
| FP634 | Firewall Insulator | 1963-64 All coupes | 229.00 |
| FP634CV | Firewall Insulator | 1963-64 All convertibles | 229.00 |



FP612

Manual Seat Adjuster Chrome Knob: Chrome 'T' design Seat Adjuster Knob for all 1961-64 models with manual seat adjustment. Attaches with included allen screw.

SAK614 Chrome Seat Adjuster Knob 1961-64 29.00

1967-72 Hazard Flasher Knobs: Two different styles available, check your car for proper application. Chrome knobs have the word 'Flasher' embossed into them and thread into switch on column.

HFK672A Hazard Flasher Knob 1967-72 (smaller version) 16.50

HFK672 Hazard Flasher Knob 1967-72 (larger version) 16.50



1968 Toronado Dash Knobs and Bezels

New Dash Knobs and Dash Bezels are made in aluminum for lasting durability. Black anodized where applicable with silver highlights. Available for 1968 Toronado models only. Headlight Switch Knob comes complete with rod on back to insert into switch.

IB68 Ignition Lock Bezel 1968 Toronado 40.00


CDB68 Cigarette Lighter Dash Bezel 1968 Toronado 41.00

WDB68 Wiper Switch Dash Bezel 1968 Toronado 41.00

HDB68 Headlight Switch Bezel 1968 Toronado 41.00

WSK68 Wiper Switch Control Knob 1968 Toronado 35.00

HSK68 Headlight Switch Knob 1968 Toronado 35.00



GM Accessory Dash Compass: Desirable accessory originally available at GM dealers. Attaches to dash with included mounting plate.

983335 GM Accessory Dash Compass 75.00



1965-67 Chrome Arm Rest Bases and Arm Rest Pads: New chromed plastic Arm Rest Bases Fit 1965 Jetstar, Jetstar I, Super 88 2 Dr hardtop & Convertible models, 1966-67 all 88 and Starfire except 4 Dr post Sedan. Also applies to 1966-67 Standard Toronados (non Deluxe models). Bases and pads are sold in pairs, separately. Arm Rest Pads are only available in black.

AB667 Chrome Arm Rest Bases 1965-67 models listed 79.00 pr.

ARP667BL Black Arm Rest Pads 1965-67 models listed 86.00 pr.



1968 88 Arm Rest Bases and Pads: Arm rest bases and pads for 1968 Delmont 88 Holiday Coupe and convertible, 1968 Delta 88 and Delta 88 Custom Holiday Coupes. Pads measure 16 1/2" and are only available in black.

ARP680 Arm Rest Pads 1968 88 models 99.00 pr.

ARP680B Arm Rest Bases 1968 88 models 99.00 pr.

ABM680 Arm Rest Base Molding 1968 88 models 39.00 pr.



1969-70 Chrome Armrest Base Plates: Chrome Armrest Backing plates used on 1969-70 Ninety-Eight, Delta 88 & Delta 88 Custom Holiday Sedans and Town Sedan models.

AB692 Chrome Arm Rest Base Plates 1969-70 55.00 pr.

Inside Rearview Mirrors and Brackets

Rearview Mirrors: New inside rearview mirrors feature polished stainless steel backings and the day/night flip levers.

549IMS



| | | | |
|---------------|------------------------------------|---------------------------------------|--------|
| 549IMS | Inside Day/Night Mirror | 1961-66 All models | 105.00 |
| IM6713 | Inside Day/Night Mirror | 1967-68 All models | 65.00 |
| IM6981 | Inside Day/Night Mirror | 1969-71 All models | 65.00 |
| IMS522 | Inside Mirror to Bracket Set Screw | 1961-69 All, 1970 All except Toronado | 3.50 |



IM6713



IM6981



IM6981L

Accessory Map Light Rearview Mirror: New reproduction of the desirable rearview mirror with map light option. Available for 1969-71 models, and can also be used on 1972 models. New mirror features polished stainless steel backing, wiring pigtail, day/night lever, map light lens and switch.

| | | | |
|----------------|---------------------------|--------------------|--------|
| IM6981L | Map Light Rearview Mirror | 1969-71 All models | 109.50 |
|----------------|---------------------------|--------------------|--------|

1961-64 Convertible Interior Rear View Mirror Bracket: Applies to 1961-64 Convertible models only. Chrome plated bracket includes mirror set screw.

| | | | |
|----------------|-----------------------------------|---------------------|-------|
| 4757750 | Interior Rear View Mirror Bracket | 1961-62 Convertible | 95.00 |
| IRV634 | Interior Rear View Mirror Bracket | 1963-64 Convertible | 79.00 |



4757750



IRV634

1968-69 Toronado and 1968 98 Rearview Mirror Bracket: Chrome plated support arm and mounting bracket for 1968-69 Toronado and 1969 98 all exc. convertibles.

| | | | |
|---------------|-----------------------|----------------------------------|-------|
| IRV682 | Inside Mirror Bracket | 1968-69 Toro, 1968 98 exc. conv. | 49.00 |
|---------------|-----------------------|----------------------------------|-------|



IRV682

Glove Box Liners

We have the following die-cut Glove Boxes available. All are pre-assembled with the original style gray flocked lining.

| | | | |
|--------------|-------------------|-----------------------------------|-------|
| GB61 | Glove Box | 1961 All | 49.00 |
| GB612 | Console Glove Box | 1961-62 All | 49.00 |
| GB62 | Glove Box | 1962 All without Air Conditioning | 49.00 |
| GB62A | Glove Box | 1962 All with Air Conditioning | 49.00 |
| GB63 | Glove Box | 1963 All | 49.00 |
| GB64 | Glove Box | 1964 All | 49.00 |
| GB65 | Glove Box | 1965-66 All except Toronado | 49.00 |



Glove Box Light Switch: New Light Switch available for all 1969-75 88 & 98 models. Switch is also used on 1970 88-98 & Toronado in the console box.

| | | | |
|---------------|--------------------------------|---------------|-------|
| CLS702 | Glove Box/Console Light Switch | 1969-75 88-98 | 35.00 |
|---------------|--------------------------------|---------------|-------|



Power Window and Power Seat Switches

1961-72 Power Window Switch Restoration Service: Restoration service available for the 4 Button Power Window Switches located in the arm rest. Requires your original switch be sent in advance. Switches are cleaned and restored to original working order and bench tested.

PWSR614 Power Window Switch Restoration 1961-72 Oldsmobile 259.00



1961-67 Power Window Switch: Two button switch with chrome housing used on 1961-62 Starfires on the console, and 1963-67 98 models with power vent windows. Reproduction switch includes the chrome housing.

4434589 Power Window Switch 1961-67 models 169.00 ea.



1961-64 Power Window Switch Bases: Four Button Switch Base for left front door, Single Button Switch Bases for the right front door and rear door or quarters. All new electrical contacts replace often worn or inoperable switch bases. Check applications below carefully.

4723099 Left Front Power Window Switch Base (4 button) 115.00

1961-63 Dynamic & Super 88, 1961-62 98

4723098 Right Front Power Window Switch Base (1 button) 45.00


1961-63 Dynamic & Super 88, 1961-62 98

4723098 Rear Door / Quarter Power Window Switch Base (1 Button) 45.00

1961-3 Dynamic & Super 88 Holiday Coupe & 4 Door

4728670 Rear Quarter Power Window Switch Base (1 button) 45.00

1961-64 Starfire & 98 2 Door models,
1963-64 Dynamic 88, Super 88, Jetstar 88 Conv.



Power Window Switch Retaining Clips: Small spring steel retaining clip used on 1961-63 power window switches.

PWSC605 Power Window Switch Retaining Clip 1961-63 Oldsmobile 5.00 ea.



Door Panel Mount Power Window Switches:

Four Button switch for driver's door and single button switches for passenger door and rear doors or quarters. Will not work on cars equipped with power window buttons on arm rests.

PWS6470 Single Button Power Window Switch 38.50 ea.

1964 88 models, 1965-70 All 88s & Starfire,
1968-69 98 Town Sedan, 1966-69 Toro w/ standard interior

PWS6471 Four Button Power Window Switch 69.50

1964 88 models, 1965-70 All 88s & Starfire,
1968-69 98 Town Sedan, 1968-69 Toro w/ standard interior

PWS7130 Single Button Switch 43.00 ea.

1971-72 All, 1973-75 All 88s

PWS7131 Four Button Switch 89.00

1971-72 All, 1973-75 All 88s



PWS6470



PWS6471



PWS7130



PWS7131



PDL717

1971-75 Power Door Lock Switch: Used on 1971-75 88-98-Toronado models with power door locks and switches mounted on door panel. New Chrome switch replaces worn or broken originals.

PDL717 Power Door Lock Switch 1971-75 All 75.00 ea.

Power Window and Door Lock Pigtails: Replacement pigtail wiring and connector for single button switches.

PWP647 Single Power Window Switch Pigtail 1964-77 29.00

PLP706 Power Door Lock Switch Pigtail 1971-75 29.00



PWP647

PLP706



Two Way Power Seat Switch Base: New electrical contacts replace worn and corroded originals. Used on 1961-64 Oldsmobile Starfire models equipped with two way power seat. Includes new retaining clips.

4728670 Two Way Power Seat Switch Base 1961-64 Starfire 45.00



Six Way Power Seat Switch Base: New electrical contacts replace worn or corroded originals. For following Oldsmobiles equipped with six way power seats; 1961-65 all models except 1965 98, 1966-72 models where buttons are on side seat panel, 1973-83 all models. Please compare your original to our photos, note pin alignment, pin bussing and notched cut out location in relation to where the word "TOP" is molded in base. If your original base differs from photos please contact us, we may be able to supply a similar base that will work for your switch.

9711651 Six Way Power Seat Switch Base 1961-81 models 125.00

9711651



Six Way Power Seat Rocker Button Assembly: New toggle lever and rocker button assembly for 1961-81 Oldsmobile models equipped with the Six Way Power Seat. Used with six way base assembly listed above.

9711696 Power Seat Button Assembly 1961-81 models 49.00

9711696



Power Seat Relay: For 4 or 6 way power seats, fits the following applications: 1965 models with 4 or 6 way except for bucket seats, 1966 Starfire, 1966-70 Toronado with 4 way buckets, 1966-72 88-98-Starfire-Toronado with 6 way seats except 1971 Toronado.

5717528 Power Seat Relay 1965-72 above models 59.95



Power Options Circuit Breaker: 40 Amp Power window and power seat control Circuit Breaker for all 1962-70 models except Toronado.

4849847 Power Options Circuit Breaker 1962-70 exc. Toro 32.00

4849847



4709879

Door Jamb Light Switch: Round Door Jamb Light Switch has a two wire connection. Can be used as a replacement on 1961-64 models but has different appearance than originals. Fits into approx. 3/4" hole in door jamb. Uses DJB614 rubber boot listed below.

4709879 Door Jamb Light Switch 1961-64 models 39.00 ea.

DJB614 Door Jamb Light Switch Rubber Boot 1961-64 models 6.00 ea.

5717528



1966-67, 1969-70 Door Jamb Light Switches: Used on all 1966-67 and 1969-70 models in the door jamb to turn on interior lights when door is open.

D7277 Door Jamb Light Switch 1966-67 All models 18.50 ea.

D6971 Door Jamb Light Switch 1969-70 All models 29.00 ea.

D7277



D6971

Door Jamb Strikers: New Door Latch Striker Bolts available for all 1968-70 and 1971-76 88-98-Toronado models.

DSA642 Door Jamb Striker 1968-70 88-98-Toronado 19.50 ea.

DSA736 Door Jamb Striker 1971-76 88-98-Toronado 25.00 ea.



DSA642

DSA736



Inside Door and Window Handles, Interior Parts

1961-64 Inside Door Handle: Chrome plated interior door handle used on 1961 88 models and 1962-64 88 4 door and wagon models.

IDH493 Inside Door Handle 1961-64 88 39.00 ea.



1965 Inside Door Handle: Chrome plated interior door handle used on 1965 88 4 door sedan models. Sold in a pair. Includes retaining clips.

IHD657 Inside Door Handle 1965 88 4 Dr sedan 49.50 pr.



1961-67 Paddle Style Inside Door Handles:

Fits all 1961-67 88s-98s & Starfires and in the front and rear on all 1966-67 Toronados except Deluxe (model 9687). Available in two finishes, one is all chrome and the other is chrome with a brushed top surface.

IHD634 Inside Door Handles, all chrome 1961-67 most models 59.50 pr.



IHD634B Inside Door Handles, brushed finish 1961-67 most models 89.50 pr.



1968-72 Inside Door Opening Handles: Used on 1968-70 all 88 models, includes retaining clips. Sold in a pair for left and right.

IHD20RL Inside Door Handles 1968-70 All 88 models 49.50 pr.



1961-64 Window Crank Handles: Window crank handle fits 1961-63 all models and 1964 98 front only. 4-1/2" long with double arm and chrome knob. 3-1/2" long double arm design vent window crank fits all 1961-64 models exc 64 98 Lux Sed. All handles include fastener clips.

IWH594 Window Crank Handle 1961-64 40.00 ea.

IVH594 Vent Window Crank Handle 1961-64 40.00 ea.



1965-66 Window Crank Handles: Chrome plated, single arm Window and Vent Window Crank Handles for 1965-66 Oldsmobile models. Retaining clips included with new handles

IWH6566 Window Crank Handle 1965-66 31.50 ea.

IVH6566 Vent Window Crank Handle 1965-66 31.50 ea.



1967-74 Window Crank Handles: New chrome window crank handles available with black plastic knobs. Includes retaining clips.

12367 Black Knob Window Crank 1967 all exc. Toronado 21.00 ea.

12315 Black Knob Window Crank 1968-74 88s and Toronado 18.50 ea.



Door and Window Handle Backing Plates: Thin plastic washer used in back of handles to prevent wear on door panels.

HBP647 Handle Backing Plates 4.00 ea.



1967-70, 1971-76 Turn Signal Levers and 1971-75 Tilt Wheel Lever:

Chrome plated lever with black rubber end cap. Turn Signal Levers fit all 1967-70 & 1971-76 models without cruise control and telescopic wheel. Tilt wheel lever fits all 1971-75 models without telescopic wheel.

| | | | |
|---------------|-------------------|------------------------------|-------|
| TSL690 | Turn Signal Lever | 1967-70 All exc. cruise/tele | 28.50 |
| TSL715 | Turn Signal Lever | 1971-76 All exc. cruise/tele | 28.50 |
| TWL715 | Tilt Wheel Lever | 1971-75 All exc. tele | 25.00 |



Chrome Door Lock Buttons: Replacements for your worn or broken door lock buttons. Chrome plated plastic.

| | | | |
|--------------|------------------|-------------|----------|
| DB660 | Door Lock Button | 1961-66 All | 7.50 ea. |
| DB670 | Door Lock Button | 1967 All | 7.50 ea. |
| DB682 | Door Lock Button | 1968-70 All | 7.50 ea. |
| DB737 | Door Lock Button | 1971-75 All | 7.50 ea. |



1961-67 Rear Arm Rest Ash Trays: Chrome plated Ash Tray located in the rear armrest on many 1961-67 2 Door 88 models and standard Toronado models. Measures 2" x 2 1/2" features a stamped knob in lid and includes the chrome bezel that attaches to the arm rest.

| | | | |
|---------------|------------------------|----------------|-----------|
| AT6145 | Rear Arm Rest Ash Tray | 1961-67 models | 26.50 ea. |
|---------------|------------------------|----------------|-----------|



1968-76 Rear Arm Rest Ash Trays: New Ash Trays for rear arm rest area. AT6869 applies to 1968-70 Standard Toronado models and 1968-76 all 4 door models except wagons. AT715 is used in 1971-75 88 Holiday Coupe and Convertible models and has a ribbed design on the lid. Two ash trays used per car.

| | | | |
|---------------|------------------------|-----------------------------------|-----------|
| AT6869 | Rear Ash Tray Assembly | 1968-70 Toro, 1968-76 All 4 Doors | 39.00 ea. |
| AT715 | Rear Ash Tray Assembly | 1971-75 88 Hol Cpe & Conv | 43.50 ea. |



1966-68 Toronado Sun Visors: New visor assemblies made in perforated material to match original headliner materials. Black visors are typically in stock, other colors available as a special order. Sold as a pair.

| | | | |
|---------------|---------------------|------------------|------------|
| SV668T | Interior Sun Visors | 1966-68 Toronado | 239.00 pr. |
|---------------|---------------------|------------------|------------|



Interior Sun Visors: New interior Sun Visors available for the listed applications.

All visors are custom order and will take approx. 6-8 weeks, contact us for colors available.

| | | | |
|-------------------|------------|----------------------------------|------------|
| SVR61OL102 | Sun Visors | 1961-62 88 2 & 4 Dr Htop Seville | 239.00 pr. |
| SVR61OL104 | Sun Visors | 1961-62 88 2 & 4 Dr Htop Ribbed | 239.00 pr. |
| SVR64OL118 | Sun Visors | 1964 98 Conv. Madrid | 239.00 pr. |
| SVR65OL130 | Sun Visors | 1965-70 88 Conv Madrid | 239.00 pr. |
| SVR65OL140 | Sun Visors | 1965 98 2 Dr Hardtop Ribbed | 239.00 pr. |
| SVR67OL180 | Sun Visors | 1967-68 88 2 Dr Hardtop Ribbed | 239.00 pr. |

Sun Visor Support Grommets: Rubber grommets used on the sun visor end rods to keep the visors tight in place. Worn grommets will typically cause visors to drop.

| | | | |
|---------------|------------------------|----------------------|-----------|
| GS592 | Sun Visor Rod Grommets | 1961-62 Conv. models | 9.50 pr. |
| GS6400 | Sun Visor Rod Grommets | 1961-75 models | 10.00 set |




Rear Shelf Package Trays

Panel between the rear seat and the rear window. Available in the following colors: Black, Red, Blue, Light Blue, Light Saddle, Dark Saddle, Gold and Green. Two styles used, either smooth plain finish or with a mesh covering.


Oversized package shipping surcharge of \$75.00 applied to all package trays

| | | | |
|------------------|--------------------|---|-------|
| PTO-133 | Mesh Package Tray | 1961 88 4 Dr Htop with 1 speaker | 89.00 |
| PTO-113 | Plain Package Tray | 1962 Starfire Coupe, 1962-63 88 2 Dr Htop | 65.00 |
| PTO-114 | Mesh Package Tray | 1962 Starfire Coupe, 1962-63 88 2 Dr Htop | 89.00 |
| PTO-716 | Plain Package Tray | 1962-63 98 2 Dr Htop | 65.00 |
| PTO-726 | Mesh Package Tray | 1962-63 98 2 Dr Htop | 89.00 |
| PTO-737 | Plain Package Tray | 1963 88 4 Dr Htop | 65.00 |
| PTO-738 | Mesh Package Tray | 1963 88 4 Dr Htop | 89.00 |
| PTO-115 | Plain Package Tray | 1963-64 Starfire Coupe, 1964 88 2 Dr Htop | 65.00 |
| PTO-116 | Mesh Package Tray | 1963-64 Starfire Coupe, 1964 88 2 Dr Htop | 89.00 |
| PTO-731 | Mesh Package Tray | 1964 98 4 Dr Htop, no rear defroster | 89.00 |
| PTO-731D | Mesh Package Tray | 1964 98 4 Dr Htop, with rear defroster | 89.00 |
| PTO-717 | Plain Package Tray | 1965 98 2 Dr Htop | 65.00 |
| PTO-718 | Mesh Package Tray | 1965 98 2 Dr Htop | 89.00 |
| PTO-719 | Mesh Package Tray | 1965 Starfire | 89.00 |
| PTO-117 | Plain Package Tray | 1966 88 4 Dr Htop | 65.00 |
| PTO-118 | Mesh Package Tray | 1966 88 4 Dr Htop | 89.00 |
| PTO-119 | Plain Package Tray | 1966 Starfire Coupe | 65.00 |
| PTO-120 | Mesh Package Tray | 1966 Starfire Coupe | 89.00 |
| PTO-700 | Plain Package Tray | 1966 98 4 Dr Sedan | 65.00 |
| PTO-701 | Mesh Package Tray | 1966 98 4 Dr Sedan | 89.00 |
| PTO-729 | Plain Package Tray | 1967-68 88 4 Dr Sedan | 65.00 |
| PTO-730 | Mesh Package Tray | 1967-68 88 4 Dr Sedan | 89.00 |
| PTO-730LS | Mesh Package Tray | 1967-68 98 Luxury 4 Dr Sedan | 89.00 |
| PTO-702 | Plain Package Tray | 1968 98 2 Dr Htop | 65.00 |
| PTO-703 | Mesh Package Tray | 1968 98 2 Dr Htop | 89.00 |
| PTO-704 | Plain Package Tray | 1970 98 2 Dr Htop | 65.00 |
| PTO-705 | Mesh Package Tray | 1970 98 2 Dr Htop | 89.00 |
| PTO-706 | Plain Package Tray | 1972 88 2 Dr Htop | 65.00 |
| PTO-707 | Mesh Package Tray | 1972 88 2 Dr Htop | 89.00 |
| PTO-724 | Plain Package Tray | 1972 88 4 Dr Htop | 65.00 |
| PTO-725 | Mesh Package Tray | 1972 88 4 Dr Htop | 89.00 |



Front Door Area Lower Kick Panels: Correct die cut profile in neutral white waterproof cardboard. Spray paint or color dye to match interior.

| | | | |
|---------------|-------------|-----------------------------|-----------|
| KP620 | Kick Panels | 1962 Dynamic & Super 88 | 49.00 pr. |
| KP621 | Kick Panels | 1962 98 models, no A/C | 49.00 pr. |
| KP621A | Kick Panels | 1962 98 models, with A/C | 49.00 pr. |
| KP630 | Kick Panels | 1963 Dyn, Super 88, no A/C | 49.00 pr. |
| KP630A | Kick Panels | 1963 Dyn, Super 88 with A/C | 49.00 pr. |



IGNITION, DOOR, TRUNK, AND GLOVE BOX LOCKS AND KEYS

Locks are available individually or in sets. Sets are set up like original with matching key for Ignition & Door Locks and Glove Box & Trunk Lock. 1961-68 models used the smaller round and octagon style keys and 1969-76 models used the larger oval and rectangular type keys. All locks and sets supplied with 2 keys.



IC3565



IC6978



DI667



DI716

Ignition Lock Cylinders

| | | |
|--------|-------------|-------|
| IC3565 | 1961-65 All | 27.50 |
| IC667 | 1966-67 All | 27.50 |
| IC68 | 1968 All | 39.00 |
| IC6978 | 1969-76 All | 39.00 |



DL614



DL7181T

Door Lock Cylinders: Door lock cylinders sold in pairs only with two keys.

| | | |
|---------|--|-----------|
| DL614 | 1961-64 2 Door Sedan and Wagon | 59.00 pr. |
| DL614C | 1961-64 Holiday Coupes, Convertibles and 4 Doors | 59.00 pr. |
| DL656 | 1965-66 All | 59.00 pr. |
| DL678 | 1967-68 All | 39.00 pr. |
| DL716 | 1971-76 All | 43.00 pr. |
| DL7181T | 1971-76 Toronado | 39.00 pr. |

Glove Box Locks: Glove box locks supplied are lock cylinder and keys only. No latch components available.

| | | |
|-------|---------------------------|-------|
| GB578 | 1961 All | 49.00 |
| GB624 | 1962-64 All | 49.00 |
| GB656 | 1965-67 exc. '67 Toronado | 49.00 |
| GB67T | 1967 Toronado | 49.00 |
| GB704 | 1969-73 All | 49.00 |



GB578L



GB67

Console Locks: Console locks are supplied as a lock cylinder and keys only. No latch components.

| | | |
|--------|------------------|-------|
| CL612 | 1961-62 Starfire | 39.00 |
| GB67 | 1963-69 All | 49.00 |
| CL7071 | 1970-71 All | 39.00 |



TL667T



TL673

Trunk Locks

| | | |
|--------|---------------------------------|-------|
| TL613 | 1961-63 All | 39.00 |
| TL667T | 1966-67 Toronado | 39.00 |
| TL66 | 1966 exc. Starfire and Toronado | 39.00 |
| TL678 | 1967-68 All exc. 67 Toronado | 29.00 |
| TL673 | 1969-73 All | 29.00 |

Door and Ignition Lock Sets

| | | |
|--------|--|-------|
| DI614 | 1961-64 2 Door Sedan and Wagons | 65.00 |
| DI614C | 1961-64 Holiday Coupes, Convertibles and 4 Doors | 65.00 |
| DI615 | 1965 All models | 59.00 |
| DI667 | 1966-67 All models | 59.00 |
| DI680 | 1968 All models | 59.00 |
| DI690 | 1969-70 All models | 59.00 |
| DI716 | 1971-76 All except Toronado | 59.00 |
| DI716T | 1971-76 All Toronado | 59.00 |



GT61



GT67

Glove Box and Trunk Lock Sets: Glove box locks supplied with kit is a lock cylinder and keys only.

No latch components available.

| | | |
|-------|-----------------------------------|-------|
| GT61 | 1961 All models | 69.00 |
| GT623 | 1962-63 All models | 69.00 |
| GT66 | 1966 All exc. Toronado & Starfire | 69.00 |
| GT66T | 1966 Toronado | 69.00 |
| GT67 | 1967 All except Toronado | 69.00 |
| GT693 | 1969-73 All models | 59.00 |

Ignition, and Door Key Blanks

| | | |
|---------|----------------------|------|
| 3694624 | 1961-66 (octagon) | 6.00 |
| 7033454 | 1967 (octagon) | 6.00 |
| 7034680 | 1968 all (octagon) | 6.00 |
| 7025014 | 1969 & 1973 (square) | 5.50 |
| 7025282 | 1970 & 1974 (square) | 5.50 |
| 7027275 | 1971 & 1975 (square) | 5.50 |
| 7024229 | 1972 & 1976 (square) | 5.50 |

Deck Lid and Glove Box

| | | |
|---------|--------------------|------|
| 7002238 | 1961-66 (round) | 6.00 |
| 7033455 | 1967 (round) | 6.00 |
| 7034702 | 1968 (round) | 6.00 |
| 7025019 | 1969 & 1973 (oval) | 5.50 |
| 7025288 | 1970 & 1974 (oval) | 5.50 |
| 7027281 | 1971 & 1975 (oval) | 5.50 |
| 7024235 | 1972 & 1976 (oval) | 5.50 |



REBUILDING SERVICES

We offer rebuilding services on the following mechanical parts. All individual services require that your existing part or parts (commonly called cores) be shipped complete and unaltered for rebuilding. If you do not send a core in advance, we will require a core charge. Core charges are basically an incentive to return a part to us so that the next enthusiast may have a unit for their restoration. Please do not disassemble old units. Cores with missing or broken parts will be assessed a deduction or rejected and returned.

Carburetors: Cosmetically restored exterior with new internal parts. Superior workmanship.

Most carburetors are in stock, you will be assessed a core charge until your existing unit is sent in to us. Allow 6-8 weeks for rebuilding service on units not in stock. **Core charge on in stock carburetors is 295.00 for 4 barrel units and 245.00 for 2 barrels.**

| | | |
|--------------|---|--------|
| RO610 | Rebuilding service on 4 Barrel Carburetor, 1961-65 88-98 | 599.00 |
| RO612 | Rebuilding service on 2 Barrel Carburetor, 1961-65 88-98 | 569.00 |
| RO660 | Rebuilding service on 4 Barrel Carburetor, 1966-70 88-98-Toro | 599.00 |



Dual Action Fuel Pumps:

Rebuilding 1961-62 (6585 AC), and 1963-64 (6620 AC) only. **Core charge for fuel pumps is 175.00.** These pumps are normally in stock for immediate shipment.

| | | |
|-----------------|--|--------|
| FP-6585 | 1961-62 Fuel Pump | 229.00 |
| FP-6620 | 1963-64 Fuel Pump, cars without air conditioning | 229.00 |
| FP-6620A | 1963-64 Fuel Pump, cars with air conditioning | 229.00 |



1961-64 Fuel Pump Repair Kits:

| | | | |
|---------------|---------------|-----------------------|--------|
| FPA266 | Fuel Pump Kit | 1961-62 (#6585 pump) | 109.00 |
| FPA271 | Fuel Pump Kit | 1963-64 (#6620 pumps) | 109.00 |



New Fuel Pumps for 1965-74 88-98-Toronado-Starfire:

The following fuel pumps are available new without a core charge.

| | | | |
|--------------|-----------|---|-------|
| 40030 | Fuel Pump | 1965 330, 1965 425 | 89.00 |
| 40262 | Fuel Pump | 1966-67 425 with AC, 1968-69 455 with AC | 89.00 |
| 40705 | Fuel Pump | 1968-69 455 without A/C | 89.00 |
| 40713 | Fuel Pump | 1970-74 88-98 455 without A/C 1970-71 Toronado 455 without A/C | 89.00 |



Harmonic Balancers: Units are revulcanized using the latest silicon polymers, cleaned and repainted or primed. Due to a lack of core units, you may need to send your balancer to us for reconditioning. Please allow 3-4 weeks lead time for this service.

Core charge for in stock units sent in advance is 250.00.

| | | |
|---------------|--|--------|
| HBR615 | 1961-64 Harmonic Balancer Rebuilding Service | 275.00 |
|---------------|--|--------|

Water Pumps: New replacement water pumps have been increasingly difficult to obtain, and are quickly being discontinued. We can now offer rebuilding service for all 1961-75 Oldsmobile water pumps. All rebuilt water pumps carry a 1 year warranty. Most applications will require original cores sent in advance, please contact us for availability. Original GM water pumps with the correct casting numbers are used when available.

| | | | |
|------------------|--------------------|----------------------|--------|
| WP-W993A | New Water Pump | 1961-62 V8 no A/C | 199.00 |
| WP-555717 | Rebuilt Water Pump | 1961-62 V8 no A/C | 295.00 |
| WP-W994A | Rebuilt Water Pump | 1961-62 V8 with A/C | 295.00 |
| WP-W996 | Rebuilt Water Pump | 1963-64 394 no A/C | 229.00 |
| WP-W996A | Rebuilt Water Pump | 1963-64 394 with A/C | 229.00 |



| | | | |
|--|---------------------------------------|-------------|--------|
| 555717, W994A, W996 & W996A requires 175.00 core charge | | | |
| WP-W655GM | Rebuilt, Correct Number GM Water Pump | 1965-75 All | 269.00 |
| W655GM requires 250.00 core charge | | | |
| WP-W655R | Rebuilt Replacement Water Pump | 1965-75 All | 199.00 |
| W655R requires 150.00 core charge | | | |



Carburetor Throttle Return Dashpots: Rebuilding service for the Carburetor Dashpots used on 1961-64 2 and 4 Barrel carburetors. **Core charge for Dashpot shipped in advance is 100.00.**

| | | | |
|------------------|--------------------|----------------------------|-------|
| CD-388172 | Carburetor Dashpot | 1961-64 with 2 Barrel Carb | 89.50 |
| CD-388173 | Carburetor Dashpot | 1961-64 with 4 Barrel Carb | 89.50 |



1966-70 Toronado Fuel Tanks: New reproduction Fuel Tanks for the 1966-1970 Toronados are now available. Due to the very large size of the fuel tanks with the necks there is an additional oversized shipping surcharge.

| | | | |
|----------------|---------------------|------------------|-----------|
| FT667T | Fuel Tank with Neck | 1966-67 Toronado | 679.00 |
| FTS667T | Fuel Tank Straps | 1966-67 Toronado | 49.50 pr. |
| FT680T | Fuel Tank with Neck | 1968 Toronado | 679.00 |
| FT690T | Fuel Tank with Neck | 1969-70 Toronado | 679.00 |
| FTS680T | Fuel Tank Straps | 1968-70 Toronado | 49.50 pr. |



Oversize shipping surcharge of \$200.00 on all Toronado Fuel Tanks

1966-70 Toronado Fuel Tank Sending Units: New replacement Fuel Tank Sending Units for the 1966-1970 Toronados.

| | | | |
|----------------|------------------------|------------------|-------|
| FTU667T | Fuel Tank Sending Unit | 1966-67 Toronado | 89.50 |
| FTU680T | Fuel Tank Sending Unit | 1968-70 Toronado | 89.50 |



Replacement Fuel Caps

We offer the following replacement fuel caps for 1964-72 Oldsmobile models. All fuel caps listed are non-vented, like originals.

| | | | |
|--------------|-------------------------|-------------|-------|
| GC64P | 'PREMIUM FUEL' Fuel Cap | 1964-69 All | 34.50 |
| GC70 | Replacement Fuel Cap | 1970 All | 18.50 |
| GC41 | Replacement Fuel Cap | 1971-72 All | 18.50 |



Fuel Tank Vent Filter and Hoses: Attaches to fittings on front of fuel tank and provides ventilation in the fuel tank. Includes plastic filter valve, hoses and pinch clamps. Used on all 1969-71 Oldsmobile models except wagons, Toronado and any models equipped with evaorative emission control (E.E.C.)

| | | | |
|----------------|-----------------------|----------------|-------|
| GTF690K | Fuel Tank Vent Filter | 1969-71 models | 39.00 |
|----------------|-----------------------|----------------|-------|



Hood Hinges

New Hood Hinges available for 1965-66 88 & 98 All models, 1966-67 Toronado and 1969-70 88 & 98 All models.

Please note: The hood springs for these models are not available.

| | | | |
|---------------|-----------------------|-----------------------------|--------|
| HH647R | Right Side Hood Hinge | 1965-66 88-98, 1966-67 Toro | 129.00 |
| HH647L | Left Side Hood Hinge | 1965-66 88-98, 1966-67 Toro | 129.00 |
| HH692R | Right Side Hood Hinge | 1969-70 88-98 | 99.00 |
| HH692L | Left Side Hood Hinge | 1969-70 88-98 | 99.00 |



Sheet Metal Floor Pan Plugs: Oval sheet metal plug measures 4 1/2" x 3 3/4" overall. Check your car for quantity needed.

| | | | |
|---------------|------------------|-------------|----------|
| DPC642 | Sheet Metal Plug | 1961-75 All | 8.50 ea. |
|---------------|------------------|-------------|----------|



Trunk Latch Assembly: New Trunk Latch assembly used on all 1963-69 models except wagons or vehicles equipped with a power trunk release.

| | | | |
|--------------|----------------------|-------------|-------|
| TL592 | Trunk Latch Assembly | 1963-69 All | 47.50 |
|--------------|----------------------|-------------|-------|



Thermostat Housing: New cast aluminum Thermostat Housing available for all 1965-76 V8 engines with the formed bypass hose, this can also be used in place of the housing for straight bypass hose.

| | | | |
|---------------|--------------------|----------------|-------|
| 574815 | Thermostat Housing | 1959-64 394 V8 | 49.00 |
| 392099 | Thermostat Housing | 1965-76 V8 | 39.00 |
| 393508 | Molded Bypass Hose | 1966-75 All | 35.00 |



| | | | |
|----------------|-----------------------|-------------|-------|
| 300-160 | 160 Degree Thermostat | 1961-72 All | 14.50 |
| 300-180 | 180 Degree Thermostat | 1961-72 All | 14.50 |
| 300-195 | 195 Degree Thermostat | 1961-77 All | 14.50 |

| | | | |
|--------------|-----------------------|-------------|------|
| TG498 | Therm. Housing Gasket | 1961-64 All | 6.00 |
| TG677 | Therm. Housing Gasket | 1965-77 All | 5.00 |



RC15R

RC27

Reproduction AC Delco Radiator Caps: Quality reproduction of the original AC radiator caps used on 1961-76 Oldsmobiles.

| | | | |
|--------------|------------------------------|---|-------|
| RC15R | Reproduction AC Radiator Cap | 1961-72 All | 39.00 |
| RC27 | Reproduction AC Radiator Cap | 1971-76 All models with closed coolant system | 39.00 |

A/C Compressor Mounts: Rubber mounts with threaded studs on both sides used to mount the A/C Compressor.

| | | | |
|---------------|-----------------------|----------------|----------|
| TMG454 | A/C Compressor Mounts | 1965-70 w/ A/C | 9.50 ea. |
|---------------|-----------------------|----------------|----------|

Radiator Insulators

Used between radiator support and radiator as cushion. Fits 1966-75 All Models.

| | | | |
|---------------|-------------------------|-------------|-----------|
| RI2021 | Insulator Set (4 piece) | 1966-70 All | 29.50 set |
| RI17 | Insulator Set (4 piece) | 1971-75 All | 33.00 set |

Radiator Core Support Kit: Fits 1966-70 88 & 98 Models, and includes rubber bushings, sleeves, bolts and washers.

| | | | |
|---------------|------------------|---------------|-----------|
| RC662K | Core Support Kit | 1966-70 88-98 | 55.00 kit |
|---------------|------------------|---------------|-----------|



Radiator Overflow Hose and Clip: Cars that were not equipped with the optional overflow jar use a rubber drain hose that attaches to the tube at the radiator neck. Hose is held to the side of the radiator with a special metal clip.

| | | | |
|----------------|---|-------------|-------|
| ROH617 | Radiator Overflow Hose (36" length) | 1961-77 All | 12.00 |
| ROHC687 | Radiator Overflow Hose Clip to Radiator | 1968-77 All | 15.00 |



Upper Radiator Hose Plastic Clamp: Attaches to radiator core support and keeps the upper hose secured and away from the fan.

| | | | |
|-------------|--------------------------|-----------------------------|------|
| HC19 | Upper Hose Plastic Clamp | 1966-70 All exc. 66-68 Toro | 9.00 |
|-------------|--------------------------|-----------------------------|------|

Heater Fan Blower Motor: New heater blower motor for all 1964-75 88-98-Toronado with or without Air Conditioning.

| | | | |
|-------------|---------------------|--------------------|-------|
| 5587 | Heater Blower Motor | 1964-75 All models | 59.50 |
|-------------|---------------------|--------------------|-------|

Rebuilt Heater Cores: Rebuilding service for original heater cores require **250.00 core charge**. Check with us on rebuilding other years not listed. May require original heter core be sent in to us in advance, please check with us on inventory.

| | | | |
|----------------|---------------------|------------------------|--------|
| 3144755 | Rebuilt Heater Core | 1961-63 88-98-Starfire | 399.00 |
|----------------|---------------------|------------------------|--------|

Original Style Ribbed Heater Hose: Black heater hose features the 5 rib design like the hoses originally used by GM. Available in 3/4" or 5/8" inner diameter, Sold by the foot.

| | | |
|--------------|-------------------------------|--------------|
| HH3/4 | Ribbed Heater Hose, 3/4" I.D. | 7.00 per ft. |
| HH5/8 | Ribbed Heater Hose, 5/8" I.D. | 7.00 per ft. |



Radiator and Heater Hoses

580258

We carry most of the radiator hoses used on 1961-70 88-98-Starfire-Toronado. All hoses are stamped with correct GM part numbers and markings.



| | | | |
|---------------|----------------------|--|-------|
| 580249 | Upper Radiator Hose | 1961 All 2 barrel | 49.00 |
| 580258 | Upper Radiator Hose | 1961 All 4 barrel | 49.00 |
| 584294 | Upper Radiator Hose | 1962 All 2 barrel | 49.00 |
| 584295 | Upper Radiator Hose | 1962 All 4 barrel | 49.00 |
| 587188 | Upper Radiator Hose | 1963-64 2 barrel | 49.00 |
| 587189 | Upper Radiator Hose | 1963-64 4 barrel | 49.00 |
| 387577 | Upper Radiator Hose | 1965 All except A/C | 49.00 |
| 390437 | Upper Radiator Hose | 1965 with A/C, 1966 except Toronado, 1967 except A/C | 49.00 |
| 387577 | Upper Radiator Hose | 1966-67 Toronado with 3 core radiator | 49.00 |
| 395056 | Upper Radiator Hose | 1966-67 Toronado with 4 core radiator | 49.00 |
| 394884 | Upper Radiator Hose | 1967 88-98 with A/C, 1968 All except Toronado | 49.00 |
| 399310 | Upper Radiator Hose | 1968-75 Toronado | 49.00 |
| 402153 | Upper Radiator Hose | 1969-73 All 88-98 | 62.50 |
| 580259 | Lower Radiator Hose | 1961 All except A/C | 49.00 |
| 586459 | Lower Radiator Hose | 1961 All with A/C | 49.00 |
| 586511 | Lower Radiator Hose | 1962 All models | 49.00 |
| 587144 | Lower Radiator Hose | 1963-64 All 394 V8 | 49.00 |
| 382986 | Lower Radiator Hose | 1964 Jetstar 88 w/ 330 V8 | 49.00 |
| 394883 | Lower Radiator Hose | 1965-68 All except Toronado | 49.00 |
| 402155 | Lower Radiator Hose | 1966-70 Toronado, 1969-70 88-98 | 49.00 |
| 408617 | Lower Radiator Hose | 1971-72 88-98 | 49.00 |
| 408624 | Lower Radiator Hose | 1971-72 Toronado | 49.00 |
| 413457 | Lower Radiator Hose | 1973 All 88-98 | 49.00 |
| 413482 | Lower Radiator Hose | 1973-75 Toronado | 49.00 |
| 575769 | Molded Heater Hose | 1961-62 All Valve to Heater | 39.00 |
| 581993 | Molded Heater Hose | 1961-62 All Pump to Heater | 49.00 |
| 409042 | Straight Bypass Hose | 1966-75 All | 12.00 |
| 393508 | Molded Bypass Hose | 1966-75 All | 35.00 |



HCK640



Radiator and Heater Hose Clamps

We have a complete line of original hose clamps for 1961-77 Oldsmobiles. Check your needs and application for proper usage.

| | | | |
|--------------|-------------------------------|---|----------|
| HC58 | Tension Spring Hose Clamp | Most 1961-70 5/8" Heater Hoses | 2.50 ea. |
| HC59 | Tension Spring Hose Clamp | Most 1961-70 3/4" Heater Hoses | 3.00 ea. |
| HC100 | Double Wire Hose Clamp | Used on All 1964-70, 1973-77 Bypass Hose | 9.00 ea. |
| HC128 | Double Wire Grip Hose Clamp | Used on 1961-70, 1973-77 Upper Hose | 9.00 ea. |
| HC202 | Double Wire Grip Hose Clamp | Used on 1961-70, 1973-77 Lower Hose at radiator | 8.00 ea. |
| HC212 | Double Wire Grip Hose Clamp | Used on 1961-70, 1973-77 Lower Hose at water pump | 8.00 ea. |
| HC55 | Post-Type Hose Clamp (Wittek) | 1971-72 Heater and Bypass Hose | 5.00 ea. |
| HC62 | Post-Type Hose Clamp (Wittek) | 1971-72 Radiator Hose at Radiator | 5.00 ea. |
| HC78 | Post-Type Hose Clamp (Wittek) | 1971-72 Radiator Hose at Pump | 5.50 ea. |

Hose Clamp Kits: Includes all the clamps needed for Radiator and Heater hoses.

| | | | |
|---------------|-------------------------|----------------------|-----------|
| HCK640 | Hose Clamp Kit (10 pcs) | 1961-70, 1973-77 All | 59.00 kit |
| HCK712 | Hose Clamp Kit (10 pcs) | 1971-72 All | 45.00 kit |



Electrical Switches and Components

1968-76 Ignition Switches:

| | | | |
|---------------|-----------------|----------------------------|-------|
| D1415B | Ignition Switch | 1968 All | 43.50 |
| D1404B | Ignition Switch | 1969-76 without Tilt Wheel | 39.00 |
| D1405B | Ignition Switch | 1969-76 with Tilt Wheel | 36.50 |

Headlight Switches and Headlight Dimmer Switch:

| | | | |
|--------------|-------------------------|---------------------------------------|-------|
| DS155 | Headlight Switch | 1967-69 88 & 98, 1970 88, 98 & Toro | 49.50 |
| D808 | Headlight Dimmer Switch | 1963-75 All except 1963-64 Guidematic | 23.50 |

1964-75 Brake Stoplight Switches:

| | | | |
|--------------|------------------|--|-------|
| SLS66 | Stoplight Switch | 1964-75 with Power Brake, no cruise, 1966-70 Toronado | 23.50 |
| D850A | Stoplight Switch | 1968-75 with Power Brake and cruise control | 29.50 |

Parking Brake Warning Light Switch: Installs into the parking brake bracket and controls the 'brake' dash light.

| | | | |
|----------------|----------------------------|---------------|-------|
| 9795358 | Parking Brake Light Switch | 1971-72 88-98 | 25.00 |
|----------------|----------------------------|---------------|-------|

1961-62 Turn Signal Circuit Switch: Attaches to lower steering column on all 1961-62 88s-98s-Starfires equipped with Hydramatic Transmissions.

| | | | |
|----------------|----------------------------|------------------------|-------|
| 1998138 | Turn Signal Circuit Switch | 1961-62 All Hydramatic | 79.50 |
|----------------|----------------------------|------------------------|-------|

Turn Signal Switches: New Turn Signal Switches include the wire pigtailed and cancel cam. Check applications carefully, switches differ depending on options.

| | | | |
|----------------|--------------------|---|-------|
| D6211 | Turn Signal Switch | 1967-68 88-98-Toronado no tilt wheel, no cornering lamp | 65.00 |
| 7800483 | Turn Signal Switch | 1967-68 88-98-Toronado WITH cornering lamps, No tilt wheel | 69.00 |
| D6208 | Turn Signal Switch | 1969-76 All models No tilt wheel, No cornering lamps | 65.00 |

Turn Signal Cancel Cams and Actuators:

| | | | |
|----------------|---------------------------------|-------------------------|-------|
| TSCA68 | Turn Signal Cancel Cam Actuator | 1968 exc. tilt wheel | 9.50 |
| TSC68T | Turn Signal Cancel Cam | 1968 with tilt wheel | 19.00 |
| TSCA694 | Turn Signal Cancel Cam Actuator | 1969-74 exc. tilt wheel | 9.50 |
| TSC694 | Turn Signal Cancel Cam | 1969-74 exc. tilt wheel | 18.00 |

1966-67, 1969-70 Door Jamb Light Switches: Used on all 1966-67 and 1969-70 models in the door jamb to turn on interior lights when door is open.

| | | | |
|--------------|------------------------|--------------------|-----------|
| D7277 | Door Jamb Light Switch | 1966-67 All models | 18.50 ea. |
| D6971 | Door Jamb Light Switch | 1969-70 All models | 29.00 ea. |

1967-68 A/C Fan Speed Switch: New GM Air Conditioner Fan Speed Switch for all 1967-68 88 & 98 models with manual control A/C.

| | | | |
|---------------|----------------------------------|------------------------|-------|
| 395168 | Air Conditioner Fan Speed Switch | 1967-68 88-98 with A/C | 59.00 |
|---------------|----------------------------------|------------------------|-------|

Windshield Wiper Switches: New windshield wiper switches for 1961 Oldsmobile models listed, at this time these are the only applications available.


| | | | |
|----------------|--------------|---------------------------------|-------|
| 1993541 | Wiper Switch | 1961 88 w/ 1 speed wipers | 55.00 |
| 1993543 | Wiper Switch | 1961 88-98-SF w/ 2 speed wipers | 55.00 |



1961-62 Starfire Neutral Safety/Back-up Light Switch:

Used on all 1961-62 Starfires, prevents car from being started while in gear and also used to light back-up lights when in reverse.

570386 Neutral Safety/Back-up Switch 1961-62 Starfire 99.00



1964-66 Neutral Safety Switch: Neutral Safety Switch used on 1964-66 Oldsmobiles with Jetaway transmission except 1964 Jetstar 88 models with column shift.

1993659 Neutral Safety Switch 1964-66 29.50

TH400 Transmission Kick Down Switch: Switch located near accelerator pedal on all 1969-76 models equipped with a TH400 automatic transmission.

TKS690 Transmission Kick Down Switch 1969-76 TH400 45.00

Oil Pressure and Temperature Sending Units:

PS12 Oil Pressure Sending Unit 1961-75 without Dash Gauges 27.50

TS15 Temperature Sending Unit 1963-70 without Dash Gauges 45.00



1961-672 Horn Relays: R203 functions as the horn relay and positive battery cable junction. Relays mount to top of driver side inner front fender well.

R203 Horn Relay 1961-67 All models, 1968 Toronado 89.00

HR680 Horn Relay 1968 All exc. Toronado 73.00

HR692 Horn Relay 1969-72 All models 89.00



1965-72 Power Seat Relay: Available for the following applications: 1965 all with 4 or 6 way power seat except buckets, 1966 Starfire w/ 4 way bucket, 1966-67 Deluxe Toronado w/ 4 way bucket, 1966-72 88-98-Starfire & Toronado w/ 6 way power seat (exc. 1971 Toronado) and 1968-70 Toronado with 4 way bucket.

5717528 Power Seat Relay above applications 59.95



Power Options Circuit Breaker: 40 Amp Power window and power seat control Circuit Breaker for all 1962-70 models except Toronado.

4849847 Power Options Circuit Breaker 1962-70 exc. Toro 32.00



Starter Bracket and Shield: Bracket was used on all 1964-71 V8 engines, then changed to a heat shield in 1972 models to prevent starter from overheating

SBS645A Bracket 1964-72 All V8 35.00

SBS645 Shield 1972-77 exc. Toro 32.00



Starter Rebuilding Service: Rebuilding service available for original equipment starters. Most starters require originals be sent in for rebuild service, please allow 2-3 weeks. There will be a **150.00 core charge** on rebuilt units until original core is returned. We can get 1964 and newer starters rebuilt, please contact us.

STA-1107665 Starter Rebuild Service 1961-62 All 88, 1963 with low compression 279.00

STA-1107776 Starter Rebuild Service 1961-63 All with high compression 279.00

Generator Rebuild Service: Rebuilding service for 1961-62 generators. Most generators require originals be sent in for rebuild service, please allow 2-3 weeks. If we do send out rebuilt units in advance there will be a **150.00 core charge** until original core is returned.

GEN-1102217 Generator Rebuilding Service 1961 88-98 no A/C 279.00

GEN-1102187 Generator Rebuilding Service 1961 88-98 with A/C 325.00

GEN-1102276 Generator Rebuilding Service 1962 88-98 no A/C 279.00

GEN-1102277 Generator Rebuilding Service 1962 88-98 with A/C 325.00



Original Equipment Style Battery Cables: We stock original style Battery Cables for most 1961-70 88-98, and 1966-69 Toronado. Complete with part number, correct color and gauge cable, hot wire pigtail, cable insulator, etc.

Negative Battery Cables

| | | |
|---------------|-------------------------|-------|
| 23590 | 1961-62 All | 79.00 |
| 28680 | 1963-64 All | 79.00 |
| N05605 | 1965 All | 79.00 |
| 29640 | 1966-68 except Toronado | 79.00 |
| 30085 | 1966-69 Toronado | 79.00 |
| 29570 | 1969-70 88-98 455 | 79.00 |
| 29685 | 1971-72 88-98 455 | 85.00 |

Junction Block to Starter Cable

| | | |
|--------------|---------------------------|-------|
| 26710 | 1961-62 All | 79.00 |
| 27280 | 1963-64 except Jetstar 88 | 79.00 |
| 21570 | 1965 All | 79.00 |
| 11540 | 1966-67 except Toronado | 69.00 |
| 28675 | 1966-68 Toronado | 79.00 |



Positive Battery Cables

| | | |
|--------------|-------------------------------------|-------|
| 26880 | 1961 All | 69.00 |
| 26895 | 1962 All | 69.00 |
| 26885 | 1963-64 All | 69.00 |
| 28665 | 1965 All | 79.00 |
| 22190 | 1966-67 88-98-SF | 79.00 |
| 28690 | 1966-68 Toronado | 79.00 |
| 29615 | 1968 88-98 350 w/ auto | 79.00 |
| 29605 | 1968 88-98 455 w/ auto | 79.00 |
| 29580 | 1969 88-98 350 w/ front drum brakes | 79.00 |
| 29565 | 1969 88-98 455 w/ front drum brakes | 79.00 |
| 29575 | 1969-70 88-98 w/ front disc | 79.00 |
| 29610 | 1970 88-98 w/ front drum brakes | 79.00 |
| 29590 | 1971-72 88-98 455 | 89.00 |



Engine Ground Strap: Goes from engine block to cowl. 10-1/2" braided cable.

| | | |
|---------------|--------------------|-------|
| GS6560 | 1965-75 All models | 13.00 |
|---------------|--------------------|-------|

Battery Support Trays, Hold Downs, and Related Parts:

| | | | |
|---------------|-------------------------|---|-----------|
| BT6584 | Battery Support Tray | 1965-73 88-98-SF, 1966-67 Toronado | 65.00 |
| BT6903 | Battery Support Tray | 1969-70 Toronado | 34.50 |
| BT7577 | Battery Support Tray | 1975-76 88-98, 1976-78 Toronado | 69.50 |
| HD6201 | Battery Hold-down | 1962 All 88-98-Starfire | 39.50 |
| HD6360 | Battery Hold-down | 1963-64 All 394 engines | 39.50 |
| HD6584 | Battery Hold-down | 1965 88-98-Starfire | 39.50 |
| HD6680 | Battery Hold-down | 1966 88-98-Starfire | 39.50 |
| HD6686 | Battery Hold-down | 1966-67 Toronado | 39.50 |
| HD6769 | Battery Hold-down | 1967-68 88-98 | 39.50 |
| HD6560 | Battery Hold-down Clamp | 1969-70 Toronado | 7.50 |
| HDB005 | Battery Hold-down Bolt | 1962 All, 64-75 All except 68-70 Toronado | 12.00 ea. |

Battery Cable Tube & Bracket: Mounts to back of the engine for correct positive battery cable routing. Used on 1968-69 88 & 98 models with auto trans, 1971-75 Toronado and 1972-74 88 & 98 models.

| | | | |
|-----------------|--------------------------------|--------------|-------|
| BCTA6874 | Battery Cable Tube and Bracket | above models | 69.50 |
|-----------------|--------------------------------|--------------|-------|

Battery Cable Terminal Block Cover: Rubber cover used on 1964-68 models at positive battery cable junction point.

| | | | |
|---------------|---------------------|-------------|-------|
| BCC648 | Battery Cable Cover | 1964-68 All | 13.50 |
|---------------|---------------------|-------------|-------|



Ignition and Tune-Up Parts

Tune-Up Kit: For all 1961-72 V-8 Engines. Includes distributor cap, rotor, point set and condenser. Short tower cap supplied in TK5A for 1961-64.

| | | | |
|---------------|------------------------|--------------------|-------|
| TK5A | Tune-up Kit | 1961-64 All 394 V8 | 95.00 |
| TK5 | Tune-up Kit | 1965-72 All models | 95.00 |
| 337166 | Ignition Coil, 12 Volt | 1961-73 All | 85.00 |



1961-64 Distributor Assembly: Rebuilding service on the 1961-64 394 V8 distributor assemblies include a rebuilt vacuum advance, cap, rotor, points and condenser. Requires a **150.00 core charge** if rebuilt unit is shipped in advance of your original coming in.

| | | | |
|----------------|------------------------------|----------------|--------|
| DIS-903 | Rebuilt Distributor Assembly | 1961-64 394 V8 | 379.00 |
|----------------|------------------------------|----------------|--------|

1961-64 Distributor Vacuum Advance: Rebuilt Vacuum Advances are available for all 1961-64 394 V8. **Core charge is 95.00.**

| | | | |
|--------------|----------------------------|----------------|-------|
| VA903 | Distributor Vacuum Advance | 1961-64 394 V8 | 89.00 |
|--------------|----------------------------|----------------|-------|



Ignition Ballast Resistor: Used only in 1961 on 88-98-Starfire models.

| | | | |
|----------------|------------------|-----------|-------|
| 1957154 | Ballast Resistor | 1961 only | 43.50 |
|----------------|------------------|-----------|-------|

AC Spark Plug Sets: AC Delco has discontinued many of the exact replacement plugs for Oldsmobile. We have found these applications to be an excellent substitute. Plugs are sold as a set of eight.

| | | | |
|-------------|---------------------|--------------------|-----------|
| R43S | Spark Plug Set of 8 | 1961-64 394 V8 | 36.00 set |
| R45S | Spark Plug Set of 8 | 1964 330, 65-72 V8 | 36.00 set |



Voltage Regulators: New Voltage Regulators for 1962-76 All Models.

| | | | |
|-------------|-------------------|-------------------------------------|--------|
| D632 | Voltage Regulator | 1962-63 All models with alternator | 89.00 |
| D663 | Voltage Regulator | 1964-72 All with external regulator | 123.00 |
| D680 | Voltage Regulator | 1969-76 All with internal regulator | 43.50 |

Ignition Wire Sets: Correct Delco-Packard Date-Coded Wire Sets. Superior workmanship, all wire sets dated for the 1st quarter of appropriate year. 1961-64 Wire Sets require a short tower distributor cap which is available in TK5A kit.



| | | | | | | | |
|-------------|-------------------|----------|--------|-------------|-------------------|----------|-------|
| 1Q61 | Ignition Wire Set | 1961 All | 115.00 | 1Q67 | Ignition Wire Set | 1967 All | 99.00 |
| 1Q62 | Ignition Wire Set | 1962 All | 115.00 | 1Q68 | Ignition Wire Set | 1968 All | 99.00 |
| 1Q63 | Ignition Wire Set | 1963 All | 115.00 | 1Q69 | Ignition Wire Set | 1969 All | 99.00 |
| 1Q64 | Ignition Wire Set | 1964 All | 115.00 | 1Q70 | Ignition Wire Set | 1970 All | 99.00 |
| 1Q65 | Ignition Wire Set | 1965 All | 99.00 | 1Q71 | Ignition Wire Set | 1971 All | 99.00 |
| 1Q66 | Ignition Wire Set | 1966 All | 99.00 | 1Q72 | Ignition Wire Set | 1972 All | 99.00 |

Ignition Wire Holders: Fit 1961-75 All Models. SPR615 are different designs for left and right, as per original.

| | | | |
|---------------|-----------------------------|-------------|-----------|
| WH518 | 4 Wire Rubber Wire Holder | 1961-64 All | 8.00 ea. |
| SPR615 | 4 Wire Plastic Wire Holders | 1965-75 All | 17.00 pr. |



Plastic Wire Harness Hold Down Straps: We have three styles of harness straps used on 1961-75 Oldsmobile models. Plastic straps attach to inner fender wells to secure wiring harnesses.

| | | | |
|--------------|--------------------|----------------|----------|
| WHF05 | Wire Harness Strap | 1961-65 models | 8.00 ea. |
| WHF07 | Wire Harness Strap | 1966-69 models | 8.00 ea. |
| WHF06 | Wire Harness Strap | 1970-75 models | 8.00 ea. |



High and Low Note Horn Assemblies: Reproduction high and low note horns for 1961-75 all models. Sold in a pair of one high note (F note) and one low note (D note). GM parts books show the low note is originally an A note for Oldsmobiles. Includes mounting brackets. Delco-Remy on horn case per original.

H3911 Horn Assemblies 1961-75 All 129.00 pr.



Oil Filler Caps

We offer the following reproduction Oil Filler Caps for 1961-75 Oldsmobiles.

| | | | | |
|----------------|---|---------------------------|-------|---|
| OF490 | Black Oil Filler Breather Cap | 1961-62 Dynamic 88 371 V8 | 69.00 |  |
| OF490CH | Chrome Oil Filler Breather Cap | 1961-62 Starfire | 89.00 | |
| OF667 | Black 'Top Hat' Oil Filler Cap | 1966-67 88-98-Toro | 39.00 |  |
| OF67C | Chrome 'Top Hat' Oil Filler Cap | 1966-67 88-98-Toro | 39.00 | |
| OF680 | Oil Filler Cap | 1968-70 88-98-Toro | 39.00 | |
| | with 'Engine Oil Fill and AC-FC60' imprinted on top | | | |
| OF6876 | Oil Filler Cap original style with tabs | 1971-75 All | 33.00 | |
| OFT6877 | Oil Filler Tube, presses into block | 1968-75 All V8 | 26.50 | |



OF667



OF67C



OF680



OF6876



OFT6877

OF490

OF490C

Air Filters and PCV Valves:

| | | | |
|---------------|--------------------|--|-------|
| A331C | Air Filter Element | 1963-74 All 2 barrel, 1964-66 All Jetstar 88 | 18.00 |
| A212CW | Air Filter Element | 1966-75 Toronado, 68-76 All 4 barrel | 23.50 |
| CV679C | PCV Valve | 1964-76 All | 12.00 |
| FB59 | Crankcase Filter | 1967 Delmont 330, 1968 All V8 | 7.50 |
| FB56 | Crankcase Filter | 1969-76 All | 18.50 |



FB56

1964-77 V8 Engine Lift Hook: Attaches to left side front of intake on all 1964-77 V8 engines. Used as a lift hook for hoisting the engine from car frame.

| | | | |
|---------------|------------------|--------------------|-------|
| ELH647 | Engine Lift Hook | 1964-77 V8 Engines | 15.00 |
|---------------|------------------|--------------------|-------|



Engine Oil Indicator Dipsticks and Tubes: New Oil Indicator Tubes and Dipsticks available for all 1968-73 350 and 455 V8 engines except Toronado.

| | | | |
|---------------|---------------------------------|---|-------|
| 401568 | Engine Oil Indicator Tube | 1968 350 w/ short tube, 1969-73 350 V8 | 19.50 |
| | | extends approx. 9 7/8" from block | |
| 401357 | Engine Oil Indicator Tube | 1969-73 455 V8 exc. Toro | 19.50 |
| | | extends approx. 11 3/4" from block | |
| 401567 | Engine Oil Indicator (dipstick) | 1968 350 w/ short tube, 1969-73 350 V8 | 33.00 |
| 419242 | Engine Oil Indicator (dipstick) | 1968 350 w/ long tube, 1969-73 455 V8 exc. Toro | 33.00 |



Carburetor Throttle Return Vacuum Tee: Rubber vacuum line union 'T' used on all 1961-64 models equipped with 4 barrel carburetor.

| | | | |
|---------------|---------------------------------|------------------|-------|
| TVT584 | Carb Throttle Return Vacuum Tee | 1961-64 4 barrel | 10.00 |
|---------------|---------------------------------|------------------|-------|



Replacement PF7 Oil Filters: New engine oil filters available for All 1961-64 Oldsmobile V8 engines.

| | | | |
|------------|-------------------|--------------------|-------|
| PF7 | Engine Oil Filter | 1961-64 V8 engines | 24.50 |
|------------|-------------------|--------------------|-------|

Carburetor Rebuild Kits

New fresh stock that includes all parts to properly rebuild all carburetor applications listed below. All components are made from modern materials to withstand today's gasoline.

Floats and base gaskets are not included in kits.

| | | | |
|---------------|----------------|--------------------------------------|-------|
| 1140 | Carburetor Kit | 1961-68 All 394-425-455 2 barrel | 53.00 |
| 1132 | Carburetor Kit | 1961-65 All 4 barrel except 330 V8 | 69.00 |
| 1133-4 | Carburetor Kit | 1964-65 330 V8 4 barrel | 59.00 |
| 1137 | Carburetor Kit | 1964-68 330-350 V8 2 barrel | 53.00 |
| 370 | Carburetor Kit | 1966 All 4 barrel | 63.00 |
| 1138 | Carburetor Kit | 1969-73 All 350-455 2 barrel | 53.00 |
| 236 | Carburetor Kit | 1967-76 All 330-350-425-455 4 barrel | 59.00 |

1961-65 4 Barrel Carburetor Base Gasket: Thick base gasket used on all 1961-65 Rochester 4 barrel carburetors.

| | | | |
|---------------|------------------|--------------------|-------|
| 573280 | Carb Base Gasket | 1961-65 Roch 4 brl | 24.00 |
|---------------|------------------|--------------------|-------|

1961-64 Fuel Filter: Replacement fuel filter element for 1961-64 Oldsmobile, located in glass sediment bowl on fuel pump or in fuel line.

| | | | |
|--------------|---------------------|---------|-------|
| GF149 | Fuel Filter Element | 1961-64 | 15.00 |
|--------------|---------------------|---------|-------|

1963-64 Fuel Pump Glass Bowls: New fuel pump glass bowls available for all 1963-64 Oldsmobiles using a glass bowl filter on fuel pump.

| | | | |
|------------|----------------------|-------------|-------|
| FP9 | Fuel Pump Glass Bowl | 1963-64 All | 29.00 |
|------------|----------------------|-------------|-------|

Carburetor Choke Stoves and Choke Rods: New Choke Stoves available for 1966-67 Oldsmobiles equipped with a four barrel. Choke Rods are sold separately.

| | | | |
|-----------------|------------------------|-------------------------|-------|
| OCS66 | Carburetor Choke Stove | 1966 All 4 barrel | 89.00 |
| OCS67 | Carburetor Choke Stove | 1967 All 4 barrel | 89.00 |
| OCS66R | Carburetor Choke Rod | 1966 4 barrel exc. Toro | 9.00 |
| OCS67R | Carburetor Choke Rod | 1967 4 barrel exc. Toro | 9.00 |
| OCS6667R | Carburetor Choke Rod | 1966-67 Toronado | 9.00 |



OCS66R



OCS67R



OCS6667R

Throttle Cable Sleeve: Small plastic bushing used on 1966-68 Toronado where throttle cable attaches to accelerator lever on carb and 1969-72 Oldsmobile V8 applications where throttle cable attaches to accelerator pedal lever.

| | | | |
|---------------|-----------------------|---------|----------|
| 403929 | Throttle Cable Sleeve | 1966-72 | 9.00 ea. |
|---------------|-----------------------|---------|----------|

Engine Mounts and Transmission Mounts


We have a good supply of the following mounts in stock, including the hard to find 1961-64 Hydramatic Transmission Mounts.

Engine Mounts

| | | | |
|----------------|--------------------|--------------------------------------|------------|
| M2215 | Front Engine Mount | 1961-64 All 88-98 except with 330 V8 | 65.00 |
| M2262/3 | Engine Mounts | 1965-70 All except Toronado | 109.00 pr. |

Transmission Mounts

| | | | |
|----------------|--------------------|-----------------------------|------------|
| M2216/7 | Transmission Mount | 1961-64 with Hydramatic | 119.00 pr. |
| M2224 | Transmission Mount | 1965-70 All except Toronado | 65.00 |



573280



FP9

OCS66



OCS67



403929



M2215



M2262/3



M2216/7

M2224




Engine Gasket Sets, Individual Gaskets

Complete Engine Overhaul Gasket Sets: Includes head, oil pan, rocker cover, valve cover, timing cover, exhaust manifold gaskets, and main bearing oil seals. Intake manifold gaskets included in 1961-64 Gasket set, order individual intake manifold gaskets for 1965-75 applications.


| | | | |
|-------------------|------------|-------------|--------|
| FS7996PT | Gasket Set | 1961-64 All | 285.00 |
| FS8171PT-4 | Gasket Set | 1965-75 All | 179.00 |

*Intake Manifold Gasket not included.



Individual Gaskets:


| | | | |
|------------------|--|--------------------|------------|
| 642G | Cylinder Head Gaskets | 1961-64 All 394 V8 | 139.00 pr. |
| MS9549SH | Intake Manifold Gasket Set | 1961-64 All 394 V8 | 32.00 |
| MS9947-1 | Intake Manifold Gasket Set (2 pc) | 1964-72 330-350 | 32.00 |
| MS96004 | Intake Manifold Gasket Set | 1965-72 425-455 | 56.00 |
| PS12420R | Pushrod Cover Set (valley pan) | 1961-64 394 | 25.00 |
| MS9977 | Exhaust Manifold Gasket Set | 1961-64 All 394 V8 | 32.50 |
| MS90021 | Exhaust Manifold Gasket Set | 1964-72 330-350 | 19.00 |
| MS90078 | Exhaust Manifold Gasket Set | 1965-72 425-455 | 19.00 |
| 6412B | Oil Pan Gasket Set | 1961-62 All | 49.00 |
| 6412C | Oil Pan Gasket Set | 1963-64 All | 49.00 |
| OS13419D | Oil Pan Gasket Set | 1965-75 All | 23.50 |
| 5145 | Rear Main Bearing Seal Set (rope type) | 1961-64 All | 35.00 |
| 3A45 | Rear Main Bearing Seal Set (rubber type) | 1961-64 All | 89.00 |
| BS13927 | Rear Main Bearing Seal Set | 1965-75 All | 23.00 |
| 12421 | Rocker Arm Cover Gaskets | 1961-64 All | 29.50 pr. |
| VS13403R | Rocker Arm Cover Gaskets | 1965-75 All | 25.00 pr. |
| TCS6402-1 | Timing Case Cover Seal and Gasket | 1961-62 All | 35.00 |
| TCS13340 | Timing Case Cover Seal and Gasket | 1963-64 All | 39.00 |
| TCS13417 | Timing Case Cover Seal and Gasket | 1965-75 All | 39.00 |
| FPG3761 | Fuel Pump Gasket | 1961-63 All | 5.00 |
| 563689 | Exhaust Flange Gasket | 1961-62 All | 7.50 ea. |



MS96004



MS90078



OS13419D

TCS13417



13403

Engine Parts

1961-63 394 V8 Engine Oil Pump: Rebuilt oil pumps available for all 1961-63 Oldsmobile 371 & 394 V8 engines that use push-in type screen filter. Requires 250.00 core charge

| | | | |
|---------------|---------------------------|--------------------|--------|
| 388203 | Rebuilt Oil Pump Assembly | 1961-63 V8 engines | 149.00 |
|---------------|---------------------------|--------------------|--------|

1961-77 V8 Freeze Plug Kits:

| | | | |
|-------------|--------------------------|----------------|-----------|
| FPK2 | Freeze Plug Kit (28 pcs) | 1961-64 394 V8 | 65.00 kit |
| FPK3 | Freeze Plug Kit (16 pcs) | 1965-77 All V8 | 29.50 kit |

1961-64 394 V8 Valve Lifters: New lifters should always be installed with a new camshaft.

| | | | |
|--------------|---------------|----------------|-----------|
| VL574 | Valve Lifters | 1961-64 394 V8 | 19.00 ea. |
|--------------|---------------|----------------|-----------|

1961-64 394 V8 Push Rods:

| | | | |
|--------------|-----------|----------------|-----------|
| PR525 | Push Rods | 1961-64 394 V8 | 15.00 ea. |
|--------------|-----------|----------------|-----------|

1961-64 394 V8 Rocker Arm Shafts:

| | | | |
|--------------|------------------|----------------|-----------|
| 42013 | Rocker Arm Shaft | 1961-64 394 V8 | 69.00 ea. |
|--------------|------------------|----------------|-----------|

1961-64 394 V8 Rocker Arms: 1961-64 394 V8 Engines used LH and RH rocker arms on each cylinder, 4 of each used per side.

| | | | |
|---------------|------------------|----------------|-----------|
| RA591R | Right Rocker Arm | 1961-64 394 V8 | 19.50 ea. |
| RA591L | Left Rocker Arm | 1961-64 394 V8 | 19.50 ea. |





1961-64 394 V8 Intake and Exhaust Valves and Valve Guide Sets:

| | | | |
|---------------|--------------------------|--------------------|------------|
| IV590 | Intake Valve | 1961 394 V8 | 25.00 ea. |
| EV560 | Exhaust Valve | 1961 394 V8 | 29.00 ea. |
| IV624 | Intake Valve | 1962-64 All 394 V8 | 25.00 ea. |
| EV624 | Exhaust Valve | 1962-64 All 394 V8 | 29.00 ea. |
| VG541 | Valve Guides (set of 16) | 1961 394 V8 | 145.00 set |
| VG624 | Valve Guides (set of 16) | 1962-64 394 V8 | 145.00 set |
| VSS514 | Valve Seals (set of 16) | 1961-64 394 V8 | 26.50 set |

1961-64 394 V8 Valve Springs: A necessary replacement with any valve job.

| | | | |
|--------------|--------------|----------------|----------|
| VS560 | Valve Spring | 1961-64 394 V8 | 9.00 ea. |
|--------------|--------------|----------------|----------|

1961-64 394 V8 Timing Chain and Gears:

| | | | |
|------------------|------------------------|----------------|------------|
| 494/44/46 | Timing Chain and Gears | 1961-64 394 V8 | 165.00 set |
|------------------|------------------------|----------------|------------|

1961-64 394 V8 Pistons and Rings:

Pistons and rings are available in standard, oversize .020 or oversize .030. All size pistons and rings are not in stock, allow 1-2 weeks for shipment. Specify size when ordering.

| | | | |
|---------------|--|----------------|------------|
| P614L | Low Compression Piston and Pin set (8.75:1) | 1961-64 394 V8 | 495.00 set |
| P614H | High Compression Pistons and Pin set (10.25:1) | 1961-64 394 V8 | 495.00 set |
| PRS614 | Piston Ring Set | 1961-64 394 V8 | 99.50 set |

1961-64 Connecting Rod Bushing to Piston Pin: This bushing is installed on the piston end of the connecting rod.

| | | | |
|---------------|------------------------|----------------|-----------|
| CRB496 | Connecting Rod Bushing | 1961-64 394 V8 | 8.50 each |
|---------------|------------------------|----------------|-----------|

1961-64 394 V8 Rod Bearing Sets: Available in standard, undersize .010, or undersize .020. Specify size when ordering.

| | | | |
|--------------|-----------------|----------------|------------|
| RB590 | Rod Bearing Set | 1961-64 394 V8 | 129.00 set |
|--------------|-----------------|----------------|------------|

1961-64 394 V8 Main Bearing Sets: Available in undersize .010, or undersize .020. Specify size when ordering.

| | | | |
|------------|------------------|----------------|------------|
| MB8 | Main Bearing Set | 1961-64 394 V8 | 209.00 set |
|------------|------------------|----------------|------------|

1961-64 394 V8 Cam Bearing Set:

Cam Bearings should be replaced when installing a new camshaft.

| | | | |
|--------------|-----------------|----------------|-----------|
| CB564 | Cam Bearing Set | 1961-64 394 V8 | 79.00 set |
|--------------|-----------------|----------------|-----------|



1961-64 394 V8 Camshafts: New replacement camshafts for all 1961-64 394 V8's are manufactured to original stock specifications


| | | | |
|---------------|----------|-------------------------|--------|
| SOC2 | Camshaft | 1961-64 88-98 394 V8 | 349.00 |
| SOC2HP | Camshaft | 1961-64 Starfire 394 V8 | 349.00 |



1965-70 425-455 V8 Dual Exhaust Manifolds: New exhaust manifolds for 1965-70 425 and 455 88-98-Starfire models with dual exhaust.

Left manifold has S casting and 384895 LH, right manifold has W casting and 389268 RH. Left manifold is available separately or sold in a pair.

| | | | |
|----------------|---------------------------------|-------------------------------------|------------|
| EM650L | Left Side Dual Exhaust Manifold | 1965-70 425-455 88-98-Starfire | 269.00 |
| EM650PR | Dual Exhaust Manifolds, pair | 1965-70 425-455 88-98-Starfire | 399.00 pr. |
| EM692WZ | Dual Exhaust Manifolds, pair | 1971-73 455 88 & 98 models | 399.00 pr. |
| EMB647 | Exhaust Manifold Bolt Kit | 1965-70 All | 36.50 kit |
| EML65 | Exhaust Manifold Lock Washer | 1965-75 All models (4 used per car) | 7.50 ea. |



Air Cleaner Vent Pipes: Metal Vent Pipe mounts into rubber grommets between the air cleaner and the valve cover breather.

| | | | |
|---------------|-----------------------|--|-------|
| 399765 | Air Cleaner Vent Pipe | 1968 88-98 exc. A/C | 39.00 |
| 399766 | Air Cleaner Vent Pipe | 1968 88-98 with A/C | 39.00 |
| 405087 | Air Cleaner Vent Pipe | 1969-74 350, 1971-76 455 1978-85 260, 307 & 350 gas engines | 23.50 |



Valve Cover Grommets: Various usage on many 1961-75 Models. Compare to pictures for correct application.

VC104 Valve Cover Grommet. 1964-75 Models, D-Shaped. 13.00



VC95 Crankcase Vent Grommet. Used on 1966-75 Most Models. 3/4" outside diameter as original 13.00



VC97 PCV Vent Pipe to Air Cleaner Grommet used on 1965 V8 w/ PCV in air cleaner and 1966-67 w/ PCV 13.00



VC44 Valve Cover Grommet used on many 1963-67 Models. 13.00

VC83 Valve Cover Grommet. Wide usage on many 1964-75 Models. Original D-shape configuration. 13.00



VC73 Vent Pipe to Air Cleaner Rubber Grommet used on all 1973-77 for the side of the air cleaner to the vent pipe 18.00

VC17 Vent Pipe to Air Cleaner Grommet. Used on all 1969-75 Models. 15.00



Air Filter Vacuum Hose Kit: Correct ribbed vacuum hose with a white stripe, used on all 1968-72 V8 4 barrel engines. Kit contains two pieces of hose.

| | | | |
|----------------|------------------------|------------------|-------|
| AFVH682 | Air Filter Vacuum Hose | 1968-72 4 barrel | 19.00 |
|----------------|------------------------|------------------|-------|



Engine Vacuum Hose: 5/32" inner diameter Black Vacuum Hose with color tracer stripes used in various areas in the engine compartment. Sold by the foot only. Check car for proper needs, we do not have any information on colors or lengths originally used.

| | | |
|---------------|-----------------------------------|---------------|
| VH898A | Vacuum Hose, all Black, no tracer | 5.00 per foot |
| VH898B | Vacuum Hose, Blue tracer | 5.00 per foot |
| VH898P | Vacuum Hose, Pink tracer | 5.00 per foot |
| VH898R | Vacuum Hose, Red tracer | 5.00 per foot |
| VH898W | Vacuum Hose, White tracer | 5.00 per foot |
| VH898Y | Vacuum Hose, Yellow tracer | 5.00 per foot |
| VH898T | Vacuum Hose Connector 'T' | 5.00 ea. |



Engine Paint

These engine enamels are computer color-matched and are the closest to original available. To properly paint an engine 3 to 4 aerosol cans will be needed. Aerosol cans are 16 oz. Please note that we can only ship paint to addresses in the continental United States. Because of air carrier regulations we will not ship paint by air or out of the United States under any circumstances.



| | | | |
|---------------|-------------------------------|--|-----------|
| EP110S | Red Engine Paint | 1961-69 394-425-455 Engines (exc 1966-69 Toronado) | 23.00 can |
| EP75S | Aqua Engine Paint | 1961-64 some 88 models w/ 2 barrel | 23.00 can |
| EP74 | Gold Engine Paint | 1964-75 All 330-350 Engines | 23.00 can |
| EP120S | Slate Blue Engine Paint | 1966-69 Toronado | 23.00 can |
| EP100S | Blue Engine Paint | 1970-75 455 Engines | 23.00 can |
| AF150S | Red Air Filter Assembly Paint | All Models using Red Air Filters | 23.00 can |



Suspension Parts

Gas Shock Absorbers: New tubular type gas shock absorbers are available to give you the quality ride and handling that you expect from your Oldsmobile. Shocks are sold in a pair.

| | | | |
|---------------|------------------------------|----------------------|------------|
| 50140G | Front Shock Absorber | 1961-64 All 88-98-SF | 149.00 pr. |
| 50152G | Front Shock Absorber | 1965-70 All 88-98-SF | 149.00 pr. |
| 50226G | Front Shock Absorber | 1966-70 Toronado | 149.00 pr. |
| 50227G | Rear Vertical Shock Absorber | 1967-70 Toronado | 149.00 pr. |

50140G

50213G

Upper and Lower Ball Joints: New Ball Joints available for the Oldsmobile models listed below. At this time there are no 1961-62 lower ball joints available new.

| | | | |
|----------------|------------------|------------------------|-----------|
| BJ10176 | Upper Ball Joint | 1961-64 88-98-Starfire | 99.00 ea. |
| BJ10747 | Upper Ball Joint | 1965-70 88-98-Starfire | 99.00 ea. |
| BJ10268 | Upper Ball Joint | 1971-76 88-98 | 59.00 ea. |
| BJ10142 | Lower Ball Joint | 1963-70 88-98-Starfire | 99.00 ea. |
| BJ10267 | Lower Ball Joint | 1971-76 88-98 | 59.00 ea. |



BJ10176

BJ10142

5171

Upper and Lower Front Control Arm Bushings: 4 Upper Bushings (2 pair) and 4 Lower Bushings (2 pair) used per car.

| | | | |
|-------------|----------------------------|------------------------|----------------|
| 5171 | Upper Control Arm Bushings | 1961-63 88-98-Starfire | 109.00 pr. |
| 6108 | Upper Control Arm Bushings | 1964-73 88-98-Starfire | 69.00 set of 4 |
| 419 | Lower Control Arm Bushings | 1961-64 88-98-Starfire | 79.00 pr. |
| 5144 | Lower Control Arm Bushings | 1965-70 88-98-Starfire | 89.00 set of 4 |



419

Stabilizer Bar End Link Kits and Stabilizer Bar to Frame Rubber Bushings:

| | | | |
|--------------|----------------------------|-------------------------|-----------|
| K440 | Front Stabilizer Link Kits | 1961-70 88-98-SF | 25.00 pr. |
| K446 | Front Stabilizer Link Kits | 1966-78 Toronado | 25.00 pr. |
| K5227 | Front Stabilizer Bushings | 1961-62 88-98-SF | 25.00 pr. |
| K8204 | Front Stabilizer Bushings | 1963-64 88-98-SF | 25.00 pr. |
| K5241 | Front Stabilizer Bushings | 1965-76 except Toronado | 25.00 pr. |
| K5253 | Front Stabilizer Bushings | 1966-78 Toronado | 23.00 pr. |

K440

K5241

FB4220

Rubber Suspension Bumpers:

| | | | |
|---------------|--------------------------|---------------------------------|-----------|
| FB4220 | Upper Control Arm Bumper | 1961-70 All except Toronado | 24.50 pr. |
| FB6410 | Lower Control Arm Bumper | 1965-70 All except Toronado | 24.50 pr. |
| AB6473 | Axle Housing Bumper | 1965-70 88-98, 1966-69 Toronado | 29.00 pr. |



FB6410

AB6473

Front Lower Control Arm Bolt Kit: New lower control arm bolts and lock nuts for all 1965-70 models except Toronado.

| | | | |
|----------------|-------------------------------|-------------------|-----------|
| FCAB642 | Front Lower Control Arm Bolts | 1965-70 exc. Toro | 29.75 kit |
|----------------|-------------------------------|-------------------|-----------|



FCAB642

Rear Control Arm Bushings and Bolts:

| | | | |
|-----------------|---------------------------|-------------------|----------------|
| K5161 | Rear Control Arm Bushings | 1965-70 All | 99.00 set of 4 |
| RCABK642 | Rear Control Arm Bolt Kit | 1965-70 exc. toro | 59.50 set |



K5161

Coil Springs and Insulators



Springs are made to order and are correct for your car. Our supplier matches the new springs to your application to ensure maintaining the proper ride, height, and handling. Springs are made from modern materials and as such may differ in appearance from originals. When ordering we need to know year, model, body style, engine size, transmission, whether or not the car is air conditioned, and if heavy duty springs are desired. Note that heavy duty springs will likely change your car's ride quality but will not change the ride height. Springs are not in stock, allow 2-3 weeks for delivery. As coil springs are a special order item, they are not returnable.

| | | | |
|---------------|-----------------------------|------------------------|------------|
| FCS615 | Front Coil Springs | 1961-75 88-98-Starfire | 299.00 pr. |
| RCS615 | Rear Coil Springs | 1961-75 88-98-Starfire | 299.00 pr. |
| RSI612 | Rear Coil Spring Insulator | 1961-75 88-98-Starfire | 15.00 ea. |
| 562197 | Front Coil Spring Insulator | 1961-64 88-98-Starfire | 19.00 ea. |

1966-70 Tornado Rear Leaf Springs: Sold in pairs only, allow 2-3 weeks delivery.

| | | | |
|---------------|-------------------|-----------------|------------|
| RL660T | Rear Leaf Springs | 1966-70 Tornado | 475.00 pr. |
|---------------|-------------------|-----------------|------------|



Wheel Bearings and Seals, 1961-75 88-98-Starfire

| | | | |
|---------------|---------------------------|-------------------------------------|-----------|
| 909066 | Front Wheel Inner Bearing | 1961 88-98-Starfire | 95.00 ea. |
| 909073 | Front Wheel Outer Bearing | 1961 88-98-Starfire | 59.50 ea. |
| S5 | Front Wheel Inner Bearing | 1962-75 except Jetstar 88 & Tornado | 33.50 ea. |
| S3 | Front Wheel Outer Bearing | 1962-75 except Jetstar 88 & Tornado | 33.50 ea. |
| S6 | Front Wheel Inner Bearing | 1964-66 Jetstar 88 | 29.50 ea. |
| S2 | Front Wheel Outer Bearing | 1964-66 Jetstar 88 | 29.50 ea. |
| 20118 | Front Wheel Grease Seal | 1961-68 except Jetstar 88 & Tornado | 29.50 ea. |
| 17815 | Front Wheel Grease Seal | 1964-66 Jetstar 88 | 26.50 ea. |
| 20113 | Front Wheel Grease Seal | 1969-70 88-98 models | 23.50 ea. |
| 88128R | Axle Bearing | 1961-67 88-98 models | 74.50 ea. |
| 88131R | Axle Bearing | 1968-70 88-98 models | 79.50 ea. |
| 15343 | Axle Oil Seal | 1961-64 88-98-Starfire | 28.50 ea. |
| 13492 | Axle Oil Seal | 1964-66 Jetstar 88 | 29.50 ea. |
| 15376 | Axle Oil Seal | 1965-70 88-98-Starfire | 29.50 ea. |



Differential Housing Gasket: Rear end cover gaskets for 1961-70 All models except Tornadoes.

| | | | |
|---------------|-----------------------------|---------|-------|
| 569569 | Differential Housing Gasket | 1961-64 | 21.50 |
| 10103E | Differential Housing Gasket | 1965-70 | 21.50 |




| | | | |
|--------------|---------------------------|--|------|
| DT642 | Differential Aluminum Tag | 1965-75 88-98-Starfire with Positraction | 6.00 |
|--------------|---------------------------|--|------|

Differential Vent Valve: Plastic differential vent used on 1973 88 and 88 Royale all models except anti-spin differential.

| | | |
|--------------|-------------------------|------|
| DIF64 | Differential Vent Valve | 9.00 |
|--------------|-------------------------|------|

Axle to Rear End Housing Gaskets (A) and Brake Backing Plate to Axle Gaskets (B) (4 piece set) Die cut gaskets apply to 1961-64 All Models.

| | | | |
|---------------|----------------------------|---------|-----------|
| ABP390 | Axle & Brake Plate Gaskets | 1961-64 | 29.00 set |
|---------------|----------------------------|---------|-----------|



Differential Pinion Shaft Seals: Seal located in the front of the differential where the driveshaft installs into the rear end.

| | | | |
|--------------|--------------------------|---------------------------------------|-------|
| 19438 | Differential Pinion Seal | 1961-62 88-98-Starfire | 33.00 |
| 19310 | Differential Pinion Seal | 1963-64, 1965 1st Type 88-98-Starfire | 33.00 |

1st type seal is 2 7/8" outer diameter, 2nd type for 1965 is 2 3/4" O.D.




Driveshaft Universal Joints: For all 1961-75 88-98-Starfire Models. Same U-joint is used at front and rear of driveshaft.

1143011 Universal Joint 1961-75 All 88-98-Starfire 65.00 ea.



1961-64 Transmission Seals and Filter: New seals and filter available for 1961-64 Oldsmobiles equipped with the Roto-Hydramatic Transmission.

| | | | |
|----------------|--------------------------------------|-------------------------|--------|
| 8619560 | Transmission Front Pump Seal | 1961-64 Roto-Hydramatic | 29.50 |
| 46144 | Transmission Tail Shaft Seal | 1961-64 Roto-Hydramatic | 29.50 |
| TG17047 | Transmission Pan Gasket | 1961-64 Roto-Hydramatic | 29.50 |
| HS750D | Transmission Filter Assembly | 1961-64 Roto-Hydramatic | 119.00 |
| H105D | Transmission Selector Shaft Seal Kit | 1961-64 Roto-Hydramatic | 21.00 |



1961-64 Roto Hydramatic Rebuild Kits: The 1961-64 Roto Hydramatic Overhaul Kit contains all gaskets, rubber seals, sealing rings and metal clad seals. The Master Kit contains everything in the Overhaul Kit with the addition of the friction and steel plates. The Bushing Kit, Washer Kit and transmission band are not included with the kits, these are sold separately. Transmission Band rebuilding service will require your original be sent in for service, please allow 2-3 weeks for this service.

| | | | |
|----------------|-----------------------------------|-------------------------|------------|
| HS102-1 | Transmission Master Rebuild Kit | 1961-64 Roto Hydramatic | 499.00 kit |
| HS102-3 | Transmission Overhaul Kit | 1961-64 Roto Hydramatic | 219.00 kit |
| KHS106 | Transmission Bushing Kit | 1961-64 Roto Hydramatic | 79.50 kit |
| KHS111 | Transmission Thrust Washer Kit | 1961-64 Roto Hydramatic | 139.00 kit |
| HS122 | Transmission Band Rebuild Service | 1961-64 Roto Hydramatic | 99.00 |

Transmission Filters and Pan Gaskets: The following transmission filter kits for TH350, TH400 & TH425 automatics include a new filter, filter gasket and pan gasket.

| | | | |
|----------------|-------------------------|---------------------------------|-----------|
| TG18621 | Transmission Pan Gasket | 1965-80 TH400 Trans | 18.50 |
| TF400E | Transmission Filter Kit | 1965-67 TH400 Trans | 43.00 kit |
| TF425E | Transmission Filter Kit | 1966-78 Toronado w/ TH425 Trans | 47.50 kit |
| TF400 | Transmission Filter Kit | 1968-80 TH400 Trans | 26.50 kit |
| TG18633 | Transmission Pan Gasket | 1969-80 TH350 Trans | 18.50 |
| TF350 | Transmission Filter Kit | 1969-74 TH350 Trans | 26.50 kit |
| TF350L | Transmission Filter Kit | 1975-80 TH350 Trans | 26.50 kit |



1967-77 TH400 Transmission Dipstick and Tube: New dipstick and tube available for all 1967-77 Oldsmobiles with the TH400 automatic transmission.

TDS677 TH400 Dipstick & Tube 1967-77 Oldsmobile 39.50



1966-78 Toronado Front Wheel Bearings, Outer CV Boots and Seals

| | | | |
|----------------|--|------------------|------------|
| 907770 | Front Wheel Bearing | 1966-68 Toronado | 199.00 ea. |
| 9078S | Front Wheel Bearing Seal | 1966-68 Toronado | 25.00 ea. |
| 66-1005 | Outer CV Boot | 1966-78 Toronado | 39.00 ea. |
| 47464 | Output Shaft Transmission Seal (LH only) | 1966-78 Toronado | 39.00 |



1966-78 Toronado Suspension Parts

Toronado Steering Idler Arm and Pitman Arm:

| | | | |
|-----------------|------------|------------------|--------|
| IA18737 | Idler Arm | 1967-78 Toronado | 139.00 |
| PIT18738 | Pitman Arm | 1967-74 Toronado | 249.00 |



Toronado Tie Rod Ends and Adjusting Sleeves:

| | | | |
|----------------|--------------------------|------------------|-----------|
| TRE361L | Outer Tie Rod End | 1966-68 Toronado | 79.00 ea. |
| TRE412L | Outer Tie Rod End | 1969-78 Toronado | 79.00 ea. |
| TRE361R | Inner Tie Rod End | 1969-78 Toronado | 79.00 ea. |
| ES2004S | Tie Rod Adjusting Sleeve | 1966-74 Toronado | 26.50 ea. |



Front Control Arm Bushings:

| | | | |
|----------------|----------------------------|-------------------------|-----------------|
| BU12227 | Upper Control Arm Bushings | 1967-75, 77-78 Toronado | 59.00 pair |
| BU12299 | Lower Control Arm Bushings | 1966-78 Toronado | 139.00 set of 4 |



Toronado Ball Joints: New upper and lower ball joints available for Oldsmobile Toronados.

| | | | |
|----------------|--------------------------------|------------------|------------|
| BJ10241 | Upper Ball Joint (either side) | 1966-70 Toronado | 99.00 ea. |
| BJ10280 | Upper Ball Joint (either side) | 1971-72 Toronado | 99.00 ea. |
| BJ10270 | Upper Ball Joint (either side) | 1973-75 Toronado | 69.00 ea. |
| BJ10242 | Lower Ball Joint (either side) | 1966-70 Toronado | 115.00 ea. |
| BJ10281 | Lower Ball Joint (either side) | 1971-78 Toronado | 115.00 ea. |



Power Steering Hose Kits

These kits include the pressure hose with correct fittings and the return hose with clamps.

| | | | |
|---------------|-------------------------|--|-----------|
| PSH590 | Power Steering Hose Kit | 1961-62 88-98-Starfire | 99.50 kit |
| 35241 | Power Steering Hose Kit | 1963-67 98, 1965-67 88, 1965 Jetstar 1, 1965-66 Jetstar 88 & Starfire | 79.50 kit |
| 36212 | Power Steering Hose Kit | 1966-67 Toronado | 79.50 kit |
| 35251 | Power Steering Hose Kit | 1968-70 88-98 | 79.50 kit |
| PSH737 | Power Steering Hose Kit | 1973-77 88-98 | 63.50 kit |



1961-77 Power Steering Pump and Gear Box Rebuilding Kits:

Kits include all gaskets and seals needed to rebuild your Power Steering Pump or Power Steering Gear Box.

| | | | |
|----------------|-------------------------------------|-------------|--------|
| 5688065 | Power Steering Pump Rebuild Kit | 1961-67 All | 69.50 |
| 5688044 | Power Steering Pump Rebuild Kit | 1968-77 All | 69.50 |
| 5687179 | Power Steering Gear Box Rebuild Kit | 1961-77 All | 139.00 |



1961-67 Power Steering Pump and Gear Box Rebuilding Services: Rebuilding service available for all 1961-67 Power Steering Pumps and Power Steering Gear Boxes. Rebuilding service requires that you send your existing units in to us to be rebuilt. Please allow 4-6 weeks.

| | | | |
|-----------------|---|-------------|--------|
| PSP-614 | Power Steering Pump Rebuilding Service | 1961-64 All | 329.00 |
| PSP-657 | Power Steering Pump Rebuilding Service | 1965-67 All | 329.00 |
| PSGB-613 | Power Steering Gearbox Rebuilding Service | 1961-63 All | 499.00 |
| PSGB-970 | Power Steering Gearbox Rebuilding Service | 1964-76 All | 359.00 |



Power Steering Reservoir Cap: New replacement cap for all 1968-77 models.

| | | | |
|---------------|------------------------------|-------------|-------|
| PSC820 | Power Steering Reservoir Cap | 1968-77 All | 12.50 |
|---------------|------------------------------|-------------|-------|

Brake Parts

Our brake parts section offers the best quality merchandise available. Many of the items listed are becoming difficult to obtain, so please plan ahead of actual use.

Brake Shoes: Brake shoes are sold in axle sets only. One set will service either both front or both rear wheels.

| | | | |
|--------------|------------------------|--|-----------|
| 160RR | Brake Shoe Set (front) | 1961-64 All except Jetstar 88 | 75.00 set |
| 228RR | Brake Shoe Set (rear) | 1961-64 All except Jetstar 88 | 75.00 set |
| 260RR | Brake Shoe Set (front) | 1966-69 Toronado, 1965-70 88-98 models except Jetstar 88 | 75.00 set |
| 262RR | Brake Shoe Set (rear) | 1966-69 Toronado, 1965-70 88-98 models except Jetstar 88 (2" wide) | 75.00 set |
| 242RR | Brake Shoe Set (rear) | 1964-66 Jetstar 88 models | 65.00 set |
| 246RR | Brake Shoe Set (front) | 1964-66 Jetstar 88 models | 65.00 set |
| 284PG | Brake Shoe Set (front) | 1966-69 Toronado w/ front drum brakes | 85.00 set |
| D52 | Brake Disc Brake Pads | 1969-76 88-98 models w/ front disc brakes 1969-73 Toronado w/ front disc brakes | 49.50 set |



Wheel Cylinders: Replace leaky or bound up Wheel Cylinders with these new replacement units.

| | | | |
|--------------|------------------------------------|--|-----------|
| 32071 | Left Front Wheel Cylinder | 1961-67 88-98-Starfire except Jetstar 88 | 55.00 |
| 32072 | Right Front Wheel Cylinder | 1961-67 88-98-Starfire except Jetstar 88 | 55.00 |
| 37022 | Left Front Wheel Cylinder | 1964-66 Jetstar 88 | 40.00 |
| 37023 | Right Front Wheel Cylinder | 1964-66 Jetstar 88 | 40.00 |
| 36041 | Left Front Wheel Cylinder | 1968-70 88-98 models | 55.00 |
| 36042 | Right Front Wheel Cylinder | 1968-70 88-98 models | 55.00 |
| 37019 | Left Front Wheel Cylinder | 1966-69 Toronado | 55.00 |
| 37020 | Right Front Wheel Cylinder | 1966-69 Toronado | 55.00 |
| 13387 | Left Rear Wheel Cylinder | 1961-70 88-98 except Jetstar 88 | 55.00 |
| 13388 | Right Rear Wheel Cylinder | 1961-70 88-98 except Jetstar 88 | 55.00 |
| 37021 | Rear Wheel Cylinders (either side) | 1964-66 Jetstar 88 | 29.50 ea. |
| 37116 | Rear Wheel Cylinders (either side) | 1966-69 Toronado | 55.00 ea. |
| 37048 | Rear Wheel Cylinder (either side) | 1971-75 88-98 exc. police pkg. | 55.00 ea. |



Brake Hoses

| | | | |
|--------------|--------------------------------------|------------------------|-----------|
| 36611 | Front Brake Hoses (drum brakes) | 1961-69 88-98-Starfire | 39.50 ea. |
| 35018 | Rear Brake Hose | 1961-62 88-98-Starfire | 49.50 |
| 36692 | Rear Brake Hose | 1966-68 88-98-Starfire | 53.00 |
| 36572 | Left Front Brake Hose (drum brakes) | 1966-69 Toronado | 53.00 |
| 36573 | Right Front Brake Hose (drum brakes) | 1966-69 Toronado | 53.00 |



Brake Hardware

Self Adjuster Screws: For 1962-70 88-98-Starfire and Toronado.

| | | | |
|--------------|---------------------------|------------------------------------|-------|
| 80551 | Left Side Adjuster Screw | 1962-70 88-98-SF, 1966-69 Toronado | 18.50 |
| 80552 | Right Side Adjuster Screw | 1962-70 88-98-SF, 1966-69 Toronado | 18.50 |



Brake Return Spring and Hold Down Hardware Kits:

Kits include all hold down springs and brake return springs for front and rear drum brakes.

| | | | |
|--------------|--|------------------------------------|-----------|
| H7124 | Rear Axle Brake Spring/Hardware Kit (both sides) | 1965-70 88-98-SF, 1966-69 Toronado | 29.00 kit |
| H7125 | Front Wheel Brake Spring/Hardware Kit (both sides) | 1965-70 88-98-SF, 1966-69 Toronado | 29.00 kit |




Brake Adjuster Rubber Plugs: Fits all 1961-75 Models. Plugs adjusting hole in brake drums.

| | | |
|-------------|---------------------------------|----------|
| 4406 | Rubber Adjuster Plug (set of 4) | 7.00 set |
|-------------|---------------------------------|----------|



Parking Brake Cables: The 1961-64 cables use a different design from left to right on the rear cables, 1967-76 88 & 98 Parking Brake Cables are sold as a complete set only, no individual parts available. Sets include Front, Intermediate, and Rear Cables plus connectors and clips as needed. Toronados use one rear cable and one front cable with no intermediate cable. Toronado cables are sold individually.

| | | | |
|----------------|---------------------------|------------------------------------|------------|
| 2195 | Front Parking Brake Cable | 1962 88-S88-Starfire | 109.00 |
| 2196 | Front Parking Brake Cable | 1962 98 | 109.00 |
| 2174 | Rear Parking Brake Cable | right side, 1961-62 88-98-SF | 79.50 |
| 2175 | Rear Parking Brake Cable | left side, 1961-62 88-98-SF | 79.50 |
| 2244 | Front Parking brake Cable | 1963 88-S88-Starfire | 109.00 |
| 2265 | Front Parking Brake Cable | 1963 98 | 109.00 |
| 2368 | Front Parking brake Cable | 1964 88-S88-Starfire | 109.00 |
| 2332 | Front Parking Brake Cable | 1964 98 | 109.00 |
| 2245 | Rear Parking Brake Cable | left side, 1963-64 88-98-Starfire | 79.50 |
| 2246 | Rear Parking Brake Cable | right side, 1963-64 88-98-Starfire | 79.50 |
| ERE801 | Rear Parking Brake Cable | 1966-68 Toronado | 110.00 |
| EFT801 | Front Parking Brake Cable | 1966-67 Toronado | 65.00 |
| PBC6788 | Parking Brake Cable Set | 1967 88 models | 179.00 set |
| PBC6798 | Parking Brake Cable Set | 1967 98 models | 179.00 set |
| PBC6888 | Parking Brake Cable Set | 1968-70 88 models | 179.00 set |
| PBC6898 | Parking Brake Cable Set | 1968-70 98 models | 199.00 set |
| PBC7188 | Parking Brake Cable Set | 1971-72 88 models | 179.00 set |
| PBC7198 | Parking Brake Cable Set | 1971-72 98 models | 179.00 set |
| PBC7388 | Parking Brake Cable Set | 1973-76 88 models | 199.00 set |
| PBC7398 | Parking Brake Cable Set | 1973-76 98 models | 179.00 set |



Dust Cap Anti-Static Coil: Brass coil installs into the front wheel dust caps to cut down on radio interference.

| | | | |
|----------------|----------------------|----------------------------|-------|
| WBSC412 | Anti-Static Coil | 1961-64 exc. 64 Jetstar 88 | 25.00 |
| WBSC612 | Anti-Static Coil | 1964-65 Jetstar 88 | 25.00 |
| DC6853 | Front Wheel Dust Cap | 1964 Jetstar 88 | 16.00 |



1961-64 Power Brake Booster/Master Cylinder Rebuild Service: Requires existing cores be sent in ahead of time for all 1961-64 Bendix or Moraine Brake Boosters. Rebuilding service available for Bendix master cylinder only, or as the master cylinder and power booster assembly. All parts are cleaned, repainted, rebuilt and bench tested. **Core charge for Power Brake Units shipped in advance is 325.00** or we can rebuild your original unit, allow 3-4 weeks delivery time.

| | | | |
|---------------|---|-------------|--------|
| PBM601 | Moraine Booster/Master Assembly Rebuild Service | 1960-61 All | 725.00 |
| PBM620 | Moraine Booster/Master Assembly Rebuild Service | 1962 All | 725.00 |
| PBM630 | Moraine Booster/Master Assembly Rebuild Service | 1963 All | 725.00 |
| PBM640 | Moraine Booster/Master Assembly Rebuild Service | 1964 All | 725.00 |
| PBB612 | Bendix Booster/Master Assembly Rebuild Service | 1961-62 All | 695.00 |
| PBB630 | Bendix Booster/Master Assembly Rebuild Service | 1963 All | 695.00 |
| PBB640 | Bendix Booster/Master Assembly Rebuild Service | 1964 All | 695.00 |



PBM601



PBB630



PBM640



Power Brake Booster Check Valves:

| | | | |
|----------------|--|---|-------|
| 62-310 | Inline Power Brake Check Valve (universal fit) | 1962-66 | 25.00 |
| 1481375 | Bendix Power Brake Check Valve | 1964-66 | 28.50 |
| BCV642B | Moraine Power Brake Check Valve | 1964-73 88-98-Starfire 1966 Toronado w/ disc, 1967-73 Toronado | 8.50 |

Please Read: A fresh rebuilt Power Brake Unit will not always guarantee a solution to your problem. Other areas to check are a lack of vacuum caused by a bad check valve or pin hole in the vacuum reserve tank. Air in the brake lines, deteriorated vacuum hoses or poorly functioning wheel cylinders are areas of concern as well. NEVER use silicone (DOT 5) brake fluid.

Replacement Master Cylinders: New Master Cylinders for 1961-69 Oldsmobile 88, 98, Starfire and Toronado with power brakes. Please note that the master cylinders are service replacements. They do not have the same appearance as the originals, but will work fine. If appearance is an issue you will need to send in your original master cylinder for rebuilding.

| | | |
|--------------|--|--------|
| 31999 | New Master Cylinder for Moraine system 1961 88-98-Starfire (4 bolt mounting) | 159.00 |
| 36137 | New Master Cylinder for Moraine system 1962 88-98-Starfire (2 bolt mounting) | 159.00 |
| 35026 | New Master Cylinder for Bendix system 1961-63 88-98-Starfire (4 bolt mounting) | 159.00 |
| 36136 | New Master Cylinder for Moraine system 1963-66 88-98-SF except Jetstar 88 (2 bolt mounting) | 159.00 |
| 36242 | New Master Cylinder for either system 1964-66 Jetstar, 1966 Toronado | 159.00 |
| 36236 | New Master Cylinder for Bendix system 1967-69 88 and 98, 1967 Toronado | 159.00 |
| 36234 | New Master Cylinder for Moraine system 1967-69 88 and 98 | 159.00 |
| 36306 | New Master Cylinder for either system 1971-76 88 and 98 | 159.00 |





Power Brake Booster Rebuild Kits: Available for Bendix or Moraine power brake booster units. Kits contain necessary parts to rebuild power booster units.

| | | | |
|---------------|--------------------------------|-------------------------|--------|
| 62-569 | Major Brake Booster Repair Kit | 1960-61 Bendix | 325.00 |
| 62-631 | Major Brake Booster Repair Kit | 1961-62 Moraine | 299.00 |
| 62-655 | Major Brake Booster Repair Kit | 1963 Moraine | 259.00 |
| 62-280 | Major Brake Booster Repair Kit | 1964-66 Moraine 9" can | 259.00 |
| 62-463 | Major Brake Booster Repair Kit | 1964-66 Bendix 9" can | 259.00 |
| 62-436 | Major Brake Booster Repair Kit | 1967-69 Bendix | 299.00 |
| 62-281 | Major Brake Booster Repair Kit | 1967-72 Moraine 11" can | 259.00 |



Power Brake Master Cylinder Kits: Rebuild kit for original moraine power brake master cylinders.

| | | | |
|---------------|----------------------------|-----------------|--------|
| 62-474 | Master Cylinder Repair Kit | 1960-63 Moraine | 119.00 |
|---------------|----------------------------|-----------------|--------|


1961-64 Wheel Studs and Lug Nuts: 1961-63 Oldsmobiles had left thread and right thread lug nuts and studs on opposite sides of the car, GM parts books show in 1964 they changed to right thread on both sides of car.

| | | | |
|---------------|-------------------------------|-------------|-----------|
| 8743 | Left Thread Lug Nut | 1961-63 All | 5.00 ea. |
| 8744 | Right Thread Lug Nut | 1961-64 All | 5.00 ea. |
| 499908 | Front Right Thread Wheel Stud | 1961-64 All | 12.00 ea. |
| 499909 | Front Left thread Wheel Stud | 1961-63 All | 12.00 ea. |
| 499542 | Rear Right Thread Wheel Stud | 1961-64 All | 12.00 ea. |
| 499543 | Rear Left Thread Wheel Stud | 1961-63 All | 12.00 ea. |



Turn Signal Flashers: New 12 volt Turn Signal Flashers available for 1961-76 Oldsmobiles. Early applications could have either two or three terminals, check your car for proper flasher.

| | | |
|---------------|--|------|
| TSF550 | Turn Signal Flasher 1961-63 w/ 3 terminals | 7.50 |
| TSF552 | Turn Signal Flasher 1961-76 w/ 2 terminals | 7.50 |



Fuse Packages: The fuses listed below are sold in packages of 5.

| | | | | | | | | |
|---------------|-------------|------|-------------------|----------------|------|----------------|-------------|--------------|
| AGA-1 | 1 Amp Fuse | 5.50 | AGC-20 | 20 Amp Fuse | 5.50 | **SFE-2 | 2 Amp Fuse | 5.50 |
| AGA-3 | 3 Amp Fuse | 5.50 | AGC-25 | 25 Amp | 5.50 | SFE-4 | 4 Amp Fuse | 5.50 |
| AGA-5 | 5 Amp Fuse | 5.50 | AGC-30 | 30 Amp Fuse | 5.50 | SFE-9 | 9 Amp Fuse | 5.50 |
| AGC-2 | 2 Amp Fuse | 5.50 | AGW-4 | 4 Amp Fuse | 5.50 | SFE-14 | 14 Amp Fuse | 5.50 |
| AGC-15 | 15 Amp Fuse | 5.50 | *AGW-7 1/2 | 7 1/2 Amp Fuse | 5.50 | SFE-20 | 20 Amp Fuse | 5.50 |
| | | | | | | | | ** Use AGA-2 |



1961-75 Interior and Exterior Light Bulbs:

| | | | |
|---------------|--|--|-----------|
| 53 | Dash Instrument Panel Bulb | 1961-63 All | 4.00 ea. |
| 57 | Dash Instrument Panel Bulb | 1961-63 All | 4.00 ea. |
| 67 | License Lamp Bulb | 1961-63 All | 4.00 ea. |
| 90 | Courtesy Lamp Bulb | 1961-75 All exc Conv. | 4.00 ea. |
| 97 | License Lamp Bulb | 1965-75 All | 4.00 ea. |
| 161 | Dash Instrument Panel Bulb | 1968-75 seat belt and brake light | 3.00 ea. |
| 168 | Dash Instrument Panel Bulb | 1964-75 All | 3.00 ea. |
| 194 | Dash and Side Marker Lamp Bulb | 1964-75 All dash, 1969-75 All front and rear Side Marker exc. 1968-69 front (uses 194A), 1963-69 All High Beam and Turn Signal Indicator | 3.00 ea. |
| 194A | Front Side Marker Lamp Bulb (Amber) | 1968-69 All | 3.00 ea. |
| 211B | Dome Light Bulb | 1968-75 Center Roof Dome | 4.00 ea. |
| 212 | Dome Light Bulb | 1968-75 Some models Center Roof Dome | 4.00 ea. |
| 563 | Map Light Bulb | 1968-75 All models | 5.50 ea. |
| 631 | Trunk Light Bulb | 1967-72 All models | 5.00 ea. |
| 1004 | Dome Light Bulb | 1961-67 Center Roof Dome | 4.00 ea. |
| 1073 | Back-Up Light Bulb | 1961-63 All | 5.00 ea. |
| 1156 | Back-Up Light Bulb | 1964-75 All models | 4.00 ea. |
| 1157 | Park, Turn Signal and Tail Lamp Bulb (Clear) | 1961-65 All Park Light, 1964-65 All, 1966-67 Toro Cornering Lamp, 1961-75 All Tail Light | 5.00 ea. |
| 1157NA | Park and Turn Signal Bulb (Amber) | 1966-75 All models | 5.00 ea. |
| 1195 | Cornering Lamp Bulb | 1965-67 All, 1968-71 Toronado | 11.50 ea. |
| 1445 | Ash Tray, Shift Indicator and Heater Controls Bulb | 1961-75 All | 4.00 ea. |
| 1893 | Radio and Clock Bulb | 1961-75 Radio, 1965-66 Clock | 3.00 ea. |
| 1895 | Glove Box Lamp Bulb | 1965-68 All models | 4.00 ea. |



LITERATURE AND PROMOTIONAL ITEMS

NOS Uncirculated Sales Literature:

| | | | | | |
|--|----------------------------|-------|--|--------------------------|-------|
| 1963 All Models Pocket Color Catalog | 16 pages 3 1/2" x 8" | 9.00 | 1965 All Models Pocket Color Catalog | 20 pages 3 1/2" x 8 1/2" | 9.00 |
| 1963 Starfire-Jetfire Sports Model Color Catalog | 8 pages 10 1/2" x 11 1/2" | 24.00 | 1966 All Models Pocket Color Catalog | 20 pages 3 1/2" x 8 1/2" | 9.00 |
| 1963 All Models Color Foldout | 10 1/2" x 10 1/2" Fold in | 20.00 | 1966 Starfire-Toronado-442 Sport Model Color Catalog | 16 pages 8 1/2" x 11" | 25.00 |
| 1963 All Models Prestige Color Catalog | 33 pages 10 1/2" x 10 1/2" | 28.00 | 1966 All Models Color Catalog | 26 pages 8 1/2" x 11" | 20.00 |

Oldsmobile Shop Manuals on CD-ROM: Many of the CD's contain Shop Manuals, Body Manuals and Parts Books. Check our website for a detailed description of contents for each year.

| | | | | | |
|-------------------|---------------------|-------|----------------|------------------|-------|
| OCD1961-62 | Olds CD-ROM 1961-62 | 49.50 | OCD1968 | Olds CD-ROM 1968 | 49.50 |
| OCD1963 | Olds CD-ROM 1963 | 49.50 | OCD1969 | Olds CD-ROM 1969 | 49.50 |
| OCD1964 | Olds CD-ROM 1964 | 49.50 | OCD1970 | Olds CD-ROM 1970 | 49.50 |
| OCD1965 | Olds CD-ROM 1965 | 49.50 | OCD1971 | Olds CD-ROM 1971 | 49.50 |
| OCD1966 | Olds CD-ROM 1966 | 49.50 | OCD1972 | Olds CD-ROM 1972 | 49.50 |
| OCD1967 | Olds CD-ROM 1967 | 49.50 | OCD1973 | Olds CD-ROM 1973 | 49.50 |

1948-63 Oldsmobile Book: Published by Brooklands Books, 172 black & white pages covering all models spanning the years 1948 through 1963. Contains Technical information, road tests, product designs, performance data and reviews.

B221 1948-63 Oldsmobile Book 39.95



LITERATURE AND PROMOTIONAL ITEMS




Owner's Manuals: High quality re-prints of the original owner's manuals.

| | | |
|--------------|------------------------------------|-------|
| OM61 | 1961 88 & 98 Owner's Manual | 24.50 |
| OM62 | 1962 88-98-Starfire Owner's Manual | 24.50 |
| OM64 | 1964 88-98-Starfire Owner's Manual | 24.50 |
| OM65 | 1965 88-98-Starfire Owner's Manual | 24.50 |
| OM66 | 1966 88-98-Starfire Owner's Manual | 24.50 |
| OM67 | 1967 88-98 Owner's Manual | 24.50 |
| OM68 | 1968 88-98 Owner's Manual | 24.50 |
| OM69 | 1969 88-98 Owner's Manual | 24.50 |
| OM70 | 1970 88-98 Owner's Manual | 24.50 |
| OM71 | 1971 88-98 Owner's Manual | 24.50 |
| OM72 | 1972 88-98 Owner's Manual | 24.50 |
| OM73 | 1973 88-98 Owner's Manual | 24.50 |
| OM74 | 1974 88-98 Owner's Manual | 24.50 |
| OM75 | 1975 88-98 Owner's Manual | 24.50 |
| OM76 | 1976 88-98 Owner's Manual | 24.50 |
| OM67T | 1967 Toronado Owner's Manual | 24.50 |
| OM68T | 1968 Toronado Owner's Manual | 24.50 |
| OM69T | 1969 Toronado Owner's Manual | 24.50 |
| OM70T | 1970 Toronado Owner's Manual | 24.50 |



1962-68 Convertible Top Manuals: Quality re-prints of the original convertible top operation manuals that were supplied when purchasing a new Oldsmobile.

| | | |
|--------------|-----------------------------|-------|
| CTM62 | 1962 Convertible Top Manual | 20.00 |
| CTM63 | 1963 Convertible Top Manual | 20.00 |
| CTM64 | 1964 Convertible Top Manual | 20.00 |
| CTM65 | 1965 Convertible Top Manual | 20.00 |
| CTM66 | 1966 Convertible Top Manual | 20.00 |
| CTM67 | 1967 Convertible Top Manual | 20.00 |
| CTM68 | 1968 Convertible Top Manual | 20.00 |



Shop Service Manuals:

Reprints or nice used originals of the repair manuals used by Oldsmobile mechanics.

| | | |
|--------------|---|--------|
| B61RM | 1961 Shop Service Manual | 79.00 |
| B61SF | 1961 Starfire Supplement | 24.50 |
| B62RM | 1962 Service Manual Supplement (Used in combination with 1961 Shop Service Manual for full coverage) | 45.00 |
| B63RM | 1963 Shop Service Manual | 85.00 |
| B64RM | 1964 Shop Service Manual (5 pc set) | 109.00 |
| B65RM | 1965 Shop Service Manual | 109.00 |
| B66RM | 1966 Shop Service Manual | 109.00 |
| B67RM | 1967 Shop Service Manual | 98.00 |
| B68RM | 1968 Shop Service Manual | 98.00 |
| B69RM | 1969 Shop Service Manual | 98.00 |
| B70RM | 1970 Shop Service Manual | 109.00 |
| B71RM | 1971 Shop Service Manual | 98.00 |
| B72RM | 1972 Shop Service Manual | 98.00 |
| B73RM | 1973 Shop Service Manual | 98.00 |
| B74RM | 1974 Shop Service Manual | 65.00 |
| B75RM | 1975 Shop Service Manual | 65.00 |
| B76RM | 1976 Shop Service Manual | 65.00 |
| B77RM | 1977 Shop Service Manual | 65.00 |



Fisher Body Manuals:

Manual covers exterior body parts of all GM lines. Includes detailed coverage of the convertible top and mechanism.

| | | |
|--------------|-------------------------|-------|
| FBM65 | 1965 Fisher Body Manual | 55.00 |
| FBM66 | 1966 Fisher Body Manual | 55.00 |
| FBM67 | 1967 Fisher Body Manual | 55.00 |
| FBM68 | 1968 Fisher Body Manual | 55.00 |
| FBM69 | 1969 Fisher Body Manual | 55.00 |
| FBM70 | 1970 Fisher Body Manual | 55.00 |
| FBM71 | 1971 Fisher Body Manual | 55.00 |
| FBM72 | 1972 Fisher Body Manual | 55.00 |
| FBM73 | 1973 Fisher Body Manual | 55.00 |
| FBM74 | 1974 Fisher Body Manual | 55.00 |
| FBM75 | 1975 Fisher Body Manual | 55.00 |
| FBM76 | 1976 Fisher Body Manual | 55.00 |



FASTENERS

Bumper Bolts: With stainless steel cap as original. For 1965-75 All Front and 1964-75 All Rear.

BB131 Bumper Bolt 2.50 ea.



Bolt: Radiator Shroud and Front Fender Attaching. Bolt is 5/16"-18 X 3/4" Black Oxide finish with a 1/2" head size.

10084 Bolt 1961-75 All 1.00 ea.




Heater Hose Insulator: Used to cushion the heater hose against the alternator bracket. Fits 1968-75 All Models. One per car.

HHI68 Hose Insulator 9.50



Interior Handle Removal Tool: Used to remove clip that fastens the interior handles in place.

T16000 Handle Tool 9.50



Door Inside Handle, Window and Quarter

Window Handle Retaining Clip: For all 1961-75 Models. Package of 10.

2451A Handle Clip All Models 9.50 pkg.



12134 Door Panel Trim Tab: Fits 1964-67 All Models 11.00 pkg. of 25

11774 Door Panel Trim Tab: Fits 1968-75 All models 11.00 pkg. of 25



Interior Screw Package: 9 different shapes and sizes to service areas such as arm rest bases, door and rear trim panels, sun visors, pillar trim, etc. 80 piece package services all 1961-75 Models.

6172 Interior Screw Package 35.00



Sun Visor Support Sleeve and Rubber Grommet: Plastic sleeve that slides into visor and rubber grommet used on visor rod. Four piece set services one car. 1961-75 All Models.

GS6400 Sun Visor Grommet Set (4 pieces) 10.00 set



Deluxe Wheel Cover Retaining Clips: For installation of deluxe wheel covers on 1961-63 88-98-Starfire models. 5 clips used per wheel. 580570 is the unique shorter clip used on 1961 Models.

580570 Wheel Cover Clip 1961 All 10.00 ea.

578143 Wheel Cover Clip 1962-63 All 10.00 ea.



580570



578143

Carburetor Wing Nut: Original and aftermarket style air cleaner wing nuts for all 1964-72 Models.

3741 Aftermarket Wing Nut 2.00

3741A Original Style Wing Nut 6.00



Roof Rail Weatherstrip Fastener: Fits 1961-75 All Models.

44701 Weatherstrip Fastener .75 ea.



Door Weatherstrip Fastener: Used on most 1961-75 Models.

11120 Weatherstrip Fastener .75 ea.



Wheel Opening Molding Screw Package: Bright Zinc finish, fits all 1961-75 Models. 35 per package.

9863 Molding Screw Package 7.50 pkg.



Alternator Plastic End Cap: Red or Black plastic cap used to cover the hot wire on 1962-75 Alternators. A part missing or broken on many cars. A necessity for detailed restorations.

APC62R Red End Cap 1962-75 All 10.00

APC62B Black End Cap 1962-75 All 10.00



License Plate Fasteners: For all 1961-75 Models. Includes 2 nylon fasteners and 2 screws. One set used per plate.

8418-89 License Plate Fasteners 3.00 set



Aluminum Air Filter Plates

Air Filter Plate Chrome Retainer:

Original chrome finish. Adds a final touch to the Air Filter Aluminum Painted Plates listed below.

| | | | |
|---------------|---------------------------|----------------------------|-------|
| FPR657 | Air Filter Plate Retainer | 1965-67 except Toronado | 29.00 |
| FPR680 | Air Filter Plate Retainer | 1968 All, 1966-72 Toronado | 29.00 |
| 3741A | Original Style Wing Nut | 1961-72 All | 6.00 |



Air Filter Aluminum Plates:

Proper color stenciled plates used on top of air cleaners for 1961-68 88-98-Starfire Models, and 1966-69 Toronado. Shipped with a protective plastic covering to prevent scratching of paint detail. Remove covering upon installation. All Plates except BC123 are GM Trademarks that have been licensed and approved.



Ultra-High Compression Plates: U-shaped plates used on 1961-64 All 4 Barrels and 1965-67 All 4 Barrels except for Toronados. 1961-64 used a red background with silver lettering and black highlights. 1965-67 has a silver background with red lettering and black highlights.

| | | | |
|---------------|--------------------------------|-------------------------------|-------|
| BC123B | 'Ultra-High Compression' plate | 1961-64 All 4 barrel | 35.00 |
| DC111A | 'Ultra-High Compression' plate | 1965-67 All 4 barrel exc.Toro | 35.00 |

Starfire Air Filter Plates: 1961-64 Starfires use a red background with silver lettering and black highlights. 1965-66 Starfires have a silver background with red lettering and black highlights and 'Use Premium Fuel' printed on the left side. Both plates are 10" diameter.

| | | | |
|--------------|---------------------------|-------------------|-------|
| BS120 | 'STARFIRE' Aluminum Plate | 1961-64 Starfires | 59.00 |
| BC124 | 'STARFIRE' Aluminum Plate | 1965-66 Starfires | 59.00 |



1961-64 88 and 98 Air Filter Plates: 1961-64 4 Barrels use the 'Sky Rocket' plate with a red background, silver lettering with black highlights. 10" diameter plate also has 'Use Premium Fuel' printed on the left side. 1961-64 2 Barrels use the 'Rocket' plate with a red background, silver lettering with black highlights. 7 1/2" diameter plate for smaller 2 barrel air filters.

| | | | |
|--------------|-----------------------------|------------------|-------|
| BC121 | 'Sky Rocket' Aluminum Plate | 1961-64 4 barrel | 59.00 |
| BC122 | 'Rocket' Aluminum Plate | 1961-64 2 barrel | 59.00 |

1965-67 88 & 98 Air Filter Plates: Both plates have 'Super Rocket' in red lettering on a silver background with black highlights. The 4 barrel plate is 10" diameter. The 2 barrel plate is 7 1/2" diameter with 'Ultra High Compression' printed under the word Oldsmobile. Also has the 'Use Premium Fuel' printed on the right side.

| | | | |
|--------------|-------------------------------|------------------|-------|
| BC125 | 'Super Rocket' Aluminum Plate | 1965-67 4 barrel | 59.00 |
| BC126 | 'Super Rocket' Aluminum Plate | 1965-67 2 barrel | 59.00 |



1966-69 Toronado Air Filter Plates: 1966-67 Toronado plate is a slate blue color with silver lettering. 1968-69 Toronado plate is a slate grey color with silver lettering. Both plates measure approx. 11 1/2" in diameter.

| | | | |
|--------------|---------------------------|------------------|-------|
| E131A | 'Toronado' Aluminum Plate | 1966-67 Toronado | 55.00 |
| E132A | 'Toronado' Aluminum Plate | 1968-69 Toronado | 55.00 |

1968 Aluminum Air Filter Plates:

There were a number of different air filter plates available in 1968 depending on the engine size and carburetor. The 2 Barrel plates measure 8" diam while all the 4 Barrel plates measure 11" diam. All plates are correctly reproduced with silver background, red lettering and black highlights. Shipped with a protective plastic film to prevent scratches while installing. They are retained to the air cleaner lid with chrome retainers listed on the previous page.

| | | | |
|---------------|--|-------------------|-------|
| DC106A | 'Rocket 350' 4 Barrel Air Filter Plate | 1968 350 4 barrel | 55.00 |
| BC133 | 'Rocket 455' 2 Barrel Air Filter Plate | 1968 455 2 barrel | 45.00 |
| DC107A | 'Rocket 455' 4 Barrel Air Filter Plate | 1968 455 4 barrel | 55.00 |



DC106A



BC133



DC107A


Air Filter Decals



| | | | |
|--------------|--|----------------------|-------|
| DC35 | Air Filter Decal 'Oldsmobile Rocket 350' | 1969-72 350 2 Brl | 12.00 |
| DC36 | Air Filter Decal 'Oldsmobile Rocket 350' | 1969-72 350 4 Brl | 12.00 |
| DC36A | Air Filter Decal 'Oldsmobile Rocket 455' | 1969-72 455 4 Brl | 12.00 |
| DC36B | Air Filter Decal 'Oldsmobile Rocket 455' | 1969-72 455 2 Brl | 12.00 |
| B134A | Air Filter Decal 'Oldsmobile Rocket 350' | 1973-75 350 2 Brl | 12.00 |
| B134 | Air Filter Decal 'Oldsmobile Rocket 350' | 1973-75 350 4 Brl | 12.00 |
| B134B | Air Filter Decal 'Oldsmobile 350' | 1973-75 350 4 Brl | 12.00 |
| B135 | Air Filter Decal 'Oldsmobile Rocket 455' | 1973-75 455 4 Brl | 12.00 |
| B135A | Air Filter Decal 'Oldsmobile 455' | 1973-75 455 4 Brl | 12.00 |
| DC101 | Air Filter Maintenance Decal | 1966-67 All 4 Barrel | 6.50 |
| DC40 | 'Keep your GM car all GM' Air Filter Decal | 1968-75 All | 6.50 |



DC36





DC36A



B135A

Miscellaneous Body, Interior, and Door Jamb Decals:







| | | | |
|--------------|---|---------------|------|
| D2 | Oil Filler Cap Decal | 1961-62 All | 5.00 |
| DC22 | GM 'MARK OF EXCELLENCE' Door Jamb Decal | 1966-70 All | 5.00 |
| BC21 | Tire Pressure Glove Box Decal | 1962 All | 5.50 |
| B22 | Tire Pressure Decal | 1963 All | 5.50 |
| DC23 | Tire Pressure Decal | 1966 All | 5.00 |
| BC23 | Tire Pressure Decal | 1968 88-98 | 5.50 |
| BC190 | Tire Pressure Decal | 1970 88-98 | 5.50 |
| E191 | Tire Pressure Decal | 1970 Toronado | 5.50 |
| DC42 | Alignment Stripes for Radiator Cap | 1968-75 All | 4.00 |
| DC43 | Engine Cooling System Decal | 1970-72 All | 5.00 |
| DC44A | GM Anti-Freeze Coolant Protection Level Decal | 1961-75 All | 5.00 |



| | | | |
|-------|----------------------------------|--|------|
| DC141 | Wheel Disc Mounting Instructions | 1961-64 Models with Deluxe Wheel Discs | 6.00 |
| BC142 | Superlift Air Shocks Decal | 1961-72 all Models with Superlift Shocks | 6.00 |
| DC27A | Glove Box Maintenance Decal | 1971-72 all Models | 6.50 |

Trunk Compartment Decals:

| | | | |
|--------|------------------------------|--|------|
| BC150A | Jack Instructions Decal | 1961 88-98-Starfire | 7.00 |
| BC150 | Jack Instructions Decal | 1962 88-98-Starfire | 7.00 |
| BC151 | Jack Instructions Decal | 1963 88-98-Starfire | 7.00 |
| BC152 | Jack Instructions Decal | 1964 88-98-Starfire | 7.00 |
| BC153 | Jack Instructions Decal | 1965 88-98-Starfire | 7.00 |
| BC155 | Jack Instructions Decal | 1966 88-98-Starfire | 7.00 |
| E159 | Jack Instructions Decal | 1966 Toronado | 7.00 |
| B162 | Jack Instructions Decal | 1967 Delta 88 | 7.00 |
| BC163 | Jack Instructions Decal | 1967 98 Models | 7.00 |
| E166 | Jack Instructions Decal | 1967 Toronado | 7.00 |
| BC167 | Jack Instructions Decal | 1968 88 Models | 7.00 |
| BC168 | Jack Instructions Decal | 1968 98 Models | 7.00 |
| E170 | Jack Instructions Decal | 1968 Toronado | 7.00 |
| B170 | Jack Instructions Decal | 1969 88 Models | 7.00 |
| E173 | Jack Instructions Decal | 1969 Toronado | 7.00 |
| BC175 | Jack Instructions Decal | 1970 88 Models | 7.00 |
| BC176 | Jack Instructions Decal | 1970 98 Models | 7.00 |
| E177 | Jack Instructions Decal | 1970 Toronado | 7.00 |
| B177 | Jack Instructions Decal | 1971 88 Models | 7.00 |
| BC179 | Jack Instructions Decal | 1972 88-98-Toronado | 7.00 |
| BC180 | Jack Instructions Decal | 1973 88-98-Toronado | 6.50 |
| BC181 | Jack Instructions Decal | 1974 88-98-Toronado | 6.50 |
| BC181A | Jack Instructions Decal | 1975 88-98-Toronado | 7.00 |
| BC154 | Jack Stowage Decal | 1965 88-98 Models | 7.00 |
| B156 | Jack Stowage Decal | 1966 88-98 Sedans | 7.00 |
| B157 | Jack Stowage Decal | 1966 88-98 Convertibles | 7.00 |
| E160 | Jack Stowage Decal | 1966 Toronado | 7.00 |
| BC164 | Jack Stowage Decal | 1967 88-98 Sedans | 7.00 |
| BC165 | Jack Stowage Decal | 1967 98 Convertibles | 7.00 |
| B168 | Jack Stowage Decal | 1968 88-98 Convertibles | 7.00 |
| BC169 | Jack Stowage Decal | 1968-70 88-98 Sedans | 7.00 |
| BC178 | Jack Stowage Decal | 1971 88-98 Sedans | 7.00 |
| BC179A | Jack Stowage Decal | 1972 88-98 Sedans | 7.00 |
| BCE182 | Jack Stowage Decal | 1973-75 88-98 Sedans and Toronado | 7.00 |
| BC191 | Jack Stowage Decal | 1971-75 Delta 88 Convertibles | 7.00 |
| DC98 | Jack Assembly Caution Decal | 1961-75 88-98-Starfire-Toronado | 6.50 |
| E161 | Jack Case Decal | 1966-70 Toronado | 7.00 |
| DC97 | Anti-Spin Differential Decal | 1962-75 88-98-Starfire with Positraction | 6.50 |



1960's Oldsmobile 'Owner Satisfaction' Decal: Reproduction of an Oldsmobile Service owner satisfaction decal from a 1965 Oldsmobile Service Department information package. Red and silver decal measures 4 1/4" x 4 1/4" and reads: "WE MAKE LITTLE THINGS COUNT...they add up to OWNER SATISFACTION" with the mid-60's Oldsmobile Service logo. A good spirit item for your 1960's Olds.

DC65S 'Owner Satisfaction' Decal 7.00



Fusick Automotive Gift Certificates: Available for any amount and customizable for any occasion. Always the right size and color. Contact us for details.



OLDSMOBILE CLUBS



Oldsmobile Club of America: For information on the club with over 6500 active members and 25 chapters worldwide, write: Oldsmobile Club of America, Inc., P.O. Box 80318, Lansing, Michigan 48908 or call 517-663-1811. You may also find information about the club online at the Oldsmobile Club of America website: <http://www.oldsobileclub.org>.



National Antique Oldsmobile Club of America: For information on the club with over 2,000 active members dedicated to the preservation, restoration, and enjoyment of all Oldsmobiles built between 1897 and 1964, write to: National Antique Oldsmobile Club, Inc., c/o Paul Hartlieb, 121 N Railroad Street, Myerstown, PA 17067 or visit the website at antiqueolds.org for more information.

OLDSMOBILE PERFORMANCE CLUB: Dedicated to Performance Oldsmobiles with a monthly e-newsletter called W-Machines Magazine that includes performance tips, historical information, technical information, parts locating, and more all geared towards performance Oldsmobiles. For information on joining contact: Olds Performance Club c/o Paul Tortorici, S&P Tees, P.O. Box 4012, South Hackensack, NJ 07606 or visit www.wildaboutcars.com for more info.



**OLDSMOBILE
PERFORMANCE CLUB**

TORONADO OWNERS ASSOCIATION: We are a non-profit volunteer organization dedicated to the preservation and promotion of one of Oldsmobile's most spectacular engineering and styling feats: the Toronado. We welcome every Toronado owner or enthusiast. Ownership of a Toronado or membership in any other organization is not required. For more information visit www.toronado.org or write Toronado Owners Association, PO Box 373, Hubertus, WI 53033-0373



For various USED parts such as sheet metal, body parts, chrome, accessories, and other parts where used will sufficiently do the job, contact the following individuals. We are not responsible for delivery or pricing nor do we have any direct business ties with the individuals listed. All individuals are responsible, quality minded Oldsmobile enthusiasts.

GM Sports Inc.
2403 Stagecoach Road
Stockton, California 95215
Phone: 209-462-4300
Fax: 209-462-4303

Reproduction 61/62/63 Starfire Panels

JASWEST
3831 Line 8
Bradford Ontario
Canada L3Z 3R8
Phone: 905-775-2641
Email: stevewestlake@jaswest.com
Website: www.jaswest.com

Bill Sandy
2403 County Rt. 1
Westtown, NY 10998
Phone: 845-726-0956
Fax: 845-726-3053
billsandy1936@hotmail.com
(Literature Only, No Parts)

Various 1960's NOS parts for
Toronado, 88's & 98's
Pat McMillan
phone: 618-554-4362
email: droidsparts@gmail.com
www.droidsmobilemuseum.com

For original seat or door panel material,
we suggest you contact:
SMS Auto Fabrics
350 South Redwood Street
Canby, Oregon 97013
Phone: 503-263-3535 Fax: 503-263-3525
www.smsautofabrics.com



| Part | Page | Part | Page | Part | Page |
|-----------------------------------|-------------|--------------------------------------|-------------|-------------------------------------|-------------|
| A-B | | G | | Power Brake Boosters | 48 |
| Antenna parts, mast, grommets | 6 | Gas Door Assemblies | 5 | Power Door Lock Switch | 23 |
| Ash Trays, rear armrest | 26 | Gaskets, Door Handle & Lock Cylinder | 12 | Power Steering Pump | 46 |
| Back Up Lenses & Housings | 6 | Gaskets, Outside Mirror | 4 | Power Window Motors | 8 |
| Battery Trays & Hold Down Parts | 35 | Gasket Sets, Engine | 39 | Power Window Switches | 23 |
| Bearings, Engine | 40 | Gasket, Trunk Lock Cylinder | 11 | Push Rods | 39 |
| Bearings, Front Wheel & Axle | 43 | Glove Boxes | 22 | R | |
| Bolts, Bumper | 52 | Grommet, Valve Cover | 41 | Radiator Cap | 31 |
| Bolts, Radiator Shroud & Fender | 52 | H | | Radiator Core Support Mount Kit | 31 |
| Boots, CV Inner and Outer | 45 | Handles, interior Door | 25 | Regulator, Voltage | 36 |
| Boots, Door Jamb Wiring | 8 | Handles, outside Door | 4 | Rocker Arms | 39 |
| Brake Master Cylinder | 48 | Handles, window crank | 25 | S | |
| Brake Shoes | 46 | Hardware, Brake | 47 | Sash Channel, quarter window | 4 |
| Bulbs, Headlamp | 5 | Harmonic Balancer Rebuilding Service | 29 | Scripts, Body Exterior | 2-3 |
| Bulbs, Interior & Exterior | 50 | Headlight Buckets | 5 | Seal, A-Frame | 9 |
| Bumper Fillers, Front and Rear | 17 | Headlight Retaining Rings | 5 | Seals, Front Wheel, Pinion, Axle | 43 |
| Bumpers, Fuel Tank Door | 12 | Heater Blower Motor | 31 | Sealing Strips, Rear Quarter Window | 14 |
| Bumpers, Hood, Trunk, Door Rubber | 12 | Hood Hinges | 30 | Seat Springs, Bucket Seat | 26 |
| Bumpers, Suspension | 42 | Hood Insulation Pad | 9 | Shock Absorbers | 42 |
| Bushings, Control Arm | 42, 45 | Hood Release Handle | 5 | Sound Deadener, Carpet to Floor | 19 |
| C | | Horns | 37 | Spare Tire Cover | 11 |
| Cables, Battery | 35 | Hoses, Front & Rear Brake | 47 | Spare Tire Retaining Parts | 11 |
| Cables, Parking Brake | 47 | Hoses, Power Steering | 45 | Spark Plugs | 36 |
| Camshaft | 40 | Hoses, Radiator | 32 | Springs, Coil | 43 |
| Carburetor Choke Stove | 38 | Housings, Dome & Courtesy Lamp | 18 | Stabilizer Links & Bushings | 42 |
| Carburetor Kits | 38 | I-J-K | | Straps, Wire Harness | 36 |
| Carburetors, Rebuilding Service | 29 | Ignition Wire Holders | 36 | Sun Visor Sleeves and Grommets | 22 |
| Carpet Sets | 19 | Ignition Wire Sets | 36 | Switch, Headlight | 33 |
| Channel, Flexible Side Window | 15 | Intake Valves | 40 | Switch, Ignition | 33 |
| Channel, Rubber Windshield & Rear | 16 | Insulator, Heater Hose | 52 | Switch, Stoplight | 33 |
| Clamps, Radiator & Heater Hose | 32 | Insulators, Coil Spring | 43 | Switch, Temp & Oil | 34 |
| Clips, Wheel Cover Retaining | 52 | Insulators, Radiator | 31 | T-U-V | |
| Coil Springs | 43 | Jar, Windshield Washer Plastic | 11 | Thermostat, Engine Coolant | 31 |
| Conduit/Boots, Door Jamb Rubber | 8 | L | | Timing Chain and Gears | 40 |
| Convertible Top Cables, Hoses | 7 | Lenses, Courtesy & Dome | 18 | Toronado Dash Knobs & Bezels | 21 |
| Convertible Top Cylinders, Pumps | 7 | Lenses, Back-up | 6 | Trim Panel Tabs | 52 |
| Convertible Top Latch, Switch | 7 | Lenses, Door Panel Lower | 18 | Trunk Bumpers, Rubber | 11 |
| Cowl Lacing Strips | 9 | Lenses, License Lamp | 6 | Trunk Cardboards | 10 |
| Cylinders, Wheel Brake | 46 | Literature | 51 | Trunk Mats | 10 |
| D | | Locks, Door, Trunk, Glove Box | 28 | Tubes, Trunk Rubber Drain | 17 |
| Decals, Engine and Body | 54-55 | M | | Tune-up Kit | 36 |
| Door Jamb Light Switch | 24 | Manifold, Exhaust | 40 | Turn Signal/Tilt Wheel Levers | 26 |
| Door Jamb Strikers | 24 | Manuals, Chassis Service | 51 | Universal Joints | 44 |
| Door Lock Buttons | 26 | Mats, Accessory rubber floor | 20 | Valve Covers | 41 |
| Door Sill Plates | 20 | Mats, Accessory rubber Trunk | 10 | Valve Guides | 40 |
| E | | Mirrors, Outside Chrome | 4 | Valve Lifters | 39 |
| Elements, Air Filter | 37 | Mirrors, Inside Rear View | 22 | Valve Springs | 39 |
| Emblems, Body Exterior | 2-3 | Motor, Heater Fan | 31 | W-X-Y-Z | |
| Engine Parts | 39-41 | Mounts, Transmission | 30 | Water Pumps | 29 |
| Exhaust Tips, Chrome, Toronado | 5 | Mounts, Engine | 30 | Washer Jars & Parts | 11 |
| Exhaust Valves | 40 | N | | Weatherstrip, Convertible Top | 13 |
| F | | Nut, Power Antenna Chrome | 6 | Weatherstrip, Door Body Pillar | 13 |
| Fasteners, License Plate | 5 | Nut, Carburetor Wing | 52 | Weatherstrip, Vent Window | 16 |
| Fender Skirt Rubber | 12 | O-P-Q | | Weatherstrip, Windshield | 16 |
| Firewall Insulation Pads | 20 | Oil Filler Cap | 37 | Weatherstrip, Rear Window | 16 |
| Floor Mats, Accessory Rubber | 20 | Oil Filter | 37 | Weatherstrip, Windshield Pillar | 13 |
| Fuel Caps | 30 | Package Trays | 27 | Weatherstrip, Door & Roof Rail | 13-15 |
| Fuel Pumps | 29 | Paint, Engine | 41 | Weatherstrip, Quarter Window | 14 |
| Fuel Pump Rebuild Kits | 29 | Pistons, Piston Rings | 40 | Weatherstrip, Trunk | 11 |
| Fuel Tank, Toronado | 30 | Plate, Air Filter Aluminum | 53 | Wire Sets, Ignition | 36 |